

VO | CC 4 / ASM 150 10795, VUA 39 | LKK 57387

Surveyor: Sathya DOI: 13-6-18 Date / Time: 12/6/2018

Pre-assign / CCU / FTE

PC 3446Y "VIRTUAL"

S8m00kel



Insured Vehicle No. : 201-WINS TRANSPORT SERVICES PVT Claim No. : 1916312
 Name of Insured : 201-WINS TRANSPORT SERVICES PVT Policy No. : 7-HIALB
 Insured Tel No. : HP: 8-6-18 Make / Model : PIE - Juny.
 Excess Sec II : \$5 D.O.A : 8-6-18 Place of Accident : PIE - Juny.
 Is driver the owner? (YES / NO) Nature of Accident :
 If NO, Driver Name / Age : ROSHAMIL BIN SUKANA OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO
 Driver Tel No. : 90029731/90029731/41412 Insured Liability : % Final ? Yes / No

SLF 5438P



INSRS: Auto Insure
WSP: Auto Insure
Tel: Auto Insure
Liability: Auto Insure
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time		STAGE	DATE / PIC
7/6/18	SLF 5438P - X ; PC 3446Y - X	Non-Reporting Itr (1st)	
7/6/18		Non-Reporting Itr (2nd)	
		Non-Reporting Itr (Final)	
		Notification Itr (if non-pickup)	
		Call OI:	
		After call Itr to OI:	
		Documentation Check List: Handler Typist	
		Notification Itr (if non-pickup)	
		After call Itr to OI:	
		Authorization To Act:	
		Release Voucher:	
		Final Repair Bill:	
		Car Rental Invoice:	
		Towing Invoice:	
		LTA / GIA :	
		Medical Bill:	
		PIR:	
		Mandate/Reject Instruction:	
		LOD	
		Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	

Pl's policy & CI attached.
 * To reject TP claim. or reported to come out from ship Ad.
 Instruction from AXA to maintain rejection.

Stamp: 13/9/18

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: _____

Repair Cost: \$5 (_____ days) Reduction: _____ % Email Call

FINAL SETTLEMENT Date/Time: _____ Confirm with: _____ Email Call

Final Liability: % (Agreed / Assessed) BOLA S/N No.:

Repair Cost: \$5

Loss of Rental (LOR): \$5 (_____ days)

Loss of Use (LOU): \$5 (5 x _____ days)

Loss of Income (LOI): \$5 (5 x _____ days)

LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

GIA/LTA Search: \$5

Medical: \$5

Disbursement: \$5 (e.g. Tow/Independent)

Legal Cost: \$5

Total: \$5 **Global Sum \$5:** _____

FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email Call

Payee 1: \$5 Name 1: _____

Payee 2: (Strike if N.A.) \$5 Name 2: _____

Payee 3: (Strike if N.A.) \$5 Name 3: _____

COPY SENT 13/9/18

- 1) Claim status: Normal/Reject/Private Settle
- 2) Report Format:
- 3) Survey fee: \$ 350

ASSIGNMENT

From: _____ Date: 13062018

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLF 5438P

at Workshop n/s: Auto Insure

of: 6 nursing care

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: 'Virtual'

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 65k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res: Yes or No

Lum Sum: PIP % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLF 5438 P Yr Regn: Aug 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Mazda 3 cc: 1496

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 163797 T/Radio: Insured / Std / NI / NA

Eng. No: P520377407

C/No: JM6BM42A8G0347362

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / SiRim / STD A/Rim or

Tyre Size F: P205 / 60 R16
R: P205 / 60 R16


BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Aeolus

Front	Rear
R/Bal. 6 mm	R/Bal. 6 mm
L/Bal. 6 mm	L/Bal. 6 mm
D.O.A 8/6/2018	D.O.I 13/6/2018

Survey held at: Auto Insure

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or Rear O/S

The UIC / Chassis frame / Body Structure affected due to collision



\$ 3337.56 (Red: \$ 8228.24 / 71%)

Date/Time, File Pass to?

 : Preli. Report
 : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Date/Time, File Return to?

- Add Fee:
- Site Insp \$
 - Interview \$
 - Tech. Invs \$
 - Weekend \$

Transportation:

Other:

Report Format :

Lump Sum / L.B.t: \$



Auto Insure Pte. Ltd.

Blk 3, 391A Woodlands Road
Yew Tee Industrial Estate
Singapore (677964)
E: claims@autoinsure.com.sg
W: www.autoinsure.com.sg
T: 6368 2788 F: 6368 0081
GST No.: 201437380M

Page No.1

AUTOMOBILE ASSESSMENT REPORT

Our Ref: SLF5438P

Your Ref: PC3446Y

Date: 11-Jun-18

BY EMAIL ONLY
(claims@autoinsure.com.sg)

ATTENTION: MOTOR CLAIMS DEPT

email: motor.survey@axa.com.sg

8 Shenton way
#27-01/02 AXA Tower
Singapore 068811

Assessed Vehicle No : SLF5438P
Car Make and Model : MAZDA3 1.5L SDN
Date of Accident : 8-Jun-18
Date of Assessment : 11-Jun-18

We have carried out a physical assessment of SLF5438P at our workshop Auto Insure Pte Ltd sustained damages to the REAR RH portion of the vehicle.


4. DESCRIPTION OF DAMAGE

At the time of the inspection observed that this vehicle had sustained damages to the REAR LH portion of the vehicle.

Please see attached schedule for details.

Remarks: NIL

Estimated Amount : P/P
Adjusted Amount : S 11,500.00
Est. Repair Days : 7



** Considering that our vehicle is less than 6 months old.
We will not agree to any repair of parts, only replacement will be done. **

Pursuant to your instruction, we have **NOT AUTHORIZED** repair.
The assessment was conducted on a "**WITHOUT PREJUDICE**" basis.

If we are not notified of anything within 14 Days from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss of occurrence in which the assessed vehicle is involved.

No liability or responsibility whatsoever shall be held by

AUTO INSURE PTE. LTD. For any reliance on this report by any third party.

Our Ref: SLF5438P
 Your Ref: PC3446Y

S/NO	QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKSHOP
PARTS REPLACEMENT - LIST ITEMS				
1	1	REAR BUMPER ✓ Dmg		\$ 1,320.00 1074.20
2	1	REAR REINFORCEMENT 3x		\$ 589.90
3	1	REAR FENDER RH X	} NN	\$ 485.50
4	1	REAR BUMPER SIDE RETAINER 3x		\$ 48.20
5	1	REAR FENDER INNER SHIELD RH X		\$ 279.20
6	1	REAR FENDER TAIL LAMP RH ✓ CRK		\$ 685.90
7	1	REAR BOOT TAIL LIGHT RH X	} NN	\$ 425.00
8	1	REAR TAIL LAMP SIDE CLIP RH 3x		\$ 45.00
9	1	REAR TAIL LAMP PANEL RH 3 ✓ OT		\$ 245.00
10	1	BOOT R		\$ 1,085.00
11	3	BOOT EMBLEM ✓ NEC		\$ 210.00
12	1	RIM R		\$ 550.00
13	1	REAR LOWER ARM RH 2x	} NN	\$ 358.00
14	1	REAR KNUCKLE ARM RH 3x		\$ 472.00
15	1	REAR ABSORBER RH 2x		\$ 498.00
16	1	REAR WHEEL BEARING RH 3x		\$ 84.90
SUB TOTAL				\$ 8,467.70
LESS 20%				\$ 1,693.54
TOTAL AMOUNT				\$ 6,774.16

Our Ref: SLF5438P
 Your Ref: PC3446Y

S/NO	QTY	SPECIAL NETT ITEMS	ASSESSED CONDITION	EST. BY WORKSHOP
1	1 SET	REAR BUMPER CLIPS		\$ 30.00 ✓ NEC
	1	REAR TOWING CAP		\$ 75.00 ✓ MS
SUB TOTAL				\$ 135.00
TOTAL PARTS COST				\$ 6,909.16

Our Ref: SLF5438P
 Your Ref: PC3446Y

S/NO	DESCRIPTION	EST. BY WORKSHOP
LABOUR & PAINTWORK		
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS	\$ 1,500.00 600
2	TOWING CHARGE	\$ -
3	TO DIAGNOSE ERASE FAULT MEMORY AFTER REPAIR	\$ 150.00 30
4	REMOVE AND REFIX REAR WINDSCREEN	\$ 200.00 X
5	TO REMOVE / REFIX WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER FUNCTIONS	\$ 200.00 30

6	TO REMOVE / REFIX UPHOSTERY, GARNISH AND ATTACHMENT PARTS	\$	-	
7	TO REMOVE /INSTALL DOOR MECHANISIM,PANEL AND MIRROR	\$	250.00	X
8	TO REMOVE / REFIX REAR LUGGAGE COMPARTMENT	\$	-	
9	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED	\$	1200.00	600
10	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	\$	200.00	100
11	TO VACUUM, WAXING & CLEAN	\$	100.00	X
12	TO PERFORM WATER SEEPAGE TEST ON REPAIRED PORTIONS	\$	100.00	X
		TOTAL BEFORE GST	\$	10,809.16
		GST 7%	\$	756.64
		TOTAL (PARTS & LABOUR):	\$	11,565.80

Adjustments / Recommendations

Our estimator have thoroughly inspected each and every item on the estimate against physical damage found on the vehicle and have listed the breakdown of our finding and recommendation.

Our Workshop has agreed to undertake the job at a sum of \$11,500.00 for direct settlement with the third party insurance.

Yours Faithfully,

Jason Heng
Claims Director

Sathya Sui
13/6/2018
98072012

3 days

<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p>
--

- Part by Part repair
- Question mark item photo
- Photo before paint

$$\begin{array}{r}
 2215.7 \\
 - \quad 20\% \\
 \hline
 1772.56 \\
 + 105 \\
 + 1460 \\
 \hline
 3337.56
 \end{array}$$

COR: \$ 3337.56 @ 3 days



Auto
Consultants
Pte Ltd

Company Registration No. 199607188R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (665) 62563561 FAX : (665) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 18/6/2018

Survey Details:

Date of loss	8-Jun-18
Date of appointment	12-Jun-18
Date of survey	13-Jun-18
Location of survey	Auto Insure Pte Ltd

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SLF 5438P
Make and Model	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT - 1496cc
Date of registration	30-Aug-16
Excess	
Market Value	\$ 65,000.00
Parf Rebate	\$ 51,460.00
Nett Loss	\$ 13,540.00

Repair details:

Initial Estimate	\$ 10,809.16
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 1,912.92
Check items (estimate)	\$ 1,872.48
Labour	\$ 1,460.00
Total	\$ 5,245.40
Lump Sum(if applicable)	\$ -

Number of days for repair	3 days
----------------------------------	---------------

<< Service Request Details

Claim: S8M00KEL
 Reference: CC4/ASM18010795/Vua3 ✎
 Loss Date: 8 June 2018
 Request Date: 12 June 2018
 Due Date: 12 June 2019
 Vendor Name: LKK AUTO CONSULTANTS PTE LTD (TP)
 Type of Loss: Third Party Vehicle Damage
 Services: Pending verification - Direct Settlement

Actions

Next Step: Finish the work

Complete Work | More ▾

Vehicle Information

Incident: 5LF5438P
 Vehicle Registration #
 Make: TPVD MAZDA
 Model: 3-1.5 4 DOOR SEDAN SP (A)

Service Address

...

Primary Contact/Insured

TRI-WINS TRANSPORT SERVICES PTE LTD
 BLK 808 FRENCH ROAD, #06-159
 KITCHENER COMPLEX, 200808, Singapore
 63380083
 GRACE@VIRTUALINVEST.BIZ

Claim Handler

OH Vale
 6568804897
 vale.oh@axa.com.sg

Additional Instructions: VIRTUAL CASE NON REPORTING DO NOT FINALISE WITH TP ON COR

Messages | Invoices | History | Documents | Assessment | Metrics | Notes

New Message

TYPE	SENT	FROM	SUBJECT	BODY	
📧	10/7/18 9:33 AM	OH Vale	Re:RE: REJECT TP CLAIM	Hi Pls maintain rejection. Regards Vale	↩
📧	9/7/18 2:52 PM	OH Vale	Re:RE: REJECT TP CLAIM	KIV COULD BE A REPUDIATION CASE NOW, WILL KEEP YOU...	↩
📧	6/7/18 3:22 PM	LKK AUTO CONSULTANTS PTE LTD (TP)	RE: REJECT TP CLAIM	Dear Vale, We refer to your message dated 21/06/20...	↩

TYPE	SENT	FROM	SUBJECT	BODY	
	21/6/18 10:08 AM	OH Vale	REJECT TP CLAIM	Hi Pls proceed to reject TP claim as Insured rep...	
	13/6/18 9:08 AM	OH Vale	VIRTUAL CASE-DO NOT FINALISE ON COR-VO		
	13/6/18 9:07 AM	OH Vale	Re:REQUEST SURVEYOR LIST	Hi Pls informed that only you or RT. If they not...	
	12/6/18 5:47 PM	LKK AUTO CONSULTANTS PTE LTD (TP)	REQUEST SURVEYOR LIST	Please be informed that repairer request Surveyor ...	

Thin Thin (LKKAuto)

From: Thin Thin (LKKAuto)
Sent: Thursday, 13 September 2018 3:18 PM
To: 'AutoInsure (Claims)'
Subject: RE: PRS SLF5438P *** LKK REF: CC4/ASM18010795/Vua3

Without Prejudice,

Dear Sir / Madam,

We refer to the below matter.

Please be inform that we have convey your message to our Principal. However, firm instruction given by our principal to inform you that we maintain our stand.

Thanks.

Best Regards,

Thin Thin Hlaing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2360 | email: thinthin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: claims01@web-designers.com <claims01@web-designers.com> **On Behalf Of** AutoInsure (Claims)

Sent: Thursday, 13 September 2018 3:15 PM

To: Thin Thin (LKKAuto) <thinthin@lkkauto.com>

Subject: Re: PRS SLF5438P *** LKK REF: CC4/ASM18010795/Vua3

Dear Thin Thin,

We refer to the above matter and to your email below.

Kindly be informed that your insured's driver has admitted liability for the above matter.

We enclosed herewith a copy of the said admission note for your attention.

Kindly let us have your reply soon.

Thanks.

****Kindly note that our mailing address is as follows:***

6 Marsiling Lane S739145

tel: (65) 3157 2626

Please mail all future correspondence to stated address.*

Regards

Alywin Yeo
did: (65) 3157 2624 / 3157 2628
mobile: (65) 9743 6363
e: claims01@autoinsure.com.sg

Auto Insure Pte. Ltd.
201437380M
6 Marsiling Lane S739145

t: (65) 3157 2626
f: (65) 6368 0081
w: www.autoinsure.com.sg
g.e: claims@autoinsure.com.sg

-- Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail.--

Data Privacy Policy Notice: *Auto Insure Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.*

On Thu, Sep 13, 2018 at 3:07 PM, Thin Thin (LKKAuto) <thinthin@lkkauto.com> wrote:

Without Prejudice,

Dear Sir / Madam,

We refer to the below matter.

We regret to inform you that we have our Principal instruction to maintain our stand.

Thanks.

Best Regards,

Thin Thin Hlaing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2360 | email: thinthin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: claims01@web-dezigners.com <claims01@web-dezigners.com> **On Behalf Of** AutoInsure (Claims)

Sent: Wednesday, 4 July 2018 5:20 PM

To: Thin Thin (LKKAuto) <thinthin@lkkauto.com>

Cc: Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>

Subject: Re: PRS SLF5438P *** LKK REF: CC4/ASM18010795/Vua3

WITHOUT PREJUDICE

Dear Thin Thin,

R

refer to your rejection email below.

We were informed by our client's hirer that he was already exited the slip road and was travelling along the said main road while your insured's driver suddenly hit onto his right rear portion and not exiting from the slip road.

However, based on conflicting version of both report, we are of the view that your insured's driver should concede certain liability for the above matter while lack of evidence such as in-car video footage and/or witness.

Please let us have your reply soon.

Thanks,

**Kindly note that our mailing address is as follows:*

6 Marsiling Lane S739145

tel: (65) 3157 2626

*Please mail all future correspondence to stated address.**

Regards

Geraldine Lim / Alywin Yeo

did: (65) 3157 2624 / 3157 2628

mobile: (65) 9743 6363

e: claims01@autoinsure.com.sg

Auto Insure Pte. Ltd.
201437380M
6 Marsiling Lane S739145

t: (65) 3157 2626

f: (65) 6368 0081

w: www.autoinsure.com.sg

g.e: claims@autoinsure.com.sg

-- Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail.--

On Wed, Jul 4, 2018 at 4:40 PM, Thin Thin (LKKAUTO) <thinthin@lkkauto.com> wrote:

"Without Prejudice"

Dear Sir / Madam,

ACCIDENT ON 08/06/2018 INVOLVING VEHICLES PC 3446Y AND SLF 5438P

We refer to the below matter.

According to our insured, he was travelling along PIE towards Jurong on the extreme left lane. Suddenly your client vehicle emerged from Upper Changi road turning out to PIE and collided with our insured vehicle. Enclosed herewith a copy of our insured's accident report for your perusal.

Under such a circumstances, our principal has given the instruction to inform you that we are to reject your client claim and deny the liability, unless you have concrete evidence to prove otherwise.

Best Regards,

Thin Thin Hlaing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2360 | email: thinthin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAuto)

Sent: Wednesday, 13 June 2018 3:46 PM

To: AutoInsure (Claims) <claims01@autoinsure.com.sg>

Cc: Thin Thin (LKKAuto) <thinthin@lkkauto.com>; Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: PRS SLF5438P *** LKK REF: CC4/ASM18010795/Vua3

Dear Sir / Madam,

We refer to the above matter.

Please be informed that OI has yet to report the accident and we are currently **pending verification for direct settlement**.

Please provide us evidence i.e. video and scene photo.

Please note that for liability, claim negotiation and settlement, please contact Thin Thin at 6841 2360.

Our respective case handler will look into the matter and revert to you in due course.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: claims01@web-dezigners.com [<mailto:claims01@web-dezigners.com>] **On Behalf Of** AutoInsure (Claims)

Sent: Monday, 11 June, 2018 4:07 PM

To: SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg>

Subject: PRS SLF5438P

WITHOUT PREJUDICE

Hi,

* Attached for your attention.

****As we are doing direct settlement with your company, please give us a list of SJE (single joint expert) to choose from.**

Thanks.

***Kindly note that w.e.f 21st Mar 2017, we are relocated to:**

6 Marsiling Lane S739145

tel: (65) 3157 2626

Please mail all future correspondence to stated address.*

Regards

Geraldine Lim

did: (65) 3157 2624 / 3157 2628

mobile: (65) 9743 6363

e: claims01@autoinsure.com.sg

**Auto Insure Pte. Ltd.
201437380M
6 Marsiling Lane S739145**

t: (65) 3157 2626

f: (65) 6368 0081

w: www.autoinsure.com.sg

g.e: claims@autoinsure.com.sg

-- Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail.--

Service Request Details

Claim	SRM00KEL
Reference	CCA/ASIM19010795/Vua3ip
Loss Date	8 June 2018
Request Date	12 June 2018
Due Date	
Vendor Name	LAX AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next Step: **Wait for Approve Invoice**

[Add Invoice](#)

Vehicle Information	
Incident Vehicle Registration #	SLF543BP
Make	TPVD MAZDA
Model	3-1.5 4 DOOR SEDAN SP (A)
Service Address	

Primary Contact/Insured	
TRI-WINS TRANSPORT SERVICES PTE LTD BLK BOB FRENCH ROAD, #06-159 KITCHENER COMPLEX, 200808, Singapore 63380083 GRACE@VIRTUALINVEST.BIZ	

Claim Handler	
OH Vale 6568804897 vale.oh@axa.com.sg	

Additional Instructions: VIRTUAL CASE NON REPORTING DO NOT FINALISE WITH TP ON COR

Messages Invoices History Documents Assessment Metrics Notes

Document Type: Document SubType:

[+ Upload Documents](#)

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
INSURED GIA REPORT	Reports & Statement	GIA Report	Meirimen	

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
■ LKKInvoice1.pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	21 September 2018
■ LKKInvoice1.pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	21 September 2018
■ LKKInvoice1.pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	21 September 2018
■ Reject letter to TP.pdf	Letters and Correspondence	Workshop	LKK AUTO CONSULTANTS PTE LTD (TP)	13 September 2018
■ email from TP.pdf	Evidence	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	6 July 2018
■ TP STATEMENT (ADMIT LIABILITY).doc	Evidence	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	6 July 2018
■ TP ESTIMATE - MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	23 June 2018
■ Immediate Advice.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 June 2018
■ LKK RESURVEY PHOTO-2.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 June 2018
■ LKK RESURVEY PHOTO-1.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 June 2018
■ LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 June 2018
■ EMAIL FROM WORKSHOP TP PRL.mog	Letters and Correspondence	Workshop	VISHNU BATHAM Shekhar	12 June 2018
■ P1916712_Itn_00005_1.pdf	Forms / Claim Documents	Policy Schedule / Coversate / Certificate of insurance	OH Vale	12 June 2018
■ P1916712_CL_00005_1.pdf	Forms / Claim Documents	Policy Schedule / Coversate / Certificate of insurance	OH Vale	12 June 2018

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary Parts

EDIT	SR MO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPL/ RTN%	DISC QUANTY	SALV AGEN.	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	1	1			REAR BUMPER			Damaged	1074.8		20		859.84	Approve	
	2	1			REAR REINFORCEMENT			Serviceable	0	0	0	0	0	Deny	
	3	1			REAR FENDER RH			Serviceable	0	0	0	0	0	Deny	
	4	1			REAR BUMPER SIDE RETAINER			Serviceable	0	0	0	0	0	Deny	
	5	1			REAR FENDER INNER SHIELD RH			Serviceable	0	0	0	0	0	Deny	
	6	1			REAR FENDER TAIL LAMP RH			Cracked	885.9		20		548.72	Approve	
	7	1			REAR BOOT TAIL LIGHT RH			Serviceable	0	0	0	0	0	Deny	
	8	1			REAR TAIL LAMP SIDE CLIP RH			Serviceable	0	0	0	0	0	Deny	
	9	1			REAR TAIL LAMP PANEL RH			Distorted	245		20		196	Approve	
	10	1			BOOT			Repair	0	0	0	0	0	Deny	
	11	3			BOOT EMBLEM			Necessary	70		20		168	Approve	
	12	1			RIM			Repair	0	0	0	0	0	Deny	
	13	1			REAR LOWER ARM RH			Serviceable	0	0	0	0	0	Deny	
	14	1			REAR KNUCKLE ARM RH			Serviceable	0	0	0	0	0	Deny	
	15	1			REAR ABSORBER RH			Serviceable	0	0	0	0	0	Deny	

EDIT	SIR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEFL/ BITTEN	DISC QUNT'S	SALV AGE'S	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	16	1			REAR WHEEL BEARING RH			Serviceable	0	0	0	0	0	Deny	

Labour

EDIT	SIR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR HR	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
	1	800	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS	0	0	0	Approve		
	2	0	TOWING CHARGE (NPA)	0	0	0	Deny		
	3	80	TO DIAGNOSE ERASE FAULT MEMORY AFTER REPAIR	0	0	0	Approve		
	4	0	REMOVE AND REFIX REAR WINDSCREEN	0	0	0	Deny		
	5	80	TO REMOVE/REFIX WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER FUNCTIONS	0	0	0	Approve		
	6	0	TO REMOVE/REFIX UPHOLSTERY ,GARNISH AND ATTACHMENT PARTS (NPA)	0	0	0	Deny		
	7	0	TO REMOVE/INSTALL DOOR MECHANISMS ,PANEL AND MIRROR	0	0	0	Deny		
	8	0	TO REMOVE/REFIX REAR LUGGAGE COMPARTMENT (NPA)	0	0	0	Deny		
	9	600	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFT ON PARTS REPLACED	0	0	0	Approve		
	10	0	TO VACUUM,WAXING & CLEAN	0	0	0	Deny		
	11	0	TO PERFORM WATER SEEPAGE TEST ON REPAIRED PORTION	0	0	0	Deny		

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR \$/HR	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
	12		TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	100	0	0	Approve		

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Rates Parts & Labour Miscellaneous Summary

EDIT	SIR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	1	DAYS OF REPAIR-3 DAYS	Approve			
	2	SET REAR BUMPER CLIPS	Approve	30	NECESSARY	
	3	REAR TOWING CAP	Approve	75	MISSING	

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary Claim Amount **\$3,337.56**

Claim Amount **\$3,337.56**

CATEGORY	ESTIMATE	REVISED AMOUNT
Spare Parts	\$1,772.56	\$1,772.56
Labour	\$1,460.00	\$1,460.00
Miscellaneous	\$105.00	\$105.00