



Auto Insure Pte. Ltd.

Blk 3, 391A Woodlands Road
Yew Tee Industrial Estate
Singapore (677964)
E: claims@autoinsure.com.sg
W: www.autoinsure.com.sg
T: 6368 2788 F: 6368 0081
GST No.: 201437380M

Page No.1

AUTOMOBILE ASSESSMENT REPORT

Our Ref: SLF5438P
Your Ref: PC3446Y
Date: 11-Jun-18

BY EMAIL ONLY
(claims@autoinsure.com.sg)

ATTENTION: MOTOR CLAIMS DEPT

email: motor.survey@axa.com.sg

8 Shenton way
#27-01/02 AXA Tower
Singapore 068811

Assessed Vehicle No : SLF5438P
Car Make and Model : MAZDA3 1.5L SDN
Date of Accident : 8-Jun-18
Date of Assessment : 11-Jun-18

We have carried out a physical assessment of SLF5438P at our workshop Auto Insure Pte Ltd sustained damages to the REAR RH portion of the vehicle.


4. DESCRIPTION OF DAMAGE

At the time of the inspection observed that this vehicle had sustained damages to the REAR LH portion of the vehicle.

Please see attached schedule for details.

Remarks: NIL

Estimated Amount : P/P
Adjusted Amount : \$ 11,500.00
Est. Repair Days : 7



** Considering that our vehicle is less then 6 months old.
We will not agree to any repair of parts, only replacement will be done. **

Pursuant to your instruction, we have **NOT AUTHORIZED** repair.
The assessment was conducted on a "**WITHOUT PREJUDICE**" basis.

If we are not notified of anything within 14 Days from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss of occurrence in which the assessed vehicle is involved.

No liability or responsibility whatsoever shall be held by

AUTO INSURE PTE. LTD. For any reliance on this report by any third party.

Our Ref: SLF5438P
 Your Ref: PC3446Y

S/NO	QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKSHOP
PARTS REPLACEMENT - LIST ITEMS				
1	1	REAR BUMPER ✓DMG		\$ 1,326.50
2	1	REAR REINFORCEMENT ?		\$ 589.90
3	1	REAR FENDER RH X		\$ 685.50
4	1	REAR BUMPER SIDE RETAINER ?		\$ 48.20
5	1	REAR FENDER INNER SHIELD RH X		\$ 279.20
6	1	REAR FENDER TAIL LAMP RH ✓CRK		\$ 685.90
7	1	REAR BOOT TAIL LIGHT RH X		\$ 425.00
8	1	REAR TAIL LAMP SIDE CLIP RH ?		\$ 45.00
9	1	REAR TAIL LAMP PANEL RH ?		\$ 245.00
10	1	BOOT R		\$ 1,965.00
11	3	BOOT EMBLEM ✓NEC		\$ 210.00
12	1	RIM R		\$ 550.00
13	1	REAR LOWER ARM RH ?		\$ 358.00
14	1	REAR KNUCKLE ARM RH ?		\$ 472.00
15	1	REAR ABSORBER RH ?		\$ 498.00
16	1	REAR WHEEL BEARING RH ?		\$ 84.50
SUB TOTAL				\$ 8,467.70
LESS 20%				\$ 1,693.54
TOTAL AMOUNT				\$ 6,774.16

Our Ref: SLF5438P
 Your Ref: PC3446Y

S/NO	QTY	SPECIAL NETT ITEMS	ASSESSED CONDITION	EST. BY WORKSHOP
1	1 SET	REAR BUMPER CLIPS		\$ 60.00 ✓NEC
	1	REAR TOWING CAP		\$ 75.00 ✓MS
SUB TOTAL				\$ 135.00
TOTAL PARTS COST				\$ 6,909.16

Our Ref: SLF5438P
 Your Ref: PC3446Y

S/NO	DESCRIPTION	EST. BY WORKSHOP
LABOUR & PAINTWORK		
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS	\$ 1,500.00 600
2	TOWING CHARGE	\$ -
3	TO DIAGNOSE ERASE FAULT MEMORY AFTER REPAIR	\$ 150.00 80
4	REMOVE AND REFIX REAR WINDSCREEN	\$ 200.00 X
5	TO REMOVE / REFIX WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER FUNCTIONS	\$ 200.00 80

6	TO REMOVE / REFIX UPHOSTERY. GARNISH AND ATTACHMENT PARTS	\$	-	
7	TO REMOVE /INSTALL DOOR MECHANISIM,PANEL AND MIRROR	\$	250.00	X
8	TO REMOVE / REFIX REAR LUGGAGE COMPARTMENT	\$	-	
9	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED	\$	1,200.00	600
10	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	\$	200.00	100
11	TO VACUUM, WAXING & CLEAN	\$	100.00	X
12	TO PERFORM WATER SEEPAGE TEST ON REPAIRED PORTIONS	\$	100.00	X
		TOTAL BEFORE GST	\$ 10,809.16	
		GST 7%	\$ 756.64	
		TOTAL (PARTS & LABOUR):	\$ 11,565.80	

Adjustments / Recommendations

Our estimator have thoroughly inspected each and every item on the estimate against physical damage found on the vehicle and have listed the breakdown of our finding and recommendation.

Our Workshop has agreed to undertake the job at a sum of \$11,500.00 for direct settlement with the third party insurance.

Yours Faithfully,

Jason Heng
Claims Director

Sathya Sai
13/6/2018
98072012

3 days

<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p>
--

- Part by Part repair
- Question mark item photo
- Photo before paint