

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4490G
 Ref. No : TAX/06/18/2046
 Reg. Date : 09/04/2014
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : ANTHONNY CHIA YONG KOON
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 09/06/2018 07:20:00 PM
 Accident Reported Date / Time : 11/06/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024096533
 Special Instruction to ARC, if any :
 SLF1163H
 Prepared Date : 11/06/2018 05:06:13 PM



Sathya Sai

12/6/2018

- Lump Sum Repair
- Question mark item photo
- Photo after paint

4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Chassis No : JTDKN36U005740897

Mileage

: 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	0.00
Total Spray Painting Charges	: 2,034.00	0.00
Total Material Charges	: 6,199.70	6,199.70
Other Charges	: 1,075.00	0.00
TOTAL	: 10,322.70	0.00
Lum Sum Total	: 10,300.00	0.00
No. of Repair Days	: 6.00	0.00 4 days
Prepared / Adjusted By	:	
Arc / Surveyor Sign Off Date	: 12/06/2018 01:42:41 PM	01/01/1900 12:00:00 AM

Prepared / Adjusted Date :

Remarks :

Prepared Date : 12/06/2018 01:40:21 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount : 0.00	Prepared Date : 6/12/2018 1:43:04 PM

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	1,014.00	0.00 800
Total Labour	1,014.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO RESPRAY FRONT FENDER LH	378.00	0.00 200
TO RESPRAY APRON PANEL LH	180.00	0.00 ?
TO RESPRAY RIM	180.00	0.00 100
TO TOUCH FRONT PILLAR LH	180.00	0.00 X
TO RESPRAY FRONT DOOR LH	378.00	0.00 200
TO RESPRAY ROCKER PANEL MOULDING	180.00	0.00 100
TO RESPRAY VIEW MIRROR	180.00	0.00 80
Total Spray Painting & Panel Beating	2,034.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 50
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 60
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00 60
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0.00 X
TO REMOVE & REFIX FRONT LHS/RHS QUATER GLASS	120.00	0.00 60
TO TRANSFER DOOR MECHANISM	120.00	0.00 60
TO REMOVE AND REFIX UNDERCARRIAGE	250.00	0.00 120
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	1,075.00	0.00

Part Number	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52119-47930	6505517 BUMPER FRT <i>R</i>	1	482.00	25.00	361.50	Replace	Replace	No
52161-16010	BUMPER CLIPS <i>✓NEC</i>	10	1.61	25.00	12.07	Replace	Replace	No
52116-47040	6505516 BUMPER SUPPORT <i>?</i> F/LH	1	76.40	25.00	57.30	Replace	Replace	No
81170-47500	6505436 HEAD LAMP LH <i>?</i>	1	945.20	10.00	850.68	Replace	Replace	No
53802-47050	6505558 FENDER FRT/LH <i>✓DT</i>	1	723.40	25.00	542.55	Replace	Replace	No
75374-47051	NAME PLATE (HYBRID) <i>✓NEC</i>	1	51.90	25.00	38.92	Replace	Replace	No
53720-12030	FENDER APRON <i>?</i> FRT/LH	1	140.80	25.00	105.60	Replace	Replace	No
53876-47030	6505554 FENDER LINER <i>?</i> FRT/LH	1	171.70	25.00	128.77	Replace	Replace	No
53852-47020	FENDER LINER PAD, <i>?</i> FR WHEEL. LH	1	49.30	25.00	36.97	Replace	Replace	No
53828-47060	PROTECTOR, FRONT FENDER SIDE PANEL <i>?</i> LH	1	114.50	25.00	85.87	Replace	Replace	No
62120-47021	QUARTER GLASS <i>X</i> FRT/LH	1	234.90	25.00	176.17	Replace	Replace	No
COMMO N	SEALANT W/SCREEN <i>X</i>	1	37.00	0.00	37.00	Replace	Replace	No
48520-80294	SHOCK ABSORBER <i>?</i> FRT/LH	1	394.20	25.00	295.65	Replace	Replace	No
43202-47030	STEERING KNUCKLE <i>?</i> LH FRT	1	580.80	25.00	435.60	Replace	Replace	No
48609-47040	SHOCK ABSORBER <i>?</i> MOUNTNG FRT, RH/LH	1	193.80	25.00	145.35	Replace	Replace	No
	6503707 TYRE <i>X</i>	1	126.74	0.00	126.74	Replace	Replace	No
42611--47140 (Frt)	6505658 WHEEL DISC. FRONT <i>R</i> <i>with</i>	1	1,484.20	25.00	1,113.15	Replace	Replace	No
61132-47030	PILLAR, FR BODY, LH <i>?</i>	1	363.10	25.00	272.32	Replace	Replace	No
75852-47900	MOULDING BODY, LH <i>✓CRK</i>	1	673.60	25.00	505.20	Replace	Replace	No
67002-47070	6505529 DOOR FRT/LH <i>✓DT</i>	1	894.40	25.00	670.80	Replace	Replace	No
	STICKER DECAL SMRT (DOOR) <i>✓NEC</i>	1	60.00	0.00	60.00	Replace	Replace	No
68740-12120	HINGE LOWER LHF, <i>?</i> DOOR	1	90.10	25.00	67.57	Replace	Replace	No
68720-15151	HINGE UPPER LHF, <i>?</i> DOOR	1	80.50	25.00	60.37	Replace	Replace	No
38610-47021	CHECK ASSY, FR <i>?</i> DOOR,	1	150.30	25.00	112.72	Replace	Replace	No
32152-47430	WIRE LHF, DOOR <i>?</i>	1	436.40	10.00	392.76	Replace	Replace	No
37940-47310	6505599 MIRROR ASSY, LH <i>X</i>	1	1,224.90	25.00	918.67	Replace	Replace	No
31740-32040	6505465 MIRROR LAMP LH <i>✓SCR</i>	1	65.30	10.00	58.77	Replace	Replace	No
37945-4010	6505597 COVER, OUTER <i>✓SCR</i> MIRROR, LH	1	107.40	25.00	80.55	Replace	Replace	No
TOTAL MATERIALS						7,749.68	7,749.62	
TOTAL MATERIALS(Discounted)						6,199.70	6,199.70	

Added Spare Parts / material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									