

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5015P**AAD1806-084***Not Authored**1/1/2018*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5015P

VF1ABL15AUC275186

RENAULT

LATITUDE

9.6.2018

AIG**PART****LIST**

1	BUMPER COVER FRT	\$	<i>Pr/um</i> 1,259.42	✓
1	BUMPER SPOILER FRT	\$	<i>Sn</i> 181.75	X
1	BUMPER ABSORBER FRT	\$	<i>Sn</i> 394.68	X
1	BUMPER RETAINER FRT RH	\$	<i>Dis</i> 150.77	✓
1	BUMPER SUPPORT FRT	\$	<i>Sn</i> 123.88	X
1	BUMPER UNDERTRAY FRT	\$	<i>Sn</i> 472.83	X
1	BUMPER GRILLE LOWER FRT	\$	<i>Sn</i> 266.80	X
1	BUMPER FOG LAMP GRILLE RH	\$	<i>Sn</i> 207.21	X
1	BUMPER BEAM FRT	\$	<i>R</i> 914.08	X
1	HEADLAMP RH	\$	<i>ngum</i> 1,184.43	✓
1	HEADLAMP PANEL FRT RH	\$	<i>R</i> 152.15	X
1	FENDER PANEL FRT RH	\$	<i>B</i> 783.83	✓
1	WHEELARCH FRT RH	\$	<i>Dis</i> 278.84	✓
1	FENDER BRACKET LOWER RH	\$	<i>Sn</i> 15.79	} X
1	FENDER INSULATOR RH	\$	<i>Sn</i> 130.84	
1	DOOR PANEL FRT RH	\$	<i>R</i> 2,844.66	
1	RADIATOR GRILLE	\$	<i>R</i> 1,707.78	
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>Sn</i> 225.36	
1	RADIATOR GRILLE FRAME	\$	<i>Sn</i> 1,353.75	
1	RADIATOR FAN COWLING	\$	<i>Sn</i> 820.54	
1	RADIATOR FAN MOTOR LH	\$	<i>Sn</i> 967.36	
1	RADIATOR FAN MOTOR RH	\$	<i>Sn</i> 1,479.46	
1	FRAME FULL SUPPORT PANEL	\$	<i>Sn</i> 615.90	
1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79	
1	DOOR MIRROR ASSY RH	\$	<i>Sn</i> 1,483.40	
1	DOOR PANEL FRT RH	\$	<i>R</i> 2,844.66	
1	BONNET	\$	<i>R</i> 1,941.63	
1	BONNET INSULATOR	\$	<i>Sn</i> 405.73	
1	BONNET STRUT LH	\$	<i>Sn</i> 88.61	
1	BONNET STRUT RH	\$	<i>Sn</i> 88.61	

Trans-cab Auto Services Pte Ltd**AAD1806-084**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5015P

1	BONNET HINGE LH	\$	R 348.31	} X
1	BONNET HINGE RH	\$	R 348.31	
1	BONNET LOCK	\$	R 305.48	
1	BONNET CABLE	\$	Sh 119.19	
1	BONNET CABLE COVER	\$	Sh 161.03	
1	BONNET SEAL OUTER	\$	na 92.36	
1	BONNET SEAL INNER	\$	Sh 157.28	
1	SUBFRAME OUTER FRT	\$	Sh 2,652.45	
1	SUBFRAME BRACKET OUTER LH	\$	Sh 92.36	
1	SUBFRAME BRACKET OUTER RH	\$	Sh 92.36	
1	ENGINE UNDERTRAY	\$	Sh 564.98	
1	A/C CONDENSER	\$	Sh 2,020.37	
1	A/C CONDENSER GARNISH LH UPPER	\$	Sh 39.67	
1	A/C CONDENSER GARNISH RH UPPER	\$	Sh 39.67	
1	A/C CONDENSER GARNISH LH	\$	Sh 58.81	
1	A/C CONDENSER GARNISH RH	\$	Sh 59.60	
1	LOWER ARM RH	\$	685.76 ?	
1	KUNCKLE ARM RH	\$	846.98 ?	
1	ABSORBER FRT RH	\$	360.54 ?	
1	STABILIZER BAR FRT	\$	604.65 ?	
1	DRIVESHAFT RH	\$	R 1,747.45 X	
1	WIPER RESERVOIR	\$	na 348.25 ✓	
1	WIPER RESERVOIR NECK	\$	Sh 136.11 X	
1	WIPER RESERVOIR MOTOR	\$	Sh 270.06 X	

TOTAL	\$	35,626.53
10%	\$	3,562.65
	\$	32,063.87

Specical Nett

1SET	BUMPER CLIP FRT	\$	na 66.00 ✓	} X
1	BUMPER BRACKET CLIP FRT RH	\$	na 12.00	
1	BUMPER SUPPORT CLIP FRT RH	\$	na 10.50	
1SET	BUMPER GRILLE LOWER CLIP	\$	na 69.00	
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na 70.00	
2	FRAME FULL SUPPORT PANEL NUT	\$	na 20.00	
2	FRAME FULL SUPPORT PANEL STUD	\$	na 30.00	

Trans-cab Auto Services Pte Ltd**AAD1806-084**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5015P

1SET	WHEELARCH CLIP FRT RH	\$	<i>nn</i> 30.50 ✓
6	BONNET INSULATOR CLIP L70Y	\$	<i>nn</i> 7.30 X
2	BONNET STRUT L70Y	\$	<i>nn</i> 88.61 X
2	BONNET CABLE CLIP L70Y	\$	<i>nn</i> 6.31 X
2	BONNET CABLE COVER SCREW L70Y	\$	<i>nn</i> 10.85 X

TOTAL	\$	421.08
--------------	-----------	---------------

TOTAL PARTS	\$	32,484.95
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00 <i>4001</i>
Putty and spray painting of the affected portion.	\$	4,000.00 <i>4401</i>
To rust-proofing of the affected areas.	\$	170.00 <i>301</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00 X
To check steering geometry and computer wheel alignment	\$	220.00 <i>601</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 <i>201</i>
To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 X
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 X
To vacuum, replace, refix and recharge air condenser	\$	<i>nn</i> 380.00 X

Trans-cab Auto Services Pte Ltd**AAD1806-084**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5015PTo replace, refix and top up coolant for radiator \$ *na* 170.00 *X*To vacuum, replace, refix and recharge Air
Intercooler \$ *na* 170.00 *X***TOTAL \$ 11,090.00****Over All Total \$ 43,574.95****LUMP SUM (REPAIR DAY)**~~15 DAYS~~*2 1/2 days***LKK Auto Consultants** hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: