

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BITTR%	DISC QUNT%	SALY AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	10	1			REAR TAILEND PANEL			Bent	458.9		10		413.01	Reviewing	
	11	1			REAR TAILEND PANEL INNER GARNISH			Serviceable	0		10		0	Reviewing	
	12	1			REAR BUMPER			Buckled	476.85		10		429.17	Reviewing	
	13	1			REAR BUMPER RETAINER (NS)			Damaged	38		10		34.2	Reviewing	
	14	2			REAR BUMPER BRACKET			Repair	0		10		0	Reviewing	
	15	1			REAR BUMPER CHROME			Necessary	184.8		10		165.32	Reviewing	
	16	1			REAR FENDER/LH			Buckled	983.4		10		885.06	Reviewing	
	17	1			REAR FENDER INNER SHIELD			Serviceable	0		10		0	Reviewing	
	18	1			REAR W/SCREEN MLDG			Necessary	98.56		10		88.7	Reviewing	
Labour															
EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE						
	1		TO APPLY RUST-PROOFING ON REPAIRED / REPLACED PANELS.	90	0	0	Reviewing								
	2		TO CHECK REAR WIRING FUNCTION.	20	0	0	Reviewing								
	3		TO CHECK WATER SEEPAGE.	30	0	0	Reviewing								
	4		TO REPAIR, RE-ALIGN ON REAR EXHAUST SILENCER.	0	0	0	Reviewing								

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION	CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Sum Insured		0	License Type		
Market Value		0	License Issue Date		mm/dd/yyyy
			License Expiration Date		mm/dd/yyyy
			Address	14 JALAN LEMPENG, #05-01, 128799, Singapore	
			Address type	Personal Correspondence	
			Gender	Female	
			Marital status	Unknown	
			Identification #	S2538383D	

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
DHAKAL Raghav	6/12/16 1:40 PM	6005.04	6005.04	Open	Share	Clone

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Immediate Advice (with mandate).dd 270718.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	July 27, 2018
TP ESTIMATE_MARKED_.pdf.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	July 27, 2018
PARF_COE Rebate.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	July 27, 2018
LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	June 21, 2018
SGB3470M TP GIA REPORT.PDF	Reports & Statement	GIA Report	DHAKAL Raghav	June 12, 2018
YM3331K INSD GIA REPORT.PDF	Reports & Statement	GIA Report	DHAKAL Raghav	June 12, 2018
TP PRI RECEIVED FROM WORKSHOP.msg	Letters and Correspondence	Workshop	DHAKAL Raghav	June 12, 2018