

## SMRT Accident Vehicle Repair Estimates



### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHF1039G  
 Ref. No : TAX/06/18/2042  
 Reg. Date : 23/12/2014  
 Vehicle Type : TAXI  
 Make : TOYOTA PRIUS  
 Model : PRIUS  
 Name of Driver : NG TECK LIANG DANNY  
 Type of Accident : HEAD TO REAR  
 Date / Time of Accident : 10/06/2018 04:10:00 AM  
 Accident Reported Date / Time : 11/06/2018 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by :  
 Vehicle is Towed Back? : Yes  
 Towed Back Date/Time : 10/06/2018  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No : 000024096521  
 Special Instruction to ARC, if any :  
 TOWED \$60 / SHA7803D (COMFORT) - III  
 Prepared Date : 11/06/2018 01:02:39 PM



Sathya Sai

13/6/2018

98072012

Sebastianyeang@lkkauto.com

- Lump Sum Repair
- Question mark item photo
- Photo after paint

3 days

**LKK Auto Consultants** hence notify the Repairer of the following:
 

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : JTDKN36U605754948

Mileage

0

Work Shop :

Repair Completed Date / Time :

**Summary of Repair Estimates**

|                              | Quotation from ARC       | Adjusted by Surveyor, if applicable |
|------------------------------|--------------------------|-------------------------------------|
| Total Labour Charges         | : 1,014.00               | 0.00                                |
| Total Spray Painting Charges | : 1,314.00               | 0.00                                |
| Total Material Charges       | : 4,143.06               | 4,143.06                            |
| Other Charges                | : 1,080.88               | 0.00                                |
| <b>TOTAL</b>                 | <b>: 7,551.94</b>        | <b>0.00</b>                         |
| <b>Lum Sum Total</b>         | <b>: 7,550.00</b>        | <b>0.00</b>                         |
| No. of Repair Days           | : 6.00                   | <del>0.00</del> 3 days              |
| Prepared / Adjusted By       | :                        |                                     |
| Arc / Surveyor Sing Off Date | : 11/06/2018 06:29:42 PM | 01/01/1900 12:00:00 AM              |



Prepared / Adjusted Date :

Remarks :

Prepared Date : 11/06/2018 06:29:07 PM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

|                  |                 |
|------------------|-----------------|
| Quotation No :   | Invoice No :    |
| Quotation Date : | Invoice Date :  |
| Invoice Amount : | Prepared Date : |

## Section D - Details of Repair Estimates

### Part 1 - Labour Works

| Job Scope                 | Quotation from ARC | Adjusted by Surveyor, if applicable |
|---------------------------|--------------------|-------------------------------------|
| TO REPAIR RH REAR PORTION | 1,014.00           | <del>0.00</del> 600                 |
| <b>Total Labour</b>       | <b>1,014.00</b>    | <b>0.00</b>                         |

### Part 2 - Spray Painting & Panel Beating Related Works

| Job Scope                                       | Quotation from ARC | Adjusted by Surveyor, if applicable |
|-------------------------------------------------|--------------------|-------------------------------------|
| TO REPSRAY REAR BUMPER                          | 378.00             | <del>0.00</del> 200                 |
| TO RESPRAY REAR PANEL                           | 180.00             | 0.00 ?                              |
| TO RESPRAY TAIL GATE                            | 378.00             | 0.00 X                              |
| TO RESPRAY REAR FENDER RH                       | 378.00             | 0.00 ?                              |
| <b>Total Spray Painting &amp; Panel Beating</b> | <b>1,314.00</b>    | <b>0.00</b>                         |

### Part 3 - Other Costs - Accident and Accident Repair Related Expenses

| Job Scope                                                   | Quotation from ARC | Adjusted by Surveyor, if applicable |
|-------------------------------------------------------------|--------------------|-------------------------------------|
| TOWING CHARGE                                               | 84.00              | <del>0.00</del> 50                  |
| TO CHECK WIRING AND SYSTEM FUNCTION                         | 80.00              | <del>0.00</del> 40                  |
| TO APPLY RUST-PROOFING ON AFFECTED AREA                     | 100.00             | <del>0.00</del> 50                  |
| TO DO WHEEL ALIGNMENT / TYRE BALANCING                      | 120.00             | <del>0.00</del> 60                  |
| TO REMOVE & REFIT EXHAUST                                   | 120.00             | <del>0.00</del> 60                  |
| TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET) | 296.88             | 0.00 ✓                              |
| TO TEST AND REFIX REVERSE SENSOR SYSTEM                     | 120.00             | <del>0.00</del> 60                  |
| TO REPLACE SUNDRY PARTS                                     | 100.00             | <del>0.00</del> 20                  |
| TO WASH AND VACUUM                                          | 60.00              | 0.00 X                              |
| <b>Total Other Costs</b>                                    | <b>1,080.88</b>    | <b>0.00</b>                         |

**Part 4 - Spare Parts / Material Usage**

| Part Number                        | Portion | Stock No | Part Name                                 | Qty | List Price (\$) | Discount (%) | Final Price (\$) | ARC Recommended | Surveyor Approved | Photos Attached |
|------------------------------------|---------|----------|-------------------------------------------|-----|-----------------|--------------|------------------|-----------------|-------------------|-----------------|
| 52159-47905                        |         | 6505548  | BUMPER REAR ✓ <i>omg</i>                  | 1   | 458.60          | 25.00        | 343.95           | Replace         | Replace           | No              |
| 52161-16010                        |         |          | BUMPER CLIPS ✓ <i>NEC</i>                 | 10  | 1.61            | 25.00        | 12.07            | Replace         | Replace           | No              |
| 76087-47020                        |         | 6505618  | BUMPER LIP COVER RR/RH ✓ <i>deform</i>    | 1   | 118.10          | 25.00        | 88.57            | Replace         | Replace           | No              |
| 76891-47020                        |         | 6505619  | BUMPER LIP REAR ✓ <i>deform</i>           | 1   | 228.90          | 25.00        | 171.67           | Replace         | Replace           | No              |
| 52023-12240                        |         | 6505547  | BUMPER REINFORCEMENT REAR ?               | 1   | 205.70          | 25.00        | 154.27           | Replace         | Replace           | No              |
| 52016-47030                        |         |          | ARM SUB-ASSY, RR BUMPER LH ?              | 1   | 139.60          | 25.00        | 104.70           | Replace         | Replace           | No              |
| 52015-47050                        |         |          | ARM SUB-ASSY, RR BUMPER RH ?              | 1   | 139.60          | 25.00        | 104.70           | Replace         | Replace           | No              |
|                                    |         |          | SENSOR REVERSE ✓ <i>omg</i>               | 1   | 180.00          | 0.00         | 180.00           | Replace         | Replace           | No              |
|                                    |         |          | PIXEL STICKER ✓ <i>NEC</i>                | 2   | 60.00           | 0.00         | 120.00           | Replace         | Replace           | No              |
| 52591-47021                        |         |          | BUMPER SEAL, RR RH ✓ <i>NEC</i>           | 1   | 65.70           | 25.00        | 49.27            | Replace         | Replace           | No              |
| 52576-47020                        |         | 6505550  | BUMPER SIDE RETAINER RR/LH ?              | 1   | 94.80           | 25.00        | 71.10            | Replace         | Replace           | No              |
| 52575-47020                        |         | 6505549  | BUMPER SIDE RETAINER RR/RH ?              | 1   | 94.80           | 25.00        | 71.10            | Replace         | Replace           | No              |
| 58308-47011                        |         |          | UNDER COVER SUB-ASSY, RR FLOOR ?          | 1   | 514.50          | 25.00        | 385.87           | Replace         | Replace           | No              |
| 37005-47241                        |         |          | TAILGATE ASY X                            | 1   | 1,007.90        | 25.00        | 755.92           | Replace         | Replace           | No              |
| 75374-47051                        |         |          | NAME PLATE (HYBRID) X                     | 1   | 51.90           | 25.00        | 38.92            | Replace         | Replace           | No              |
| 58307-47060                        |         | 6505522  | END PANEL ?                               | 1   | 602.10          | 25.00        | 451.57           | Replace         | Replace           | No              |
|                                    | COMMO N | 4006314  | SEALANT SIKAFLEX ?                        | 1   | 37.00           | 0.00         | 37.00            | Replace         | Replace           | No              |
| 38327-47020                        |         |          | EXHAUST HEAT SHIELD, REAR <i>all new?</i> | 1   | 107.40          | 25.00        | 80.55            | Replace         | Replace           | No              |
| 17430-37380                        |         |          | EXHAUST TAIL PIPE ✓ <i>cut</i>            | 1   | 656.20          | 25.00        | 492.15           | Replace         | Replace           | No              |
| 17565-22030                        |         |          | SUPPORT, EXHAUST REAR ?                   | 2   | 33.60           | 25.00        | 50.40            | Replace         | Replace           | No              |
| 52562-17010                        |         |          | TAIL LAMP BRACKET, RH ?                   | 1   | 30.70           | 25.00        | 23.02            | Replace         | Replace           | No              |
| 51551-17180                        |         | 6505462  | TAIL LAMP RH ?                            | 1   | 557.80          | 10.00        | 502.02           | Replace         | Replace           | No              |
| 51604-17090                        |         |          | FENDER RR/RH ?                            | 1   | 766.80          | 25.00        | 575.10           | Replace         | Replace           | No              |
|                                    | COMMO N |          | SMRT LOGO ?                               | 1   | 7.80            | 0.00         | 7.80             | Replace         | Replace           | No              |
|                                    |         |          | STICKER DECAL 6555 8888 ?                 | 1   | 21.60           | 0.00         | 21.60            | Replace         | Replace           | No              |
| 5637-17021                         |         | 6505480  | FENDER LINER RR/RH ?                      | 1   | 141.30          | 25.00        | 105.97           | Replace         | Replace           | No              |
| 52940-6060                         |         |          | DUCT ASSY, QUARTER ?                      | 1   | 70.40           | 25.00        | 52.80            | Replace         | Replace           | No              |
|                                    |         | 6503707  | TYRE X                                    | 1   | 126.74          | 0.00         | 126.74           | Replace         | Replace           | No              |
| <b>TOTAL MATERIALS</b>             |         |          |                                           |     |                 |              |                  | <b>5,178.89</b> | <b>5,178.83</b>   |                 |
| <b>TOTAL MATERIALS(Discounted)</b> |         |          |                                           |     |                 |              | <b>4,143.06</b>  | <b>4,143.06</b> |                   |                 |

Added Spare Parts / Material Usage After Surveyor Signed off

| Part Number                   | Portion | Part Name | Qty | List Price (\$) | Discount (%) | Final Price (\$) | ARC Check | Surveyor Check | LT Check |
|-------------------------------|---------|-----------|-----|-----------------|--------------|------------------|-----------|----------------|----------|
| TOTAL SUPPLEMENTARY MATERIALS |         |           |     |                 |              |                  |           |                |          |