

ASS. REC. BY:

REF: CS/FCI18010816/K1+d3 12

Special Instruction:

Surveyor: Kalvin
CWS

ASSIGNMENT (Office)

From (Person): Sereher

of

FCI

Date/Time: 13/6/18 @ 4:27pm

Estimated Cost:

Bill to:

OD/TP WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SBS 6430DInsured: SHC 8789Uat Workshop m/s LexBuild InternationalTel: 6456 3533 / 9615 8280of 2 woodlands see 1# 05-12

Policy No:

Claim No: D18004491MP84

Sum Insured:

Excess:

Make of Veh:
(Client's Record)D.O.A. 01/06/2018

CA / REV / REP. / REV 24 HRS

Imp?

Imp: 210yung walk @ Go-Ahead

H.O.D. Endorsement:

Date/Time: 4:46pm @ 13/6/18

Person Contacted:

ShirleyVehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SBS 6430D - X</u>
	<u>SHC 8789U - NA / CFI 18009779/24</u>
	<u>DOA: 29/5/2018</u>

Kalvin

REF: FCI

ASSIGNMENT

From: Date: 13062018

Estimated Cost:

OD TP WS TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SBS 6450D

at Workshop m/s: Go - Ahead.

of 2 Loyang Way

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh: Yong Shun - 9029 6574

10am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SBS 6430D Yr Regn: 3 Feb 2014

Type: M.Car / M.Cycle / B / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz C126 C.C. 6374

Colour: Green A/C: Insured / Std / NI / NA

Sp. Reading: 260493 T/Radio: Insured / Std / NA

Eng/No:

C/No: WEB 62808323125316

Gen. Cond: Good / Poor / Burnt

Steering: Inop / Jammed / Leaked / Burnt or

Brake: Inop / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD Rim or

Tyre Size: F: 275/70 R22.5

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 4 mm R/Bal. 4x mm

L/Bal. 4 mm L/Bal. 4x mm

D.O.A. 12/6/8 D.O.I. 13/6/8

Survey held at Go - Ahead

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Front.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

19/6/18 Chd 45\$3250/3 hrs. (Red: 1h 39\$54: 83%) 4/5

RECEIVED 20 JUN 2018

Date/Time: File Pass to?

1) 20/6 Typist

Date/Time: File Return to?

3)

Report Format:

Lump Sum / I.B.I: (\$

TP
3250/-

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech Invs (\$☐ Weekend (\$

Survey Fee:

Transportation

S + RS \$

Photo OSP
25/6/18

TOTAL

9x15=135

170+135

50

50

34

439

MOTOR SURVEY ASSIGNMENT

Date	05-06-2018	Our Ref No. D18004491MFSH
Accident Date	01-06-2018	Claim Type. Third Party
Insured Vehicle	SHC8789U	Third Party Vehicle. SBS6430D
Survey Location	2 WOODLANDS SECTOR 1 #05-12(WOODLANDS SPECTRUM 1)	
Contact Person.	SHIRLEY LIM	
Contact No.	64563533/ 96158280	Fax No. 64563353
Survey Type	WITHOUT PREJUDICE: NO EST. PROVIDED (SJE)	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

*4-26/6/18
 Shirley Lim
 LKK*

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	LEXBUILD INTERNATIONAL PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/241131)



PRI Documents



Close



PRI Header Details

Claim No	D18004491MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & LEXBUILD [M/S GO AHE
Workshop Name	LEXBUILD INTERNATIONAL PTE LTD (Contact Person : SHIRLEY LIM)	Survey Location & Contact Details	2 WOODLANDS SECTOR 1 #05-12(WOODLANDS SPECTI Mobile: 96158280 , Phone: 64563533 , Fax: 6456335: EmailId: SHIRLEYLIM@LEXBUILD.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: NO EST. PROVIDED (SJE)		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC8789U	TP Vehicle No	SBS6430D
PRI Recieved Date	11-06-2018 08:55:23 PM	Surveyor Appointed Date	13-06-2018 04:26:26 PM	Surveyor Accept Date	13-06-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	13-06-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FEDERAL CAPITAL INSURANCE LTD

Ref : CS/FCI18010816/K1td3

300 BINSON ROAD

#01-01 CITY HOUSESINGAPORE 068877

Date : 13-06-2018



Code : FCI2

Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 8789U	Veh. Inspected	SBS 6430D
Policy No.		Coverage (\$)	0.00
Claim No.	D18004491MFSH	Excess (\$)	0.00
Assign From	CWS (SERENE LER)	Assign Date	13/06/2018

Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

Conditions of Tyres

	Size	Make	Balance
LH Front Tyre			mm
RH Front Tyre			mm
LH Rear Tyre			mm
RH Rear Tyre			mm

Description of Damages

General Information

Accident Date	01/06/2018	Inspection Date	13/06/2018
Survey held at	GO AHEAD-2 LOYANG WALK		
Repairer	LEXBUILD INTERNATIONAL PTE LTD		


Remarks

THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Accident Photo




Accident Photo



Accident Photo



Accident Photo



12th June 2018

Quotation No.: Q18-OPS-0602

First Capital Insurance Ltd
36 Robinson Road
#16-01 City House
Singapore 068877

Dear Sir/Mdm

Estimated Cost of Repair job for SBS6430D (Accident on 12/06/18, along Killiney Road / Penang Road involving SBS6430D & SHC8789U)

We are pleased to submit herein, our quotation for your consideration.

S/N	Description	Qty.	Unit Price	Total Price
1	Supply skilled labour to dismantle broken glass debris, clean up mount, assembly new parts with sealant, install with alignment adjustment according to Cycle & carriage specification on entrance RHS door	2 day	\$880.00	\$1,760.00 880
2	Supply Labour & paint Material to spray paint front LHS wheelArc body panel & LHS skirting	2 day	\$1,600.00	\$1,600.00 1000
3	Swivel Bar (1st Door) <i>see</i>	1 pc	\$4,362.90	\$4,362.90
4	Weather Strip <i>broken - 10%</i>	1 pc	\$1,052.82	\$1,052.82
5	Door Rubber seal LHS <i>see</i>	1 pc	\$681.85	\$681.85
6	Door Rubber seal RHS <i>see</i>	1 pc	\$598.41	\$598.41
7	Door Rubber seal Top <i>see</i>	1 pc	\$181.17	\$181.17
8	Door Rubber seal Bottom <i>see</i>	1 pc	\$179.28	\$179.28
9	Door Frame <i>see</i>	1 pc	\$7,605.27	\$7,605.27
10	Door Handle <i>see</i>	1 pc	\$253.67	\$253.67
11	Door Glass (100) <i>slightly - 10%</i>	1 pc	\$1,323.17	\$1,323.17
12	Sticker "Go-Ahead" <i>see - 10%</i>	1 pc	\$50.00	\$50.00
Total				\$19,648.54
GST				\$1,256.03
Sub-Total				\$21,023.94

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

LexBuild International Pte. Ltd.

2 Woodlands Sector 1, #05-12 (Woodlands Spectrum 1), Singapore 738068.

Tel: (65) 6456 3533, Fax: (65) 6456 3353

Website: www.LexBuild.com, Email: sales@LexBuild.com



ROC / CR / GST Reg No: 200004370R

Kalina (C/C)
13/6/18
361
45
Alto Ruyell

Terms and Conditions:

Payment Terms : 30 days upon invoice
Quotation Validity : 30 days
Lead-Time : 4 working day
Price quoted subject to 7% GST

Yours faithfully



Tien Yong Shun
Operation Executive

LexBuild International Pte. Ltd.

2 Woodlands Sector 1, #05-12 (Woodlands Spectrum 1), Singapore
738068.

Tel: (65) 6456 3533, Fax: (65) 6456 3353

Website: www.LexBuild.com, Email: sales@LexBuild.com



ROC / CR / GST Reg No: 200004370R



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18010816/K1td3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 25-06-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8789U	Veh. Inspected	SBS 6430D	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18004491MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	13/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ CITARO	c.c	6374	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	WEB62808323125316	Colour	GREEN	
Odometer	260493	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	275/70 R22.5	CONTINENTAL	4 mm	
L/H Front Tyre	275/70 R22.5	CONTINENTAL	4 mm	
R/H Rear Tyre	275/70 R22.5 (D)	CONTINENTAL	4/4 mm	
L/H Rear Tyre	275/70 R22.5 (D)	CONTINENTAL	4/4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/06/2018	Inspection Date	13/06/2018	
Survey held at	GO AHEAD-2 LOYANG WALK			
Repairer	LEXBUILD INTERNATIONAL PTE LTD			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBS 6430D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SWIVEL BAR (1 ST DOOR)	SERVICEABLE	4,362.90	-
1	DOOR RUBBER SEAL LHS	SERVICEABLE	681.85	-
1	DOOR RUBBER SEAL RHS	SERVICEABLE	598.41	-
1	DOOR RUBBER SEAL TOP	SERVICEABLE	181.17	-
1	DOOR RUBBER SEAL BOTTOM	SERVICEABLE	179.28	-
1	DOOR FRAME	TO REPAIR SEE LABOUR	7,605.27	-
1	DOOR HANDLE	SERVICEABLE	253.67	-
1	DOOR GLASS (100)	SHATTERED	1,323.17	1,323.17
1	STICKER "GO-AHEAD"	NECESSARY	50.00	50.00
1	WEATHER STRIP	TORN	1,052.82	1,052.82
	LESS 10% DISCOUNT		-	-242.60
			16,288.54	2,183.39
LABOUR				
	SUPPLY SKILLED LABOUR TO DISMANTLE BROKEN GLASS DEBRIS,CLEAN UP MOUNT,ASSEMBLY NEW PARTS WITH SEALANT,INSTALL WITH ALIGNMENT ADJUSTMENT ACCORDING TO CYCLE & CARRIAGE SPECIFICATION ON ENTRANCE RHS DOOR.INCLUSIVE OF THE REPAIR OF DOOR FRAME.		1,760.00	880.00
	SUPPLY LABOUR & PAINT MATERIAL TO SPRAY PAINT FRONT LHS WHEELARC BODY PANEL & LHS SKIRTING.		1,600.00	1,000.00
			3,360.00	1,880.00
GRAND TOTAL			19,648.54	4,063.39
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,250.00

Report Ref No. CS/FCI18010816/K1td3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.