

ASS. REC. BY:

REF: CS/CTI18010825/Nrd3n2 Special Instruction:

Surveyor:

M. Men

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTI

Date/Time:

13/6/18 @ 3:15pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLL 434B

Insured:

GBF 386G

at Workshop m/s:

World Auto

Tel:

6362 1776

of

No. 1 Krunji Loop

Policy No:

DMCVSN 3032401800

Claim No:

SNM18D0295302

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 11/06/2018

CA / REV / REP. / REV 24 HRS

lup)

14/06/2018

H.O.D. Endorsement:

Date/Time:

5:45pm @ 13/6/18

Person Contacted:

Ainee

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

SLL 434B - NA/ANA 18010669/13

DOA: 11/06/18

GBF 386G - X.

Confirm \$11141.60 @ 11 days

Red: \$14,395.20 x 56%.

REF: CTI

ASSIGNMENT

From:

Date:

11/06/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLL 434 B

at Workshop n/s:

World Auto

of

No. 1 Kuraji Loop

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS *hup*

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLL 434 B

Yr Regn:

Feb / 2017

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Vezzel

C.O. 1496

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp. Reading:

85330

T/Radio: Insured / Std / NI / NA

Eng/No:

LEB5917430

C/No:

RU31217422

Gen. Cond: Good / Fair / ☒ Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 215/60 R16

R: 215/60 R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or *Pirelli (Front), Dunlop (Rear)*

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

14/6/2018

Survey held at

World Auto

Des. of Damages: ☒ Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 29 AUG 2018

Date/Time: File Pass to?

1) *typist*

Date/Time: File Return to?

2)

☐ : Preli. Report☒ : Final Report

Days Of Repair:

4

Resurvey No. of Trip:

1

Survey Fee:

Transportation

) \$ + RS \$

) Photos

) Others

TOTAL

220

Report Format:

7P

Lump Sum / I.B.I. (\$

11141.60

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Jun 2018		13 Jun 2018 15:15 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	LCRF PTE LTD		
Vehicle Reg. No.:	SLL434B	Date of Loss:	11/06/2018 00:00 - :59
Claim Type:	TP / SNM18D02953C02	Policy/Cover Note No.:	DMCVSN3032401800
Vehicle Reg. No. (Insured):	GBF386G	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	World Auto Pte Ltd - Kranji (HQ) No 1 Kranji Loop, 739535 Kranji - Tel: 63621776		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 25/06/2018]		
Adj Asg. Remarks:	NO EST, ASSIGN HENRY NG AS SJE.		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



Reg No: 52977287 J

CASH SALE/WORK ORDER

迅速拖車服務

SPEEDWAY RECOVERY SERVICE

Singapore Post Centre Post Office P.O. Box 201 Singapore 914007

Tel: 6841 0080

No: B 23290

Date: 11/6/18

Name/Company World Auto

Vehicle No SL 434 B Model VEZEL

From 3/634 A.M.K AVE 6 main rd

To Kranji Loop (World Auto)

Remarks 96780857

- ☐ Jump Start
- ☐ Tyre Replacement
- ☐ Accident/Breakdown
- ☐ Multi/Basement
- ☐ With Load/Cargo Box
- ☐ King Dolly
- ☐ Transport Charge
- ☐ Low Body Kit
- ☐ Door Opening Service
- ☐ Crane Up/Winch Out
- ☐ Collect Doc/Key
- ☐ Repo Payment
- ☐ Trips

Time: 11:05 - 11:25 - 10:50

Amount \$ 60

NOTE: Vehicle is towed at owner's risk. The Company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

mice
Tow Truck

24 HRS TOWING SERVICE
6841 0080

www.speedwayrecovery.com
Email: speedwaytowing@gmail.com

Thuy
Received By

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

CHINA INSURANCE COMPANY LIMITED
105 CECIL STREET #18-00 & #19-00 THE OCTAGON
069534

Attention : Motor Claim Department

Contact : 6222 2366 Fax No. : 62247478

Estimate : ES000165

Date : 11/06/2018

Vehicle Num. : SLL 434B (LCR)

Make/Model : HONDA VEZEL HYBRID

Chassis/Eng# :

Accident Date : 11/06/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :

1.	1	REAR BOOT LID ✓ OT		1,250.00 1100
2.	1	REAR WINDSCREEN GLASS ✓ BR		1,000.00 ✓
3.	1	REAR WINDSCREEN GLASS MOULDING ✓ NEC		150.00 ✓
4.	1	REAR WINDSCREEN SEALANT ✓ NEC		120.00 50
5.	1	REAR BOOT VEZEL EMBLEM (VEZEL) ✓ NGL		100.00 55
6.	1	REAR BOOT HYBRID EMBLEM (VEZEL) ✓ NEC		100.00 78
7.	1	REAR NUMBER PLATE LAMP GARNISH ✓ BR		250.00 180
8.	1	REAR BOOT HONDA LOGO EMBLEM ✓ NEC		150.00 27
9.	1	REAR BOOT WIPER MOTOR ASSY ?		360.00 } X NN
10.	1	WIPER ARM ASSY ?		180.00 }
11.	1	REAR BOOT INNER TRIM BOARD ✓ Deform		280.00 ✓
12.	1	REAR BOOT HAND GRIP COVER ✓ Deform		60.00 ✓
13.	2 LH & RH	REAR BOOT HINGE ?	90.00	180.00 X }
14.	2 LH & RH	REAR BOOT ABSORBER ?	150.00	300.00 X }
15.	1	REAR BOOT WEATHER STRIP ✓ Deform		180.00 155
16.	2 LH & RH	REAR BOOT REFLECTOR LAMP ✓ CRK	900.00 422	1,800.00 844
17.	2 LH & RH	REAR TAIL LAMP ✓ CRK	700.00 460	1,400.00 920
18.	1	REAR BOOT LOCK ASSY ?		330.00 X }
19.	1	REAR BOOT LOCK CATCH ?		65.00 X }
20.	1	REAR BUMPER ✓ DMG		900.00 ✓
21.	2 LH & RH	REAR BUMPER RETAINER ?	120.00	240.00 X NN
22.	2 LH & RH	REAR SIDE BUMPER ✓ CRK	250.00 195	500.00 390
23.	2 LH & RH	REAR BUMPER REFLECTOR LENS X	250.00	500.00 X }
24.	1	REAR BUMPER UNDERDUST COVER X		165.00 X }
25.	1	REAR END PANEL ✓ OT		860.00 550
26.	1	REAR END PANEL TOP GARNISH ✓ Deform		200.00 155
27.	1	REAR FLOOR BOARD X		330.00 X NN
28.	1	REAR FLOOR PANEL ✓ OT		790.00 ✓
29.	1	REAR FLOOR PANEL STIFFENER R		160.00

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

CHINA INSURANCE COMPANY LIMITED105 CECIL STREET #18-00 & #19-00 THE OCTAGON
069534

Attention : Motor Claim Department

Contact : 6222 2366 Fax No. : 62247478

Estimate : ES000165

Date : 11/06/2018

Vehicle Num. : SLL 434B (LCR)

Make/Model : HONDA VEZEL HYBRID

Chassis/Eng# :

Accident Date : 11/06/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
30.	1	REAR COMPARTMENT BOX ✓ Deform		280.00
31.	1	REAR FENDER LH R		850.00
32.	2 LH & RH	REAR FENDER INNER TRIM BOARD ?	280.00	560.00 x
33.	2 LH & RH	REAR WHEEL ARCH ?	250.00	500.00 x
34.	1	SMART BUZZER SENSOR ?		180.00 x
35.	1	REAR ANTENNA SENSOR X		180.00 x
36.	1	REAR EXHAUST MUFFLER ?		750.00 x
37.	1	FRONT BUMPER R		900.00
38.	2 LH & RH	FRONT BUMPER RETAINER X	150.00	300.00 x
39.	1	FRONT CHROME GRILLE MOULDING ✓ CRK		380.00
40.	1	FRONT CHROME STRIP ✓ CRK		180.00
41.	1	FRONT GRILLE BASE ✓ CRK		380.00 ✓
42.	2 LH & RH	HEADLAMP ASSY LED X	1,850.00	3,700.00 x
43.	2 LH & RH	FRONT HEADLAMP LOWER BRACKET ✓ CRK	78.00	156.00 ✓
44.	1	FRONT BUMPER REINFORCEMENT ✓ DT		450.00
List Total S\$:				22,646.00
20.00% Discount S\$:				4,529.20
				18,116.80
SPECIAL NETT ITEMS :				
1.	1	REAR BOOT INNER TRIM BOARD CLIP		35 50.00 ✓ NEC
2.	1	REAR BUMPER CLIP		35 50.00 ✓ NEC
3.	1	REAR END PANEL TOP GARNISH CLIPS		35 50.00 ✓ NEC
4.	2 LH & RH	REAR WHEEL ARCH MOULDING CLIPS	50.00	100.00 x
5.	1	REVERSE SENSOR		250 280.00 ✓ DMG
6.	1	REAR NUMBER PLATE		40.00 X NN
7.	1	PRIVATE HIRER DECAL		20.00 ✓ NEC
8.	1	FRONT BUMPER CLIP		35 50.00 ✓ NEC
9.	1	FRONT NUMBER PLATE		40.00 X NN

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

CHINA INSURANCE COMPANY LIMITED
 105 CECIL STREET #18-00 & #19-00 THE OCTAGON
 069534

Attention : Motor Claim Department
 Contact : 6222 2366 Fax No. : 62247478

Estimate : ES000165

Date : 11/06/2018
 Vehicle Num. : SLL 434B (LCR)
 Make/Model : HONDA VEZEL HYBRID
 Chassis/Eng# :
 Accident Date : 11/06/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
10.	1	TOWING CHARGE		60.00 ✓
		Special Nett Total S\$:		740.00
		LABOUR :		
		REMOVE & REFIT REAR WINDSCREEN GLASS		180.00 120
		TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES		180.00 100 60
		WIRINGS CHECK AND RECTIFY WHERE NECESSARY		180.00 100 30
		LABOUR TO REMOVE REAR ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS.		1,800.00 1400 1200
		PUTTY & SPRAY PAINT REAR & ALL AFFECTED AREAS (INNER/ OUTER)		1,600.00 1000
		TO REMOVE AND INSTALL HIGH VOLTAGE HYBRID BATTERY AS A REQUIREMENTS FOR SAFETY PRECAUTIONS.		380.00 200 80
		TO CONDUCT A STANDARD OF OPEARTING PROCEDURE POST REPAIRS DIAGNOSTIC SCAN TEST A REQUIREMENT FOR HYBRID CARS UPON COMPLETION OF COLLISION REPAIRS.		380.00 200 100
		LABOUR TO REMOVE FRONT ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS.		900.00 400 300
		PUTTY & SPRAY PAINT FRONT & ALL AFFECTED AREAS (INNER/ OUTER)		800.00 400

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

CHINA INSURANCE COMPANY LIMITED
 105 CECIL STREET #18-00 & #19-00 THE OCTAGON
 069534

Attention : Motor Claim Department
 Contact : 6222 2366 Fax No. : 62247478

Estimate : ES000165

Date : 11/06/2018
 Vehicle Num. : SLL 434B (LCR)
 Make/Model : HONDA VEZEL HYBRID
 Chassis/Eng# :
 Accident Date : 11/06/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

REMOVE REAR UPHOLSTERY IN ORDER TO FACILITATE REPAIRS
 AND REFIT BACK SAME

~~280.00~~ / 20


Labour Total S\$:

6,680.00

Sathya Sai

18/6/2018

98072012


 19/6/18

11 days

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

- Part by Part repair
- Question mark item photo
- Photo before paint.

E. & O.E.

Total S\$: 25,536.80

for WORLD AUTO PTE LTD

9077
 - 20%
 7261.6
 + 470
 + 3410
 11141.6

\$ 11141.60 @ 11 days
 confirmed

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel.No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

CHINA INSURANCE COMPANY LIMITED

105 CECIL STREET #18-00 & #19-00 THE OCTAGON
069534

Attention : Motor Claim Department

Contact : 6222 2366 Fax No. : 62247478

Estimate : ES000165

Date : 11/06/2018

Vehicle Num. : SLL 434B (LCR)

Make/Model : HONDA VEZEL HYBRID

Chassis/Eng# :

Accident Date : 11/06/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR BOOT LID ✓ OT		1,250.00 1100
2.	1	REAR WINDSCREEN GLASS ✓ OR		1,000.00 ✓
3.	1	REAR WINDSCREEN GLASS MOULDING ✓ NEC		150.00 ✓
4.	1	REAR WINDSCREEN SEALANT ✓ NEC		120.00 50
5.	1	REAR BOOT VEZEL EMBLEM (VEZEL) ✓ NEC		100.00 55
6.	1	REAR BOOT HYBRID EMBLEM (VEZEL) ✓ NEC		100.00 38
7.	1	REAR NUMBER PLATE LAMP GARNISH ✓ OR		250.00 180
8.	1	REAR BOOT HONDA LOGO EMBLEM ✓ NEC		150.00 29
9.	1	REAR BOOT WIPER MOTOR ASSY ?		360.00 } x 1000
10.	1	WIPER ARM ASSY ?		180.00 }
11.	1	REAR BOOT INNER TRIM BOARD ✓ Deform		280.00 ✓
12.	1	REAR BOOT HAND GRIP COVER ✓ Deform		60.00 ✓
13.	2 LH & RH	REAR BOOT HINGE ?	90.00	180.00 ✓ } 2nd
14.	2 LH & RH	REAR BOOT ABSORBER ?	150.00	300.00 ✓ }
15.	1	REAR BOOT WEATHER STRIP ✓ Deform		180.00 155
16.	2 LH & RH	REAR BOOT REFLECTOR LAMP ✓ CRK	900.00 422	1,800.00 844
17.	2 LH & RH	REAR TAIL LAMP ✓ CRK	700.00 1460	1,400.00 920
18.	1	REAR BOOT LOCK ASSY ?		330.00 x } 1000
19.	1	REAR BOOT LOCK CATCH ?		65.00 x }
20.	1	REAR BUMPER ✓ DMG		900.00 ✓
21.	2 LH & RH	REAR BUMPER RETAINER ?	120.00	240.00 x 1000
22.	2 LH & RH	REAR SIDE BUMPER LH ✓ CRK	250.00 195	500.00 390
23.	2 LH & RH	REAR BUMPER REFLECTOR LENS x	250.00	500.00 x } 1000
24.	1	REAR BUMPER UNDERDUST COVER x		165.00 ✓ }
25.	1	REAR END PANEL ✓ OT		860.00 550
26.	1	REAR END PANEL TOP GARNISH ✓ Deform		200.00 155
27.	1	REAR FLOOR BOARD x		330.00 x 1000
28.	1	REAR FLOOR PANEL ✓ OT		790.00 ✓
29.	1	REAR FLOOR PANEL STIFFENER R		160.00

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

CHINA INSURANCE COMPANY LIMITED
 105 CECIL STREET #18-00 & #19-00 THE OCTAGON
 069534

Attention : Motor Claim Department
 Contact : 6222 2366 Fax No. : 62247478

Estimate : ES000165

Date : 11/06/2018
 Vehicle Num. : SLL 434B (LCR)
 Make/Model : HONDA VEZEL HYBRID
 Chassis/Eng# :
 Accident Date : 11/06/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
30.	1	REAR COMPARTMENT BOX ✓ Deform		280.00
31.	1	REAR FENDER LH R		850.00
32.	2 LH & RH	REAR FENDER INNER TRIM BOARD ?	280.00	560.00 ✓
33.	2 LH & RH	REAR WHEEL ARCH ?	250.00	500.00 ✓
34.	1	SMART BUZZER SENSOR ?		180.00 ✓
35.	1	REAR ANTENNA SENSOR X		180.00 ✓
36.	1	REAR EXHAUST MUFFLER ?		750.00 ✓
37.	1	FRONT BUMPER R		900.00
38.	2 LH & RH	FRONT BUMPER RETAINER X	150.00	300.00 ✓
39.	1	FRONT CHROME GRILLE MOULDING ✓ CRK		380.00 76
40.	1	FRONT CHROME STRIP ✓ CRK		180.00
41.	1	FRONT GRILLE BASE ✓ CRK		380.00 ✓
42.	2 LH & RH	HEADLAMP ASSY LED X	1,850.00	3,700.00 ✓
43.	2 LH & RH	FRONT HEADLAMP LOWER BRACKET ✓ CRK	78.00	156.00 ✓
44.	1	FRONT BUMPER REINFORCEMENT ✓ OT		450.00 371
List Total S\$:				22,646.00
20.00% Discount S\$:				4,529.20
				18,116.80
SPECIAL NETT ITEMS :				
1.	1	REAR BOOT INNER TRIM BOARD CLIP		35 50.00 ✓ NEC
2.	1	REAR BUMPER CLIP		35 50.00 ✓ NEC
3.	1	REAR END PANEL TOP GARNISH CLIPS		35 50.00 ✓ NEC
4.	2 LH & RH	REAR WHEEL ARCH MOULDING CLIPS	50.00	100.00 3 x NN
5.	1	REVERSE SENSOR		250 280.00 ✓ DMG
6.	1	REAR NUMBER PLATE		40.00 X
7.	1	PRIVATE HIRER DECAL		20.00 ✓ NEC
8.	1	FRONT BUMPER CLIP		35 50.00 ✓ NEC
9.	1	FRONT NUMBER PLATE		40.00 X

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

CHINA INSURANCE COMPANY LIMITED
 105 GECIL STREET #18-00 & #19-00 THE OCTAGON
 069534

Attention : Motor Claim Department
 Contact : 6222 2366 Fax No. : 62247478

Estimate : ES000165

Date : 11/06/2018
 Vehicle Num. : SLL 434B (LCR)
 Make/Model : HONDA VEZEL HYBRID
 Chassis/Eng# :
 Accident Date : 11/06/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
10.	1	TOWING CHARGE		60.00 ✓
		Special Nett Total S\$:		740.00
		LABOUR :		
		REMOVE & REFIT REAR WINDSCREEN GLASS		180.00 120
		TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES		180.00 60
		WIRINGS CHECK AND RECTIFY WHERE NECESSARY		180.00 30
		LABOUR TO REMOVE REAR ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS.		1,800.00 1,400 1,200
		PUTTY & SPRAY PAINT REAR & ALL AFFECTED AREAS (INNER/ OUTER)		1,500.00 1,000
		TO REMOVE AND INSTALL HIGH VOLTAGE HYBRID BATTERY AS A REQUIREMENTS FOR SAFETY PRECAUTIONS.		380.00 200 80
		TO CONDUCT A STANDARD OF OPEARTING PROCEDURE POST REPAIRS DIAGNOSTIC SCAN TEST A REQUIREMENT FOR HYBRID CARS UPON COMPLETION OF COLLISION REPAIRS.		380.00 200 100
		LABOUR TO REMOVE FRONT ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS.		900.00 400 300
		PUTTY & SPRAY PAINT FRONT & ALL AFFECTED AREAS (INNER/ OUTER)		800.00 400

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

CHINA INSURANCE COMPANY LIMITED
 105 CECIL STREET #18-00 & #19-00 THE OCTAGON
 069534

Attention : Motor Claim Department
 Contact : 6222 2366 Fax No. : 62247478

Estimate : ES000165

Date : 11/06/2018
 Vehicle Num. : SLL 434B (LCR)
 Make/Model : HONDA VEZEL HYBRID
 Chassis/Eng# :
 Accident Date : 11/06/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

REMOVE REAR UPHOLSTERY IN ORDER TO FACILITATE REPAIRS
 AND REFIT BACK SAME

~~280.00~~ / 10

Labour Total S\$:

6,680.00

Sathya Sai
 13/6/2018
 98072012

[Signature]
 19/6/18

11 days

- Part by Part repair
- Question mark item photo
- Photo before paint.

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

E. & O.E.

Total S\$: 25,536.80

for WORLD AUTO PTE LTD

9077
 - 20%
 7261.6
 + 470
 + 3410
 11141.6

\$ 11141.60 @ 11 days
 confirmed

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18010825/NRD3N2

Date: 29/08/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3032401800
Claimant Vehicle No :	SLL434B	Insured Vehicle No :	GBF386G
Date of Loss:	11/06/2018	Nature of Claim:	TP
		Claim No:	SNM18D02953C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLL434B	Engine No:	LEB5917430
Make & Model:	HONDA VEZEL, 1.5 (A)	Chassis No:	RU31217422
Reg. Date:	10/02/2017 (Man. Year: 2016)	Odometer:	85330 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,796.80	7,671.60	11,125.20	59.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,740.00	3,470.00	3,270.00	48.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	25,536.80	11,141.60	14,395.20	56.37
+ GST 7.00/7.00% (\$\$)	1,787.58	779.91	1,007.67	56.37
Nett Amount (\$\$)	27,324.38	11,921.51	15,402.87	56.37

INSPECTION

Date of Assignment:	13/06/2018	
Date Inspected:	14/06/2018	Inspected At:
		World Auto Pte Ltd - Kranji (HQ)
		No 1 Kranji Loop
		Singapore 739535
Estimated Period of Repair:	11.0 days	

Adjuster: Muhammad Nazril Bin Abdullah

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Aug 2018)
Parts:	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLL434B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BOOT LID	Dented	1,250.00 FL	*1,100.00 FL
2	1	*REAR WINDSCREEN GLASS	Broken	1,000.00 FL	*1,000.00 FL
3	1	*REAR WINDSCREEN GLASS MOULDING	Necessary	150.00 FL	*150.00 FL
4	1	*REAR WINDSCREEN SEALANT	Necessary	120.00 FL	*50.00 FL
5	1	*REAR BOOT VEZEL EMBLEM (VEZEL)	Necessary	100.00 FL	*55.00 FL
6	1	*REAR BOOT HYBRID EMBLEM (VEZEL)	Necessary	100.00 FL	*78.00 FL
7	1	*REAR NUMBER PLATE LAMP GARNISH	Broken	250.00 FL	*180.00 FL
8	1	*REAR BOOT HONDA LOGO EMBLEM	Necessary	150.00 FL	*27.00 FL
9	1	*REAR BOOT WIPER MOTOR ASSY	Not Necessary	360.00 FL	*- FL
10	1	*WIPER ARM ASSY	Not Necessary	180.00 FL	*- FL
11	1	*REAR BOOT INNER TRIM BOARD	Deformed	280.00 FL	*280.00 FL
12	1	*REAR BOOT HAND GRIP COVER	Deformed	60.00 FL	*60.00 FL
13	2	*REAR BOOT HINGE LH & RH	Not Necessary	180.00 FL	*- FL
14	2	*REAR BOOT ABSORBER LH & RH	Not Necessary	300.00 FL	*- FL
15	1	*REAR BOOT WEATHER STRIP	Deformed	180.00 FL	*155.00 FL
16	2	*REAR BOOT REFLECTOR LAMP LH & RH	Cracked	1,800.00 FL	*844.00 FL
17	2	*REAR TAIL LAMP LH & RH	Cracked	1,400.00 FL	*920.00 FL
18	1	*REAR BOOT LOCK ASSY	Not Necessary	330.00 FL	*- FL
19	1	*REAR BOOT LOCK CATCH	Not Necessary	65.00 FL	*- FL
20	1	*REAR BUMPER	Damaged	900.00 FL	*900.00 FL
21	2	*REAR BUMPER RETAINER LH & RH	Not Necessary	240.00 FL	*- FL
22	2	*REAR SIDE BUMPER LH & RH	Cracked	500.00 FL	*390.00 FL
23	2	*REAR BUMPER REFLECTOR LENS LH & RH	Not Necessary	500.00 FL	*- FL
24	1	*REAR BUMPER UNDERDUST COVER	Not Necessary	165.00 FL	*- FL
25	1	*REAR END PANEL	Dented	860.00 FL	*550.00 FL
26	1	*REAR END PANEL TOP GARNISH	Deformed	200.00 FL	*155.00 FL
27	1	*REAR FLOOR BOARD	Not Necessary	330.00 FL	*- FL
28	1	*REAR FLOOR PANEL	Dented	790.00 FL	*790.00 FL
29	1	*REAR FLOOR PANEL STIFFENER	Repair	160.00 FL	*- FL
30	1	*REAR COMPARTMENT BOX	Deformed	280.00 FL	*280.00 FL
31	1	*REAR FENDER LH	Repair	850.00 FL	*- FL
32	2	*REAR FENDER INNER TRIM BOARD LH & RH	Not Necessary	560.00 FL	*- FL
33	2	*REAR WHEEL ARCH LH & RH	Not Necessary	500.00 FL	*- FL
34	1	*SMART BUZZER SENSOR	Not Necessary	180.00 FL	*- FL
35	1	*REAR ANTENNA SENSOR	Not Necessary	180.00 FL	*- FL
36	1	*REAR EXHAUST MUFFLER	Not Necessary	750.00 FL	*- FL
37	1	*FRONT BUMPER	Repair	900.00 FL	*- FL
38	2	*FRONT BUMPER RETAINER LH & RH	Not Necessary	300.00 FL	*- FL
39	1	*FROTN CHROME GRILLE MOULDING	Cracked	380.00 FL	*76.00 FL
40	1	*FROTN CHROME STRIP	Cracked	180.00 FL	*180.00 FL
41	1	*FRONT GRILLE BASE	Cracked	380.00 FL	*380.00 FL
42	2	*HEADLAMP ASSY LED LH & RH	Not Necessary	3,700.00 FL	*- FL
43	2	*FRONT HEADLAMP LOWER BRACKET LH & RH	Cracked	156.00 FL	*156.00 FL
44	1	*FRONT BUMPER REINFORCEMENT	Dented	450.00 FL	*321.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*REAR BOOT INNER TRIM BOARD CLIP	Necessary	50.00 FS	*35.00 FS
46	1		*REAR BUMPER CLIP	Necessary	50.00 FS	*35.00 FS
47	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*35.00 FS
48	2		*REAR WHEEL ARCH MOULDING CLIPS LH & RH	Not Necessary	100.00 FS	*- FS
49	1		*REVERSE SENSOR	Damaged	280.00 FS	*250.00 FS
50	1		*REAR NUMBER PLATE	Not Necessary	40.00 FS	*- FS
51	1		*PRIVATE HIRER DECAL	Necessary	20.00 FS	*20.00 FS
52	1		*FRONT BUMPER CLIP	Necessary	50.00 FS	*35.00 FS
53	1		*FRONT NUMBER PLATE	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	23,326.00	9,487.00
- List Item Discount on L Items 20.00/20.00% (S\$)	4,529.20	1,815.40

Total Parts (S\$)	18,796.80	7,671.60
--------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING CHARGE	New	60.00	60.00
2	REMOVE & REFIT REAR WINDSCREEN GLASS	New	180.00	120.00
3	TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES	New	180.00	60.00
4	WIRING CHECK AND RECTIFY WHERE NECESSARY	New	180.00	30.00
5	LABOUR TO REMOVE REAR ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT,CUT/WELD,STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS	New	1,800.00	1,200.00
6	PUTTY & SPRAY PAINT REAR & ALL AFFECTED AREAS (INNER/OUTER)	New	1,600.00	1,000.00
7	TO REMOVE AND INSTALL HIGH VOLTAGE HYBRID BATTERY AS A REQUIREMENTS FOR SAFETY PRECAUTIONS	New	380.00	80.00
8	TO CONDUCT A STANDARD OF OPERATING PROCEDURE POST REPAIRS DIAGNOSTIC SCAN TEST A REQUIREMENT FOR HYBRID CARS UPON COMPLETION OF COLLISION REPAIRS	New	380.00	100.00
9	LABOUR TO REMOVE FRONT ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT,CUT/WELD,STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS	New	900.00	300.00
10	PUTTY & SPRAY PAINT FRONT & ALL AFFECTED AREAS (INNER/OUTER)	New	800.00	400.00
11	REMOVE REAR UPHOLSTERY IN ORDER TO FACILITATE REPAIRS AND REFIT BACK SAME	New	280.00	120.00
Gross Labour Cost (S\$)			6,740.00	3,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >