

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

AIG

Name : Muhammad Shahrizal Bin Adnan

Accident Date : 21-Apr-18

Vehicle No : FBC 9928 A

Vehicle Model : Yamaha X-1

Estimated Repair Costs

Qty	Description <u>List Items</u>		Amount S(\$)
1	Front fender	not fitted	CU1 \$ 65.00 ✓
2	Fork inner tubes	new	11 \$ 250.00 x
2	Fork outer tubes	2/5 #850/2	11 \$ 270.00 x
1	Fork under bracket	4 day.	11 \$ 195.00 x
1	Front brake disc	13/6/18	11 \$ 145.00 x
1	Front rim shaft	to be ph. At the age	11 \$ 45.00 x
1	Front sport rim		11 \$ 280.00 x
1	Top cowl		11 \$ 85.00 x
1	Front cowl		CU1 \$ 95.00 ✓
1	Front cowl bracket		11 \$ 48.00 x
1	Headlamp		11 \$ 185.00 x
2	Side cowlings		CU1 \$ 180.00 ✓
2	Front signals		CU1 \$ 96.00 ✓
1	Side mirror -L/H		CU1 \$ 55.00 ✓
1	Meter		11 \$ 320.00 x
1	Front footrest bracket		CU1 \$ 40.00 ✓
1	Front footrest rubber -L/H		CU1 \$ 18.00 ✓
1	Gear pedal		CU1 \$ 45.00 ✓
1	Basket		11 \$ 32.00 x
1	Side stand		11 \$ 75.00 x
1	Main stand		11 \$ 95.00 x
1	Rear footrest -L/H		11 \$ 28.00 x
1	Rear footrest bracket -L/H		11 \$ 45.00 x
1	Rear tailboard -L/H		11 \$ 95.00 x
			\$ 2,787.00
Less 10%			\$ 278.70
			\$ 2,508.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

594
534.6

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

Name : Muhammad Shahrizal Bin Adnan

Accident Date : 21-Apr-18

Vehicle No : FBC 9928 A

Vehicle Model : Yamaha X-1

Estimated Repair Costs

Special Nett Items

1	Number plate (1 set)	Scd	\$	28.00	10
2	Fork oils	11	\$	30.00	x
2	Fork oil seals	11	\$	56.00	9
1	Steering cone (1 set)	11	\$	75.00	x
1	ERP IU	cu7	\$	170.00	165
1	Rear box	cu7	\$	180.00	150
1	Rear box bracket	1	\$	100.00	x
				\$	639.00

S/No. Labour

1	To provide towing service.	\$	35	45.00
2	To check wiring and reset headlamp focusing.	\$	11	80.00 x
3	To provide labour.	\$	200	380.00
		\$		505.00

Grand Total

\$ 3,652.30

1094.6

Dollars: Three Thousand Six Hundred Fifty-Two And Thirty Cents Only.



EROFIA MOTOR TRADING PTE LTD