

15/9/2010

INS. CASE OWNER:

Salam

CC6 /AIG1801

0852, 71 1/2 52

LKK:

IDAC:

Surveyor:

Taufich

DOI:

ASSIGNMENT

13/6/18

Date / Time:

13/6/18

Registered in Merimen:

14/6/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKS 9039A

Name of Insured:

PINE STAR CONCIERGE Pte

Insured Tel No.:

HP:

D.O.A:

7/6/18

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

KUAN YIN KUAN

Driver Tel No.:

(V/L: YES/ NO)

Claim No.:

250888109456

Policy No.:

Make / Model:

MERLETS

Place of Accident:

CHANNI AIRPORT T3 B1 UP

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SLM 7873R

INSRS:
WSP:
Tel:
Liability:
RMKS:

pengasas

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

18/6/18

7/11

11/12/18

14/12/18

17/12/18

SLM 7873R - X

SKS 9039A - X

- Old reversing into parking lot while TP came out from parking lot

- Rec'd email from OI: OI had done private settlement

- File pass to SP to check

RECEIVED 17 DEC 2018

STAGE	DATE / PIC
Non-Reporting ltr (1st):	
Non-Reporting ltr (2nd):	
Non-Reporting ltr (Final):	
Notification ltr (if non-pickup):	
Call OI:	25/11/18
After call ltr to OI:	
Documentation Check List: Handler Typist	
Notification ltr (if non-pickup)	
After call ltr to OI:	
Authorisation To Act:	
Release Voucher:	
Final Repair Bill:	
Car Rental Invoice:	
Towing Invoice:	
LTA / GIA:	
Medical Bill:	
PIR:	
Mandate/Reject Instruction:	
LOD:	
Payment Breakdown Form:	
Post-Repair Photos:	
Others:	

PRELIMINARY ADVICE Date/Time:		Sent By:	
FINALIZATION Date/Time:		Confirm with:	
Repair Cost:	SS	(days) Reduction:	%
FINAL SETTLEMENT Date/Time:		Confirm with:	
Final Liability:	% 50	(Agreed / Assessed) BOLA S/N No.:	25.
Repair Cost:	SS		
Loss of Rental (LOR):	SS	(days)	
Loss of Use (LOU):	SS	(S x days)	
Loss of Income (LOI):	SS	(S x days)	
LOR only ☐ LOU only ☐	LOR + LOU ☐ LOR + LO ☐	[Tick only one]	
GIA/LTA Search	SS		
Medical:	SS		
Disbursement:	SS	(e.g. Tow/ Independent)	
Legal Cost	SS		
Total:	SS	Global Sum SS:	
FINAL PAYMENT Date/Time:		Confirm with:	
Payee 1:	SS	Name 1:	
Payee 2: (Strike if N.A.)	SS	Name 2:	
Payee 3: (Strike if N.A.)	SS	Name 3:	

COPY SENT

- 1) Claim status: Normal/Reject/Private Settle (UP)
 2) Report Format: TP
 3) Survey fee: \$250.00

WY/MA/

Tauplin

REF:

ALG

ASSIGNMENT

From: Date:

Estimated Cost:

OD 7 / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days: Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

WP

Date:

Person Contacted:

Vehicle IN / OUT

Veh No: SLM787BR

Vr Regn: 217 April

Type: B Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or:

Make:

Mazda 3

C.G.

1496

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

52660

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JMB3N22A 8H0152381

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60R16

R:

205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Went/Alto

Front

Rear

R/Bal:

6

mm

R/Bal:

6

mm

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A.

D.O.I.

13/6/18 @ 1150

Survey held at

Pegasus

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

w/s will mail estimate with price

Submit

US \$ 1000 (Red \$ 3045.00 / 754.7)

Date/Time: File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time: File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / L.B.I. / S

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

1) S + RS \$

2) Photos

3) Clean

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG18010852/T1ub3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 14-06-2018		
Code : AIG				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKS 9039A	Veh. Inspected	SLM 7873R	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	14/06/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	07/06/2018	Inspection Date	13/06/2018	
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

SLM 7873R

Front Bumper ~~✓~~ \$925
\$6075

Front Bumper side retainers (LEFT) ~~✓~~ \$36.10

Front indicator right ? \$140

Front Bumper indicator right Garnish ? \$38

Front Bumper indicator right Extension ? \$20

Front Bumper reinforcement ? \$478

Front Bumper clip ~~✓~~ \$30

Front Bumper reinforcement cover ? \$67

Front Bumper reinforcement cover clips ? \$25

Radiator Grille x ~~✓~~ \$129

Radiator Grille chrome Garnish x ^{nm} \$183

Radiator Grille chrome Garnish Base ^{nm} x \$38

Radiator Grille outer Garnish rivets (4 pc) x ^{nm} \$36

Radiator Grille outer Garnish rivets clips (4 pc) x ^{nm} \$20

Headlamp (Left) x ^{nm} \$1020

1) To check Electrical lighting concerned → \$606-30

2) Panel Beating, knocking and straighten the necessary
portion, remove and renewal of parts, adjust and
realign the same 200
\$4006

3) Putty and spray-painting of the affected portion 200
\$4006

Tanfikh 97495749
"WP"

13/6/18 @ 1150

Resurvey after repair
2 days

sur e lkkauto.com

4045.10



Hsiao Tong (LKKAuto)

From: Victor Ong <victor.ong@bluestarconcierge.com.sg>
Sent: Friday, 14 December 2018 3:00 PM
To: Hsiao Tong (LKKAuto)
Cc: edmund.han@bluestarconcierge.com.sg; Dandy Tan; benongyr@gmail.com
Subject: Accident involving SKS9039A & SLM7873R on 07/06/2018
Attachments: LKK Letter.pdf; Private settlement 9039.pdf

Hi Mr Chew

Good Afternoon

We had today received a letter with regards to the above subject as attached. We would like to inform you that we have reached a mutual private settlement dated 27/7/18 as attached that we should not claim against each other insurance. Therefore Third Party should not claim against our insurance.

Tks
Victor
Bluestar Concierge Pte Ltd

Mutual Settlement Form


When involved in a motor accident, you can choose to enter into a private settlement with the OWNER of the other car if there are:-

- no personal injuries or death of motorist and/or pedestrians
- damages are minor
- no involvement in chain collisions

Under this private settlement, both parties agree to settle the matter amicably without suing each other.

It is a legally binding agreement.

1. Details of the Accident:-
 Date (dd/mm/yyyy): 07/06/2018 Time: 0635 hrs
 Location: Ayerhempstead
- 2a. Vehicle registration no. SUM7873R driven by NG YAN SIN JAYDEN (S8035701E)
 (Name & Nric no) and owned by GRAB RENTALS PTE LTD (Name & Nric no).
- 2b. Vehicle registration no. SKS9039A driven by CHUA YIN CHUAN (S7736138C)
 (Name & Nric no) and owned by BLUE STAR CONCIERGE PTE LTD (Name & Nric no).
3. The parties have agreed to settle this matter amicably as follows: *delete a or b as applicable.
 - *a. Neither party shall be liable to compensate the other party for any loss or damages incurred or To be incurred as a result of the accident.
 - *b. Without any admission of liability, Blue Star Concierge Pte Ltd (party paying compensation) has paid a sum of \$ 1250.00 which _____ (owner receiving compensation) hereby acknowledge receipt thereof in full and final settlement of all damages and costs incurred and/or to be incurred as a result of the accident.
4. There are no personal injuries to the undersigned parties.
- 5.

	Vehicle A no. : <u>SUM7873R</u>	Vehicle B no. : <u>SKS9039A</u>
Name	<u>Grab Rentals Pte Ltd</u>	<u>CHUA YIN CHUAN</u>
NRIC no.	<u>201672006</u>	<u>S7736138C</u>
Address		<u>Blk 683B Ponggol Drive #14-22</u> <u>S'pore 822663</u>
Tel no.		<u>92386008</u>
Signature & Date	 <u>GRAB RENTALS PTE LTD</u>	 <u>27/7/2018</u> 

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Friday, 14 December 2018 4:31 PM
To: 'Syed-Yusoff, Saliha'
Subject: Your Ref: 2508881095SG *LKK REF: CC6/AIG18010852/T1pb3 [ACCIDENT INVOLVING SKS 9039A(OI) & SLM 7873R(TP) ON 07/06/2018]
Attachments: Private settlement_SLM 7873R vs SKS 9039A.pdf

Hi Saliha,

We refer to the above matter.

Please be informed that OI & TP had done private settlement. Kindly refer to the private settlement letter uploaded in Merimen for your easy reference.

In view of this, we will proceed to close file and submit wp report to you good office.

Thank you.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG18010852/T1pb3

13 DEC 2018

BLUE STAR CONCIERGE PTE LTD

621 Aljunied Rd

#06-07

Lipo building, Singapore 389834

Dear Sir/Madam,

**ACCIDENT INVOLVING SKS 9039A & SLM 7873R ALONG/AT CHANGI AIRPORT T3
B1 CARPARK ON 07/06/2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SLM 7873R against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that both parties should exercise caution on this matter. Under Motor Accident Guide, vehicle reversing in/out or moving in/out of parking lot should exercise caution. Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

If you have evidence/information to proof that we should not settle the third party claim, kindly let us have them in writing within the next 10 days i.e. by 23/12/2018, after we shall proceed with negotiation with Third Party claimant on the without prejudice basis and any settlement should not bind any claims whatsoever by you/your driver against the other party's insurer arising from this particular accident.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

CHEW HSIAO TONG

Case Handler

DID: 6742 3197

FAX: 6741 4108

Email: chewht@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Jun 2018 Edit Reg		13 Jun 2018 00:00 Edit Adj Rpt	S\$1,000.00 Edit Estimates	S\$1,000.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	BLUE STAR CONCIERGE PTE LTD , Co. Reg. No.: 201506692D		
Main Claimant:	GRAB RENTALS PTE LTD , Co. Reg. No.: 201617200G		
Vehicle Reg. No.:	SLM7873R	Date of Loss:	07/06/2018 06:00 - :59 [13 Months and 27 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 2508881095SG	Policy/Cover Note No.:	0999994959 (Comprehensive)
Vehicle Reg. No. (Insured):	SKS9039A	Policy No. (Claimant):	A29069766MKF
		Excess:	
Repairer:	Pegasus Engineering & Trading Pte Ltd (HQ) 51 DEFU LANE 10, 539216 Defu Lane - Tel: 68581846		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com		
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 26/06/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLM7873R (2508881095SG)**
[SKS9039A]
TP
GRAB RENTALS PTE LTD
Jun 7 2018 6:00AM
[BLUE STAR CONCIERGE PTE LTD]
Pegasus Engineering & Trading Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Photos/Images															3 per page			☒		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	11/12/18 11:16	Odometer Reading														Load JPG	☒			
2	11/12/18 11:16	Chassis Number														Load JPG	☒			
3	11/12/18 11:16	General View														Load JPG	☒			
4	11/12/18 11:16	General View														Load JPG	☒			
5	11/12/18 11:16	General View														Load JPG	☒			
6	11/12/18 11:16	General View														Load JPG	☒			
7	11/12/18 11:16	General View														Load JPG	☒			
8	11/12/18 11:16	General View														Load JPG	☒			
9	11/12/18 11:16	General View														Load JPG	☒			
10	11/12/18 11:16	General View														Load JPG	☒			
11	11/12/18 11:16	General View														Load JPG	☒			
12	11/12/18 11:16	General View														Load JPG	☒			
13	11/12/18 11:16	General View														Load JPG	☒			
14	11/12/18 11:16	General View														Load JPG	☒			
15	11/12/18 11:16	General View														Load JPG	☒			
16	11/12/18 11:16	General View														Load JPG	☒			
17	11/12/18 11:16	General View														Load JPG	☒			
18	11/12/18 11:16	General View														Load JPG	☒			
19	11/12/18 11:16	General View														Load JPG	☒			
20	11/12/18 11:16	General View														Load JPG	☒			
21	11/12/18 11:16	General View														Load JPG	☒			
22	11/12/18 11:16	General View														Load JPG	☒			
23	11/12/18 11:16	General View														Load JPG	☒			
24	11/12/18 11:16	General View														Load JPG	☒			
25	11/12/18 11:16	General View														Load JPG	☒			
26	11/12/18 11:16	General View														Load JPG	☒			
Documentation															1 per page			☒		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	14/06/18 15:48	TP ESTIMATE- MARKED														Load PDF				
2	14/06/18 15:48	TP GIA REPORT														Load PDF				
3	14/12/18 16:31	Private settlement_SLM 7873R vs SKS 9039A														Load PDF				
4	15/12/18 14:22	Email_to_AIG_dd_141218														Load PDF				
5	15/01/19 08:44	LETTER TO OI														Load PDF				
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)														Thumbnail	Print			
1	18/06/18 12:46	OI GIA REPORT														Load PDF				

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18010852/T1PB3S2
Date: 15/01/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994959
Claimant Vehicle No: SLM7873R Insured Vehicle No: SKS9039A
Date of Loss: 07/06/2018 Nature of Claim: TP Claim No: 2508881095SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLM7873R
Make & Model: MAZDA 3, 1.5 SEDAN EU6 (A) Engine No: P520443971
Reg. Date: 11/04/2017 (Man. Year: 2017) Chassis No: JM6BN22A8H0152381
Colour: Black Odometer: 52660 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60R16 Rear Tyre Size: 205/60R16
Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6 mm
Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,185.10	792.88	2,392.22	75.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	860.00	430.00	430.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	4,045.10	1,222.88	2,822.22	69.77
Approved Total (Overridden) (\$\$)		1,000.00		
(\$\$)	4,045.10	1,000.00	3,045.10	75.28
+ GST 7.00/7.00% (\$\$)	283.16	70.00	213.16	75.28
Nett Amount (\$\$)	4,328.26	1,070.00	3,258.26	75.28

INSPECTION

Date of Assignment: 13/06/2018
Date Inspected: 13/06/2018 Inspected At: Pegasus Engineering & Trading Pte Ltd (HQ)
51 DEFU LANE 10
Singapore 539216
Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_printtrpt&caseid=716800&extid=274971&CFID=47005447&C... 1/5

any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$614.40 NETT)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	925.00 F	*925.00 FL
2	1		*FRONT BUMPER SIDE RETAINER (LEFT)	Necessary	36.10 F	*36.10 FL
3	1		*FRONT INDICATOR LIGHT	*Check	140.00 F	*- FL
4	1		*FRONT BUMPER INDICATOR LIGHT GARNISH	*Check	38.00 F	*- FL
5	1		*FRONT BUMPER INDICATOR LIGHT EXTENSION	*Check	20.00 F	*- FL
6	1		*FRONT BUMPER REINFORCEMENT	*Check	478.00 F	*- FL
7	1		*FRONT BUMPER CLIP	Necessary	30.00 F	*30.00 FL
8	1		*FRONT BUMPER REINFORCEMENT COVER	*Check	67.00 F	*- FL
9	1		*FRONT BUMPER REINFORCEMENT COVER CLIPS	*Check	25.00 F	*- FL
10	1		*RADIATOR GRILLE	Not Necessary	129.00 F	*- FL
11	1		*RADIATOR GRILLE CHROME GARNISH	Not Necessary	183.00 F	*- FL
12	1		*RADIATOR GRILLE CHROME GARNISH BASE	Not Necessary	38.00 F	*- FL
13	4		*RADIATOR GRILLE OUTER GARNISH RIVETS	Not Necessary	36.00 F	*- FL
14	4		*RADIATOR GRILLE OUTER GARNISH RIVETS CLIPS	Not Necessary	20.00 F	*- FL
15	1		*HEADLAMP (LEFT)	Not Necessary	1,020.00 F	*- FL

F=Franchise part, L=ListItemDisc.

Sub Total (\$\$)	3,185.10	991.10
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	198.22
Total Parts (\$\$)	3,185.10	792.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ELECTRICAL LIGHTING CONCERNED.	New	60.00	30.00
2	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	New	400.00	200.00
3	PUTTY AND SPRAY-PAINTING OF THE AFFECTED PORTION.	New	400.00	200.00
Gross Labour Cost (\$\$)			860.00	430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >