

SLM 7873R

Front Bumper de✓

Front Bumper side retainers (LEFT) de✓

Front indicator light ?

Front Bumper indicator light Garnish ?

Front Bumper indicator light Extension ?

Front Bumper reinforcement ?

Front Bumper clip de✓

Front Bumper reinforcement cover ?

Front Bumper reinforcement cover clips ?

Radiator Grille X

Radiator Grille chrome Garnish X

Radiator Grille chrome Garnish Base X

Radiator Grille outer Garnish rivets (4 pc) X

Radiator Grille outer Garnish rivets clips (4 pc) X

Headlamp (Left) X



1) To check Electrical lighting concerned → \$ 60/2 30

2) Panel Beating, knocking and straighten the necessary
portion, remove and renewal of parts, adjust and
realign the same 200
\$ 400/2

3) Putty and spray-painting of the affected portion 200
\$ 400/2

Tanfikh 97495749
- WP -

13/6/18 @ 11:50

Resurvey after repair

• 2 days

sur @ lkkauto.com.