

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 771G**AAF1806-100***Not Notarized**Recovery B4 paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHF 771G

VF1ABL15AUC283243

RENAULT

LATITUDE

12.6.2018

III

PART		LIST	
1	FENDER PANEL FRT RH	\$	<i>R</i> 783.83 X
1	WHEELARCH FRT RH	\$	<i>Sn</i> 278.84 X
1	FENDER BRACKET LOWER RH	\$	<i>Sn</i> 15.79 X
1	FENDER INSULATOR RH	\$	<i>Sn</i> 130.84 X
1	DOOR PANEL FRT RH	\$	<i>B</i> 2,844.66 ✓
1	DOOR HINGE UPPER RH	\$	<i>R</i> 261.28
1	DOOR HINGE LOWER RH	\$	<i>R</i> 300.55
1	DOOR CHECK FRT RH	\$	<i>Sn</i> 194.77
1	DOOR LOCK FRT RH	\$	<i>R</i> 908.75 } X
1	DOOR CATCH FRT RH	\$	<i>Sn</i> 131.23
1	DOOR HANDLE OUTER FRT RH	\$	<i>Sn</i> 477.76
1	DOOR HANDLE COVER FRT RH	\$	<i>Sn</i> 13.22
1	DOOR HANDLE MODULE FRT RH	\$	<i>Sn</i> 133.60
1	DOOR REGULATOR FRT RH	\$	505.19 ✓
1	DOOR REGULATOR MOTOR FRT RH	\$	796.46 ✓
1	DOOR REGULATOR GUIDE FRT RH	\$	<i>Sn</i> 120.97 X
1	DOOR PANEL REAR RH	\$	<i>R</i> 2,844.66 X
1	DOOR MIRROR ASSY RH	\$	<i>Sn</i> 1,483.40 X
1	ROCKER PANEL INNER GARNISH RH	\$	<i>Sn</i> 466.51 X
1	ROCKER PANEL INNER RH	\$	<i>R</i> 1,024.79 X
1	ROCKER PANEL CENTER RH	\$	<i>R</i> 990.25 X

\$	14,707.35
----	------------------

10% \$	1,470.74
--------	-----------------

\$	13,236.62
----	------------------

Special Nett

1	FRONT DOOR STICKER 'Trans-cab'	\$	<i>me</i> 80.00 <i>60.50</i>
1	FRONT DOOR STICKER 'Chassis'	\$	<i>me</i> 50.00 <i>15.50</i>

Trans-cab Auto Services Pte Ltd

AAF1806-100

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 771G

1	REAR DOOR STICKER '6555 3333'	\$	nn 80.00	}
1	DOOR CHECK BOLT	\$	sn 22.69	
1	DOOR GUIDE SCREW	\$	sn 10.85	
1	DOOR HINGE BOLT	\$	sn 10.85	
1	DOOR HINGE NUT RH	\$	sn 14.60	
1	DOOR CHECK BOLT	\$	sn 22.69	
1	DOOR CHECK NUT	\$	sn 3.75	
1	DOOR LOCK SCREW L70Y	\$	sn 6.12	
1	DOOR CATCH SCREW L70Y	\$	sn 10.06	

TOTAL	\$	311.63
--------------	-----------	---------------

TOTAL PARTS	\$	13,548.25
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$	2000 4,500.00
----	---------------

Putty and spray painting of the affected portion.

\$	3200 4,200.00
----	---------------

To rust-proofing of the affected areas.

\$	300 170.00
----	------------

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$	nn 380.00 X
----	-------------

To check steering geometry and computer wheel alignment

\$	nn 220.00 X
----	-------------

To transfer of tire, rim and on wheel balancing.

\$	nn 170.00 X
----	-------------

To Check Electrical Lighting Concerned.

\$	200 170.00
----	------------

To transfer of front fender fittings, attachment and perform water seepage test.

\$	nn 380.00 X
----	-------------

Trans-cab Auto Services Pte Ltd

AAF1806-100

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 771G

To transfer of front door fittings, attachment and perform water seepage test.	\$	380.00	601
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	380.00	na X
Towing Fees.	\$	120.00	na X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00	na X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	na X

TOTAL	\$	11,830.00
--------------	-----------	------------------

Over All Total	\$	25,378.25
-----------------------	-----------	------------------

LUMP SUM (REPAIR DAY)~~15 DAYS~~

2 day,

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: