

To Survey by (KK)

VEHICLE NO : SELA 997Z

DATE : 13.06.2018

TEL : 6542 5119

FAX : 6542 6039

INDIA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bumper Assy, Frt <i>Dented</i>			\$ 1,890.50 ✓
	Bumper Bracket, Frt/LH <i>SVC</i>			\$ 95.00 X
	Bumper Frame, Frt/LH <i>NN</i>			\$ 39.45 <i>X</i>
	Bumper Sponge, Frt/LH <i>NN</i>			\$ 250.00 X
	Bumper Sponge Extension , Frt/LH <i>NN</i>			\$ 54.00 X
	Bumper Inner Clip, Frt <i>Nuc</i>			\$ 22.00 ✓
	Head Lamp Assy (LH) <i>broken</i>			\$ 2,380.00 —
	Head Lamp Bracket (LH) <i>X Vst</i>			\$ 300.00 <i>L</i>
	Head Lamp Panel (LH) <i>Vst</i>			\$ 480.00 <i>L</i>
	Bonnet Assy <i>Vst</i>			\$ 2,850.60 <i>L</i>
	Bonnet Mercedes Star Logo <i>SVC</i>			\$ 56.70 X
	Fender, Frt/LH <i>Nuc</i>			\$ 996.08 —
	Fender Splashshield , Frt/LH (Front) <i>X deformed</i>			\$ 257.00 <i>L</i>
	Fender Splashshield , Frt/LH(Rear) <i>X deformed</i>			\$ 263.00 <i>L</i>
	Wheel Rim, LH <i>Cnt</i>			\$ 1,250.00 ✓
	Tyre 205/60R16 Yokohama <i>SVC</i>			\$ 480.00 X
	Wheel Hub Bearing ,Frt <i>X Dam.</i>			\$ 1,250.00 <i>L</i>
	Windscreen Side Moulding,Frt/LH <i>NN</i>			\$ 330.00 X
	Door Shell, Frt/LH <i>Vst</i>			\$ 2,970.00 <i>L</i>
	Mirror Housing W/Signal Lamp, Frt/LH <i>Cnt</i>			\$ 414.00 <i>L</i>
	Side Panel Garnish, LH <i>Nuc</i>			\$ 624.00 X
	S/Absorber, Front LH <i>X distorted</i>			\$ 944.00 <i>L</i>
	Strur, Frt/LH <i>NN</i>			\$ 604.00 X
	Steering Knuckle Arm, Frt/LH <i>X distorted</i>			\$ 1,119.00 <i>L</i>
	Lower Arm Assy, Frt/LH <i>X distorted</i>			\$ 661.05 <i>L</i>
	Lower Arm Bolt <i>SVC</i>			\$ 55.00 X
	Top Arm Assy, Frt/LH <i>X distorted</i>			\$ 479.15 <i>L</i>
	Torsion Bar Rod, Frt/LH <i>NN</i>			\$ 105.60 <i>X</i>
	Torsion Bar Frt/LH <i>NN</i>			\$ 405.00 <i>X</i>
	Engine Crossmember <i>X distorted</i>			\$ 2,985.50 <i>L</i>
	Engine Mounting (LH/RH) <i>crack / damaged</i>	\$	450.80	\$ 901.60 <i>L</i>
	P/Steering Gear Assy <i>broken</i>			\$ 7,167.00 <i>L</i>
	SUB TOTAL			\$ 32,679.23
	LESS 10%			\$ 3,267.92
	DISCOUNTED TOTAL			\$ 29,411.31

SHA 997Z

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 1,200.00
	Spray Painting Charge			\$ 1,500.00
	Wiring Charge			\$ 100.00
	Towing Charges			\$ 50.00
	Tuff Kote			\$ 150.00
	Transfer Of Door			\$ 120.00
	Remove/Refix Undercarriage (FRT)			\$ 400.00
	FRT Wheel Alignment			\$ 120.00
		</		

REPAIR ESTIMATE*

DATE : 18.06.2018

TEL : 6542 5119

FAX : 6542 6039

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 997Z (Supplementary)

DATE : 27.06.2018

MAKE :

TEL : 6542 5119

MODEL : MERCEDES

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet Air Inlet Grille <i>on panel</i>			\$ 369.25
	SUB TOTAL			\$ 369.25
	LESS 10%			\$ 36.93
	DISCOUNTED TOTAL			\$ 332.33
	 <i>2Kk Auto</i> 			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.