

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 8215C

DATE 12/6/2018 11:37

MAKE :

DOA : 12.06.18

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid <i>x rep</i>			\$ 1,681.40
	Boot Lid 'H' Emblem			\$ 27.20
	Boot Lid CRDI Plate			\$ 41.00
	Boot Lid Lamp (LH)			\$ 556.80
	Bootlid Moulding			\$ 85.00
	Bootlid i40 Emblem			\$ 41.00
	Bootlid Lower Garnish <i>x rep</i>			\$ 398.00
	Rear Bumper			\$ 603.60
	Rear Bumper Reinforcement ?			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH) ?		\$ 180.00	\$ 360.00
	Rear Bumper Side Bracket ?		\$ 49.00	\$ 98.00
	Rear Bumper Clips			\$ 22.00
	Rear Bumper Sponge			\$ 143.40
	Rear Bumper Under Cover			\$ 225.00
	Rear Bumper Reflector Lamp (LH)			\$ 32.00
	Tail Lamp (LH)			\$ 565.60
	Rear Panel <i>x rep</i>			\$ 592.30
	Rear Panel Garnish ?			\$ 57.70
	Rear Panel Lower Panel <i>x rep</i>			\$ 495.50
	SUB TOTAL			\$ 6,529.85
	LESS 20%			\$ 1,305.97
	DISCOUNTED TOTAL			\$ 5,223.88
	Boot Lid Comfort Logo & Tel No. Sticker			\$ 30.00 Nett
	Rear Bumper Reverse Sensor			\$ 135.70 Nett
	Rear Bumper Rubber Mat			\$ 50.00 Nett
				\$ 215.70
	Labour Charge			
	Panel Beating			\$ 850.00 <i>600</i>
	Spray Painting Charge			\$ 750.00 <i>600</i>
	Wiring Charge			\$ 50.00 <i>20</i>
	Tuff Kote			\$ 50.00 <i>x</i>
	Remove/Refix Reverse Sensor			\$ 120.00 <i>30</i>
	TOTAL LABOUR			\$ 1,820.00
	ESTIMATE TOTAL			\$ 7,259.58
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

CHINA

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Kalvin

13/6/18 1045 hrs

3 Days

4/3

After Repair p.h.t.

Larry Ng