

ESTIMATE TO REPAIR

VEHICLE NO. : SJD 3062 L
 MAKE : TOYOTA
 MODEL : VIOS E AUTO
 YEAR : 2008
 CHASSIS NO : MR053HY9305042746

SURVEYOR NAME	:
DATE OF SURVEY	: 18.06.2018
TIME OF SURVEY	:

DATE : 13-Jun-18
 DATE OF ACCIDENT : 11-Jun-18
 THIRD PARTY REF : SKW 5839 M / EQ INSURANCE

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper			\$ 458.90	
1 pc	N/S Rear Bumper Retainer			\$ 81.40	
1 pc	N/S Taillamp			\$ 298.50	
1 pc	N/S Rear Fender Undershield			\$ 78.70	
				\$ 917.50	
	Less 25%			\$ 229.38	
				\$ 688.13	
	To putty & spray painting.			\$ 450.00	
	Labour Charges.			\$ 300.00	
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date: <i>Not Authorise</i> <i>11/6/18</i> <i>Murray Allen Paine</i>					
TG-RA/-	TOTAL				\$ 1,438.13

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel: 65-64520893 Fax: 65-64583127

Website : www.LTM.sg

Co.Reg No. 199307277D

GST Reg No. M2-0019086-0