

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

GY6700J
 TP/EQ

M/S : EQ INSURANCE CO LTD
 22 GEMMILL LANE
 SINGAPORE 069257

TEL: 62239433
 ATTN: Motor Claim Department
 WS Ref: TP/EQ/WL
 Claim Type: Third Party
 Accident Date: 04/06/2018
 TP Veh Reg No: GBE8257Z

FAX: 62243903

Not Authorized
6/1 Day & ?
Resurvey After Repair 1 day

Claim No: ES1890651
 Estimate No: ES1890651/WL
 Date: 13 Jun 2018
 Policy No: DMCV17S011962
 Veh Reg No: GY6700J
 Make/Model: TOYOTA DYNA 150 D
 Chassis No: JTFUF34Y003010678
 Engine No: 5L5593642
 Reg. Date: 29/06/2005

Estimate Repair Cost to Vehicle No : GY6700J

Description	U/Price	Quantity	Cost	Amount
			<u>SS</u>	<u>SS</u>
Cost Plus				
1 FRONT BUMPER	160.00	1 PC	160.00	✓
2 FRONT GRILLE	155.00	1 PC	155.00	✓
3 HEADLAMPS	210.00	2 PCS	420.00	✓
4 FRONT PANEL	350.00	1 PC	350.00	✓
5 FRONT PANEL LOGO	30.00	1 PC	30.00	✓
6 FRONT CENTRE GARNISH	105.00	1 PC	105.00	✓
7 FRONT SIDE GARNISHS	45.00	2 PCS	90.00	✓
8 FRONT WINDSCREEN GLASS RUBBER	105.00	1 PC	105.00	✓
9 REAR TAILGATE	420.00	1 PC	420.00	✓
10 LH TAILLAMP	65.00	1 PC	65.00	✓
11 TAILGATE LH SAFETY LOCK	35.00	1 PC	35.00	✓
12 TAILGATE LH HANDLE	48.00	1 PC	48.00	✓
13 TAILGATE RH SAFETY LOCK	35.00	1 PC	35.00	✓
14 TAILGATE RH HANDLE	48.00	1 PC	48.00	✓
15 REAR BUMPER PLATE PANEL	55.00	1 PC	55.00	✓
16 RH SIDE GATE	480.00	1 PC	480.00	✓
17 AIR-CON BLOWER	280.00	1 PC	280.00	✓
			2,881.00	
	Add 20%		576.20	3,457.20

Special Net				
18 REAR NUMBER PLATE	12.00	1 PC	12.00	✓
19 SPEED LIMIT STICKER	10.00	1 PC	10.00	✓
20 13 PAX STICKER	10.00	1 PC	10.00	✓
21 FRONT NUMBER PLATE	12.00	1 PC	12.00	✓
22 TAILGATE INNER PROTECTOR	280.00	1 PC	280.00	✓
23 RH SIDE GATE INNER PROTECTOR	380.00	1 PC	380.00	✓
24 RAILING	450.00	1 SET	450.00	✓

LKK Auto Consultants hereby
 the Repairer of the following
 • To resurvey before after spray painting
 • To display damaged parts for survey
 • Parts prices are subject to inspection
 • Third party survey on a "without prejudice" basis
 • No illegal modifications is allowed
 • Supplementary for must be checked and
 is subject to final approval of Insurance Company

Acknowledged by Repairer:

Signature:

Date:

1,154.00

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : EQ INSURANCE CO LTD
22 GEMMILL LANE
SINGAPORE 069257

TEL: 62239433 FAX: 62243903
ATTN: Motor Claim Department
WS Ref: TP/EQ/WL
Claim Type: Third Party
Accident Date: 04/06/2018
TP Veh Reg No: GBE8257Z

Claim No: ES1890651
Estimate No: ES1890651/WL
Date: 13 Jun 2018
Policy No: DMCV17S011962
Veh Reg No: GY6700J
Make/Model: TOYOTA DYNA 150 D
Chassis No: JTFUF34Y003010678
Engine No: 5L5593642
Reg. Date: 29/06/2005

Estimate Repair Cost to Vehicle No : GY6700J

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
Labour				
25 REMOVE AND REFIX FRONT WINDSCREEN GLASS	60.00	1 LA	60.00	✓
26 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00	✓
27 REMOVE & REFIX FRT BUMPER ASSY,GRILLE,HEADLAMPS,SIDE MIRROR,FRT GARNISH,CUT,WELD & RENEW FRT PANEL,KNOCK & REPAIR FRT LH DOOR PILLAR,FRT CROSS MEMBER & REALIGN THE SAME INCLUDING REALIGN CABIN POSITION	900.00	1 LA	900.00	For
28 REMOVE & REFIX DASHBOARD,METER ASSY & CHECK WIRING	250.00	1 LA	250.00	✓
29 PUTTY & RESPRAY ON FRT BUMPER,PANEL,FRT LH DOOR REAR PILLAR,FRT BUMPER & FRT AFFECTED AREAS	800.00	1 LA	800.00	For
30 REMOVE & REFIX TAILGATE,SIDE GATE,CUT,WELD,KNOCK & REPAIR REAR TRUCK END PANEL & END CROSS MEMBER & REALIGN REAR TRUCK POSITION	900.00	1 LA	900.00	For
31 PUTTY & RESPRAY ON RH SIDE GATE,TAILGATE,REAR TRUCK FLOOR BOARD PANEL,END CROSS MEMBER	900.00	1 LA	900.00	For
32 RUSTPROOFING	30.00	1 LA	30.00	✓
				3,940.00

Total	S\$ 8,551.20
Add GST @ 7%	598.58
Total Amount payable	S\$ 9,149.78

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE