

INS. CASE OWNER:

Gerald.

CC /LPC1801

0867, U Ph 3⁵²

LKK:
IDAC

Supervisor:

marms

DOI:

ASSIGNMENT

4/6/08

Date / Time :

12/6/08

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. _____

SFS 6789 Y

Name of Insured

TEE DAY GUAT

Insured Tel No.

HP:

Excess Sec II :SS

D.O.A.:

Is driver the owner?

(YES / NO)

Nature of Accident :

If **NO**, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

OL GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%	Final ? Yes / No
100	Yes
90	Yes
80	Yes
70	Yes
60	Yes
50	Yes
40	Yes
30	Yes
20	Yes
10	Yes
0	Yes

FBI 679B



INRS
WSP:
Tel :
Liability
RMKS

Don Hock



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/Time	STAGE	DATE / PIC
6/8/18	Non-Reporting ltr (1st):	
6/8/18	Non-Reporting ltr (2nd):	
6/8/18	Non-Reporting ltr (Final):	
6/8/18	Notification ltr (if non-pickup):	
6/8/18	Call OI:	
6/8/18	After call ltr to OI:	
30/7/18	Documentation Check List:	Handler Typist
30/7/18	Notification ltr (if non-pickup)	☐
30/7/18	After call ltr to OI:	☐
30/7/18	Authorisation To Act:	☒
30/7/18	Release Voucher:	☒
30/7/18	Final Repair Bill:	☒
30/7/18	Car Rental Invoice:	☐
30/7/18	Towing Invoice:	☐
30/7/18	LTA / GIA :	☒
30/7/18	Medical Bill:	☐
30/7/18	PIR:	☐
30/7/18	Mandate/Reject Instruction:	☒
30/7/18	LOD:	☐
30/7/18	Payment Breakdown Form:	☐
30/7/18	Post-Repair Photos:	☐
30/7/18	Others:	☐

PRELIMINARY ADVICE	Date/Time:	Sent By:
FINALIZATION	Date/Time:	Confirm with:
Repair Cost:	\$S	(days) Reduction: %
FINAL SETTLEMENT	Date/Time:	Confirm with:
Final Liability:	%	(Agreed / Assessed) BOLA SN No. :
Repair Cost:	\$S	
Loss of Rental (LOR):	\$S	(days)
Loss of Use (LOU):	\$S	(S x 5 days)
Loss of Income (LOI):	\$S	(S x days)
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LO ☐		[Tick only one]
GIA/LTA Search	\$S	
Medical:	\$S	
Disbursement:	\$S	(e.g. Tow/ Independent)
Legal Cost	\$S	
Total:	\$S	Global Sum \$S:
FINAL PAYMENT	Date/Time:	Confirm with:
Payee 1:	\$S	Name 1:
Payee 2: (Strike if N.A.)	\$S	Name 2:
Payee 3: (Strike if N.A.)	\$S	Name 3:

REF: **IPC**

ASSIGNMENT

From:

Date:

14/06/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

FBH 679 B

at Workshop n/s

Bgm Hock Hin
No. 6 Defu Lane 4

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

6800

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

1 up**274710**

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

FBH 679 B

Yr Regn:

213

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Sym GTS 200

C.C.

172

Colour:

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

no key

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

RFGLM18WXS002058

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 110-80-13

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

mm

Rear

6

mm

R/Bal.

R/Bal.

L/Bal.

mm

L/Bal.

mm

D.O.A.

25/5/18

D.O.I.

14/6/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

frt o/s / 115 Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

not 6090**14/6/18 conf. and L/S & 4100 with Raymond****(Red #1898/324)**

Date/Time: File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) \$ + RS \$

) Photos

) Others

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Insp (\$

☐

: Weekend (\$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC4/LPC18010867/Upp3		
300 BEACH ROAD		Date : 14-06-2018		
#17-04/07 THE CONCOURSESINGAPORE 199555		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SFS 6789Y	Veh. Inspected	FBH 679B	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	14/06/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	25/05/2018	Inspection Date	14/06/2018	
Survey held at	BAN HOCK HIN CO.PTE LTD NO 6 DEFU LANE 4 SINGAPORE 539410			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/LPC18010867/Upb3

Date: 18.06.2018

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

FBH679B


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 14.06.2018 at the premises of M/s Ban Hock Hin Co. Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	5,500.00
Revised Estimate Amount	: S\$	3,947.00
"Check" Items Amount	: S\$	1,269.00
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Front O/S Portion & N/S Body



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5 days

Yours faithfully,

MARCUS CHUA
Licensed Appraiser



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K
MOTORCYCLE ACCESSORIES SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

NO. : 32690

Customer :

LONPAC INSURANCE BHD
100 BEACH ROAD
#19-00 SHAW TOWER
SINGAPORE 189702
MOTOR CLAIMS DEPT

DATE : 12/06/2018
CLAIM NO. : 11146
POLICY NO. : P20048236R00
FROM : RAYMOND

VEHICLE NO. : FBH0679B
MAKE/MODEL : SYM / GTS200

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	ALIGNMENT BODY P/N: 29561	REPLACE	1.00	\$375.00	375.00
2	BALANCER HANDLE P/N: 29008	REPLACE	2.00	\$40.00	80.00
3	BALL RACE SET P/N: 52798	REPLACE	1.00	\$55.00	55.00
4	BAR HANDLE P/N: 52791	REPLACE	1.00	\$136.00	136.00
5	BOX REAR (GIVI) E450N BLACK W/O STOP LIGHT P/N: 27220	REPLACE	1.00	\$217.00	217.00
6	COVER BACK P/N: 51896	REPLACE	1.00	\$24.00	24.00
7	COVER HANDLE P/N: 52787	REPLACE	1.00	\$24.00	24.00
8	COVER HANDLE LH P/N: 52823	REPLACE	1.00	\$21.00	21.00
9	COVER HANDLE RH P/N: 52802	REPLACE	1.00	\$21.00	21.00
10	COVER NECK WATER COOLANT P/N: 29012	REPLACE	1.00	\$62.00	62.00
11	COVER SIDE LH REAR	REPLACE	1.00	\$92.00	92.00
12	COVER SIDE LOWER RH (BLACK)	REPLACE	1.00	\$78.00	78.00
13	COWLING FRONT	REPLACE	1.00	\$214.00	214.00

1024



Quotation Nos. : 32690

S/N	Description	Action	Qty	Unit Price	Amount
14	EMBLEM (SYM LOGO) P/N: 52810	REPLACE	1.00	\$55.00	55.00
15	FLOOR PANEL P/N: 52821	REPLACE	1.00	\$160.00	160.00
16	FOOTBOARD UPPER P/N: 40150	REPLACE	1.00	\$156.00	156.00
17	HEADLAMP ASSY P/N: 29004	REPLACE	1.00	\$569.00	569.00
18	INNER BOX UP CASE	REPLACE	1.00	\$22.00	22.00
19	L PILLION STEP	REPLACE	1.00	\$49.00	49.00
20	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING PARTS QUOTED.	Supply/Install	1.00	\$784.00	784.00
21	LAMP SIGNAL FRONT RH P/N: 52793	REPLACE	1.00	\$262.00	262.00
22	MIRROR LH	REPLACE	1.00	\$178.00	178.00
23	MIRROR RH	REPLACE	1.00	\$178.00	178.00
24	MUDGUARD FRONT	REPLACE	1.00	\$118.00	118.00
25	PAD COVER	REPLACE	1.00	\$5.00	5.00
26	RIM SPORT FRONT ASSY P/N: 52806	REPLACE	1.00	\$555.00	555.00
27	S LOGO EMBLEM	REPLACE	1.00	\$9.00	9.00
28	SPOILER UNDER FRONT	REPLACE	1.00	\$115.00	115.00
29	STAY HEADLAMP P/N: 29010	REPLACE	1.00	\$185.00	185.00
30	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921	REPLACE	1.00	\$19.00	19.00
31	STRG. STEM COMP. P/N: 52797	REPLACE	1.00	\$252.00	252.00
32	SYM MARK (POLY) P/N: 50910	REPLACE	1.00	\$20.00	20.00
33	TRANSPORT CHARGES P/N: 07169		1.00	\$35.00	35.00
34	VALVE RIM P/N: 55062	REPLACE	1.00	\$10.00	10.00

2917-P
535-L



S/N	Description	Action	Qty	Unit Price	Amount
35	WINDSCREEN GARNISH	REPLACE	1.00	\$75.00	75.00
36	WINDSHIELD P/N: 28994	REPLACE	1.00	\$290.00	290.00

SUB TOTAL

\$5,500.00

GST @ 7 %

\$385.00

GRAND TOTAL

\$5,885.00

5998.00

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

365-P

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:





BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

LONPAC INSURANCE BHD
100 BEACH ROAD
#19-00 SHAW TOWER
SINGAPORE 189702

NO. : 33204

Supplementary 1 To QTN: 32690

DATE : 01/11/2018
CLAIM NO. : 11146
POLICY NO. : P20048236R00
FROM : RAYMOND

VEHICLE NO. : FBH0679B
MAKE/MODEL : SYM / GTS200

S/N	Description	Action	Qty	Unit Price	Amount
1	FORK FRONT ASSY LH P/N: 29035	Replace	1.00	\$232.00	232.00
2	SWITCH IGNITION (COMPLETE SET) P/N: 60335	Replace	1.00	\$266.00	266.00
SUB TOTAL					\$498.00
GST @ 7 %					\$34.86
GRAND TOTAL					\$532.86

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.



5998





BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 32690

- Rev. 1

LONPAC INSURANCE BHD
100 BEACH ROAD
#19-00 SHAW TOWER
SINGAPORE 189702

DATE : 12/06/2018
CLAIM NO. : 11146
POLICY NO. : P20048236R00

MOTOR CLAIMS DEPT

FROM : RAYMOND

VEHICLE NO. : FBH0679B
MAKE/MODEL : SYM / GTS200

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	ALIGNMENT BODY P/N: 29561	REPLACE	1.00	\$280.00	280.00
2	BALANCER HANDLE P/N: 29008	REPLACE	2.00	\$40.00 Disc %: 10.00	72.00
3	BALL RACE SET P/N: 52798	REPLACE	1.00	\$55.00 Disc %: 10.00	49.50
4	BAR HANDLE P/N: 52791	REPLACE	1.00	\$136.00 Disc %: 10.00	122.40
5	BOX REAR (GIVI) E450N BLACK W/O STOP LIGHT P/N: 27220	REPLACE	1.00	\$217.00 Disc %: 10.00	195.30
6	COVER BACK P/N: 51896	REPLACE	1.00	\$24.00 Disc %: 10.00	21.60
7	COVER HANDLE P/N: 52787	REPLACE	1.00	\$24.00 Disc %: 10.00	21.60
8	COVER HANDLE LH P/N: 52823	REPLACE	1.00	\$21.00 Disc %: 10.00	18.90
9	COVER HANDLE RH P/N: 52802	REPLACE	1.00	\$21.00 Disc %: 10.00	18.90
10	COVER NECK WATER COOLANT P/N: 29012	REPLACE	1.00	\$62.00 Disc %: 10.00	55.80
11	COVER SIDE LH REAR	REPLACE	1.00	\$92.00 Disc %: 10.00	82.80
12	COVER SIDE LOWER RH (BLACK)	REPLACE	1.00	\$78.00 Disc %: 10.00	70.20
13	COWLING FRONT	REPLACE	1.00	\$214.00 Disc %: 10.00	192.60
14	EMBLEM (SYM LOGO) P/N: 52810	REPLACE	1.00	\$55.00 Disc %: 10.00	49.50



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO.: 2002-1-0363
ISO 9001 : 2015

S/N	Description	Action	Qty	Unit Price	Amount
15	FLOOR PANEL P/N: 52821	REPLACE	1.00	\$160.00 Disc %: 10.00	144.00
16	FOOTBOARD UPPER P/N: 40150	REPLACE	1.00	\$156.00 Disc %: 10.00	140.40
17	HEADLAMP ASSY P/N: 29004	REPLACE	1.00	\$569.00 Disc %: 10.00	512.10
18	INNER BOX UP CASE	REPLACE	1.00	\$22.00 Disc %: 10.00	19.80
19	L PILLION STEP	REPLACE	1.00	\$49.00 Disc %: 10.00	44.10
20	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING PARTS QUOTED.	Supply/Install	1.00	\$500.00	500.00
21	LAMP SIGNAL FRONT RH P/N: 52793	REPLACE	1.00	\$262.00 Disc %: 10.00	235.80
22	MIRROR LH	REPLACE	1.00	\$178.00 Disc %: 10.00	160.20
23	MIRROR RH	REPLACE	1.00	\$178.00 Disc %: 10.00	160.20
24	MUDGUARD FRONT	REPLACE	1.00	\$118.00 Disc %: 10.00	106.20
25	PAD COVER	REPLACE	1.00	\$5.00 Disc %: 10.00	4.50
26	RIM SPORT FRONT ASSY P/N: 52806	REPLACE	1.00	\$555.00 Disc %: 10.00	499.50
27	S LOGO EMBLEM	REPLACE	1.00	\$9.00 Disc %: 10.00	8.10
28	SPOILER UNDER FRONT	REPLACE	1.00	\$115.00 Disc %: 10.00	103.50
29	STAY HEADLAMP P/N: 29010	REPLACE	1.00	\$185.00 Disc %: 10.00	166.50
30	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921	REPLACE	1.00	\$19.00 Disc %: 10.00	17.10
31	STRG. STEM COMP. P/N: 52797	REPLACE	1.00	\$252.00 Disc %: 10.00	226.80
32	SYM MARK (POLY) P/N: 50910	REPLACE	1.00	\$20.00 Disc %: 10.00	18.00
33	TRANSPORT CHARGES P/N: 07169		1.00	\$35.00	35.00
34	VALVE RIM P/N: 55062	REPLACE	1.00	\$10.00 Disc %: 10.00	9.00
35	WINDSCREEN GARNISH	REPLACE	1.00	\$75.00 Disc %: 10.00	67.50



<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
36	WINDSHIELD P/N: 28994	REPLACE	1.00	\$290.00 Disc %: 10.00	261.00
37	FORK FRONT ASSY LH P/N: 29035	Replace	1.00	\$232.00 Disc %: 10.00	208.80
38	SWITCH IGNITION (COMPLETE SET) P/N: 60335	Replace	1.00	\$266.00 Disc %: 10.00	239.40
SUB TOTAL					\$5,138.60
GST @ 7 %					\$359.70
GRAND TOTAL					\$5,498.30

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



RAYMOND

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.



Bike model
SYM GTS 200

Type
Any

Price From
Any

Price To
Any

Class
Any

MORE SEARCH OPTIONS ▼

Q SEARCH

VIEW ALL (/LISTING/USEDBIKES/LISTING/)

Q SEARCH ▼

SYM GTS 200 (/listing/usedbike/sym-sym-gts-200/8115/)



(/listing/usedbike/sym-sym-gts-200/8115/)

SGD **\$4000**

Reg : 03/10/2011

Type: Scooters

172cc

68100km

2011 SYM GTS200. COE till 2 Oct 2021 (renewable). Good condition bike. Well maintained. Great for daily commute. Cash deal only. Keen buyers, please contact 90922199 for more details or viewi...

Posted on : 11/06/2018

★ PAID AD

★ DEALER AD

■ COMPARE

DETAILS > (/LISTING/USEDBIKE/SYM-SYM-GTS-200/8115/)

SYM GTS 200 (/listing/usedbike/sym-sym-gts-200/6562/)



(/listing/usedbike/sym-sym-gts-200/6562/)

SGD\$7500

Reg : 29/04/2013

Type: Scooters

172cc

Visit us at Aljunied Motor Works. Well Maintained Condition. Seldom use, Trade In welcome / Loan available.

Showroom Condition

Posted on : 11/06/2018


★ PAID AD

★ DEALER AD

■ COMPARE

DETAILS > (/LISTING/USEDBIKE/SYM-SYM-GTS-200/6562/)

SYM GTS 200 (/listing/usedbike/sym-sym-gts-200/7443/)



(/listing/usedbike/sym-sym-gts-200/7443/)

SGD\$4700

Reg : 12/07/2012

Type: Scooters

172cc

68700km

SYM GTS 200 for Sale. Visit us at Ah Fook Motor. Well maintained condition. Trade in welcome / Loan available.

Posted on : 02/06/2018

★ PAID AD

★ DEALER AD

Nivitha (LKK Auto)

From: ERIC WOO JUN KIAT <ericwoo@lonpac.com>
Sent: Wednesday, 13 June 2018 3:40 PM
To: assignments@lkkauto.com
Cc: MT_Claim_SG
Subject: Our Ref: 18/18/18/VP05/020671 Accident involving SFS6789Y & FBH679B along Lornie Rd on 25/5/18 PRI
Attachments: 13062018153533.pdf

4pm @ 13/6/2018
person @ Raymond
vehicle in
damage on 14/6/18

Dear Catherine / Nivitha,

Kindly refer to our attachment.

Please proceed to conduct a survey of the vehicle FBH 679B on without Prejudice Basis.

We look forward to receiving your report soon.

Thank you.

Best Regards,
Eric Woo
Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6279 9253 | Fax: (65) 6296 3767



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 187000208K
MOTORCYCLE ACCESSORIES / SERVICE CENTRE
MODIFICATIONS / SPRAY PAINTING AND BODY WORK / METAL
WORKS / LEASING & RENTALS / FLEET SALES / INSURANCE SALES


FACIMILE TRANSMITTAL

Date : 12 JUN 2018

To : Lompac Insurance Bhd FAX : 6296 3767
Attn : Motor Claims Dept

Our Ref : TP/11146/FBH679B/SFS6789Y

RE : Accident Involving FBH679B & SFS6789Y on 25/05/2018



Dear Sir / Madam,

We attached the following documents for your perusal.

1. Log Card
2. Certificate of Insurance
3. NRIC & Driving Licence
4. GIA Report
5. GIA Insurance Search
6. Estimate

Appreciate for you to arrange for the survey at our workshop as soon as possible.

Shall you need further clarification, please feel free to contact the writer at 62816520 ext. 220.

Thank you.

For Ban Hock Hin Co., Pte Ltd

(Raymond Tan)

Tel : 62816520 ext. 220

Fax : 62963767

Email : raymond@bhh.com.sg



Shu Pei (LKKAUTO)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Thursday, 5 July 2018 12:05 PM
To: Shu Pei (LKKAUTO)
Cc: MT_Claim_SG; Hsiao Tong (LKKAUTO)
Subject: RE: Our Ref: 18/18/18/VP05/020671 Accident involving SFS6789Y & FBH679B along Lornie Rd on 25/5/18 PRI ***LKK REF:CC4/LPC18010867/Upb3
Attachments: 05072018115412.pdf

Dear Shu Pei,

We attached a copy of the police report lodged by insured driver.

He has not lodged the accident report and there were no photos taken as the vehicle was repaired after the accident.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]

Sent: Tuesday, 3 July, 2018 10:25 AM

To: GERALD POH WEE BIN; ONG LI LI; ERIC WOO JUN KIAT

Cc: MT_Claim_SG; Hsiao Tong (LKKAUTO)

Subject: RE: Our Ref: 18/18/18/VP05/020671 Accident involving SFS6789Y & FBH679B along Lornie Rd on 25/5/18 PRI ***LKK REF:CC4/LPC18010867/Upb3

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

Kindly advice whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: GERALD POH WEE BIN [<mailto:geraldpoh@lonpac.com>]
Sent: Monday, 18 June 2018 4:26 PM
To: Shu Pei (LKKAUTO) <shupeil@lkkauto.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>; Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>
Subject: RE: Our Ref: 18/18/18/VP05/020671 Accident involving SFS6789Y & FBH679B along Lornie Rd on 25/5/18 PRI
***LKK REF:CC4/LPC18010867/Upb3

Dear Shu Pei,

Our insured has not lodged a report and we are making enquiries.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Shu Pei (LKKAUTO) [<mailto:shupeil@lkkauto.com>]
Sent: Monday, 18 June, 2018 4:23 PM
To: ERIC WOO JUN KIAT; GERALD POH WEE BIN; ONG LI LI
Cc: MT_Claim_SG; Admin A; Hsiao Tong (LKKAUTO)
Subject: RE: Our Ref: 18/18/18/VP05/020671 Accident involving SFS6789Y & FBH679B along Lornie Rd on 25/5/18 PRI
***LKK REF:CC4/LPC18010867/Upb3

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle FBH 679B at M/s Ban Hock Hin Co. Pte Ltd.

Enclosed for your perusal is:

- Preliminary advice
- TP estimated cost of repair

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Hsiao Tong and she can be contacted at DID: 6742 3197.

Thank you.

Best Regards,
Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 13 June 2018 4:02 PM
To: 'ERIC WOO JUN KIAT' <ericwoo@lonpac.com>; assignments <assignments@lkkauto.com>

Cc: 'MT_Claim_SG' <mt_claim@lonpac.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: Our Ref: 18/18/18/VP05/020671 Accident involving SFS6789Y & FBH679B along Lornie Rd on 25/5/18 PRI

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ERIC WOO JUN KIAT [<mailto:ericwoo@lonpac.com>]

Sent: Wednesday, 13 June 2018 3:40 PM

To: assignments@lkkauto.com

Cc: MT_Claim_SG <mt_claim@lonpac.com>

Subject: Our Ref: 18/18/18/VP05/020671 Accident involving SFS6789Y & FBH679B along Lornie Rd on 25/5/18 PRI

Dear Catherine / Nivitha,

Kindly refer to our attachment.

Please proceed to conduct a survey of the vehicle FBH 679B on without Prejudice Basis.

We look forward to receiving your report soon.

Thank you.

Best Regards,

Eric Woo

Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6279 9253 | Fax: (65) 6296 3767

Hsiao Tong (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Monday, 30 July 2018 9:08 AM
To: 'Raymond'
Cc: 'MT_Claim_SG'; 'GERALD POH WEE BIN'; Admin A; Vivian Lau (LKKAUTO)
Subject: RE: Accident Involving FBH679B & SFS6789Y on 25/05/2018 *LKK REF: CC4/LPC18010867/Upb3

Without Prejudice

Hi Sirs,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Please note that all finalisation subject insurer's approval.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Raymond <raymond@bhh.com.sg>
Sent: Friday, 27 July 2018 4:50 PM
To: Vivian Lau (LKKAUTO) <vivianlau@lkkauto.com>; Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>; Shu Pei (LKKAUTO) <shupeil@lkkauto.com>
Cc: 'MT_Claim_SG' <mt_claim@lonpac.com>; 'GERALD POH WEE BIN' <geraldpoh@lonpac.com>
Subject: RE: Accident Involving FBH679B & SFS6789Y on 25/05/2018

Dear Vivian / Hsiao Tong / Shu Pei,

We attached the Traffic Police Investigation Result for your perusal.

Appreciate for you to revert with your insured liability for direct settlement as soon as possible.

Thanks

Best Regards,

Raymond

Ban Hock Hin Co., Pte Ltd

Tel: (65) 6281 6520 x 220 | Fax: (65) 6284 2969

Visit us at <http://www.bhh.com.sg>

Facebook: <http://www.facebook.com/bhhsg>



No. 6 Defu Lane 4, Singapore 539410

www.bhh.com.sg

MOTORCYCLE ACCESSORIES | SERVICE CENTRE | MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL WORKS | L



From: Raymond <raymond@bhh.com.sg>

Sent: Saturday, 21 July, 2018 2:35 PM

To: 'Vivian Lau (LKKAUTO)' <vivianlau@lkkauto.com>; 'Hsiao Tong (LKKAUTO)' <chewht@lkkauto.com>; 'Shu Pei (LKKAUTO)' <shupeil@lkkauto.com>

Cc: 'MT_Claim_SG' <mt_claim@lonpac.com>; 'GERALD POH WEE BIN' <geraldpoh@lonpac.com>

Subject: RE: Accident Involving FBH679B & SFS6789Y on 25/05/2018

Dear All,

It has been more than 8 weeks after the accident, anyone can advise your insured liability for direct settlement.

As requested by our client, please revert with your insured liability as soon as possible.

Thanks

Best Regards,

Raymond

Ban Hock Hin Co., Pte Ltd

Tel: (65) 6281 6520 x 220 | Fax: (65) 6284 2969

Visit us at <http://www.bhh.com.sg>

Facebook: <http://www.facebook.com/bhhsg>



BAN HOCK HIN
Co., Pte Ltd

No. 6 Defu Lane 4, Singapore 539410

www.bhh.com.sg

MOTORCYCLE ACCESSORIES | SERVICE CENTRE | MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL WORKS | L



From: Raymond <raymond@bhh.com.sg>

Sent: Monday, 16 July, 2018 4:31 PM

To: 'Vivian Lau (LKKAUTO)' <vivianlau@lkkauto.com>; 'Hsiao Tong (LKKAUTO)' <chewht@lkkauto.com>; 'Shu Pei (LKKAUTO)' <shupeil@lkkauto.com>

Cc: 'MT_Claim_SG' <mt_claim@lonpac.com>; 'GERALD POH WEE BIN' <geraldpoh@lonpac.com>

Subject: RE: Accident Involving FBH679B & SFS6789Y on 25/05/2018

Urgent!

Dear Hsiao Tong / Shu Pei,

As requested by our insured, please advise your insured liability as soon as possible.

Thanks

Best Regards,
Raymond

Ban Hock Hin Co., Pte Ltd

Tel: (65) 6281 6520 x 220 | Fax: (65) 6284 2969

Visit us at <http://www.bhh.com.sg>

Facebook: <http://www.facebook.com/bhhsg>



BAN HOCK HIN
Co., Pte Ltd

No. 6 Defu Lane 4, Singapore 539410

www.bhh.com.sg

MOTORCYCLE ACCESSORIES | SERVICE CENTRE | MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL WORKS | L



From: Raymond <raymond@bhh.com.sg>

Sent: Thursday, 5 July, 2018 3:06 PM

To: 'Vivian Lau (LKKAUTO)' <vivianlau@lkkauto.com>; 'Hsiao Tong (LKKAUTO)' <chewht@lkkauto.com>; 'Shu Pei (LKKAUTO)' <shupeil@lkkauto.com>

Cc: 'MT_Claim_SG' <mt_claim@lonpac.com>; 'GERALD POH WEE BIN' <geraldpoh@lonpac.com>

Subject: RE: Accident Involving FBH679B & SFS6789Y on 25/05/2018

Dear Hsiao Tong / Shu Pei,

Please advise your insured liability.

Thanks

Best Regards,

Raymond

Ban Hock Hin Co., Pte Ltd

Tel: (65) 6281 6520 x 220 | Fax: (65) 6284 2969

Visit us at <http://www.bhh.com.sg>



Facebook: <http://www.facebook.com/bhhsg>



No. 6 Defu Lane 4, Singapore 539410

www.bhh.com.sg

MOTORCYCLE ACCESSORIES | SERVICE CENTRE | MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL WORKS |



From: Raymond <raymond@bhh.com.sg>

Sent: Friday, 29 June, 2018 9:41 AM

To: 'Vivian Lau (LKKAUTO)' <vivianlau@lkkauto.com>; 'Hsiao Tong (LKKAUTO)' <chewht@lkkauto.com>; 'Shu Pei (LKKAUTO)' <shupeil@lkkauto.com>

Cc: 'MT_Claim_SG' <mt_claim@lonpac.com>; 'GERALD POH WEE BIN' <geraldpoh@lonpac.com>

Subject: RE: Accident Involving FBH679B & SFS6789Y on 25/05/2018

Dear Vivian,

We refer to your email dated 25/06/2018.

Please advise your insured liability for direct settlement.

Thanks

Best Regards,

Raymond

Ban Hock Hin Co., Pte Ltd

Tel: (65) 6281 6520 x 220 | Fax: (65) 6284 2969

Visit us at <http://www.bhh.com.sg>


Facebook: <http://www.facebook.com/bhhsg>



No. 6 Defu Lane 4, Singapore 539410

www.bhh.com.sg

MOTORCYCLE ACCESSORIES | SERVICE CENTRE | MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL WORKS |



From: Vivian Lau (LKKAUTO) <vivianlau@lkkauto.com>

Sent: Monday, 25 June, 2018 5:28 PM

To: Raymond <raymond@bhh.com.sg>; Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>; Shu Pei (LKKAUTO) <shupe@lkkauto.com>

Cc: 'MT_Claim_SG' <mt_claim@lonpac.com>; 'GERALD POH WEE BIN' <geraldpoh@lonpac.com>

Subject: RE: Accident Involving FBH679B & SFS6789Y on 25/05/2018

WITHOUT PREJUDICE

Dear Raymond,

Thank you for the email.

Please be informed that we are currently **pending for our insured's report.**

Dear Hsiao Tong / Shu Pei

Kindly assist CC4/LPC18010867/Upb3

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Raymond [<mailto:raymond@bhh.com.sg>]

Sent: Monday, 25 June, 2018 5:23 PM

To: Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>

Cc: 'MT_Claim_SG' <mt_claim@lonpac.com>; 'GERALD POH WEE BIN' <geraldpoh@lonpac.com>

Subject: RE: Accident Involving FBH679B & SFS6789Y on 25/05/2018

Dear Vivian,

We refer to Lonpac's email below.

Appreciate for you to advise your insured liability for direct settlement.

Thanks

Best Regards,

Raymond

Ban Hock Hin Co., Pte Ltd

Tel: (65) 6281 6520 x 220 | Fax: (65) 6284 2969

Visit us at <http://www.bhh.com.sg>

Facebook: <http://www.facebook.com/bhhsg>



No. 6 Defu Lane 4, Singapore 539410

www.bhh.com.sg

MOTORCYCLE ACCESSORIES | SERVICE CENTRE | MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL WORKS |



From: GERALD POH WEE BIN <geraldpoh@lonpac.com>

Sent: Monday, 18 June, 2018 5:13 PM

To: Raymond <raymond@bhh.com.sg>

Cc: MT_Claim_SG <mt_claim@lonpac.com>

Subject: FW: Accident Involving FBH679B & SFS6789Y on 25/05/2018

WITHOUT PREJUDICE

Our Ref : 18/18/18/VP05/020671

Dear Raymond,

We are unable to comment on liability as our insured has yet to lodge a report.

We have written to him to do so and upon of his report, we shall then revert on liability.

For your information, LKK Consultants Pte Ltd is handling the direct settlement cases on our behalf.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: LILY KOH

Sent: Monday, 18 June, 2018 4:49 PM

To: GERALD POH WEE BIN; ONG LI LI

Subject: FW: Accident Involving FBH679B & SFS6789Y on 25/05/2018

Dear All

Kindly attend to the claim, thanks

Lily

From: Raymond [<mailto:raymond@bhh.com.sg>]

Sent: Monday, 18 June, 2018 4:46 PM

To: LILY KOH

Subject: FW: Accident Involving FBH679B & SFS6789Y on 25/05/2018

Dear Lily,

Appreciate for you to advise your insured liability for direct settlement.

Thanks

Best Regards,

Raymond

Ban Hock Hin Co., Pte Ltd

Tel: (65) 6281 6520 x 220 | Fax: (65) 6284 2969

Visit us at <http://www.bhh.com.sg>

Facebook: <http://www.facebook.com/bhhsg>



BAN HOCK HIN
Co., Pte Ltd

No. 6 Defu Lane 4, Singapore 539410

www.bhh.com.sg

MOTORCYCLE ACCESSORIES | SERVICE CENTRE | MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL WORKS |



From: Raymond <raymond@bhh.com.sg>
Sent: Thursday, 14 June, 2018 2:38 PM
To: 'lilykoh@lonpac.com' <lilykoh@lonpac.com>
Subject: Accident Involving FBH679B & SFS6789Y on 25/05/2018

Dear Lily,

We attached the third party claim document for your perusal.

Your company appointed surveyor from LKK Auto Consultants Pte Ltd have conducted the pre-repair survey at our workshop this afternoon.

Appreciate for you to advise your insured liability for direct settlement.

If you are not the officer in charge for this case, kindly assist to forward this email to the officer in charge.

Thanks

Best Regards,
Raymond

Ban Hock Hin Co., Pte Ltd

Tel: (65) 6281 6520 x 220 | Fax: (65) 6284 2969

Visit us at <http://www.bhh.com.sg>

Facebook: <http://www.facebook.com/bhhsg>




BAN HOCK HIN
Co., Pte Ltd

No. 6 Defu Lane 4, Singapore 539410

www.bhh.com.sg

MOTORCYCLE ACCESSORIES | SERVICE CENTRE | MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL WORKS |





**SINGAPORE
POLICE FORCE**

Traffic Police
10 Ubi Avenue 3
Singapore 408865
Tel +65 6547 0000
Fax +65 6547 6259
www.police.gov.sg

Our Ref : TP/IP/31139/2018
Date : 9 July, 2018

GIAM MINGYAO KENNY
APT BLK 409A FERNVALE ROAD
#08-44
SINGAPORE 791409

Dear Sir/Madam

**ACCIDENT INVOLVING FBH679B AND SFS6789Y ON 25/05/2018 AT 1726 HRS, ALONG
YISHUN AVE 7 X YISHUN INDUSTRIAL PARK A**

I refer to the above accident.

2. Please be informed that we have completed our investigations which shows that the driver of SFS6789Y had committed an offence of Inconsiderate Driving under Section 65(b) of the Road Traffic Act Chapter 276. Action has been initiated against the said driver for the said offence.
3. If you have any queries, please contact the Investigation Officer, **Muhammad Azan** at telephone 65476256 or via email at Muhammad_Azan_AWANG@spf.gov.sg.

Yours faithfully

Juremah Ahmad SSI(2)
For Head, Traffic Investigation
Traffic Police
Singapore Police Force



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC4/LPC18010867/Upb3s2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 17-01-2019	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SFS 6789Y	Veh. Inspected	FBH 679B	
Policy No.		Coverage (\$)	0.00	
Claim No.	18/18/18/VP05/020671	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	13/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	SYM GTS200	c.c	172	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	RFGLM18WXDS002058	Colour	BLUE	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	110-90-13	MICHELIN	6 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	110-90-13	MICHELIN	6 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION AND N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/05/2018	Inspection Date	14/06/2018	
Survey held at	BAN HOCK HIN CO.PTE LTD NO 6 DEFU LANE 4 SINGAPORE 539410			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBH 679B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
2	BALANCER HANDLE @ \$40.00	SCRATCHED	80.00	80.00
1	SET BALL RACE	NECESSARY	55.00	55.00
1	BAR HANDLE	BENT	136.00	136.00
1	BOX REAR (GIVI) E450N BLACK W/O STOP LIGHT	CUT	217.00	217.00
1	COVER BACK	CUT	24.00	24.00
1	COVER HANDLE	CUT	24.00	24.00
1	COVER HANDLE LH	CRACKED	21.00	21.00
1	COVER HANDLE RH	CRACKED	21.00	21.00
1	COVER NECK WATER COOLANT	MISSING	62.00	62.00
1	COVER SIDE LH REAR	CUT	92.00	92.00
1	COVER SIDE LOWER RH (BLACK)	CUT	78.00	78.00
1	COWLING FRONT	CRACKED	214.00	214.00
1	EMBLEM (SYM LOGO)	NECESSARY	55.00	55.00
1	FLOOR PANEL	BROKEN	160.00	160.00
1	FOOTBOARD UPPER	CRACKED	156.00	156.00
1	HEADLAMP ASSY	CRACKED	569.00	569.00
1	INNER BOX UP CASE	CRACKED	22.00	22.00
1	L PILLION STEP	BENT	49.00	49.00
1	LAMP SIGNAL FRONT RH	BROKEN	262.00	262.00
1	MIRROR LH	CUT	178.00	178.00
1	MIRROR RH	BROKEN	178.00	178.00
1	MUDGUARD FRONT	BROKEN	118.00	118.00
1	PAD COVER	BROKEN	5.00	5.00
1	RIM SPORT FRONT ASSY	BENT	555.00	555.00
1	S LOGO EMBLEM	NECESSARY	9.00	9.00
1	SPOILER UNDER FRONT	BROKEN	115.00	115.00
1	STAY HEADLAMP	BENT	185.00	185.00
1	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT	NECESSARY	19.00	19.00
1	STRG. STEM COMP.	BENT	252.00	252.00
1	SYM MARK (POLY)	NECESSARY	20.00	20.00
1	VALVE RIM	NECESSARY	10.00	10.00

Report Ref No. CC4/LPC18010867/Upb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	WINDSCREEN GARNISH	CRACKED	75.00	75.00
1	WINDSHIELD	CRACKED	290.00	290.00
1	FORK FRONT ASSY LH (ADDITIONAL)	BENT	232.00	232.00
1	SWITCH IGNITION (COMPLETE SET) (ADDITIONAL)	CRACKED	266.00	266.00
	LESS 10% DISCOUNT		-	-480.40
			4,804.00	4,323.60
	LABOUR			
	ALIGNMENT BODY.		375.00	280.00
	LABOUR - TO DISMANTLE AND ASSEMBLING PARTS QUOTED.		784.00	500.00
	TRANSPORT CHARGES.		35.00	35.00
			1,194.00	815.00
GRAND TOTAL			5,998.00	5,138.60
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,100.00

Report Ref No. CC4/LPC18010867/Upb3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.