



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

NO. : 32690

Customer :

LONPAC INSURANCE BHD
100 BEACH ROAD
#19-00 SHAW TOWER
SINGAPORE 189702

MOTOR CLAIMS DEPT

DATE : 12/06/2018
CLAIM NO. : 11146
POLICY NO. : P20048236R00

FROM : RAYMOND

VEHICLE NO. : FBH0679B
MAKE/MODEL : SYM / GTS200

*not before
date
14/6/18
2/5/18
Sdy.
Chap. Officer*

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	ALIGNMENT BODY P/N: 29561	REPLACE	1.00	\$375.00	375.00 ?
2	BALANCER HANDLE P/N: 29008	REPLACE	2.00	\$40.00	80.00 <i>scr</i>
3	BALL RACE SET P/N: 52798	REPLACE	1.00	\$55.00	55.00 ?
4	BAR HANDLE P/N: 52791	REPLACE	1.00	\$136.00	136.00 <i>cu</i>
5	BOX REAR (GIVI) E450N BLACK W/O STOP LIGHT P/N: 27220	REPLACE	1.00	\$217.00	217.00 <i>cu</i>
6	COVER BACK P/N: 51896	REPLACE	1.00	\$24.00	24.00 <i>cu</i>
7	COVER HANDLE P/N: 52787	REPLACE	1.00	\$24.00	24.00 <i>cu</i>
8	COVER HANDLE LH P/N: 52823	REPLACE	1.00	\$21.00	21.00 <i>cu</i>
9	COVER HANDLE RH P/N: 52802	REPLACE	1.00	\$21.00	21.00 <i>cu</i>
10	COVER NECK WATER COOLANT P/N: 29012	REPLACE	1.00	\$62.00	62.00 <i>ms</i>
11	COVER SIDE LH REAR	REPLACE	1.00	\$92.00	92.00 <i>cu</i>
12	COVER SIDE LOWER RH (BLACK)	REPLACE	1.00	\$78.00	78.00 <i>cu</i>
13	COWLING FRONT	REPLACE	1.00	\$214.00	214.00 <i>cu</i>



S/N	Description	Action	Qty	Unit Price	Amount
14	EMBLEM (SYM LOGO) P/N: 52810	REPLACE	1.00	\$55.00	55.00
15	FLOOR PANEL P/N: 52821	REPLACE	1.00	\$160.00	160.00
16	FOOTBOARD UPPER P/N: 40150	REPLACE	1.00	\$156.00	156.00
17	HEADLAMP ASSY P/N: 29004	REPLACE	1.00	\$569.00	569.00
18	INNER BOX UP CASE	REPLACE	1.00	\$22.00	22.00 ?
19	L PILLION STEP	REPLACE	1.00	\$49.00	49.00
20	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING PARTS QUOTED.	Supply/Install	1.00	\$784.00	784.00
21	LAMP SIGNAL FRONT RH P/N: 52793	REPLACE	1.00	\$262.00	262.00
22	MIRROR LH	REPLACE	1.00	\$178.00	178.00
23	MIRROR RH	REPLACE	1.00	\$178.00	178.00
24	MUDGUARD FRONT	REPLACE	1.00	\$118.00	118.00
25	PAD COVER	REPLACE	1.00	\$5.00	5.00
26	RIM SPORT FRONT ASSY P/N: 52806	REPLACE	1.00	\$555.00	555.00 ?
27	S LOGO EMBLEM	REPLACE	1.00	\$9.00	9.00
28	SPOILER UNDER FRONT	REPLACE	1.00	\$115.00	115.00
29	STAY HEADLAMP P/N: 29010	REPLACE	1.00	\$185.00	185.00
30	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921	REPLACE	1.00	\$19.00	19.00
31	STRG. STEM COMP. P/N: 52797	REPLACE	1.00	\$252.00	252.00 ?
32	SYM MARK (POLY) P/N: 50910	REPLACE	1.00	\$20.00	20.00
33	TRANSPORT CHARGES P/N: 07169		1.00	\$35.00	35.00
34	VALVE RIM P/N: 55062	REPLACE	1.00	\$10.00	10.00 ?



S/N	Description	Action	Qty	Unit Price	Amount
35	WINDSCREEN GARNISH	REPLACE	1.00	\$75.00	75.00
36	WINDSHIELD P/N: 28994	REPLACE	1.00	\$290.00	290.00
SUB TOTAL					\$5,500.00
GST @ 7 %					\$385.00
GRAND TOTAL					\$5,885.00

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

