

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Kindly Help to arrange
Surveyor to Survey this
Vehicle thanks

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SLU2757J
Chassis No : MRHFC5650HT000632
Model : CIVIC 1.6 VTI YM2017
Owner's Name : SITI
Ins Policy No :
Date of Accident : 10/6/2018

Document No. : SQT18002419
Date : 11. Jun 2018
Customer No. : WZA006
Svc Advisor : LIM CHOU SIONG
Engine No : R16B22001064
Date | Time : 11. Jun 2018 8:02:20 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: SITI						
	OWNER INSURER: TOKIO MARINE INSURANCE SINGAPORE L						
	ACC DATE: 10/6/2018						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: AXA INSURANCE S'PORE PTE LTD						
	TP VEH: SHC5094K						
67010-TEA-T00ZZ	PANEL COMPR.FR.DOOR <i>DO/Bar</i>	1	761.40	✓ 25	571.05	39.97	611.02
72425-TBA-A01	MOLDING ASSYR.FR.DOOR SASH <i>nu</i>	1	25.80	✓ 25	19.35	1.35	20.70
67510-TEA-T00ZZ	PANELR.RR.DOOR <i>2.6500</i>	1	696.60	✓ 25	522.45	36.57	559.02
72925-TEA-T01	MOLDING ASSY,R.RR.DRINNER <i>nu</i>	1	28.30	✓ 25	21.22	1.49	22.71
72810-TEA-T01	WEATHERSTRIP,R.RR.DOOR <i>nu</i>	1	96.40	✓ 25	72.30	5.06	77.36
72828-TEA-T01	SEALRR.DOOR LOWER <i>nu</i>	1	6.10	✓ 25	4.57	0.32	4.89
72135-SDA-A01	STRIKER ASSYDOOR LOCK <i>11</i>	1	15.10	X 25	11.32	0.79	12.11
72610-TEX-Y01	LATCH ASSYR.RR.DOOR POWER <i>?</i>	1	69.90	25	52.42	3.67	56.09
71800-TEA-T01ZB	GARNISH ASSYR.SIDE SILL <i>Deep cut/To. 1</i>	1	114.40	✓ 25	85.80	6.01	91.81
73500-TEA-T01	GLASS ASSYR.QUARTER WINDSHIEL <i>nu</i>	1	132.60	✓ 25	99.45	6.96	106.41
04636-TEA-T00ZZ	PANEL SETR.RR.OUTSIDE <i>3.6500</i>	1	691.00	✓ 25	518.25	36.28	554.53
73227-TEA-003	RUBBER CWINDSHIELD DAM <i>nu</i>	1	16.70	✓ 25	12.52	0.88	13.40
73525-SYY-000	RUBBERRR QTR W/SHIELD <i>nu</i>	3	9.50	✓ 25	21.37	1.50	22.87
91501-S70-003	FASTENER BW/SHIELD <i>nu</i>	2	3.20	✓ 25	4.80	0.34	5.14
91536-SS0-J01	FASTENER AW/SHIELD <i>nu</i>	2	3.50	✓ 25	5.25	0.37	5.62
91568-TF0-003	CLIPFR.WINDSHIELD.UPPER. <i>nu</i>	2	2.80	✓ 25	4.20	0.29	4.49
73125-SR3-000	RUBBER, W/SHIELD <i>nu</i>	1	12.40	✓ 25	9.30	0.65	9.95
73126-SR3-000	RUBBER, W/SHIELD <i>nu</i>	1	14.10	✓ 25	10.57	0.74	11.31
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>nu</i>	3	60.00	✓	180.00	12.60	192.60
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER <i>R</i>	1	617.20	X 25	462.90	32.40	495.30



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
 8 SHENTON WAY
 #27-01 AXA TOWER
 SINGAPORE 068811

Registration No : SLU2757J

Chassis No : MRHFC5650HT000632

Model : CIVIC 1.6 VTI YM2017

Owner's Name : SITI

Ins Policy No. :

Date of Accident : 10/6/2018

Document No. : SQT18002419

Date : 11. Jun 2018

Customer No. : WZA006

Svc Advisor : LIM CHOU SIONG

Engine No : R16B22001064

Date | Time : 11. Jun 2018 8:02:20 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
71593-TEA-T01	SPACERR.RR.BUMPER SIDE <i>11</i>	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIPBUMPER <i>nei</i>	7	2.00	25	10.50	0.74	11.24
42700-TEA-T61	DISKALUMINIUM WHEEL <i>cur/00</i>	3	289.10	25	650.47	45.53	696.00
HK-215/55R16H452	HANKOOK TYRE <i>2/5 cur 2 pcs o/s?</i>	3	148.00	25	444.00	31.08	475.08
<i>Sum Item</i>					3802.68	266.19	4,068.87
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00		180.00	12.60	192.60
BO-R-COOL-RRQ	SUPPLY & INSTALL SOLAR FILM ON REAR R QTR GLASS.	1	250.00		250.00	17.50	267.50
<i>Sum Ext. Service</i>					430.00	30.10	460.10
BOSUN	SUNDRIES <i>nei</i>	1	30.00		30.00	2.10	32.10
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	80.00		80.00	5.60	85.60
BOBC	BODY UNDERSIDE COATING (N)	1	100.00		100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	130.00		130.00	9.10	139.10
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00		250.00	17.50	267.50
BG52R	REPLACE RR. R QTR GLASS.(N)	1	280.00		280.00	19.60	299.60
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	300.00		300.00	21.00	321.00
BOMISC1	RESET SMART ENTRY SYSTEM & REMOVE NECESSARY	1	320.00		320.00	22.40	342.40
BMI02D	REMOVE & INSTALL REAR COMPARTMENT LININGS, RR1	1	350.00		350.00	24.50	374.50
BKDR12R	REMOVE & TRANSFER ITEMS TO NEW FR R DR. ADJUST	1	380.00		380.00	26.60	406.60
BKDR22R	REMOVE & TRANSFER ITEMS TO NEW RR R DR. ADJUST	1	380.00		380.00	26.60	406.60
BKFE22R	CUT OFF & RENEW RR R FENDER, REPLACE R SIDE STILL <i>160</i>	1	2600.00		2600.00	182.00	2782.00
BP06R	SPRAY PAINTING ON FR BUMPER, RR BUMPER, FR R DOOR, <i>450</i>	1	3300.00		3300.00	231.00	3531.00
BOJSE	BODY JOINT SEALANT. <i>nei</i>	1	80.00		80.00	5.60	85.60
<i>Sum Labor</i>					8580.00	600.60	9,180.60

Survey By

Printed on 12/6/2018 6:26:31 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SLU2757J
Chassis No : MRHFC5650HT000632
Model : CIVIC 1.6 VTI YM2017
Owner's Name : SITI
Ins Policy No. :
Date of Accident : 10/6/2018

Document No. : SQT18002419 **Page** 3
Date : 11. Jun 2018
Customer No. : WZA006
Svc Advisor : LIM CHOU SIONG
Engine No : R16B22001064
Date | Time : 11. Jun 2018 8:02:20 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Date & Time	14/6/18 @ 12pm. C Slim				Total Amount	12,812.68	13,709.57
Excess					Total (Inclusive of GST)		13,709.57
Status	Not followed						
Signature	Take photo before repair.						

mercus lkh
8-9 day.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 12/6/2018 6:26:31 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)