

ASS. REC. BY:

REF: es/MSG18010876/Avd3

Special Instruction:

Surveyor:  
Merimen

Adrian

ASSIGNMENT (Office)

From (Person):

Ng Chen Chow

of

MSG

Date/Time:

14/6/18 @ 11:44am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGT 6228H

Insured:

WC 4888R

at Workshop m/s

SM - Automotive

Tel:

6747 9241

of

BK C-1 kaki Bukit Ave G # 01-43

Policy No:

B28985078MCF

Claim No:

561097

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

12/06/2018

CA / REV / REP. / REV 24 HRS 'up'

H.O.D. Endorsement:

Date/Time:

12:49pm @ 14/6/18

Person Contacted:

sukyi

Vehicle IN/OUT

(OUT)

Date/Time

Action/Instruction (✓) Estimate

SGT 6228H - NA / FWD 18010761 / r3

DOA: 12/06/18

WC 4888R - NA / FWD 18010761 / r3

DOA: 12/06/18

18/6/18

Informed Chen How pending workshop est by merimen

5/7/18

Rece email from sukyl owner withdraw claim

15/8/18

Submit preli report

ASS. REC. BY: Adrian King

REF:

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SGT6228H Yr Regn: 2007, April  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Honda Airwave c.c. 1496  
 Colour: Blue A/C: Insured / Std / NI / NA  
 Sp. Reading: 285982 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: GJ1118677  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 205/45R17  
 R: 205/45R17

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Continental

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lump Sum: \_\_\_\_\_ % 3 Val.: Yes or No

Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. 06 mm R/Bal. 06 mm  
 L/Bal. 06 mm L/Bal. 06 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 13/06/18  
 Survey held at SM

CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

Des. of Damages: Frt / Rear O/S / N/S / U/C / Rooftop or \_\_\_\_\_  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time \_\_\_\_\_ Action / Instruction  
TP MSLG.

RECEIVED 15 AUG 2018

Date/Time, File Pass to?  : Preli. Report  
 : Final Report  
 Date/Time, File Return to? \_\_\_\_\_

Days Of Repair: 7  
 Resurvey No. of Trip: -

1) 15/8 - typst  
 Report Format: maximen  
 Lump Sum / L.B.I: (\$) LS \$5800

Add Fee:  Site Insp (\$)  Interview (\$)  Tech. Invs (\$)  Weekend (\$)

Survey Fee:	
Transportation:	
3 + RS. 50	250
Photos	10
Others	
TOTAL	260



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18010876/Avd3

16 RAFFLES QUAY  
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 14-06-2018



Code : MSG

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	WC 4888R	Veh. Inspected	SGT 6228H
Policy No.	B28985078MKF	Coverage (\$)	0.00
Claim No.	561097	Excess (\$)	0.00
Assign From	MERIMEN (NG CHEN CHOW)	Assign Date	14/06/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	12/06/2018	Inspection Date	14/06/2018
Survey held at	SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Jun 2018		14 Jun 2018 11:44 <input type="button" value="Assign"/>				<b>New Assignment</b> <input type="button" value="Cancel Case"/>

Main

Reference

Claim Details

Documents

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	Alliance Concrete Singapore Pte. Ltd., Co. Reg. No.: 200516266D		
Main Claimant:	LIM YUEN LI, ID: S8015909I		
Vehicle Reg. No.:	SGT6228H	Date of Loss:	12/06/2018 17:00 - :59 [133 Months and 25 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 561097	Policy/Cover Note No.:	B28985078MKF (Comprehensive) Coverage: 01/07/2017 - 30/06/2018
Vehicle Reg. No. (Insured):	WC4888R	Policy No. (Claimant):	
		Excess:	
Repairer:	Sm Automotive - Kaki Bukit (HQ) BLOCK C - 1, KAKI BUKIT AVE 6, #01-43, 417883 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by NG CHEN HOW - 6643 1391]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 15/06/2018]		
Driver/Custodian (Insured):	SATHAIAH KARUPPIAH (49 / Male), NRIC: G7309227U		
Adj Asg. Remarks:	on WP. SJE Agree Please appoint Adrain Ling from LKK and contact Sukyi @ 6747 9241 Liability (Dispute Case)		

### ASSOCIATED MAIL RECEIVED

 

There are no mail for this case.

### ALL ASSOCIATED TASKS

   

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## View Received Message

This mail is associated with :

**\*SGT6228H (561097)**  
**[WC4888R]**

TP

LIM YUEN LI

Jun 12 2018 5:00PM

[Alliance Concrete Singapore Pte. Ltd.]  
Sm Automotive - Kaki Bukit

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** MSIG Insurance (Singapore) Pte. Ltd. (MSIG\_SG), sent on 05/07/2018 13:07 PM.

**To** LKK\_HQ

**Subject** 3rd Party withdrew claim from SM Automotive

Dear Madam,

As titled.

Chen How

### DOCUMENTS SUMMARY

There are no documents.

## Veron Chen (LKKAuto)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Thursday, 5 July 2018 12:44 PM  
**To:** 'sm automotive'; SUR  
**Cc:** assignments; Adrian Ling (LKKAuto)  
**Subject:** RE: SGT6228H CLAIMING AGAINST WC4888R DOA:12.06.18

BEST REGARDS,

G.Nivitha | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Nivitha (LKK Auto) [<mailto:admin-d@lkkauto.com>]  
**Sent:** Thursday, 5 July 2018 12:38 PM  
**To:** 'sm automotive' <[sm\\_automotive@hotmail.com](mailto:sm_automotive@hotmail.com)>; 'Admin A' <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>  
**Cc:** [assignments@lkkauto.com](mailto:assignments@lkkauto.com); 'Adrian Ling (LKKAuto)' <[adrianling@lkkauto.com](mailto:adrianling@lkkauto.com)>  
**Subject:** RE: SGT6228H CLAIMING AGAINST WC4888R DOA:12.06.18

Dear Sukyi,

Noted, with thanks.

BEST REGARDS,

G.Nivitha | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** sm automotive [[mailto:sm\\_automotive@hotmail.com](mailto:sm_automotive@hotmail.com)]  
**Sent:** Thursday, 5 July 2018 12:31 PM  
**To:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>  
**Cc:** [assignments@lkkauto.com](mailto:assignments@lkkauto.com); Adrian Ling (LKKAuto) <[adrianling@lkkauto.com](mailto:adrianling@lkkauto.com)>  
**Subject:** SGT6228H CLAIMING AGAINST WC4888R DOA:12.06.18

Without Prejudice

Hi Admin

We would like to inform you that owner of SGT6228H withdraw the claim from our workshop,thanks.

Regards,

**Sukyi Chong**  
**SM AUTOMOTIVE**

1 Kaki Bukit Ave 6  
Blk C #01-43

Singapore 417883  
Tel: 6747 9241 Fax: 6741 7276



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

## View Sent Message

This mail is associated with :

**\*SGT6228H (561097)**  
**[WC4888R]**

TP

LIM YUEN LI

Jun 12 2018 5:00PM

[Alliance Concrete Singapore Pte. Ltd.]

Sm Automotive - Kaki Bukit

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on **18/06/2018 08:15 AM**.  
**To** MSIG\_NCH1  
**Subject** TP SURVEY SGT 6228H

Dear Chen How,

Please be informed that we have inspected the vehicle SGT 6228H on 13/6/2018 .

We are pending estimate from repairer.

Best Regards,  
Veron Chen

### DOCUMENTS SUMMARY

There are no documents.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC  
Owner ID: S909I

**Vehicle Details**

Vehicle No.: SGT6228H  
Vehicle to be Exported: No  
Intended De-registration Date: 13 Jun 2018  
Vehicle Make: HONDA  
Vehicle Model: AIRWAVE 1.5 A  
Primary Colour: Silver  
Manufacturing Year: 2007  
Engine No.: L15A5122625  
Chassis No.: GJ11118677  
Maximum Power Output: 81.0 kW (108 bhp)  
Open Market Value: \$16,932.00  
Original Registration Date: 18 Apr 2007  
First Registration Date: 18 Apr 2007  
Transfer Count: 0  
Actual ARF Paid: \$0.00

**Intended PARF Rebate Details**

PARF Eligibility: Forfeited  
PARF Eligibility Expiry Date: -  
PARF Rebate Amount: \$0.00

**Intended COE Rebate Details**

COE Rebate Amount: \$0.00  
**Total Rebate Amount: \$0.00**

**Message**

Transfer of ownership or de-registration is not allowed for this vehicle.

The information contained herein is correct as at 13 Jun 2018

OK

> Back to OneMotoring

## Enquire Transfer Fee

Vehicle Details	
Vehicle No.:	SGT6228H
Vehicle Type:	P11 - Passenger Station Wagon/Jeep/Land Rover
Vehicle Attachment 1:	Disabled
Vehicle Scheme:	Disabled Person
Vehicle Make:	HONDA
Vehicle Model:	AIRWAVE 1.5 A
Chassis No.:	GJ11118677
Propellant:	Petrol
Engine No.:	L15A5122625
Engine Capacity:	1496 cc
Maximum Power Output:	81.0 kW ( 108 bhp)
Maximum Laden Weight:	1455 kg
Unladen Weight:	1180 kg
Year Of Manufacture:	2007
Original Registration Date:	18 Apr 2007
Lifespan Expiry Date:	-
Road Tax Expiry Date:	17 Oct 2018
Inspection Due Date:	17 Apr 2019
Intended Transfer Date:	14 Jun 2018
CO2 Emission:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
<b>Total Amount Payable:</b>			<b>25.00</b>

Message  
Transfer of ownership is not allowed for this vehicle.

You may print this page for reference.

OK

Print

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	13/06/2018 11:00
Date Of Accident	12/06/2018 18:20
Exact Location Of Accident	LOYANG AVE TWDS (TPE PIE/ECP)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGT6228H
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LIM YUEN LI
NRIC No	S8015909I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91916920
Alternative Phone No	OTHERS-91916920

### Vehicle Particulars

Manufacturer	HONDA
Model	AIRWAVE
Exact Purpose for which vehicle was being used at time of accident	OTW HOME
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	PNPV2018-00004835
Cover Note Number	

### Driver

Name of Driver	LIM YUEN LI
NRIC No	S8015909I
Date Of Birth	05/06/1980
Occupation	INDOOR
Date Of Driving Pass	08/12/2006
Driving Experience	11 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91916920
Fax Number	
Contact Number	OTHERS-91916920
EMail Address	NOEMAIL

Address	23 ANG MO KIO AVE 9 #02-09
Postcode	569787
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

### General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

### Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	WC4888R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

### DETAILS OF INJURED PERSON 1

Name	LIM YUEN LI
------	-------------

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

NECK & BACK

SGT6228H

YES

NO

# Accident Sketch Plan

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to re-evaluate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of the report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information"); and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident [all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"], the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
\_\_\_\_\_  
Policyholder's Signature  
Date & Time

  
\_\_\_\_\_  
Driver's Signature  
(if driver is not the policyholder)  
Date & Time

 13/06/18  
\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## Individual Statement

SKETCH PLAN



A: 447 6228H  
B: WC 4888R

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS TRAVELLING ALONG JOYANG AVE ON THE LEFT MOST LANE OF 3 LANES. AS I WAS TRAVELLING STRAIGHT TOWARDS THE (P10), ONE (CEMENT) MIXER WC 4888R SUDDENLY FROM THE OPPOSITE LANE, ENCRONCHED INTO MY PATH AND COLLIDED ONTO THE RIGHT SIDE OF MY VEHICLE. AS THE RESULT OF THE ACCIDENT, I SUSTAINED PAIN ON MY NECK, BACK.

**DECLARATION**

(We declare the foregoing particulars are true in every respect)

  
Police Officer's Signature  
Date & Time:

  
Driver's Signature  
(if driver is not the police officer)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/IN No.:

# SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM\_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

13/06/2018

Blk 1 Kaki Bukit Ave 6

# 01-43

Singapore 417883

TPMS16

Vover

Accident date: 12/06/2018

Estimated repair cost for vehicle no: SGT6228H HONDA AIRWAVE 1.5 A '07

CHASSIS: GJ11118677

S/N	QTY	Items	U/PRICE	AMOUNT
1	1	Front Bumper <i>detd</i>		\$1,050.90 ✓
2	10	Front Bumper Clip <i>n</i>	\$6.50	\$65.00 30
3	2	Front Bumper Side Retainer <i>RT Dmgd</i>	\$33.70	\$67.40 33.70
4	1	Front Bumper Centre Garnish Cover <i>Free</i>		\$144.50 ✗
5	1	Front R/H Bumper Fog Lamp Cover <i>n</i>		\$60.70 ✗
6	8	Front Grille Clip <i>nter</i>	\$6.50	\$52.00 ✗
7	1	Front R/H Head Lamp <i>2 not</i>		\$625.80 ✗
8	1	Front R/H Head Lamp Lower Bracket <i>new</i>		\$48.30 ✗
9	1	Front R/H Fender <i>Dented</i>		\$565.00 ✓
10	1	Front R/H Fender Cowling <i>tom</i>		\$105.00 ✓
11	10	Front R/H Fender Cowling Clip <i>new</i>	\$6.50	\$65.00 30
12	1	Front R/H Fender Signal Lamp <i>nter</i>		\$58.50 ✗
13	1	Front R/H Fender Quarter Glass <i>Shattered</i>		\$281.90 ✓
14	1	Front R/H Door <i>Dented</i>		\$1,045.00 ✓
15	1	Front R/H Door Side Mirror Assy <i>Distorted</i>		\$681.90 ✓
16	2	Front R/H Door Hinge <i>Bent</i>	\$39.10	\$78.20 ✓
17	1	Front R/H Door Glass <i>nter</i>		\$480.00 ✗
18	1	Front R/H Door Glass Outer Moulding <i>detd</i>		\$110.30 ✓
19	2	Front R/H Door Frame Sticker <i>n</i>	\$48.80	\$97.60 ✓
20	1	Front R/H Door Outer Handle <i>nter</i>		\$90.50 ✗
21	1	Front R/H Door Inner Lock <i>nter</i>		\$350.60 ✗
22	1	Front R/H Door Inner Rubber <i>2 new</i>		\$170.90 ✗
23	1	Front R/H Door Inner Trim Board <i>Free</i>		\$610.20 ✗
24	1	Front R/H Door Gear Motor Assy		\$480.70 ✗
25	1	Front R/H Lower Arm <i>2</i>		\$385.70 ✗
26	1	Front R/H Knuckle Arm <i>nter</i>		\$351.50 ✗
27	1	Front R/H Knuckle Arm Bearing <i>nter</i>		\$115.80 ✗
28	1	Front R/H Shock Absorber		\$334.40 ✗

29	1	Front R/H Drive Shaft		\$1,100.60	x	
30	1	Front Stabilizer Bar		\$185.00	x	
31	1	Front Steering Rack	not me	\$2,127.80	x	
32	1	Front Crossmember		\$1,145.00	x	
33	1	R/H Rocker Panel Skirt		\$280.30	x	
34	1	Rear R/H Door	Dented	\$982.30	✓	
35	2	Rear R/H Door Hinges	Bent	\$39.60	\$79.20	✓
36	1	Rear R/H Door Outer Handle	new	\$90.50	x	
37	2	Rear R/H Door Frame Sticker	me	\$48.80	\$97.60	✓
38	1	Rear R/H Door Inner Lock		\$350.60	+	
39	1	Rear R/H Door Inner Rubber	new	\$170.90	+	
40	1	Rear R/H Door Inner Trim Board		\$610.20	x	
41	1	Rear R/H Door Gear Motor Assy		\$480.70	x	
42	1	Rear R/H Fender	Repair	\$1,005.00	x	
43	1	Rear R/H Fender Glass Assy	new	\$550.10	+	
44	1	Rear R/H Tail Lamp	new	\$258.30	+	
45	1	Rear Bumper	Repair	\$1,078.50	+	
46	10	Rear Bumper Clip		\$6.50	\$65.00	+
47	2	Rear Bumper Side Retainer	not me	\$35.00	\$70.00	+
48	1	Rear R/H Shock Absorber		\$290.90	+	
49	1	Rear Axle		\$1,300.00	+	
50	2	Rear Axle Bearing		\$288.50	\$577.00	+

5268.6  
4214.88

Subtotal:- \$21,468.80

S/N	QTY	Items / Special Nett	U/PRICE	AMOUNT	
51	1	Front R/H Bumper Fog Lamp	new	\$380.00	+
52	1	Front Grille	new	\$480.00	+
53	1	Front R/H Rim	lit	\$680.00	4.00
54	1	Front R/H Tyre		\$350.00	+
55	1	Rear R/H Rim		\$680.00	+
56	1	Rear R/H Tyre		\$350.00	+

4.00

Subtotal:- \$2,920.00

**Labour charges**

To remove & refit cushion		<del>\$380.00</del> 60
To remove & refit R/H fender glass		<del>\$120.00</del> 60
Gum		<del>\$50.00</del> 30 nec
To remove & refit front & rear door, glass, trim board, lock, gear motor & frame sticker		<del>\$300.00</del> 160
To remove & refit quarter glass		\$80.00 +
Gum		\$40.00 + pm
To remove & refit rear axle		\$380.00 +
To remove & refit front R/H undercarriage		\$380.00 +
To remove & refit front R/H drive shaft, steering rack & crossmember	2720	\$480.00 +
To check wheel alignment		<del>\$150.00</del> 80
To check wiring		<del>\$100.00</del> 30
Tuff kote		\$150.00 +
Towing fee		\$100.00 +
Panel beating		<del>\$2,400.00</del> 1000
Spray painting		<del>\$2,000.00</del> 1300

total: 7334.88  
 4/5: 5.8K.  
 07 Days

Subtotal:- \$7,110.00  
 Total:- \$31,498.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18010876/AVD3N2

Date: 16/08/2018

**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	B28985078MKF
Claimant Vehicle No :	SGT6228H	Insured Vehicle No :	WC4888R
Date of Loss:	12/06/2018	Nature of Claim:	TP
		Claim No:	561097

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	SGT6228H	Engine No:	L15A5122625
Make & Model:	HONDA AIRWAVE, 1.5 (A)	Chassis No:	GJ11118677
Reg. Date:	18/04/2007 (Man. Year: 2007)	Odometer:	285982 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	205/45R17	Rear Tyre Size:	205/45R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	24,478.80	4,644.88	19,833.92	81.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,020.00	2,690.00	4,330.00	61.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>31,498.80</b>	<b>7,334.88</b>	<b>24,163.92</b>	<b>76.71</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,800.00</b>		
<b>Nett Amount (S\$)</b>	<b>31,498.80</b>	<b>5,800.00</b>	<b>25,698.80</b>	<b>81.59</b>

**INSPECTION**

Date of Assignment:	14/06/2018	
Date Inspected:	13/06/2018	Inspected At:
		Sm Automotive - Kaki Bukit (HQ) BLOCK C - 1, KAKI BUKIT AVE 6, #01-43 Singapore 417883
Estimated Period of Repair:	7.0 days	

Adjuster: ADRIAN LING

Manager: VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

Please be informed that owner of SGT6228H has withdraw the claim.

{REPAIR COST NOT CONCLUDE}

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 16 Aug 2018)
<b>Parts:</b> M1-MPV	HONDA AIRWAVE 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SGT6228H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,050.90 F	*1,050.90 FL
2	10		*FRONT BUMPER CLIP	Necessary	65.00 F	*30.00 FL
3	1		*FRONT BUMPER SIDE RETAINER	O/s Damaged	67.40 F	*33.70 FL
4	1		*FRONT BUMPER CENTRE GARNISH COVER	Not Necessary	144.50 F	*- FL
5	1		*FRONT R/H BUMPER FOG LAMP COVER	Not Necessary	60.70 F	*- FL
6	8		*FRONT GRILLE CLIP	Not Necessary	52.00 F	*- FL
7	1		*FRONT R/H HEAD LAMP	Not Necessary	625.80 F	*- FL
8	1		*FRONT R/H HEAD LAMP LOWER BRACKET	Not Necessary	48.30 F	*- FL
9	1		*FRONT R/H FENDER	Dented	565.00 F	*565.00 FL
10	1		*FRONT R/H FENDER COWLING	Torn	105.00 F	*105.00 FL
11	10		*FRONT R/H FENDER COWLING CLIP	Necessary	65.00 F	*30.00 FL
12	1		*FRONT R/H FENDER SIGNAL LAMP	Not Necessary	58.50 F	*- FL
13	1		*FRONT R/H FENDER QUARTER GLASS	Shattered	281.90 F	*281.90 FL
14	1		*FRONT R/H DOOR	Dented	1,045.00 F	*1,045.00 FL
15	1		*FRONT R/H DOOR SIDE MIRROR ASSY	Distorted	681.90 F	*681.90 FL
16	2		*FRONT R/H DOOR HINGE	Bent	78.20 F	*78.20 FL
17	1		*FRONT R/H DOOR GLASS	Not Necessary	480.00 F	*- FL
18	1		*FRONT R/H DOOR GLASS OUTER MOULDING	Deformed	110.30 F	*110.30 FL
19	2		*FRONT R/H DOOR FRAME STICKER	Necessary	97.60 F	*97.60 FL
20	1		*FRONT R/H DOOR OUTER HANDLE	Not Necessary	90.50 F	*- FL
21	1		*FRONT R/H DOOR INNER LOCK	Not Necessary	350.60 F	*- FL
22	1		*FRONT R/H DOOR INNER RUBBER	Not Necessary	170.90 F	*- FL
23	1		*FRONT R/H DOOR INNER TRIM BOARD	Not Necessary	610.20 F	*- FL
24	1		*FRONT R/H DOOR GEAR MOTOR ASSY	Not Necessary	480.70 F	*- FL
25	1		*FRONT R/H LOWER ARM	Not Necessary	385.70 F	*- FL
26	1		*FRONT R/H KNUCKLE ARM	Not Necessary	351.50 F	*- FL
27	1		*FRONT R/H SHOCK ABSORBER	Not Necessary	334.40 F	*- FL
28	1		*FRONT R/H DRIVE SHAFT	Not Necessary	1,100.60 F	*- FL
29	1		*FRONT STABILIZER BAR	Not Necessary	185.00 F	*- FL
30	1		*FRONT STEERING RACK	Not Necessary	2,127.80 F	*- FL
31	1		*FRONT CROSSMEMBER	Not Necessary	1,145.00 F	*- FL
32	1		*R/H ROCKER PANEL SKIRT	Not Necessary	280.30 F	*- FL
33	1		*REAR R/H DOOR	Dented	982.30 F	*982.30 FL
34	2		*REAR R/H DOOR HINGES	Bent	79.20 F	*79.20 FL
35	1		*REAR R/H DOOR OUTER HANDLE	Not Necessary	90.50 F	*- FL
36	2		*REAR R/H DOOR FRAME STICKER	Necessary	97.60 F	*97.60 FL
37	1		*REAR R/H DOOR INNER LOCK	Not Necessary	350.60 F	*- FL
38	1		*REAR R/H DOOR INNER RUBBER	Not Necessary	170.90 F	*- FL
39	1		*REAR R/H DOOR INNER TRIM BOARD	Not Necessary	610.20 F	*- FL
40	1		*REAR R/H DOOR GEAR MOTOR ASSY	Not Necessary	480.70 F	*- FL
41	1		*REAR R/H FENDER	Repair	1,005.00 F	*- FL
42	1		*REAR R/H FENDER GLASS ASSY	Not Necessary	550.10 F	*- FL
43	1		*REAR R/H TAIL LAMP	Not Necessary	258.30 F	*- FL
44	1		*REAR BUMPER	Repair	1,078.50 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	10		*REAR BUMPER CLIP	Not Necessary	65.00 F	*- FL
46	2		*REAR BUMPER SIDE RETAINER	Not Necessary	70.00 F	*- FL
47	1		*REAR R/H SHOCK ABSORBER	Not Necessary	290.90 F	*- FL
48	1		*REAR AXLE	Not Necessary	1,300.00 F	*- FL
49	2		*REAR AXLE BEARING	Not Necessary	577.00 F	*- FL
50	1		*FRONT R/H BUMPER FOG LAMP	Not Necessary	380.00 FS	*- FS
51	1		*FRONT GRILLE	Not Necessary	480.00 FS	*- FS
52	1		*FRONT R/H RIM	Cut	680.00 FS	*400.00 FS
53	1		*FRONT R/H TYRE	Not Necessary	350.00 FS	*- FS
54	1		*REAR R/H RIM	Not Necessary	680.00 FS	*- FS
55	1		*REAR R/H TYRE	Not Necessary	350.00 FS	*- FS
56	1		*GUM	Necessary	90.00 FS	*30.00 FS
57	1		*FRONT R/H KNUCKLE ARM BEARING	Not Necessary	115.80 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>24,478.80</b>	<b>5,698.60</b>
- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	1,053.72
<b>Total Parts (S\$)</b>	<b>24,478.80</b>	<b>4,644.88</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE & REFIT CUSHION	New	380.00	60.00
2	TO REMOVE & REFIT R/H FENDER GLASS	New	120.00	60.00
3	TO REMOVE & REFIT FRONT & REAR DOOR, GLASS, TRIM BOARD, LOCK, GEAR MOTOR & FRAME STICKER	New	300.00	160.00
4	TO REMOVE & REFIT QUARTER GLASS	New	80.00	-
5	TO REMOVE & REFIT REAR AXLE	New	380.00	-
6	TO REMOVE & REFIT FRONT R/H UNDERCARRIAGE	New	380.00	-
7	TO REMOVE & REFIT FRONT R/H DRIVE SHAFT, STEERING RACK & CROSSMEMBER	New	480.00	-
8	TO CHECK WHEEL ALIGNMENT	New	150.00	80.00
9	TO CHECK WIRING	New	100.00	30.00
10	TUFF KOTE	New	150.00	-
11	TOWING FEE	New	100.00	-
12	PANEL BEATING	New	2,400.00	1,000.00
13	SPRAY PAINTING	New	2,000.00	1,300.00
<b>Gross Labour Cost (\$\$)</b>			<b>7,020.00</b>	<b>2,690.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >