

Ace Auto Solution
 Registration number : 53228991M
 23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

Repair Estimate

Date : 18/6/2018

Reference: SKG1076H
 Make: CHEVROLET
 CRUZE

To Whom It May Concern

TPAXA-
 Vivian.

Dear Sir,

RE: VEHICLE :SKG1076H
CHASSIS NO.:KL1JA69E9CK648134
ENGINE NO.:F16D4314349KA

Name of insured :Chin Kee Yong
 Date of accident.: 12/06/2018

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)	
1	1	Boot lid Buckled	\$ 1,701.11	✓
2	1	Bootlid Chrome Moulding He m	\$ 380.00	+
3	2	Bootlid No. Plate Lamp Not m	\$ 130.00	+
4	1	Boot lid Emblem 2	\$ 85.00	✓
5	1	Boot lid lettering 'CHEVROLET' New	\$ 65.00	✓
6	1	Boot lid lettering 'CRUZE'	\$ 45.00	✓
7	1	Boot lid lettering 'LS'	\$ 25.00	✓
8	1	Boot lid lettering 'SS'	\$ 35.00	✓
9	1	RHR Bootlid Lamp 3 m	\$ 454.00	+
10	1	LHR Bootlid Lamp 2 m	\$ 454.00	+
11	1	LH Bootlid hinge 3 m	\$ 75.00	+
12	1	RH Bootlid hinge 1 m	\$ 75.00	+
13	1	Boot lid Insulator He m	\$ 330.00	+
14	1	Boot lid lock mechanism Damaged	\$ 250.00	✓
15	1	Boot lid striker He m	\$ 42.00	+
16	1	Boot lid weatherstrip 1 m	\$ 189.00	✓
17	1	RHR Tail lamp Corbbed	\$ 606.00	✓
18	1	RHR Tail lamp panel Repair	\$ 271.00	+

19	1	RHR Fender Liner <i>Not in</i>	\$ 115.00	+
20	1	LHR Tail lamp <i>cut</i>	\$ 606.00	✓
21	1	LHR Tail lamp panel <i>Repair</i>	\$ 271.00	+
22	1	LHR Fender Liner <i>Not in</i>	\$ 115.00	+
23	1	Rear bumper <i>Distorted</i>	\$ 1,536.00	✓
24	1	Rear bumper tow hook cover <i>Missing</i>	\$ 30.00	✓
25	1	Centre Bumper Guide	\$ 75.00	✓
26	1	RHRC Bumper Guide	\$ 65.00	—
27	1	LHRC Bumper Guide	\$ 65.00	—
28	1	RHR Bumper Guide	\$ 60.00	—
29	1	LHR Bumper Guide	\$ 60.00	—
30	1	Rear bumper reinforcement <i>Best</i>	\$ 736.00	✓
31	1	Reverse sensor wire harness <i>Not in</i>	\$ 339.00	+
32	1	Rear end panel <i>Repair</i>	\$ 906.00	+
33	1	Rear end panel trim <i>Not in</i>	\$ 139.00	+
34	1	LHR Fender Inner Trim <i>Not in</i>	\$ 430.00	+
35	1	RHR Fender Inner Trim <i>Not in</i>	\$ 430.00	+
36	1	Rear Spare Tyre Cover <i>Not in</i>	\$ 325.00	+
37	1	Rear Spare Tyre Panel <i>Repair</i>	\$ 1,384.00	+
38	1	Rear Exhaust <i>Not in</i>	\$ 1,400.00	+

6234.11
5610.69

Parts Total: \$ 14,299.11
Less 10%: \$ 1,429.91
Total : \$ 12,869.20

Labour

No.	Labour Description	Price (SGD)
Rear portion		
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$200 per day)	\$ 1,400.00 <i>800</i>
2	Carry out spray painting on accident affected area (\$200 per panel)	\$ 1,400.00 <i>200</i>
3	To conduct anti rust of under carriage tuff coat	\$ 120.00 <i>50</i>
4	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00 ✓
5	To remove and refix reverse sensor and conduct test	\$ 80.00 <i>50</i>
6	To remove and refix reverse camera and conduct test	\$ 80.00 <i>50</i>
7	To remove undercarriage parts to replace rear exhaust	\$ 180.00 <i>X</i>
8	To conduct transfer of parts from old bootlid to new bootlid	\$ 80.00 ✓
9	To conduct water leakage test after repairs of vehicle	\$ 80.00 <i>X</i>

1860

Labour Total : \$ 3,450.00

Others

Other Description

<u>No.</u>	<u>Qty</u>		<u>Price (SGD)</u>	
<u>Rear portion</u>				
1	1	Rear number plate <i>Not New</i>	\$ 45.00	+
2	10	Rear bumper clip <i>New</i>	\$ 65.00	30
3	6	Rear Fender Liner Clip <i>2</i>	\$ 39.00	+
4	5	Rear end panel trim clip <i>1</i>	\$ 32.50	+
5	10	Bootlid Insulator Clip	\$ 65.00	+
6	1	Reverse sensor (4pcs) <i>Payed</i>	\$ 320.00	250
7	1	Reverse camera <i>Not in</i>	\$ 480.00	+
8	1	Rear floor panel insulation seal <i>Not in</i>	\$ 160.00	+
9	1	Rear end panel insulation seal <i>New</i>	\$ 80.00	60
10	12	Rear Fender Inner Trim Clip <i>Not in</i>	\$ 78.00	+
11	1	Rear Spoiler <i>Not in</i>	\$ 350.00	+
12	1	Rear Bodykit <i>Discontinued</i>	\$ 1,500.00	800
13	1	NavTrack Lettering <i>New</i>	\$ 30.00	✓

1170

Other Total: \$ 3,244.50

GRAND TOTAL: \$ 19,563.70

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully

Service Advisor
Suhaimi

HP : 9189 2617 Email: aceautosolution@gmail.com

- the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian King
1/5 19/06/18

told: 8640.69

1/5: 3.5K (Nett Value)

04 Days