

22/03/2002

ASS. REC. BY:

REF: CS/MSG18010881 / D9d3^m Special Instruction:

Surveyor:

Menimen

Bryan.

ASSIGNMENT (Office)

From (Person):

Muhd Ashik

of

MSIG

Date/Time:

13/6/18 @ 4.07pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GU 7096J

Insured:

SJP 6799L

at Workshop m/s

Slp Motoring

Tel:

910 04390

of

Blk 10 AMK Autopoint, AMK Ind. Park 2A #03-07

Policy No:

A28891921QMX

Claim No:

560355

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

04/06/2018

18/06/2018

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

Date/Time:

9.55am @ 14/6/18

Person Contacted:

Susan

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

GU 7096J - x

SJP 6799L - x

19/6/18 @ 1.16pm revised to Muhd Ashik via Menimen.

28/06/18

Jnapw 2/15 1250/- with 4 days of r
(led 4 4825.75, 792.7)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Jun 2018		13 Jun 2018 16:07 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by Insurer]

Insured:	OONG YONG WEE, ID: S7928852G, Tel: +6598894584, Email: NOEMAIL		
Main Claimant:	RICO ENGINEERING WORKS PTE LTD, Co. Reg. No.: 199800407G		
Vehicle Reg. No.:	GU7096J	Date of Loss:	04/06/2018 18:00 - :59 [204 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 560355	Policy/Cover Note No.:	A28891921QMX (Comprehensive) Coverage: 01/04/2018 - 31/03/2019
Vehicle Reg. No. (Insured):	SJP6799L	Policy No. (Claimant):	
		Excess:	
Repairer:	Slp Motoring Services - Amk (HQ) BLK 10 Amk Autopoint, Ang Mo Kio Ind Park 2A #03-08, 568047 Ang Mo Kio - Tel: 9100 4390		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 14/06/2018]		
Driver/Custodian (Insured):	OONG YONG WEE (38 / Male), NRIC: S7928852G, Tel: +6598894584		
Adj Asg. Remarks:	Liability 100%. BOLA S28 chain collision applicable. Estimate will be provided to the surveyor upon his arrival Contact Susan at 91004390 (unit #03-07)		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 19 Jun 2018

Preliminary Advice

Insured Vehicle No	: SJP6799L	Accident Date	: 04/06/2018
TP Vehicle No	: GU7096J	Assignment Date	: 13/06/2018
Make	: SUZUKI CARRY	Est. Duration of Repair	: 4.00
Date of Inspection	: 18/06/2018		
Inspection At	: SLP MOTORING SERVICES - AMK (HQ) BLK 10 AMK AUTOPOINT, ANG MO KIO IND PARK 2A #03-08 SINGAPORE 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:SS	6,225.75
Revised Amount	:SS	1,653.60
Check Items (Estimated)	:SS	0.00
Total	:SS	1,653.60

Lump Sum Repair :SS

Total Loss Consideration

New for Old Value	:SS
Pre-Accident Value	:SS
COE / PARF Rebate	:SS
Salvage Value	:SS
Margin for Repair	:SS

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/06/2018 11:59
Date Of Accident	04/06/2018 18:30
Exact Location Of Accident	TPE GOING TOWARDS SLE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GU7096J
Insured/Policyholder	
Name Of Registered Owner	RICO ENGINEERING WORKS PTE LTD
Co Reg No	199800407G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-64820153

Vehicle Particulars

Manufacturer	SUZUKI
Model	CARRY 1.3
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5055295438-05
Cover Note Number	

Driver

Name of Driver	SUBRAMANIAN VETRIVEL
Passport No/FIN	G6955335X
Date Of Birth	15/06/1990
Occupation	OUTDOOR
Date Of Driving Pass	26/12/2017
Driving Experience	0 YEAR AND 5 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-91749752
Fax Number	
Contact Number	
Email Address	VETRIKUMAR1989@GMAIL.COM

Address NO. 8 SELETAR NORTH LINK (PPT LODGE 1A)
 Postcode 797455
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 Vehicle -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1
 NAME: : BALASUBRAMANIAN DHINESH
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO ACCIDENT STATEMENT AS ATTACHED.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJP6799L
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver OONG YONG WEE
 NRIC/Passport Number S7928852G
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	PC3284Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	ZHANG JIPING
NRIC/Passport Number	G2930706M
Contact Number	91811555
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form, and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Venug
Driver's Signature
(If driver is not the policyholder)
Date & Time:

Jbelle Tan
Reporting Centre Personnel's Signature
Name: *Jbelle Tan*
NRIC/TIN No.: *AMK AUTOPPOINT PTE LTD*

05.06.2018

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along TPE going towards SLE. Just as I was moving, I felt an impact on my rear. Vehicle "B" collided into me. unsure if its an impact from vehicle "C" which collided into vehicle "B" thus collided into me. That's all.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



© 2000 Blackwell Science Ltd *Journal of Internal Medicine* 247: 347–353

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Shelle Tan
NRIC No.: AMK AUTOPOINT PTE LTD
05.06.2018

SLP Motoring Services

102 Gerald Drive #04-75 Singapore 798593

HP 91004390/91254449 Fax 6484 1482

Email: slpmotoring@gmail.com

M/s MSIG Insurance (Singapore) Pte Ltd

DATE

18.06.2018

4 Shenton Way #21-01

CAR NO

GU 7096 J

SGX Centre 2 S608807

MAKE

Suzuki Carry

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE
YOUR INSURED : SJP 6799 L

Qty	Pcs	JSAFDA32V00127969	UNIT PRICE	Amount
1	pcs	Tailgate <i>sgv</i>		\$895.10 X
1	pcs	Tailgate garnish <i>nm</i>		\$57.15 X
1	pcs	Tailgate lock <i>nm</i>		\$55.05 X
1	pcs	Tailgate lock catch <i>nm</i>		\$20.15 X
1	pcs	Tailgate emblem "70km/h" <i>nm</i>		\$10.00 ✓
1	pcs	Tailgate emblem "4 pax" <i>nm</i>		\$10.00 ✓
1	pcs	Tailgate weather stripe <i>sgv</i>		\$125.10 X
1	pcs	Rear windscreen moulding <i>nm</i>		\$94.25 X
1	pcs	Rear windscreen sealant <i>nm</i>	Nett	\$30.00 X
1	pcs	RH tail lamp <i>broken</i>		\$120.05 ✓
1	pcs	LH tail lamp <i>nm</i>		\$128.25 X
5	pcs	Tail lamp clips <i>sgv</i>	\$3.50	\$17.50 X
1	pcs	Reverse sensor <i>HF</i>	S/Nett	\$200.00 X
1	pcs	Rear bumper <i>entire damaged</i>		\$413.55 ✓
10	pcs	Rear bumper clips <i>nm</i>	\$5.00	\$50.00 ✓
1	pcs	Rear number plate <i>nm</i>		\$50.00 X
2	pcs	Rear number plate lamp <i>nm</i>	\$20.75	\$41.50 X
1	pcs	Rear exhaust <i>nm</i>		\$348.10 X
1	pcs	Rear exhaust moulding <i>nm</i>		\$20.00 X
To be continue at page 2				
Total				

603.60
15% 513.06
disc



SLP Motoring Services

SLP Motoring Services

102 Gerald Drive #04-75 Singapore 798593

HP 91004390/91254449 Fax 6484 1482

Email:slpmotoring@gmail.com

M/s MSIG Insurance (Singapore) Pte Ltd DATE 18.06.2018
 4 Shenton Way #21-01 CAR NO GU 7096 J
 SGX Centre 2 S608807 MAKE Suzuki Carry

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE
 YOUR INSURED : SJP 6799 L

Qty	Pcs	JSAFDA32V00127969	UNIT PRICE	Amount
		Continue from page 1		\$2,685.75
		Labour for jacking, knocking rear right/right mudguard, cutting for rear end panel (inner & outer), dismantle dismantle & replace the above mentioned parts.		\$1,300.00 600/-
		To spray paint tailgate, end panel (inner & outer) left rear mudguard panel, right side rear mudguard panel.		\$1,500.00 300/-
		Remove and reinstall rear windscreen		\$160.00 NH
		Remove and reinstall all tailgate parts into new tailgate		\$160.00 NH
		Test and refix reverse sensor system	1050/-	\$120.00 NH
		Remove and refix rear exhaust		\$150.00 NH
		To supply sticker "RICO" & sticker for tel number.		\$ 150.00 NH
		18/06/2018 @ 1145h NA Antm 2/5mm Ryan 4 days. 2kk Antm		6225.75
		Total		\$6,075.75

to Consultants hence notify
 or of the following:
 -fore/aft spray painting
 -end part(s) during resurvey
 -sent to confirmation
 "Without Prejudice" basis
 allowed
 resurveyed and
 with Insurance Company
 SLP Motoring Services
 Date:

Page 2 of 2

97237799

1563.06
 4/5 1250/-

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18010881/DQD3N2

Date: 02/07/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A28891921QMX
Claimant Vehicle No :	GU7096J	Insured Vehicle No :	SJP6799L
Date of Loss:	04/06/2018	Nature of Claim:	TP
		Claim No:	560355

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GU7096J	Engine No:	G13BB706877
Make & Model:	SUZUKI CARRY, 1.3 D (M)	Chassis No:	JSAFDA32V00127969
Reg. Date:	24/05/2001 (Man. Year: 2001)	Odometer:	363187 km
Colour:	White		
Engine Capacity:	1298 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	165 R13C	Rear Tyre Size:	165 R13C
Front Left Side:	Maxxis 6 mm	Rear Left Side:	Maxxis 6 mm
Front Right Side:	Maxxis 6 mm	Rear Right Side:	Maxxis 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,685.75	513.06	2,172.69	80.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,540.00	1,050.00	2,490.00	70.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,225.75	1,563.06	4,662.69	74.89
Approved Total (Overridden) (S\$)		1,250.00		
Nett Amount (S\$)	6,225.75	1,250.00	4,975.75	79.92

INSPECTION

Date of Assignment:	13/06/2018	
Date Inspected:	18/06/2018 Inspected At:	Slp Motoring Services - Amk (HQ) BLK 10 Amk Autopoint, Ang Mo Kio Ind Park 2A #03-08 Singapore 568047
Estimated Period of Repair:	4.0 days	

Adjuster: BRYAN TANI

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 02 Jul 2018)	
Parts:	N/A	SUZUKI CARRY 1.3 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GU7096J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	895.10 F	*- FL
2	1		*TAILGATE GARNISH	Not Necessary	57.15 F	*- FL
3	1		*TAILGATE LOCK	Not Necessary	55.05 F	*- FL
4	1		*TAILGATE LOCK CATCH	Not Necessary	20.15 F	*- FL
5	1		*TAILGATE EMBLEM 70KM/H	Necessary	10.00 F	*10.00 FL
6	1		*TAILGATE EMBLEM 4PAX	Necessary	10.00 F	*10.00 FL
7	1		*TAILGATE WEATHER STRIPE	Serviceable	125.10 F	*- FL
8	1		*REAR WINDSCREEN MOULDING	Not Necessary	94.25 F	*- FL
9	1		*RH TAIL LAMP	Broken	120.05 F	*120.05 FL
10	1		*LH TAIL LAMP	Not Necessary	128.25 F	*- FL
11	5		*TAIL LAMP CLIPS	Serviceable	17.50 F	*- FL
12	1		*REAR BUMPER	Cut/Deformed	413.55 F	*413.55 FL
13	10		*REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
14	1		*REAR NUMBER PLATE	Not Necessary	50.00 F	*- FL
15	2		*REAR NUMBER PLATE LAMP	Not Necessary	41.50 F	*- FL
16	1		*REAR EXHAUST	Not Necessary	348.10 F	*- FL
17	1		*REAR EXHAUST MOULDING	Not Necessary	20.00 F	*- FL
18	1		*REAR WINDSCREEN SEALANT	Not Necessary	30.00 FS	*- FS
19	1		*REVERSE SENSOR	Not fitted	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,685.75	603.60
- List Item Discount on L Items 0.00/15.00% (\$\$)	0.00	90.54
Total Parts (\$\$)	2,685.75	513.06

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR JACKING,KNOCKING REAR RIGHT/RIGHT MUDGUARD,CUTTUNG FOR REAR END PANEL (INNER & OUTER),DISMANTLE & REPLACE THE ABOVE MENTIONED PARTS	New	1,300.00	600.00
2	TO SPRAY PAINT TAILGATE,END PANEL (INNER & OUTER),LEFT REAR MUDGUARD PANEL,RIGHT SIDE REAR MUDGUARD PANEL	New	1,500.00	300.00
3	REMOVE AND REINSTALL REAR WINDSCREEN	New	160.00	-
4	REMOVE AND REINSTALL ALL TAILGATE PARTS INTO NEW TAILGATE	New	160.00	-
5	TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	-
6	REMOVE AND REFIX REAR EXHAUST	New	150.00	-
7	TO SUPPLY STICKER RICO & STICKER FOR TEL NUMBER	New	150.00	150.00
Gross Labour Cost (\$\$)			3,540.00	1,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >