

(05/01/11)

INS CASE OWNER:

CC /AIG1801

0885, A

LKK:

IDAC:

Surveyor:

WMP

DOI:

ASSIGNMENT

18/6/18

Date / Time:

14/6/18

Registered in Merit:

14/6/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SCA 61H

Name of Insured:

LEE Yim POK

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

8/6/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

NEW Ma moi

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

0A1506494756

Policy No.:

180017124

Make / Model:

VOLVO

Place of Accident:

SA custom

OI GLA REPORT: YES / NO: TP GLA REPORT: YES / NO

Insured Liability:

Final? Yes / No

SLC8782R

INSRS:
WSP:
Tel:
Liability:
RMKS:

modern

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time

18/6/18

TH

19/6/18

Spoke to OIP she confirmed the accident details. Informed it claim and she agree to settle.

STAGE

DATE / PIC

Non-Reporting hr (1st):

Non-Reporting hr (2nd):

Non-Reporting hr (Final):

Notification hr (if non-pickup):

Call OI:

After call hr to OI: 20/7

Documentation Check List: Handler Typist

Notification hr (if non-pickup)

After call hr to OI

Authorisation To Act

Release Voucher

Final Repair Bill

Car Rental Invoice

Towing Invoice

LTA / GLA

Medical Bill

PIR

Mandate/Reject Instruction

LOD

Payment Breakdown Form:

Post-Repair Photos

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

5,300

days Reduction:

Email

Call

FINAL SETTLEMENT

Date/Time:

15-4-19

Confirm with:

CHIN

Email

Call

Final Liability:

%

100

(Agreed) Assessed

BOLA S/N No:

27

Repair Cost:

SS

5,671.XX

Loss of Rental (LOR):

SS

600

(6 days) 100

Loss of Use (LOU):

SS

X

(5 x days)

Loss of Income (LOI):

SS

X

(5 x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GLA/LTA Search

SS

2.X1

Medical:

SS

X

Disbursement:

SS

X

(e.g. Tow/Independent)

Legal Cost

SS

X

Total:

SS

6,273.X1

Global Sum SS:

6,270

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

6,270

Name 1:

MODERN AUTOMOTIVE PTE LTD

Payee 2: (Strike if N.A.)

SS

X

Name 2:

X

Payee 3: (Strike if N.A.)

SS

X

Name 3:

X

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

COPY SENT
9/5/19

REF:

M

ASS. REC. BY: Adrian Ling

ASSIGNMENT

From _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLC8982R Yr Regn: 206, May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Wish c.c. 1797

Colour: Maroon A/C: Insured / Std / NI / NA

Sp. Reading: 18698 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ZGE20608720

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Morder / Jammed / Leaked / Burnt or

Brake: Morder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 175/65R15

R: 175/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal: 06 mm R/Bal: 06 mm

L/Bal: 06 mm L/Bal: 06 mm

D.O.A. _____ D.O.I. 19/06/18

Survey held at: Modern

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP A16

\$5,300

R (\$6,722.58/529.)

Date/Time, File Pass to?

☐

: Prel. Report

n

☐

: Final Report

Date/Time, File Return to?

3

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + PS \$

Photos:

Others:

TOTAL

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$

Report Format:

Lump Sum / L.B.B. (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG18010885/ub3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 14-06-2018		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SCA 61H	Veh. Inspected	SLC 8782R	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	14/06/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	08/06/2018	Inspection Date		
Survey held at	MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 #01-61 SINGAPORE 408717			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD

Charts Building
78 Shenton Way #07-16
Singapore 079120
Tel : 6419 - 3000
Fax : 6835 - 7416

Thin thin

Quotation
DATE : 19.06.2018
VEH NO : SLC8782R
MODEL : Toyota Wish
D O A : 08.06.2018
YR REF : SCA61H

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SLC8782R (Toyota Wish)

Item	Description	Qty	Amt
NO	LIST ITEMS		
1	Rear Bumper <i>Rebond</i>	1	566.80 ✓
2	Rear Bumper Clips <i>m</i>	1 set	30.00 ✓
3	Rear Bumper Side Holder - LH & RH <i>m</i>	2	131.60 ✓
4	Rear Bumper Reflector - LH & RH <i>Not new</i>	2	137.00 ✗
5	Rear Bumper Impact Bracket - LH & RH <i>RH Bent</i>	2	137.20 <i>68.60</i>
6	Rear End Panel Outer <i>Dented</i>	1	618.90 ✓
7	Rear End Panel Inner <i>Repair</i>	1	454.30 ✗
8	Rear End Panel Top Garnish <i>Rebond</i>	1	285.60 ✓
9	Taillamp - LH & RH <i>RH cut</i>	2	986.40 <i>483.20</i>
10	Tailgate <i>Dishbed</i>	1	1,342.60 ✓
11	Tailgate Lock <i>Damaged</i>	1	389.50 ✓
12	Tailgate Lock Sensor <i>Damaged</i>	1	107.90 ✓
13	Tailgate Weatherstripe <i>bit</i>	1	219.40 ✓
14	Tailgate Chrome Moulding <i>Cracked</i>	1	327.70 ✓
15	Tailgate Inner Trim Board <i>Rebond</i>	1	483.20 ✓
16	Tailgate Inner Trim Board Clips <i>m</i>	1 set	30.00 ✓
17	Tailgate Reflector - LH & RH <i>RH cut</i>	2	562.80 <i>281.40</i>
18	Tailgate Glass Moulding <i>new</i>	1	246.00 ✓
19	Toyota Logo <i>3 new</i>	1	66.50 ✓
20	Valve Matic Emblem <i>3 new</i>	1	68.00 ✓
21	Rear Fender Inner Trim Board - LH & RH <i>3 new</i>	2	1,497.40 ✗
22	Rear Fender Inner Trim Board Clips	2 sets	60.00 ✗
23	Floor Panel Top Board <i>3 new</i>	1	561.60 ✗
24	Rear Exhaust Pipe <i>3 new</i>	1	794.40 ✗
25	Rear Exhaust Mounting	1	65.30 ✗
			10,150.10
Less 25%			(2,537.53)

RE : ESTIMATE FOR ACCIDENT REPAIR SLC8782R (Toyota Wish)

\$ 7,612.58

S/NETT ITEMS

1	Reverse Sensor	2nd	320	1 set	280.00	200
2	Rear End Panel Sealant	1		1	60.00	✓
3	Tailgate Glass Sealant	1		1	60.00	✓
4	Rear Camera	1st		1	580.00	✓

Total Parts \$ 8,592.58

LABOUR CHARGE

1	To knocking & pull out rear portion & renew above parts	\$	1,200.00 800
2	To putty & spray up paint works	\$	1,200.00 800
3	To check wiring	\$	50.00 30
4	To underseal	\$	150.00 40
5	To remove reverse sensor	2030 \$	100.00 50
6	To remove rear camera	\$	100.00 50
7	To transfer tailgate fittings	\$	150.00 80
8	To remove tailgate glass	\$	180.00 120
9	To remove exhaust pipe	\$	150.00 X
10	To remove upholstery	\$	150.00 60

Total Labour \$ 3,430.00

Grand Total \$ 12,022.58

LKK Auto Consultants hence notify the Repairer of the following:

NOTE:

- To rectify before/after spray painting
- To display damaged part(s) during resurvey
- Repairs are subject to confirmation
- Third party survey is on a 'Without Prejudice' basis
- No legal action will be taken

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE
is subject to final approval from Insurance Company.
FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

Acknowledged by Repairer

Signature:

Date:

total: 6660.17
4/5 5.3K.
06 Days.

MODERN AUTOMOTIVE PTE LTD

BLK 3023A UBI ROAD 1 # 01 - 61

SINGAPORE 408717

GST REG. NO : 200501102H

TEL : 6748-4422 / 6745-4422 FAX : 6-747- 6720

Email: chin@modernautomotive.com.sg

Your Ref : SCA61H
Our Ref : SLC8782R

Date : 14.08.2018

The Claims Manager
AIG Asia Pacific Insurance Pte Ltd
AIG Building
78, Shenton Way #07-16
Singapore 079120
Tel : 6-419-3000 Fax : 6-415-3727

Attn : The Motor Claim Dept

**RE : ACCIDENT INVOLVING SLC8782R & SCA61H ON 08.06.2018
AT WOODLANDS CHECKPOINT TOWARDS JOHORE**

We refer to the above matter.

We have been authorized by our client Mr Kow Weijie, Kelvin to make claim against your insured vehicle No. SCA61H in respect of the above accident for the following :

Repair Cost	\$ 5,671.00 (Incl GST)
Loss of rental (6 days x \$200)	\$ 1,200.00
Search fee	\$ 2.00
Total :	\$ 6,873.00

Enclosed herewith a copy each of the supporting documents for your perusal.
Kindly process the above and remit the payment to us asap

Yours faithfully



Modern Automotive Pte Ltd



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG18010885/ub3

20 JULY 2018

LEE YAM POH
61 CHUN TIN ROAD
SINGAPORE 599637

Dear Sir/Madam,

ACCIDENT INVOLVING SCA 61H & SLC 8782R ON 08/06/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

THIN THIN HLAING
Case Handler
DID: 6841 2360
FAX: 6741 4108
Email: thinthin@lkkauto.com

c.c. *AIG Asia Pacific Insurance Pte Ltd*
(Motor Claims Dept)

LETTER OF AUTHORIZATION

Date: 19/6/18

TO WHOM IT MAY CONCERN

Dear Sir,

RE: ACCIDENT INVOLVING VEHICLE

SLC 8782 R / SCA 61 H

ON 08/6/2018 ALONG Woodlands Checkpoint

Towards Johore

This letter is to authorize **MODERN AUTOMOTIVE PTE LTD** at Block 3023A, Ubi Road 1, #01-61, Singapore 408717 to resolve the above matter.

In respect of this authorization, **MODERN AUTOMOTIVE PTE LTD** has my/our authority to decide on my/our behalf whether to accept any offer of settlement from the third party insurers. I/we also agreed that all payments include Loss of Use to make in favour of **MODERN AUTOMOTIVE PTE LTD**.

MODERN AUTOMOTIVE PTE LTD is also authorized to sign all the required documents include Discharge Voucher from the third party insurers on my/our behalf.

Yours Faithfully



Signature of Owner

Kow Wengie, Kelvin / S8400912A

Name / NRIC

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, **MODERN AUTOMOTIVE PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$6,270.00** (Global Sum) for vehicle no. **SLC 8782R** that was damaged pursuant to the accident which occurred on **08/06/2018** (date) along **SINGAPORE CUSTOM** (location) involving vehicle no/s **SCA 61H**. This is pursuant to the inspection conducted on **19/06/2018** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **KOW WEIJIE KELVIN** ("the third party claimant") of vehicle no. **SLC 8782R** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SLC 8782R** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 07 (day) of May (month) 2019 (year)



Signed by appointed surveyor



Signed by "the workshop" (with chop)

MODERN AUTOMOTIVE PTE LTD

BLK 3023A UBI ROAD 1 #01-58 / 61 SINGAPORE 408717
TEL : 67474422, 67454422 FAX : 67476720
GST REG. NO : 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
SINGAPORE 079120

Attention : Motor Claim Department
Contact : 6415-3727 6419-3000

Tax Invoice : TP001241

Date : 10/08/2018
Vehicle Num. : SLC 8782R
Make/Model : TOYOTA WISH-2016
Chassis/Eng# :
Accident Date : 08/06/2018
Claim No. :
Reference :
Policy No. : 10836441

S/N	Quantity	Particular	Unit Price	Amount S\$
		LABOUR :		
		ACCIDENT REPAIR (LUMPSUM)		5,300.00
		Labour Total S\$:		5,300.00

Total S\$:	5,300.00
GST @ 7% S\$:	371.00
Amount Due S\$:	5,671.00
	=====


MODERN AUTOMOTIVE PTE LTD



DAWN ENTERPRISES

21 SELETAR WEST FARMWAY 1
SINGAPORE 798125
TEL: 6383 2661 FAX: 6484 2836
REG. NO. 430058/00D

No. 19392

Date, 25/6/18

OFFICIAL RECEIPT

Received from Kow Wei Jie Kelvin

the sum of Dollars One thousand two hundred only

being Payment Of SKX 24370 (19/6/18 - 25/6/18)

DAWN ENTERPRISES

\$ 1200/-
Cash/Cheque No.





DAWN ENTERPRISES

21 Seletar West Farmway 1
Singapore 798125
Tel: 63832661 Fax: 64842836
Reg No.430058/00D

N^o 35539

RENTAL AGREEMENT

DATE 19/6/18

HIRER'S PARTICULARS

Name Kow Weijie Kelvin

Address _____

I/C or Passport No. 8A00917A Country _____

Occupation _____

Date of Birth _____ Age _____

Driving Licence No. _____ Date Passed _____

Tel: (HP) _____ (Residence) _____

DRIVER'S PARTICULARS

Name GLORIA TAN

Address BLK 152 TOA PAYOH LORONG 2

#17-324 S3160 S31052

I/C or Passport No. 386307513 Country SINGAPORE

Occupation CIVIL SERVANT

Date of Birth 31/10/1986 Age _____

Driving Licence No. _____ Date Passed _____

Tel: (Office) _____ (Residence) _____

IMPORTANT NOTES:

1. No insurance coverage if the driver is below 24yrs old or less than 2 years driving licence.
2. This vehicle is licenced to carry 04 passengers only.
3. Hirer is liable to pay first \$ 2000 as excess all claims any accident plus loss of earning while damaged vehicle is under repair.
4. For usage to Malaysia subject to higher excess all claims of \$55,000.00 and different rental rate.
5. Please notify our office should there be any accident involving this hired vehicle within 24 hrs.
6. No refund will be given for vehicle returns early.
7. No refund will be given for petrol left in vehicle.
8. Hirer is liable to pay all parking fee and traffic summonses.
9. Vehicles to be return during office hour only.
10. No Service on Public Holiday and Sunday.

SCHEDULE

9CX 2457D

2000 CC

MODEL

T / Picnic

Date

Time

Mileage

19/6/18

9-45am

25/6/18

CHARGES

6 Day at \$ <u>200.00</u> per days	\$ <u>1200.00</u>
Day at \$ _____ per week	
Day at \$ _____ per month	
TOTAL AMOUNT	\$ <u>1200.00</u>
AMOUNT PAID	\$ <u>1200.00</u>
BALANCE DUE	
Days Extension From _____ To _____	
Amount Deposit (refundable) \$	

FROM

19/6/18

TO

25/6/18

I/we have read and understood the terms and conditions above and hereby agreed to abide

[Signature]

Hirer's Signature

Driver/Gurantor's Signature

[Signature]

DAWN ENTERPRISES



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-090392

Date of Request: 13/06/2018

Your Ref No: Online Purchase

Modern Automotive Pte Ltd
Blk 3023A Ubi Road 1
#01-61 & #01-58
Singapore 408717

Dear Sir/Madam,

Enquiry Date 13/06/2018
Enquiry By Chin Sol Shong
TP Vehicle No. SCA61H
Accident Date 08/06/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SCA61H	AIG Asia Pacific Insurance Pte. Ltd.	28/02/2018-31/08/2019	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-090392

Date of Request: 13/06/2018

Your Ref No: Online Purchase

Modern Automotive Pte Ltd
Blk 3023A Ubi Road 1
#01-61 & #01-58
Singapore 408717

Dear Sir/Madam,

Enquiry Date 13/06/2018
Enquiry By Chin Soi Shong
TP Vehicle No. SCA61H
Accident Date 08/06/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING












































Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Jun 2018 Edit Reg		14 Jun 2018 00:00 Edit Adj Rpt	S\$5,300.00 Edit Estimates	S\$5,300.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: LEE YAM POH , ID: S2091585D									
Main Claimant: KOW WEIJIE, KELVIN , ID: S8400912A									
Vehicle Reg. No.: SLC8782R		Date of Loss: 08/06/2018 11:00 - :59 [24 Months and 12 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 0995064943SG		Policy/Cover Note No.: 1800021134 (Comprehensive)							
Vehicle Reg. No. (Insured): SCA61H		Policy No. (Claimant): 10836441							
		Excess:							
Reparer: Modern Automotive Pte Ltd (HQ) Blk 3023A Ubi Road 1, #01-61 & #01-58, 408717 Ubi - Tel: 6748 4422 / 6747 4422									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Kesaval, Jaclyn-M]									
Claimant's Insurer: Aviva Ltd (HQ) - Tel: (65) 6827 9966									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 26/06/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLC8782R (0995064943SG)
[SCA61H]
TP
KOW WEIJIE, KELVIN
Jun 8 2018 11:45AM
[LEE YAM POH]
Modern Automotive Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Letters/Correspondences											1 per page		<input checked="" type="checkbox"/>	
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)								Thumbnail		Print	
1	(Draft)		Third Party Express Settlement – Payment Breakdown								1		Edit	
Photos/Images											3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)								Thumbnail		Print	
1	27/07/18 15:09		General View								1		Load JPG <input checked="" type="checkbox"/>	
2	27/07/18 15:09		General View								1		Load JPG <input checked="" type="checkbox"/>	
3	27/07/18 15:09		General View								1		Load JPG <input checked="" type="checkbox"/>	
4	27/07/18 15:09		General View								1		Load JPG <input checked="" type="checkbox"/>	
5	27/07/18 15:09		General View								1		Load JPG <input checked="" type="checkbox"/>	
6	27/07/18 15:09		General View								1		Load JPG <input checked="" type="checkbox"/>	
7	27/07/18 15:09		General View								1		Load JPG <input checked="" type="checkbox"/>	
8	27/07/18 15:09		General View								1		Load JPG <input checked="" type="checkbox"/>	
9	27/07/18 15:09		General View								1		Load JPG <input checked="" type="checkbox"/>	
10	27/07/18 15:09		General View								1		Load JPG <input checked="" type="checkbox"/>	
11	27/07/18 15:09		General View								1		Load JPG <input checked="" type="checkbox"/>	
12	27/07/18 15:09		General View								1		Load JPG <input checked="" type="checkbox"/>	
13	27/07/18 15:09		General View								1		Load JPG <input checked="" type="checkbox"/>	
14	27/07/18 15:09		General View								1		Load JPG <input checked="" type="checkbox"/>	
15	27/07/18 15:09		General View								1		Load JPG <input checked="" type="checkbox"/>	
16	27/07/18 15:09		General View								1		Load JPG <input checked="" type="checkbox"/>	
17	27/07/18 15:09		General View								1		Load JPG <input checked="" type="checkbox"/>	
18	27/07/18 15:09		General View								1		Load JPG <input checked="" type="checkbox"/>	
19	27/07/18 15:09		General View								1		Load JPG <input checked="" type="checkbox"/>	
20	27/07/18 15:09		General View								1		Load JPG <input checked="" type="checkbox"/>	
21	27/07/18 15:09		General View								1		Load JPG <input checked="" type="checkbox"/>	
22	27/07/18 15:09		General View								1		Load JPG <input checked="" type="checkbox"/>	
23	27/07/18 15:09		General View								1		Load JPG <input checked="" type="checkbox"/>	
24	27/07/18 15:09		General View								1		Load JPG <input checked="" type="checkbox"/>	
25	27/07/18 15:09		General View								1		Load JPG <input checked="" type="checkbox"/>	
26	27/07/18 15:09		General View								1		Load JPG <input checked="" type="checkbox"/>	
27	27/07/18 15:09		General View								1		Load JPG <input checked="" type="checkbox"/>	
28	27/07/18 15:09		General View								1		Load JPG <input checked="" type="checkbox"/>	
29	27/07/18 15:09		General View								1		Load JPG <input checked="" type="checkbox"/>	
30	27/07/18 15:09		General View								1		Load JPG <input checked="" type="checkbox"/>	
31	27/07/18 15:09		Reinspection Photo								1		Load JPG <input checked="" type="checkbox"/>	
32	27/07/18 15:09		Reinspection Photo								1		Load JPG <input checked="" type="checkbox"/>	
33	27/07/18 15:09		Reinspection Photo								1		Load JPG <input checked="" type="checkbox"/>	
34	27/07/18 15:09		Reinspection Photo								1		Load JPG <input checked="" type="checkbox"/>	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	27/07/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	27/07/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	27/07/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	27/07/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	27/07/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	27/07/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	27/07/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	27/07/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	27/07/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	27/07/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	27/07/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	27/07/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	27/07/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	27/07/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	27/07/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	27/07/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	27/07/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	27/07/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	27/07/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	27/07/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	27/07/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	27/07/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	27/07/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	27/07/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	27/07/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	27/07/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	27/07/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	27/07/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	27/07/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	27/07/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	27/07/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	27/07/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	27/07/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	27/07/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	27/07/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/06/18 15:17	TP GIA REPORT	 Load PDF	
2	15/05/19 12:13	WORKSHOP INVOICE	 Load PDF	
3	15/05/19 12:13	AUTHORISATION TO ACT FORM	 Load PDF	
4	15/05/19 12:13	Release Voucher	 Load PDF	
5	15/05/19 12:13	RENTAL RECEIPT	 Load PDF	
6	15/05/19 12:13	GIA SEARCH	 Load PDF	
7	15/05/19 12:13	LETTER TO OI	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	18/06/18 11:59	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)



Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SCA61H (Insd veh)	Model:	TOYOTA WISH 1.8 (A)
	SLC8782R (TP veh)		
Date of Accident:	08/06/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	12,864.15
Final Repair Cost	:	\$	6,270.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	6 days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	6,270.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Modern Automotive Pte Ltd	:	\$ 6,270.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

15 May
2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC8/AIG18010885/AJB3Q2

Date: 15/05/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800021134
Claimant Vehicle No : SLC8782R **Insured Vehicle No :** SCA61H
 Date of Loss: 08/06/2018 Nature of Claim: TP Claim No: 0995064943SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLC8782R**
 Make & Model: TOYOTA WISH, 1.8 (A) Engine No: 2ZR1677095
 Reg. Date: 27/05/2016 (Man. Year: 2016) Chassis No: ZGE206028720
 Colour: Maroon Odometer: 18698 km
 Engine Capacity: 1797 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,592.57	4,630.17	3,962.40	46.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,430.00	2,030.00	1,400.00	40.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,022.57	6,660.17	5,362.40	44.60
Approved Total (Overridden) (S\$)		5,300.00		
(S\$)	12,022.57	5,300.00	6,722.57	55.92
+ GST 7.00/7.00% (S\$)	841.58	371.00	470.58	55.92
Nett Amount (S\$)	12,864.15	5,671.00	7,193.15	55.92
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,273.00		
Global Sum Settlement (S\$)		6,270.00		

INSPECTION

Date of Assignment: 14/06/2018
 Date Inspected: 19/06/2018 Inspected At:

Modern Automotive Pte Ltd (HQ)
Blk 3023A Ubi Road 1, #01-61 & #01-58
Singapore 408717

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	566.80 FL	*566.80 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
3	2		*REAR BUMPER SIDE HOLDER -LH & RH	Necessary	131.60 FL	*131.60 FL
4	2		*REAR BUMPER REFLECTOR -LH & RH	Not Necessary	137.00 FL	*- FL
5	1		*REAR BUMPER IMPACT BRACKET -LH & RH	O/S Deformed	137.20 FL	*68.60 FL
6	1		*REAR END PANEL OUTER	Dented	618.90 FL	*618.90 FL
7	1		*REAR END PANEL INNER	Repair	454.30 FL	*- FL
8	1		*REAR END PANEL TOP GARNISH	Deformed	285.60 FL	*285.60 FL
9	1		*TAILLAMP -LH & RH	O/S Cut	966.40 FL	*483.20 FL
10	1		*TAILGATE	Distorted	1,342.60 FL	*1,342.60 FL
11	1		*TAILGATE LOCK	Damaged	389.50 FL	*389.50 FL
12	1		*TAILGATE LOCK SENSOR	Damaged	107.90 FL	*107.90 FL
13	1		*TAILGATE WEATHERSTRIPE	Cut	219.40 FL	*219.40 FL
14	1		*TAILGATE CHROME MOULDING	Cracked	327.70 FL	*327.70 FL
15	1		*TAILGATE INNER TRIM BOARD	Deformed	483.20 FL	*483.20 FL
16	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	30.00 FL	*30.00 FL
17	1		*TAILGATE REFLECTOR -LH & RH	O/S Cut	562.80 FL	*281.40 FL
18	1		*TAILGATE GLASS MOULDING	Necessary	246.00 FL	*246.00 FL
19	1		*TOYOTA LOGO	Necessary	66.50 FL	*66.50 FL
20	1		*VALVE MATIC EMBLEM	Necessary	68.00 FL	*68.00 FL
21	2		*REAR FENDER INNER TRIM BOARD -LH & RH	Not Necessary	1,497.40 FL	*- FL
22	2		*SETS REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	60.00 FL	*- FL
23	1		*REAR EXHAUST PIPE	Not Necessary	794.40 FL	*- FL
24	1		*REAR EXHAUST MOUNTING	Not Necessary	65.30 FL	*- FL
25	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
26	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
27	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
28	1		*REAR CAMERA	Not Necessary	580.00 FS	*- FS
29	1		*FLOOR PANEL TOP BOARD	Not Necessary	561.60 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,130.10	6,066.90
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,537.53	1,436.73
Total Parts (\$\$)	8,592.57	4,630.17

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCKING & PULL OUT REAR PORTION & RENEW ABOVE PARTS	New	1,200.00	800.00
2	TO PUTTY & SPRAY UP PAINT WORKS	New	1,200.00	800.00
3	TO CHECK WIRING	New	50.00	30.00
4	TO UNDERSEAL	New	150.00	40.00
5	TO REMOVE REVERSE SENSOR	New	100.00	50.00
6	TO REMOVE REAR CAMERA	New	100.00	50.00
7	TO TRANSFER TAILGATE FITTINGS	New	150.00	80.00
8	TO REMOVE TAILGATE GLASS	New	180.00	120.00
9	TO REMOVE EXHAUST PIPE	New	150.00	0.00
10	TO REMOVE UPHOLSTERY	New	150.00	60.00
Gross Labour Cost (S\$)			3,430.00	2,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >