

ASS. REC. BY:

REF: CS/FCI18010891/TI9d3/n2 Special Instruction:

Surveyor:

CWS

ASSIGNMENT (Office)

From (Person): Lurene jaw

of FCI

Date/Time: 14/6/18 @ 6.20pm

Estimated Cost:

Bill to:

OD / ~~FP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLQ 8586S

Insured: SHB 2249G

at Workshop m/s: Cycle & Carriage Kia

Tel: 6568 4501

of 209 Pandan Gardens

Policy No: D-18088937MFSH

Claim No: D18004707MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 09/06/2018

CA / REV / REP. / REV 24 HRS (PS)

22.062018 @ 10.30am owner waiting

H.O.D. Endorsement:

Date/Time: 9.03am @ 14/6/18

Person Contacted:

Don Bong

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLQ 8586S-X
	SHB 2249G-CC3/AIC/17026458/Klyb3q2 DOA: 23/10/17
22/6/18 @ 1.42pm	Varised to Lurene by email.
15/1/19 @ 5.30pm	confirmed with Jo Jo Anal fig 84219, 5 days.
	(Red 87242, 63%)

REF: FCI

ASSIGNMENT

From:

Date:

22/6/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLQ 8586S

at Workshop m/s

Cycle & Carriage Kira
209 Pandan Gardens

of

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

10:30am @ owner waiting


Make of Veh:

Don Bong

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

up

Vehicle: IN / OUT

Date:

Person Contacted:

Don.

Veh No:

SLQ 8586S

Yr Regn:

217 July

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Kia Soneto

C.C.

299

Colour:

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading:

12243

T/Radio:

Insured / Std / NI / NA

Eng/No:

KNAPH81BM45366925

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

235/55R19

R:

22

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Kumho

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

22/6/18 @ 11am

Survey held at

C&C Pandan Garden

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 17 JAN 2019

Date/Time File Pass to?



: Preli. Report

1) 17/1 11:00am



: Final Report

Date/Time File Return to?

Days Of Repair:

5

Resurvey No. of Trip:

1

Survey Fee:

Transportation

) S + RE) SI

1 Photos

1 Others

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Report Format :

TP

Lump Sum / I.B.I. (\$

4219

170+15

50

50

42

327



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18004707MFSH

Date: 27 June 2018

Our Ref: CS/FCI18010891/T1qd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLQ 8586S

Please be informed that we had conducted the inspection of the abovementioned vehicle on 22/06/2018 at the premises of M/s CYCLE & CARRIAGE, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>11,461.00</u>
Revised Estimate Amount	: S\$ <u>3,827.00</u>
"Check" Items Amount	: S\$ <u>1,589.00</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

Taufikh
Automotive Assessor

MOTOR SURVEY ASSIGNMENT**Date** 13-06-2018 **Our Ref No.** D18004707MFSH**Accident Date** 09-06-2018 **Claim Type.** Third Party**Insured Vehicle** SHB2249G **Third Party Vehicle.** SLQ8586S**Survey Location** 209 PANDAN GARDENS**Contact Person.** DON BONG**Contact No.** 65684501/0 **Fax No.** 65651240**Survey Type** DIRECT SETTLEMENT:**Appointed Surveyor** LKK AUTO CONSULTANTS PTE LTD**Contact Person** NA **Fax No.** 68416315**Contact Number.** NA**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST**Cc : Workshop** CYCLE & CARRIAGE KIA
PTE LTD **Attention.** NIL**Cc : TP Solicitor** NA **TP Solicitor Fax No.** NA**Officer Incharge** LURENE**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/241409)



PRI Documents



Close



PRI Header Details

Claim No	D18004707MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & CYCLE & (
Workshop Name	CYCLE & CARRIAGE KIA PTE LTD (Contact Person : DON BONG)	Survey Location & Contact Details	209 PANDAN GARDENS Mobile: 0 , Phone: 65684501 , Fax: 65651240 EmailId: KIONGHUA.BONG@CYCLECARRIAGE.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHB2249G	TP Vehicle No	SLQ8586S
PRI Recieved Date	13-06-2018 03:28:05 PM	Surveyor Appointed Date	13-06-2018 06:19:40 PM	Surveyor Accept Date	14-06-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	14-06-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 15 January 2019 5:30 PM
To: 'Cheng Jo Jo'; Taufikh (LKKAUTO); Mei Kwan (LKKAUTO); Admin A; Admin-D (LKKAUTO)
Cc: Songcuan JR Lauro Araos; Loi Ai Ting; Andre Chow En De
Subject: RE: FINALISE - SLQ8586S (KIA) - TP FIRST CAPITAL / DOA: 09/06/2018

Dear Jo Jo,

WITHOUT PREJUDICE

Confirm final fig \$4,219.00 before GST and 5 repair days.

Kindly send the relevant documents to First Capital Insurance.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Cheng Jo Jo <jojo.cheng@cyclecarriage.com.sg>
Sent: Monday, 7 January 2019 3:06 PM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; Mei Kwan (LKKAUTO) <Meikwan@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Cc: Songcuan JR Lauro Araos <lauro.songcuan@cyclecarriage.com.sg>; Loi Ai Ting <aiting.loi@cyclecarriage.com.sg>; Andre Chow En De <andre.chow@cyclecarriage.com.sg>
Subject: FINALISE - SLQ8586S (KIA) - TP FIRST CAPITAL / DOA: 09/06/2018

Hi Taufikh,

Attached file for your kind perusal.

Kindly confirm finalise amount at \$ 4,514..33 after GST.

Best Regards,

JoJo Cheng
Customer Service



Exceptional Journeys

Cycle & Carriage Singapore • 209 Pandan Gardens, Singapore 609339
T: +65 6568 4554 • F: +65 6565 1240 • www.cyclecarriage.com.sg

 A member of the Jardine Cycle & Carriage Group

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 27 June 2018 1:42 PM
To: 'Claim Workflow System'; assignments
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18004707MFSH/1
Attachments: CSFCI18010891T1qd3.pdf

Dear Lurene,

Enclosed herewith preliminary advice of SLQ 8586S.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 14 June 2018 3:36 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18004707MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 13 June 2018 6:19 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18004707MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System



CERTIFICATE OF INSURANCE

KIA AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : KOO E CHOONG
 Period of Insurance : 25 Jul 2017 To 24 Jul 2018
 Engine No. : D4HBHH324848
 Chassis No. : KNAPH81BMH5366925

Vehicle No. : SLQ8586S
 Policy No. : 1700030001
 Endorsement No. :
 Issued Date : 03 Aug 2017

ABOUT THE COVER

Make/Model : KIA SORENTO 2.2 A DIESEL

Engine Capacity/Tonnage : 2,199.00 CC

Driver Restriction : NA

Sum Insured : Market Value

Off Peak Car : No

First Year of Registration : 2017

Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive* :

a) The Policyholder

b) Any other person who is driving on the Policyholder's order or with his/her permission

This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDER") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the damage of goods other than empties in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use (15 days) 150000 + 160000

* Uninsured Roadside Repatriation by Section 5 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia) are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$300 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

KOO E CHOONG - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Cycle & Carriage Body & Paint Centre Add: 379 Pandan Gardens Singapore 659339 65994501

2 Cycle & Carriage Customer Service Centre (For Windscreen claim only) Add: 241 Alexandra Road Singapore 159931 64278800

3 Cycle & Carriage Customer Service Centre (For windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6336 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: Standard Chartered Bank (Singapore) Limited

We hereby certify that this policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0500709915

CYCLE & CARRIAGE - GRACIE(KIA)

219 ALEXANDRA ROAD

SINGAPORE 159930 ANSP-MOTOR

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Signature

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

1000259960/AC4/Doc4

REPUBLIC OF SINGAPORE DRIVING LICENCE


 Licence Number: **S7223258E**
 Name: **KOO E CHOONG**
 Birth Date: **12 Mar 1972**
 Issue Date: **08 Jul 2003**

Barcode: 000639274E

FOR C&C USE ONLY

REPUBLIC OF SINGAPORE


 IDENTITY CARD NO. **S7223258E**
古裕聰
 CHINESE
 Date of Birth: **12-03-1972** Sex: **M**
 Country of Birth: **SINGAPORE**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms
 PASS DATE: **10 May 1993**

NP 428A

Barcode: Licence No: S7223258E

FOR C&C USE ONLY

2169654

Barcode: NRIC No: **S7223258E**


 Blood Group: **O+** Date of issue: **20-06-1994**
APT BLK 316A ANG MO KIO STREET 31 #22-513
SINGAPORE 562316
 NRIC No: **S7223258E** Date: **20-06-2006** No: **5467033**



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
MR KOO E CHOONG	Cust No/Name /MR KOO E CHOONG
BLK 316A ANG MO KIO ST 31	Reg No/Reg Date SLQ8586S / 25/07/201
#22-313	Date In/Mileage / 0
SINGAPORE 562316	Chassis No KNAPH81BMH5366925
Contact No Mobile: 90489848	Engine No D4HBHH324848
	Make/Model KIA/SORENTO2.2ASXSRGBV3
	Colour/Trim ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00081	Cash	11/06/2018/ 10:59	QUD	247 / DonBong	30159		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							1650 2200.00
RENEW ACCIDENT DAMAGED PARTS ON REAR TAILGATE, REAR BUMPER FACE, REPAIR REAR END PANEL							117 X 300.00
E PNT88000							117 X 80.00
REMOVE AND INSTALL REAR WINDSCREEN GLASS							80 100.00
M SUNDRY							117 X 400.00
SUPPLY WINDSCREEN SEALANT							840 1680.00
E PNT88000							✓ 50.00
REMOVE AND INSTALL PARKING ASSIST							117 X 160.00
E PNT88000							✓ 200.00
TRANSFER REAR TAILGATE MECHANISM, TRIM AND OTHERS ATTACHMENT TO NEW PANEL							60 120.00
E PNT98000							117 X 40.00
PAINT WORK SPRAY REAR END PANEL, REAR TAILGATE, REAR BUMPER AND AFFECTED PORTION							20 50.00
A 54900099							117 X 1445.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM							117 X 690.00
M SUNDRY							117 X 28.00
APPLY BODY SEALANT							117 X 69.00
A 10028901							117 X 37.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							
M SUNDRY							
PERFORM RUST PREVENTION							
M SUNDRY							
SUPPLY C&C LOGO							
M SUNDRY							
SUNDRIES							
M	PANEL ASSY-TAIL GATE			1.00	1445.00	00.00	117 X 1445.00
M	GLASS ASSY-TAIL GATE			1.00	690.00	00.00	117 X 690.00
M	EMBLEM-SORENTO			1.00	28.00	00.00	117 X 28.00
M	LOGO ASSY-KIA SUB			1.00	69.00	00.00	117 X 69.00
M	EMBLEM-ECO DYNAMICS			1.00	37.00	00.00	117 X 37.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



ESTIMATE

Co Req No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
MR KOO E CHOONG	Cust No/Name	/MR KOO E CHOONG
BLK 316A ANG MO KIO ST 31	Reg No/Reg Date	SLQ8586S / 25/07/201
#22-313	Date In/Mileage	/ 0
SINGAPORE 562316	Chassis No	KNAPH81BMH5366925
	Engine No	D4HBHH324848
Contact No Mobile: 90489848	Make/Model	KIA/SORENTO2.2ASXSRGBV3
	Colour/Trim	ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	11/06/2018/ 10:59	0UD	247 / DonBong	30159

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M RAIL ASSY-REAR BUMPER	1.00	392.00	00.00	✓ 392.00
M ANTENNA ASSY-SMARTKEY	1.00	53.00	00.00	? 53.00
M WIRING HARNESS-RR BUMPER	1.00	248.00	00.00	? 248.00
M BRACKET ASSY-RR BUMPER SIDE,LH	1.00	25.00	00.00	? 25.00
M BRACKET ASSY-RR BUMPER SIDE,RH	1.00	25.00	00.00	? 25.00
M BRACKET-RR BUMPER SIDE LWR,LH	1.00	18.00	00.00	? 18.00
M BRACKET-RR BUMPER SIDE LWR,RH	1.00	18.00	00.00	? 18.00
M BRACKET-RR BPR SIDE REINF,LH	1.00	18.00	00.00	? 18.00
M BRACKET-RR BPR SIDE REINF,RH	1.00	18.00	00.00	? 18.00
M COVER-RR BUMPER,UPR	1.00	696.00	00.00	R? 696.00
P COVER-RR BUMPER LWR	1.00	650.00	00.00	de 650.00
M SKID PLATE-RR BUMPER	1.00	103.00	00.00	de 103.00
M LAMP ASSY-REAR FOG,RH	1.00	129.00	00.00	x 129.00
M LAMP ASSY-REAR FOG,LH	1.00	129.00	00.00	x 129.00
M ULTRASONIC SENSOR-S.P.A.S	1.00	215.00	00.00	x 215.00
M ULTRASONIC SENSOR-S.P.A.S	1.00	215.00	00.00	y 215.00
M ULTRASONIC SENSOR-S.P.A.S	1.00	215.00	00.00	y 215.00
M ULTRASONIC SENSOR-S.P.A.S	1.00	215.00	00.00	? 215.00
M ULTRASONIC SENSOR-S.P.A.S	1.00	215.00	00.00	? 215.00
M ULTRASONIC SENSOR-S.P.A.S	1.00	215.00	00.00	? 215.00

SURVEYOR NAME: Tanjin 97495749

SURVEYOR SIGNATURE: _____

DATE: 22/6/18 @ 11am

REMARKS: Resurvey before paint

sur @ Wladimir.com

05 days

Auto Consultants hence notify

Repaier of the following:

Survival before/after spray painting

Imaged part(s) during resurvey

Is price: are subject to confirmation

Third party survey is on a "Without Prejudice" basis.

- No illegal modification(s) is allowed

- Supplement: any item(s) must be resurveyed and

is subject to final approval from Insurance Company

Confirm & accepted by

Structure

Nett

11.461.00

7% GST on	11461.00
-----------	----------

802.27

Total Payable

12,263.27

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

ADDITIONAL PARTS CHANGE

Car No: SLQ 858 6S WIP

S/No	Parts Name	? /Supp	CSA Sign	Photo Taken	Remarks
1	Reinforcement	? /Supp	<i>[Signature]</i>	<i>[Signature]</i>	
2		? /Supp			
3		? /Supp			
4		? /Supp			
5		? /Supp			
6		? /Supp			
7		? /Supp			
8		? /Supp			
9		? /Supp			
10		? /Supp			
11		? /Supp			
12		? /Supp			
13		? /Supp			
14		? /Supp			
15		? /Supp			
16		? /Supp			
17		? /Supp			
18		? /Supp			
19		? /Supp			
20		? /Supp			

TAKEN BY	
DATE	
PHOTO BEFORE PAINT	
PHOTO AFTER PAINT	
PHOTO OF DAMAGED PARTS (DPS)	
PHOTO OF CELLITE BENCH	
REMOVE & INSTALL ENGINE	
REMOVE & INSTALL DASHBOARD	
PHOTO B4 SUSP & U/C REMOVE	

Model: Sonoda 2.2
 Surveyor: tanish - LK



Exceptional Journeys

Surveyor : Taufikh
Company : LKK
DOA : 09/06/2018
CSE : Don

VEHICLE NO : SLQ8586S
MODEL : KIA/SORENTO 2.2 ASX SRGBV 3
WIP : 30159

Material	:	\$	1,279.00
Labour	:	\$	2,940.00
Sub-Total	:	\$	4,219.00
	:		
Less Excess	:	\$	-
Total	:	\$	4,219.00
GST 7%	:	\$	295.33
Grand Total	:	\$	4,514.33
Finalise By/Date	:	JoJo dtd 07/01/2019	

Email :

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 5 WORKING DAYS + 2 Days (1) Weekends
+ Days () Public Holiday
TOTAL DAYS REPAIR TOOK = 7

☒ TP Claim FIRST CAPITAL - SHB2249G

☐ Claim GIA / LTA fee

☒ Claim Loss ☐ Use ☒ Rental

☐ Claim Medical Fee / Others

☐ Third Party Report



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
MR KOO E CHOONG	Cust No/Name	/Koo E Choong
BLK 316A ANG MO KIO ST 31	Reg No/Reg Date	SLQ8586S / 25/07/2017
#22-313	Date In/Mileage	22/06/2018/ 12293
SINGAPORE 562316	Chassis/Package	KNAPH81BMH5366925 /KC17
Contact No Mobile: 90489848	Engine No	D4HBHH324848
22/06/	Make/Model	KIA/SORENTO2.2ASXSRGBV3
	Colour/Trim	ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00081	Cash	07/01/2019/ 14:54	TLD	881 / Jojo Cheng	30159		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							✓1650.00
RENEW DAMAGED PARTS ON REAR BUMPER FACE,REPAIR REAR TAILGATE							
E PNT88000							✓ 80.00
REMOVE AND INSTALL PARKING ASSIST							
E PNT98000							✓840.00
RESPRAY REAR TAILGATE, REAR BUMPER AND AFFECTED PORTION							
A 54900099							✓50.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM							
A 10028901							✓200.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST							
USING HI-SCAN PRO TEST							
M SUNDRY							✓60.00
PERFORM RUST PREVENTION							
M SUNDRY							✓40.00
SUPPLY C&C LOGO							
M SUNDRY							✓20.00
SUNDRIES							
X	EMBLEM-SORENTO			1.00	28.00	00.00	✓28.00
X	LOGO ASSY-KIA SUB			1.00	69.00	00.00	✓69.00
X	EMBLEM-ECO DYNAMICS			1.00	37.00	00.00	✓37.00
X	RAIL ASSY-REAR BUMPER			1.00	392.00	00.00	✓392.00
X	COVER-RR BUMPER LWR			1.00	650.00	00.00	✓650.00
X	SKID PLATE-RR BUMPER			1.00	103.00	00.00	✓103.00
Z	TEXT						
FIRST CAPITAL TP CLAIM SHB2249G							
DOA: 09/06/2018							
SURVEYOR: TAUFIKH LKK 22/06/2018							
"Guarantee your warranty, maintain with Cycle & Carriage."							

This is not an official tax invoice.
This is a computer generated document, no signature is required.

Car No: SLQ 85865 WIP ADDITIONAL PARTS CHANGE

S/No	Parts Name	? /Supp	CSA Sign	Photo Taken	Remarks
1	Reubornant <i>PR</i>	? /Supp	<i>PR 25/01</i>		
2		? /Supp			
3		? /Supp			
4		? /Supp			
5		? /Supp			
6		? /Supp			
7		? /Supp			
8		? /Supp			
9		? /Supp			
10		? /Supp			
11		? /Supp			
12		? /Supp			
13		? /Supp			
14		? /Supp			
15		? /Supp			
16		? /Supp			
17		? /Supp			
18		? /Supp			
19		? /Supp			
20		? /Supp			

DATE	TAKEN BY
PHOTO BEFORE PAINT	
PHOTO AFTER PAINT	
PHOTO OF DAMAGED PARTS (DPS)	
PHOTO OF CELLITE BENCH	
REMOVE & INSTALL ENGINE	
REMOVE & INSTALL DASHBOARD	
PHOTO B4 SUSP & U/C REMOVE	

Model: Sonoma 2.2
 Surveyor: tasketh - LKX



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18010891/T1qd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 17-01-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 2249G	Veh. Inspected	SLQ 8586S	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18004707MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	14/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	KIA SORENTO	c.c	2199	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	KNAPH81BMH5366925	Colour	GREY	
Odometer	12293	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/55 R19	KUMHO	6 mm	
L/H Front Tyre	235/55 R19	KUMHO	6 mm	
R/H Rear Tyre	235/55 R19	KUMHO	6 mm	
L/H Rear Tyre	235/55 R19	KUMHO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/06/2018	Inspection Date	22/06/2018	
Survey held at	CYCLE & CARRIAGE KIA PTE LTD 209 PANDAN GARDENS SINGAPORE 609339			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 8586S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	PANEL ASSY-TAIL GATE (SN)	TO REPAIR SEE LABOUR	1,445.00	-
1	GLASS ASSY-TAIL GATE (SN)	NOT NECESSARY	690.00	-
1	EMBLEM-SORENTO (SN)	NECESSARY	28.00	28.00
1	LOGO ASSY-KIA SUB (SN)	NECESSARY	69.00	69.00
1	EMBLEM-ECO DYNAMICS (SN)	NECESSARY	37.00	37.00
1	RAIL ASSY-REAR BUMPER (SN)	BENT	392.00	392.00
1	ANTENNA ASSY-SMARTKEY (SN)	NOT NECESSARY	53.00	-
1	WIRING HARNESS-RR BUMPER (SN)	NOT NECESSARY	248.00	-
1	BRACKET ASSY-RR BUMPER SIDE,LH (SN)	NOT NECESSARY	25.00	-
1	BRACKET ASSY-RR BUMPER SIDE,RH (SN)	NOT NECESSARY	25.00	-
1	BRACKET-RR BUMPER SIDE LWR,LH (SN)	NOT NECESSARY	18.00	-
1	BRACKET-RR BUMPER SIDE LWR,RH (SN)	NOT NECESSARY	18.00	-
1	BRACKET-RR BPR SIDE REINF,LH (SN)	NOT NECESSARY	18.00	-
1	BRACKET-RR BPR SIDE REINF,RH (SN)	NOT NECESSARY	18.00	-
1	COVER-RR BUMPER,UPR (SN)	TO REPAIR SEE LABOUR	696.00	-
1	COVER-RR BUMPER,LWR (SN)	DEFORMED	650.00	650.00
1	SKID PLATE-RR BUMPER (SN)	DEFORMED	103.00	103.00
1	LAMP ASSY-REAR FOG,RH (SN)	NOT NECESSARY	129.00	-
1	LAMP ASSY-REAR FOG,LH (SN)	NOT NECESSARY	129.00	-
1	ULTRASONIC SENSOR-S.P.A.S (SN)	NOT NECESSARY	215.00	-
1	ULTRASONIC SENSOR-S.P.A.S (SN)	NOT NECESSARY	215.00	-
1	ULTRASONIC SENSOR-S.P.A.S (SN)	NOT NECESSARY	215.00	-
1	ULTRASONIC SENSOR-S.P.A.S (SN)	NOT NECESSARY	215.00	-
1	ULTRASONIC SENSOR-S.P.A.S (SN)	NOT NECESSARY	215.00	-
1	ULTRASONIC SENSOR-S.P.A.S (SN)	NOT NECESSARY	215.00	-
1	WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	BODY SEALANT (SN)	NOT NECESSARY	160.00	-
1	C&C LOGO (SN)	NECESSARY	40.00	40.00

Report Ref No. CS/FCI18010891/T1qd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
			6,411.00	1,339.00
	LABOUR			
	RENEW ACCIDENT DAMAGED PARTS ON REAR TAILGATE, REAR BUMPER FACE, REPAIR REAR END PANEL, INCLUSIVE OF THE REPAIR OF PANEL ASSY-TAIL GATE AND COVER-RR BUMPER, UPR.		2,200.00	1,650.00
	REMOVE AND INSTALL REAR WINDSCREEN GLASS.	NOT NECESSARY	300.00	-
	REMOVE AND INSTALL PARKING ASSIST.		100.00	80.00
	TRANSFER REAR TAILGATE MECHANISM, TRIM AND OTHERS ATTACHMENT TO NEW PANEL.	NOT NECESSARY	400.00	-
	PAINT WORK SPRAY REAR END PANEL, REAR TAILGATE, REAR BUMPER AND AFFECTED PORTION.		1,680.00	840.00
	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM.		50.00	50.00
	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST.		200.00	200.00
	PERFORM RUST PREVENTION.		120.00	60.00
			5,050.00	2,880.00
	GRAND TOTAL		11,461.00	4,219.00
RECOMMENDED COST OF REPAIRS				4,219.00

Report Ref No. CS/FCI18010891/T1qd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.