

ASS. REC. BY:

REF: CS/EGI 18010893/Tied3ⁿ² Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Yee Pei Si of EGI Date/Time: 14/6/18 @ 10:31am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLQ 6344L Insured: XB 8081 T

at Workshop m/s Cycle & Carriage Kga Tel: 6568 4567

of 209 Pandan Gardens

Policy No: Claim No: XD 8081 T / RH/p1

Sum Insured: Excess:

Make of Veh: D.O.A. 12/06/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

20062018 @ 3pm- 5pm

H.O.D. Endorsement:

Date/Time: 11:57am @ 14/6/18

Person Contacted: COCO

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLQ 6344L - X
	XB 8081 T - X

REF: EGI

ASSIGNMENT

From:

Date:

20/06/2018

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLQ 6344L

at Workshop n/s

Cycle & Carriage Kia
209 Pandan Gardens

Insured

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

3pm - 5pm

Make of Veh:

COCO B 6568 4567

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res: Yes or No

Lum Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLQ 6344L

Yr Regn:

2017, July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Kia Forte 1.3

C.C.

1591

Colour:

Red.

A/C:

Insured / Std / NI / NA

Sp. Reading:

15038

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KNA FJ411 MJS 725370

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65K15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Nexen

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

20/6/18 @ 1730

Survey held at

CSC Pandan

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

22/1/19

44951, 5 days email w/s Soja. (Red 31491, 4420)

RECEIVED 20 MAR 2019

Date/Time: File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time: File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

-

Survey Fee:

Transportation

1) \$ + RS \$

1) Photos:

1) Others:

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Ins (\$)

☐

Weekend (\$)

250

TOTAL

Report Format:

TP

Lump Sum / (B): (\$)

H451.00

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Thursday, 14 June 2018 10:34 AM
To: 'admin-d@lkkauto.com'
Cc: ASSIGNMENTS@LKKAUTO.COM
Subject: OI : XB8081T / TP : SLQ6344L/LKK / DOA : 12/06/2018
Attachments: XB8081T - SAS.pdf; SLQ6344L - SAS.pdf; SLQ6344L - ESTIMATE.pdf; SLQ6344L - PRS FORM.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **CYCLE & CARRIAGE KIA PTE LTD.**

ADDRESS : 209 PANDAN GARDENS
SINGAPORE 609339

PERSON TO CONTACT : COCO LU TING @ 6568 4567

ERGO OFFICER-IN-CHARGE : ROHAINI

Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate, insured and TP's SAS (**note: reports not to be released to any Third Party**).

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel : 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

Date: 13.06.2018
Our Reference: XB 8081T/RH/pl
Your Reference: SLQ 6344L

Sent via Fax

or

Email

coco.lu@cyclecarriage.com.sg

To: CYCLE & CARRIAGE KIA PTE LTD

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SLQ 6344L
Insured's Vehicle: XB 8081T
Date Of Accident: 12.06.2018

We acknowledge receipt of your request for PRS on: 12.06.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* LKK

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

☐	Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
☐	Your request for inspection does not have your client's GIA report, kindly forward a copy.
☐	We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
☐	Our Insured's driver has not reported the accident to us to date.
☒	Others: <u>We write to confirm our agreement to have a direct settlement of this claim with quantum to be agreed. OFFICER-IN-CHARGE - ROHAINI</u>

Prepared by:	<u>Pei Li</u>	6829 9194	claims@ergo.com.sg
Signature:	<u>[Signature]</u>		FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____

Inspector: _____

☒ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job.

Workshop Acknowledgement & Stamp

Note: Our inspection is on a without admission to liability basis.



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9514H
Vehicle Details	
Vehicle No.:	SLQ6344L
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Mar 2019
Vehicle Make:	KIA
Vehicle Model:	FORTE K3 1.6A
Primary Colour:	Red
Manufacturing Year:	2017
Engine No.:	G4FGGH636769
Chassis No.:	KNAFJ411MJ5725370
Maximum Power Output:	95.3 kW (127 bhp)
Open Market Value:	\$12,073.00
Original Registration Date:	18 Jul 2017
First Registration Date:	18 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$12,073.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Jul 2027
PARF Rebate Amount:	\$9,054.00
Intended COE Rebate Details	
COE Expiry Date:	17 Jul 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$42,801.00
COE Rebate Amount:	\$35,625.00
Total Rebate Amount:	\$44,679.00

The information contained herein is correct as at 20 Mar 2019

OK

KIA AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Lim Hui Wen
Period of Insurance : 18 Jul 2017 To 17 Jul 2018
Engine No. : G4FGGH636769
Chassis No. : KNAFJ411MJ5725370

Vehicle No. : SLQ6344L
Policy No. : 1700025856
Endorsement No. :
Issued Date : 28 Jul 2017

ABOUT THE COVER

Make/Model : KIA Cerato K3 1.6 EX
Engine Capacity/Tonnage : 1,591.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2017
Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive*

1. The Policyholder
 2. Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorized driver only if he/she meets the specified age condition.
 *You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDER") if you are or Your Authorized Driver named or unnamed is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, roadwork, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use (15 days) 1500cc - 1800cc

* Limitations required in accordance with Section 5 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 109) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Lim Hui Wen - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Body & Paint Centre, Add: 209 Pandan Gardens Singapore 609339 65934501
2. Cycle & Carriage Customer Service Centre (For Windscreen claim only), Add: 241 Alexandra Road Singapore 159331 64276900
3. Cycle & Carriage Customer Service Centre (For Windscreen claim only), Add: 303 Ubi Rd 3 Singapore 400660 67491903

For other Approved Reporting Centres/AIG Authorized Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: Standard Chartered Bank

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 109), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0500710050

C&C FULCO-CORP SALES
 22 UBI ROAD 4 FULCO BUILDING
 SINGAPORE 408617 ANSP - MOTOR

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S8629514H**

Name: **LIM HUI WEN**

Birth Date: **01 Oct 1986**
Issue Date: **09 Apr 2009**

001726261H

FOR C&C USE ONLY

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S8629514H**

Name: **LIM HUI WEN**

林惠文

Race: **CHINESE**

Date of Birth: **01-10-1986** Sex: **M**

Country/Place of Birth: **SINGAPORE**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3: Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg

PASS DATE: **09 Apr 2009**

Licence No: **S8629514H**

NP 428A

FOR C&C USE ONLY

5669345

S8629514H

NRIC No: **S8629514H**

Date of issue: **07-11-2016**

Address: **APT BLK 252 HOUGANG AVENUE 3
#07-356
SINGAPORE 530252**

Yes, U Can!

On 12/6/18 at about 9:00am, I could not stop my
vehicle on time. Therefore I collided with the vehicle in front of
me SLQ63496. We remained at the side of the road and
exchanged our particulars. No mutually agreed no one was
injured.

Driver:
ZHENG YANPING
G2373041W
郑炎平

VICTIM DRIVER
Lin Hu Wen
S8629514X

林胡文

Dawood (boss of Kien Hock Pte L+D)
81837608

9am, 12/6/18
XC88081T
Zhang Yanping (G2373041W)
M: 84336798
Company: Kien Hock Construction



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Lim Hui Wen	Cust No/Name LCV04135/MR LIM HUI WEN
B1k 252 Hougang Ave 3	Reg No/Reg Date SLQ6344L / 18/07/201
#07-356	Date In/Mileage / 0
Singapore 530252	Chassis No KNAFJ411MJ5725370
Contact No	Engine No G4FGGH636769
	Make/Model KIA/FORTE K3 1.6 A L 189
	Colour/Trim K3R TEMPTATION RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LCV04135	CRDVCH	12/06/2018/ 12:34	TLC	442 / CocoLu	30249
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	TO RENEW REAR BUMPER, BOOTLID, REPAIR REAR END PANEL				1100 2200.00
E PNT98000	TO SPRAY PAINT FOR REAR BUMPER, BOOTLID, REAR END PANEL <i>T. photo</i>				1840 1680.00
E PNT88000	TO REMOVE & INSTALL PARKING SENSOR				60 100.00
M SUNDRY	C&C LOGO				30.00
A 90000001	TO CHECK WIRING & ELECTRICAL SYSTEM				20.00
A 90000001	TO CONDUCT DIAGNOSTIC CHECK FOR THE CAR SYSTEM				200.00
M SUNDRY	TO APPLY SEALANT FOR ACCIDENT PORTION				40.00
M SUNDRY	REAR NUMBER PLATE WITH FRAME				50.00
M SUNDRY	Sundry				20.00
P COVER-RR BUMPER		1.00	688.00	00.00	688.00
M BEAM-RR BUMPER		1.00	318.00	00.00	318.00
M STAY-RR BUMPER RH		1.00	120.00	00.00	120.00
M STAY-RR BUMPER LH		1.00	120.00	00.00	120.00
M COVER-RR BUMPER,CTR		1.00	347.00	00.00	347.00
M BRACKET-RR BUMPER SIDE MTG,RH		1.00	29.00	00.00	29.00
M BRACKET-RR BUMPER SIDE MTG,LH		1.00	29.00	00.00	29.00
P PANEL ASSY-TRUNK LID		1.00	1297.00	00.00	1297.00
M LATCH ASSY-TRUNK LID		1.00	112.00	00.00	112.00
M W/STRIP-TRUNK LID OPNG		1.00	100.00	00.00	100.00
M LAMP ASSY-REAR COMB INSIDE,RH		1.00	242.00	00.00	242.00
M LAMP ASSY-REAR COMB INSIDE,LH		1.00	242.00	00.00	242.00
M LAMP ASSY-REAR COMBINATION,LH		1.00	354.00	00.00	354.00
M LAMP ASSY-REAR COMBINATION,RH		1.00	354.00	00.00	354.00
M LAMP ASSY-LICENSE PLATE,LH		1.00	18.00	00.00	18.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Lim Hui Wen	Cust No/Name	LCV04135/MR LIM HUI WEN
Blk 252 Hougang Ave 3	Reg No/Reg Date	SLQ6344L / 18/07/201
#07-356	Date In/Mileage	/ 0
Singapore 530252	Chassis No	KNAFJ411MJ5725370
Contact No	Engine No	G4FGGH636769
	Make/Model	KIA/FORTE K3 1.6 A L 189
	Colour/Trim	K3R TEMPTATION RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LCV04135	CRDVCH	12/06/2018/ 12:34	TLC	442 / CocoLu	30249

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M LAMP ASSY-LICENSE PLATE,RH	1.00	18.00	00.00	18.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

SURVEYOR NAME: Tan Jun 97495749

SURVEYOR SIGNATURE: [Signature]

DATE: 20/6/18 @ 1730

REMARKS: Resurvey before paint
sent @ lkkauto.com
At 5 days.

Confirm & accepted by

Nett	8,728.00
7% GST on	8728.00
Total Payable	9,338.96

Authorized signatory and company stamp

8900.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Exceptional Journeys

Surveyor : Taufikh
Company : LKK
DOA : 12/06/2018
CSE : Coco

VEHICLE NO : SLQ6344L
MODEL : KIA/FORTE K3 1.6 A L189
WIP : 30249

Material	:	\$	2,556.00
Labour	:	\$	2,395.00
Sub-Total	:	\$	4,951.00
	:		
Less Excess	:	\$	-
Total	:	\$	4,951.00
GST 7%	:	\$	346.57
Grand Total	:	\$	5,297.57
Finalise By/Date	:	JoJo dtd 07/01/2019	

Email :

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 5 WORKING DAYS + 2 Days (1) Weekends
+ Days () Public Holiday
TOTAL DAYS REPAIR TOOK = 7


☒ TP Claim Ergo - XB8081T

☐ Claim GIA / LTA fee \$ 2.00

☒ Claim Loss ☐ Use ☒ Rental

☐ Claim Medical Fee / Others

☐ Third Party Report



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
MR LIM HUI WEN	Cust No/Name LCVO4135/LIM HUI WEN
BLK 252 HOUGANG AVE 3	Reg No/Reg Date SLQ6344L / 18/07/2017
#07-356	Date In/Mileage 20/06/2018/ 13568
SINGAPORE 530252	Chassis/Package KNAFJ411MJ572537C /KCX17
Contact No Mobile: 91126890	Engine No G4FGGH636769
20/06/	Make/Model KIA/FORTE K3 1.6 A L 189
	Colour/Trim K3R TEMPTATION RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CTP00080	Cash	07/01/2019/ 15:18	TLC	881 / Jojo Cheng	30249			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								1100.00
RENEW REAR BUMPER, BOOTLID								840.00
E PNT98000								60.00
RESPRAY PAINT FOR REAR BUMPER, BOOTLID								30.00
E PNT88000								20.00
TO REMOVE & INSTALL PARKING SENSOR								200.00
M SUNDRY								40.00
SUPPLY C&C LOGO								20.00
A 90000001								85.00
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								688.00
A 90000001								1297.00
TO CONDUCT DIAGNOSTIC CHECK FOR THE CAR SYSTEM								242.00
M SUNDRY								242.00
APPLY SEALANT FOR AFFECTED PORTION								37.00
M SUNDRY								15.00
SUNDRY								35.00
S SPECIALISTJOB								
WO: T148990 ACCIDENT TOWING FROM HOUGANG AVE3 TO PG CNC - Supp					1.00	688.00	00.00	688.00
X COVER-RR BUMPER					1.00	1297.00	00.00	1297.00
X PANEL ASSY-TRUNK LID					1.00	242.00	00.00	242.00
X LAMP ASSY-REAR COMB INSIDE,RH					1.00	242.00	00.00	242.00
X LAMP ASSY-REAR COMB INSIDE,LH					1.00	37.00	00.00	37.00
X LOGO ASSY-KIA SUB					1.00	15.00	00.00	15.00
X EMBLEM K3					1.00	35.00	00.00	35.00
X EMBLEM-CERATO								
Z TEXT								
ERGO TP CLAIM XB8081T								
DOA: 12/06/2018								
SURVEYOR: TAUFIKH LKK 20/06/2018								
"Guarantee your warranty, maintain with Cycle & Carriage."								
Parts	2,556.00					Nett		4,951.00
Labour	2,220.00				7% GST on	4951.00		346.57
Standard Menu	0.00							
Specialist Job	85.00					Total Payable		5,297.57
Diagnostics Job	0.00							
Sundry/Others	90.00							
Total(w/o GST)	4,951.00							

This is not an official tax invoice.
This is a computer generated document, no signature is required.

SUPPLEMENTARY

INSURANCE CO : ERGO INSURANCE PTE LTD

REGISTRATION NO : SLQ6344L

S/N	Description	Qty	Unit Price	Disc%	Amount
<u>PARTS</u>					
1	LOGO ASSY-KIA SUB	1.00	37.00	0.00	37.00
2	EMBLEM K3	1.00	15.00	0.00	15.00
3	EMBLEM-CERATO	1.00	35.00	0.00	35.00
Total Parts					87.00
<u>LABOUR</u>					
1	TOWING FROM HOUGANG AVE 3 TO PG CNC	1.00	85.00	0.00	85.00
Total Parts & Labour					172.00
7 % GST					12.04
Grand Total					<u>184.04</u>

Thank You.

Yours faithfully

CYCLE & CARRIAGE KIA PTE LTD

JoJo Cheng

Customer Service

Tel : +65 6568 4554

ADDITIONAL PARTS CHANGE

Car No: SLR 6344L WIP 30249

S/No	Parts Name	? /Supp	CSA Sign	Photo Taken	Remarks
1	logo	? /Supp	<i>[Signature]</i>	<i>[Signature]</i>	
2	k3 emblem	? /Supp			
3	forte	? /Supp	22.6.2018	20/6/18 Cagcam	
4		? /Supp			
5		? /Supp			
6		? /Supp			
7		? /Supp			
8		? /Supp			
9		? /Supp			
10		? /Supp			
11		? /Supp			
12		? /Supp			
13		? /Supp			
14		? /Supp			
15		? /Supp			
16		? /Supp			
17		? /Supp			
18		? /Supp			
19		? /Supp			
20		? /Supp			

✓	PHOTO BEFORE PAINT	DATE	TAKEN BY
	PHOTO AFTER PAINT	20/6/18	Andr Cag Cam
	PHOTO OF DAMAGED PARTS (DPS)		
	PHOTO OF CEILITE BENCH		
	REMOVE & INSTALL ENGINE		
	REMOVE & INSTALL DASHBOARD		
	PHOTO B4 SUSP & U/C REMOVE		

Model: k3

Surveyor: Taufik



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EG18010893/T1cd3n2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 20-03-2019		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XB 8081T	Veh. Inspected	SLQ 6344L	
Policy No.		Coverage (\$)	0.00	
Claim No.	XB8081T/RH/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	14/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	KIA FORTE K3	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	KNAFJ411MJ5725370	Colour	RED	
Odometer	15038	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	NEXEN	6 mm	
L/H Front Tyre	195/65 R15	NEXEN	6 mm	
R/H Rear Tyre	195/65 R15	NEXEN	6 mm	
L/H Rear Tyre	195/65 R15	NEXEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/06/2018	Inspection Date	20/06/2018	
Survey held at	CYCLE & CARRIAGE KIA PTE LTD 209 PANDAN GARDENS SINGAPORE 609339			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 6344L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	COVER-RR BUMPER (SN)	DEFORMED	688.00	688.00
1	BEAM-RR BUMPER (SN)	NOT NECESSARY	318.00	-
1	STAY-RR BUMPER RH (SN)	NOT NECESSARY	120.00	-
1	STAY-RR BUMPER LH (SN)	NOT NECESSARY	120.00	-
1	COVER-RR BUMPER,CTR (SN)	NOT NECESSARY	347.00	-
1	BRACKET-RR BUMPER SIDE MTG,RH (SN)	NOT NECESSARY	29.00	-
1	BRACKET-RR BUMPER SIDE MTG,LH (SN)	NOT NECESSARY	29.00	-
1	PANEL ASSY-TRUNK LID (SN)	BENT	1,297.00	1,297.00
1	LATCH ASSY-TRUNK LID (SN)	NOT NECESSARY	112.00	-
1	W/STRIP-TRUNK LID OPNG (SN)	NOT NECESSARY	100.00	-
1	LAMP ASSY-REAR COMB INSIDE,RH (SN)	CRACKED	242.00	242.00
1	LAMP ASSY-REAR COMB INSIDE,LH (SN)	CRACKED	242.00	242.00
1	LAMP ASSY-REAR COMBINATION,LH (SN)	NOT NECESSARY	354.00	-
1	LAMP ASSY-REAR COMBINATION,RH (SN)	NOT NECESSARY	354.00	-
1	LAMP ASSY-LICENSE PLATE,LH (SN)	NOT NECESSARY	18.00	-
1	LAMP ASSY-LICENSE PLATE,RH (SN)	NOT NECESSARY	18.00	-
1	LOGO ASSY-KIA SUB (ADDITIONAL)(SN)	NECESSARY	37.00	37.00
1	EMBLEM K3 (ADDITIONAL)(SN)	NECESSARY	15.00	15.00
1	EMBLEM-CERATO (ADDITIONAL)(SN)	NECESSARY	35.00	35.00
1	SUNDRY (SN)	NECESSARY	20.00	20.00
1	REAR NUMBER PLATE WITH FRAME (SN)	NOT NECESSARY	50.00	-
1	C&C LOGO (SN)	NECESSARY	30.00	30.00
			4,575.00	2,606.00
LABOUR				
TO RENEW REAR BUMPER,BOOTLID,REPAIR REAR END PANEL.			2,200.00	1,100.00
TO SPRAY PAINT FOR REAR BUMPER,BOOTLID,REAR END PANEL.			1,680.00	840.00
TO REMOVE & INSTALL PARKING SENSOR.			100.00	60.00
TO CHECK WIRING & ELECTRICAL SYSTEM.			20.00	20.00
TO CONDUCT DIAGNOSTIC CHECK FOR THE CAR SYST			200.00	200.00

Report Ref No. CS/EGI18010893/T1cd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY SEALANT FOR ACCIDENT PORTION.		40.00	40.00
	TOWING FROM HOUGANG AVE 3 TO PG CNC.		85.00	85.00
	(ADDITIONAL)			
			4,325.00	2,345.00
	GRAND TOTAL		8,900.00	4,951.00
RECOMMENDED COST OF REPAIRS				4,951.00

Report Ref No. CS/EG18010893/T1cd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.