

Su Brothers' Motor Workshop

Blk 5034 Ang Mo Kio Industrial Park 2

#01-341/343

Singapore 569537

Tel : 64824355 Fax : 64824788 Email : su_bros@singnet.com.sg

Co. Reg. No : 26584500M GST Reg No : M9-0008282-A

Date : 14/06/2018

Pg 1/2

Our Ref : SB/MC/0280/06/18 C

Sompo Insurance Singapore Pte Ltd

50 Raffles Place

Fax: 6221 3147

#05-01/06 Singapore Land Tower

Singapore 048623

Attention : Motor Claims Department

Policyholder : Tay Hock Hai Stephen

Policy No : D18MTPV01000045

Vehicle No : SGE 2609 Y

Make/Model : Honda Fit

DOA : 13/06/2018

Cost of Repair:-

1 pc	Front bumper <i>displaced</i>	\$	450.00	✓
2 pcs	Front bumper side retainer @ \$12.00 <i>SVC</i>	\$	24.00	X
2 pcvs	Front bumper bracket @ \$25.00 <i>broken</i>	\$	50.00	✓
1 pc	Front bumper reinforcement <i>bt</i>	\$	165.00	✓
1 pc	Front bumper lower grille <i>cut</i>	\$	45.00	✓
2 pcs	Front bumper fog lamp garnish @ \$23.00 <i>dislodged</i>	\$	46.00	✓
10 pcs	Front bumper clip @ \$2.50 <i>hec</i>	\$	25.00	✓
1 pc	Radiator grille <i>broken</i>	\$	205.00	✓
1 pc	Radiator grille top garnish <i>cut</i>	\$	18.00	✓
8 pcs	Radiator grille top garnish clip @ \$2.50 <i>hec</i>	\$	20.00	✓
1 pc	Front support panel <i>Replaced</i>	\$	280.00	✓
2 pcs	Headlamp assy @ \$350.00 <i>crack mounting</i>	\$	700.00	✓
1 pc	Air outer duct <i>deformed</i>	\$	25.00	✓
1 pc	Air outer duct hose <i>SVC</i>	\$	30.00	✓
1 pc	Front o/s fender <i>Replaced</i>	\$	145.00	✓
1 pc	Washer tank <i>deformed</i>	\$	60.00	✓
1 pc	Air con condensor <i>damaged</i>	\$	400.00	✓
2 pcs	Air con condensor side garnish @ \$16.00 <i>o/s torn n/s HH</i>	\$	32.00	✓
1 pc	Radiator fan cowlng ?	\$	75.00	?
1 pc	Radiator fan blade ?	\$	55.00	?
1 pc	Radiator fan motor <i>HH</i>	\$	200.00	✓
1 pc	Radiator assy ?	\$	780.00	?
1 pc	Radiator spare tank ?	\$	28.00	?
1 pc	Bonnet <i>Replaced</i>	\$	260.00	✓
2 pcs	Bonnet hinge @ \$25.00 <i>lego o/s bt n/s HH</i>	\$	50.00	✓
Bal c/d		\$	4,168.00	

Our Ref : SB/MC/0280/06/18 C
 Vehicle No : SGE 2609 Y

Bal b/f \$ 4,168.00

1 pc	Bonnet lock <i>1st</i>	\$	75.00	✓
2 pcs	Bonnet rubber @ \$20.00 <i>SVL</i>	\$	40.00	×
1 pc	Bonnet insulator <i>7H</i>	\$	65.00	×
1 pc	Front parts w/s o/s upside garnish <i>SVL</i> <i>o/s</i>	\$	45.00	×
		\$	4,393.00	
Add 10%		\$	439.30	
		\$	4,832.30	

Special Nett Items:-

1 pc	Front number plate <i>SVL</i>	\$	20.00	×
1 pc	Front number plate garnish <i>SVL</i>	\$	20.00	×
		\$	40.00	

Labour Charges:-

To check & reconnect harness wiring.	\$	35.00 20/-
To putty & spray painting.	\$	980.00 600/-
To remove/refit/renew front air con pipe, hose, fan, condensor & refill gas.	\$	100.00 80/-
To cut/weld front support panel, knock & reshape front o/s wheel house inner panel, front o/s door, front n/s fender, to renew above parts & to realign front portion the same.	\$	850.00 600/-
		\$ 6,837.30

18/06/2018 @ 1100w

Not Antenn

3/Part.

Photo with damaged parts

6 days. Excess TBC

2KK Auto

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: