

ASS. REC. BY:

REF: CS/FCI18010903/Avd3n2 Special Instruction:

Surveyor:

Adnan

ASSIGNMENT (Office)

CWS

From (Person):

May chua

of

FCI

Date/Time: 14/6/18 @ 3:14pm

Estimated Cost:

Bill to:

OD ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJT 39392

Insured:

SHA 7610T

at Workshop m/s

SM Automotive

Tel:

67479241

of

Blk C, 1 Kaki Bukit Ave 6 # 01-43

Policy No:

Claim No:

D18004725MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 13/06/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

4:19pm @ 14/6/18

Person Contacted:

Sukyi

Vehicle

IN/OUT

Date/Time	Action/Instruction (✓) Estimate	
	SJT 39392 - CCG / III 7023439 / Uwg 392	DOA: 8/12/2017
	SHA 7610T - NS / INCIS 017459 / H1/bn2	DOA: 14/10/2015
19/6/18	Informed FCI pending workshop est by merimen	
17/8/18	Adnan confirmed LS \$ 11,200 (Red 24, 247.50, 6870)	
24/8/18	Email preli revised to FCI	

ASS. REC. BY: Adrian King

REF:

ASSIGNMENT

18/07/08.

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SIT3939Z

Yr Regn:

2008, July.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Civic Type R

C.G

1988.

Colour:

Red.

A/C: Insured / Std / NI / NA

Sp. Reading:

225380

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

FD2140 1745.

Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 225/45R17.

R: 225/45R17.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

14/06/18.

Survey held at

SM.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP 1st Cap.

Pending COE Renewal.

Note:

MV: 781K (EST)

PV: 3TK

Net: 41K.

RECEIVED 24 AUG 2018

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 24/8 - typist

Report Format:

CWS

Lump Sum / I.B.I. (\$

11, 200/2

Days Of Repair:

12

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$1

Photos

Other

TOTAL

25x15=375

170+375

50

50

101

746



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18004725MFSH
Our ref: CS/FCI18010903/Avd3

Date : 24/8/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SJT 3939Z


We thank you for your instruction on 14/6/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on
14/6/2018 at the premises of M/s SM AUTOMOTIVE
and have the following to report:-

Workshop Estimate Amount	: S\$35,447.50
Revised Estimate Amount	: S\$11,200.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the
rear portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A.M.MATAI

Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	13-06-2018	Our Ref No. D18004725MFSH
Accident Date	13-06-2018	Claim Type. Third Party
Insured Vehicle	SHA7610T	Third Party Vehicle. SJT3939Z
Survey Location	BLK C, 1 KAKI BUKIT AVENUE 6 #01-43	
Contact Person.	SUKYI	
Contact No.	67479241/ 0	Fax No. 67417276
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SM AUTOMOTIVE	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/241430)



PRI Documents



Close



PRI Header Details

Claim No	D18004725MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & SM AUTOI
Workshop Name	SM AUTOMOTIVE (Contact Person : SUKYI)	Survey Location & Contact Details	BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 Mobile: 0 , Phone: 67479241 , Fax: 67417276 EmailId: ADMIN@NHTMOTOR.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA7610T	TP Vehicle No	SJT3939Z
PRI Recieved Date	13-06-2018 10:15:42 PM	Surveyor Appointed Date	14-06-2018 03:13:35 PM	Surveyor Accept Date	14-06-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	14-06-2018	Upload Survey Report *:	Choose File
------------------------------------	--	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
----------------	----------------------	-------------------------------------

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 24 August 2018 9:51 AM
To: 'Claim Workflow System'
Cc: 'MAYCHUA@MSFIRSTCAPITAL.COM.SG'; SUR
Subject: RE: SURVEY ASSESSMENT - D18004725MFSH/1, SJT 3939Z
Attachments: SJT 3939Z PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SJT 3939Z
Date of survey: 14/6/2018
Number of days : 12 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 19 June 2018 8:13 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18004725MFSH/1, SJT 3939Z

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SJT 3939Z on 14/6/2018 .

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 14 June 2018 4:23 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18004725MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

Sent: Thursday, 14 June 2018 3:13 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; MAYCHUA@MSFIRSTCAPITAL.COM.SG

Subject: PRI: SURVEY ASSESSMENT - D18004725MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 19 June 2018 8:13 AM
To: 'Claim Workflow System'
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18004725MFSH/1, SJT 3939Z

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SJT 3939Z on 14/6/2018 .

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 14 June 2018 4:23 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18004725MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 14 June 2018 3:13 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; MAYCHUA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18004725MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0940I
Vehicle Details	
Vehicle No.:	SJT3939Z
Vehicle to be Exported:	No
Intended De-registration Date:	17 Aug 2018
Vehicle Make:	HONDA
Vehicle Model:	CIVIC TYPE-R 2.0 M
Primary Colour:	Silver
Manufacturing Year:	2007
Engine No.:	K20A5821824
Chassis No.:	FD21401745
Maximum Power Output:	165.0 kW (221 bhp)
Open Market Value:	\$27,605.00
Original Registration Date:	18 Jul 2008
First Registration Date:	18 Jul 2008
Transfer Count:	4
Actual ARF Paid:	\$27,605.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	17 Jul 2028
COE Category:	E - Open Category
COE Period(Years):	10
PQP Paid:	\$36,888.00
COE Rebate Amount:	\$36,580.00
Total Rebate Amount:	\$36,580.00

The information contained herein is correct as at 17 Aug 2018

OK



FOR SALE BY OWNER

Post an Advertisement
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

Post an Ad
 Advertiser Login
 Ways of Selling

New 5 Years Coe Renewal Honda Stream 1.8A

\$2500 Downpayment Monthly From \$688 Onwards. Lowest 3.68% P.A. @ GV Cars Financing
 GV Credit Pte Ltd StarAd

Lake View Credit Pte Ltd [view our cars](#)

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

Browse by Category
 Save Search
 Print
 Sort by Date Posted 20 results/page

18 vehicles **Search** type

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

Search Selection	type	Any	Any	> 10 year(s) old	Any	Any	Any	Available
------------------	------	-----	-----	------------------	-----	-----	-----	-----------



☐ **Honda Civic Type R EK9 (COE till 04/2019)**
 \$68,888 \$98,220 /yr 25-Jul-2000 1,595 cc - Sports Available

One Of The Two Unit In Singapore. Not The Fake Unit, Full Restored To Stock Condition. Come View To Believe! The B16B Engine Boasted One Of The Highest Power Output Per Litre Of All Time For A Natural...

Posted: 04-Jul-2018 Tags: 2000 Honda Civic, Honda Civic, Honda, Civic, Used Honda



☐ **Honda Integra Type R 2.0M (COE till 05/2026)**
 \$60,000 \$7,700 /yr 21-Jun-2005 1,998 cc 120,000 km Sports Available

A Tastefully Done Up Fully Converted DC5. Championship White Exterior On Full DC5R Interior With Original Black Recaro Seats. Always Parked Under Shelter. Never Tracked. Well Maintained By Meticulous ...

Monster Motors Pte Ltd

Posted: 02-Jul-2018 Tags: 2005 Honda Integra, Honda Integra, Honda, Integra, Used Honda



☐ **Honda Integra Type R 2.0M (COE till 06/2026)**
 \$73,888 \$9,380 /yr 18-Jul-2006 1,998 cc 160,000 km Sports Available

Original Enkel Rpf01 17" Rims, AP Racing Bbk, Defi Gauges X03, Aftermarket Anti Roll Bars, Full Hard Race Undercarriage With Rear Lower Control Arms, Ksport Racing Coilovers Fully Height Damping A...

Posted: 16-Aug-2018 Tags: 2006 Honda Integra, Honda Integra, Honda, Integra, Used Honda



☐ **Honda Civic Type R 2.0M (COE till 07/2027)**
 \$78,888 \$8,810 /yr 01-Aug-2007 1,998 cc 170,000 km Sports Available

Honda's Signature VTEC JDM Lifestyle In Championship White And Carbon Fibre. Extremely Well Maintained Interior And Exterior, Serviced At Reputable Honda Workshops. Over 6k Spent On Wear And Tear Repl...

Monster Motors Pte Ltd

Posted: 14-Jul-2018 Tags: 2007 Honda Civic, Honda Civic, Honda, Civic, Used Honda



Buying a pre-owned car, but Unsure of its Condition?
Get STA Car Evaluation



☐ **Honda S2000 Type V 2.2M (COE till 09/2027)**
 \$83,800 \$9,210 /yr 21-Sep-2007 2,156 cc 79,800 km Sports Available

AP2 Come With New Electric Power Steering, Accident Free, Stock Internal, Never Track, LTA Friendly, Drive With Peace Of Mind, Loan Up To \$70-80k. High Trade In, Call Now!

Posted: 26-Jul-2018 Tags: 2007 Honda S2000, Honda S2000, Honda, S2000, Used Honda



☐ **Honda Civic Type R 2.0M (COE till 09/2027)**
 \$80,888 \$8,890 /yr 22-Sep-2007 1,998 cc - Sports Available

Needs No Introduction. Freshly Painted Yellow, 100% Accident Free, Straight Chassis. 1 Of Few Pristine Condition. Road Legal Usage. Wear And Tear Replaced By Fussy Owner. Park Under Shelter Daily. 9.5/...

Posted: 06-Aug-2018 Tags: 2007 Honda Civic, Honda Civic, Honda, Civic, Used Honda



☐ **Honda Civic Type R 2.0M 3DR (COE till 09/2027)**
 \$67,800 \$7,440 /yr 26-Sep-2007 1,998 cc 159,000 km Sports Available

In House Finance Available, Low Down Payment. Owner Consignment. In Immaculate Condition, Rare 3 Doors Type R With Mugen Bodykit, Well Maintained And Religiously Serviced By Reputable Workshop, Road T...

CONSIGNMENT

Compare

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 0940I

Vehicle Details

Vehicle No.: SJT3939Z
Vehicle to be Exported: No
Intended De-registration Date: 13 Jun 2018
Vehicle Make: HONDA
Vehicle Model: CIVIC TYPE-R 2.0 M
Primary Colour: Silver
Manufacturing Year: 2007
Engine No.: K20A5821824
Chassis No.: FD21401745
Maximum Power Output: 165.0 kW (221 bhp)
Open Market Value: \$27,605.00
Original Registration Date: 18 Jul 2008
First Registration Date: 18 Jul 2008
Transfer Count: 3
Actual ARF Paid: \$27,605.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 17 Jul 2018
PARF Rebate Amount: \$13,802.00

Intended COE Rebate Details

COE Expiry Date: 17 Jul 2018
COE Category: E - Open Category
COE Period(Years): 10
QP Paid: \$18,451.00
COE Rebate Amount: \$164.00
Total Rebate Amount: \$13,966.00

The information contained herein is correct as at 13 Jun 2018

OK

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

13/06/2018

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP 1st Cap

Veron.

Accident date: 13/06/2018

Estimated repair cost for vehicle no: SJT3939Z HONDA CIVIC TYPE R 2.0 M '08

CHASSIS: FD21401745

S/N	QTY	Items	U/PRICE	AMOUNT	
1	1	Rear Boot Lid Buckled		\$750.70	✓
2	2	Rear Boot Lid Hinge Best	\$58.10	\$116.20	✓
3	1	Rear Boot Lid Emblem Logo New		\$80.00	✓
4	1	Rear Boot Lid Number Plate New		\$50.00	+
5	2	Rear Boot Lid Side Reflector Bulb	\$252.40	\$504.80	✓
6	1	Rear Boot Lid Inner Lock Key		\$194.50	✓
7	1	Rear Boot Lid Inner Rubber Kit		\$97.60	✓
8	2	Rear Tail Lamp Bulb	\$305.60	\$611.20	✓
9	4	Rear Tail Lamp Clip m	\$8.00	\$32.00	✓
10	2	Rear Tail Lamp Panel Buckled.	\$130.10	\$260.20	✓
11	1	Rear Bumper Distorted		\$920.30	✓
12	10	Rear Bumper Clip New	\$6.50	\$65.00	30
13	2	Rear Bumper Side Retainer m	\$35.40	\$70.80	✓
14	2	Rear Bumper Bracket 2 New	\$27.50	\$55.00	X
15	2	Rear Bumper Mud Shield	\$85.10	\$170.20	X
16	1	Rear End Panel Distorted		\$680.40	✓
17	1	Rear End Panel Top Garnish Distorted		\$196.70	✓
18	2	Rear Fender Repair	\$780.50	\$1,561.00	+
19	2	Rear Fender Air Duct New	\$35.40	\$70.80	+
20	2	Rear Fender Inner Trim Board crumpled.	\$325.90	\$651.80	✓
21	1	Rear Spare Tyre Panel Distorted.		\$948.50	✓
22	1	Rear Spare Tyre Panel Top Cover Distorted		\$316.70	✓
23	1	Rear Spare Tyre Panel Under Cover Distorted		\$305.40	✓
24	6	Rear Spare Tyre Panel Under Cover Clip New	\$6.50	\$39.00	✓
25	2	Rear Spare Tyre Side Panel Repair	\$257.10	\$514.20	X
26	1	Rear Spare Tyre Lock New		\$89.80	X
27	1	Rear Chassis Repair		\$376.10	X
28	1	Rear Centre Exhaust Best.		\$980.60	✓

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

13/06/2018

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 13/06/2018

Supplementary cost for vehicle no: SJT3939Z HONDA CIVIC TYPE R 2.0 M '08

CHASSIS: FD21401745

S/N	QTY	Items / Special Nett	U/PRICE	AMOUNT
1	1	Rear Spare Tyre Panel Tool Box <i>Deformed</i>		\$240.00 <i>OK</i>
2	1	Rear Centre Exhaust <i>Reported</i>		\$1,800.00 <i>OK</i>
3	1	Front Exhaust <i>Not new</i>		\$2,800.00 <i>OK</i>

240

Subtotal:- \$4,840.00

192

Labour charges

To check exhaust for LTA inspection

\$120.00 *OK*
80.

80

Subtotal:- \$120.00

Total:- \$4,960.00

Supplementary: 272

29	1	Rear Exhaust Chrome Pipe <i>AT NEW</i>		\$398.70 <i>+</i>
30	1	Rear Exhaust Aluminium Cover <i>crumpled</i>		\$73.80 <i>+</i>
31	2	Rear Exhaust Mounting <i>new</i>	\$37.50	\$75.00 <i>+</i>
32	1	Rear Windscreen Moulding <i>new</i>		\$80.50 <i>+</i>

7861-20
6288-96

Subtotal:- \$11,337.50

S/N	QTY	Items	U/PRICE	AMOUNT	
33	1	Rear Boot Lid Top Spoiler <i>new</i>		\$2,500.00	+ refer photo
34	1	Rear Boot Lid Camera <i>new</i>		\$550.00	x
35	1	Rear Bumper Lower Spoiler <i>Disheled</i>		\$1,200.00	920
36	1	Rear Bumper Reverse Sensor <i>new</i>		\$350.00	200
37	1	Rear Spare Tyre Panel & End Panel Sealant <i>AT NEW</i>		\$450.00	x
38	1	Rear Exhaust <i>Best</i>		\$3,800.00	1300
39	1	Rear R/H Seat Cushion <i>"Damaged"</i>		\$2,800.00	1200

front

Subtotal:- \$11,650.00

3880

Labour charges

To remove & refit cushion	\$280.00 80
To remove & refit reverse sensor	\$100.00 50
To remove & refit rear camera	\$180.00 50
To remove & refit petrol tank	\$280.00 80
To remove & refit rear windscreen	\$120.00 X
Gum	nn \$50.00 X
To remove & refit roof lining	\$380.00 X
To remove & refit rear & centre exhaust	\$380.00 160
To remove & refit top & lower spoiler	\$380.00 160
To check wiring	\$100.00 30
Tuff kote	3530 \$150.00 80
Towing fee	3630 \$100.00 60
Panel beating	\$3,000.00 1400
Spray painting	\$2,000.00 1300

Subtotal:- \$7,500.00

35,447.50

Total:- \$30,487.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Supplementary : 272

Total: 13970.86

L/S: 11.2K

12 Days

11.2K

12 Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18010903/Avd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 31-08-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 7610T	Veh. Inspected	SJT 3939Z	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18004725MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	14/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CIVIC TYPE-R	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	FD21401745	Colour	RED	
Odometer	225390	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	YOKOHAMA	6 mm	
L/H Front Tyre	225/45 R17	YOKOHAMA	6 mm	
R/H Rear Tyre	225/45 R17	YOKOHAMA	6 mm	
L/H Rear Tyre	225/45 R17	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/06/2018	Inspection Date	14/06/2018	
Survey held at	SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJT 3939Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT LID	BUCKLED	750.70	750.70
2	REAR BOOT LID HINGE @\$58.10	BENT	116.20	116.20
1	REAR BOOT LID EMBLEM LOGO	NECESSARY	80.00	80.00
1	REAR BOOT LID NUMBER PLATE	NOT NECESSARY	50.00	-
2	REAR BOOT LID SIDE REFLECTOR @\$252.40	CRACKED	504.80	504.80
1	REAR BOOT LID INNER LOCK	DAMAGED	194.50	194.50
1	REAR BOOT LID INNER RUBBER	CUT	97.60	97.60
2	REAR TAIL LAMP @\$305.60	CRACKED	611.20	611.20
4	REAR TAIL LAMP CLIP @\$8.00	NECESSARY	32.00	32.00
2	REAR TAIL LAMP PANEL @\$130.10	BUCKLED	260.20	260.20
1	REAR BUMPER	DISTORTED	920.30	920.30
10	REAR BUMPER CLIP @\$6.50	NECESSARY	65.00	30.00
2	REAR BUMPER SIDE RETAINER @\$35.40	NECESSARY	70.80	70.80
2	REAR BUMPER BRACKET @\$27.50	NOT NECESSARY	55.00	-
2	REAR BUMPER MUD SHIELD @\$85.10	NOT NECESSARY	170.20	-
1	REAR END PANEL	DISTORTED	680.40	680.40
1	REAR END PANEL TOP GARNISH	DEFORMED	196.70	196.70
2	REAR FENDER @\$780.50	TO REPAIR SEE LABOUR	1,561.00	-
2	REAR FENDER AIR DUCT @\$35.40	NOT NECESSARY	70.80	-
2	REAR FENDER INNER TRIM BOARD @\$325.90	CRUMPLED	651.80	651.80
1	REAR SPARE TYRE PANEL	DISTORTED	948.50	948.50
1	REAR SPARE TYRE PANEL TOP COVER	DEFORMED	316.70	316.70
1	REAR SPARE TYRE PANEL UNDER COVER	DEFORMED	305.40	305.40
6	REAR SPARE TYRE PANEL UNDER COVER CLIP @\$6.50	NECESSARY	39.00	39.00
2	REAR SPARE TYRE SIDE PANEL @\$257.10	TO REPAIR SEE LABOUR	514.20	-
1	REAR SPARE TYRE LOCK	NOT NECESSARY	89.80	-
1	REAR CHASSIS	TO REPAIR SEE LABOUR	376.10	-
1	REAR CENTRE EXHAUST	BENT	980.60	980.60
1	REAR EXHAUST CHROME PIPE	NOT NECESSARY	398.70	-

Report Ref No. CS/FCI18010903/Avd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607196-R

Page No.: 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR EXHAUST ALUMINIUM COVER	CRUMPLED	73.80	73.80
2	REAR EXHAUST MOUNTING @\$37.50	NOT NECESSARY	75.00	-
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	80.50	-
1	REAR SPARE TYRE PANEL TOOL BOX (ADDITIONAL)	DEFORMED	240.00	240.00
1	REAR CENTRE EXHAUST (ADDITIONAL)	REPEATED	1,800.00	-
1	FRONT EXHAUST (ADDITIONAL)	NOT NECESSARY	2,800.00	-
	LESS 20% DISCOUNT		-	-1,620.24
			16,177.50	6,480.96
	SPECIAL NETT ITEMS			
1	REAR BOOT LID TOP SPOILER (SN)	NOT NECESSARY	2,500.00	-
1	REAR BOOT LID CAMERA (SN)	NOT NECESSARY	550.00	-
1	REAR BUMPER LOWER SPOILER (SN)	DISTORTED	1,200.00	980.00
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	350.00	200.00
1	REAR SPARE TYRE PANEL & END PANEL SEALANT (SN)	NOT NECESSARY	450.00	-
1	REAR EXHAUST (SN)	BENT	3,800.00	1,300.00
1	FRONT R/H SEAT CUSHION (SN)	DAMAGED	2,800.00	1,400.00
1	GUM (SN)	NOT NECESSARY	50.00	-
			11,700.00	3,880.00
	LABOUR			
	TO CHECK EXHAUST FOR LTA INSPECTION (ADDITIONAL).		120.00	80.00
	TO REMOVE & REFIT CUSHION.		280.00	180.00
	TO REMOVE & REFIT REVERSE SENSOR.		100.00	50.00
	TO REMOVE & REFIT REAR CAMERA.		180.00	50.00
	TO REMOVE & REFIT PETROL TANK.		280.00	80.00
	TO REMOVE & REFIT REAR WINDSCREEN.	NOT NECESSARY	120.00	-
	TO REMOVE & REFIT ROOF LINNING.	NOT NECESSARY	380.00	-
	TO REMOVE & REFIT REAR & CENTRE EXHAUST.		380.00	160.00
	TO REMOVE & REFIT TOP & LOWER SPOILER.		380.00	160.00
	TO CHECK WIRING.		100.00	30.00
	TUFF KOTE.		150.00	80.00
	TOWING FEE.		100.00	60.00

Report Ref No. CS/FCI18010903/Avd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING INCLUSIVE OF THE REPAIR OF REAR FENDER, REAR SPARE TYRE SIDE PANEL AND REAR CHASSIS.		3,000.00	1,400.00
	SPRAY PAINTING.		2,000.00	1,300.00
			7,570.00	3,630.00
GRAND TOTAL			35,447.50	13,990.96
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				11,200.00

Report Ref No. CS/FCI18010903/Avd3n2

MARKET VALUE: \$78,000.00 (EST)-PAPER VALUE: \$37,000.00=NETT VALUE: \$41,000.00

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.