

ASS. REC. BY:

REF: CS/FCI18010910/ U 1d3 ⁰²

Special Instruction:

Surveyor

CWS

ASSIGNMENT (Office)From (Person): May Chua of FCI Date/Time: 14/6/18 @ 3.13pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SKS 9761 Y Insured: SH 6200 Hat Workshop m/s: Abwin Service Tel: 9751 9596of No. 8 Kaki Bukit Ave 4 #07-48Policy No: _____ Claim No: D18003076MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 18/04/2018(Client's Record) 18/6/2018 11amCA / REV / REP. / REV 24 HRS wp H.O.D. Endorsement: _____Date/Time: 4.14pm @ 14/6/18 Person Contacted: Linda Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate	
	<u>SKS 9761 Y - CC3 / AIG 15018810 / F1bc2</u>	<u>DOA: 3/11/2015</u>
	<u>SH 6200 H - NSI/NCI 4018809 / H1f3k3</u>	<u>DOA: 01/10/2014</u>
<u>26/6</u>	<u>Revert via email</u>	

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SK8 9761Y
 at Workshop m/s Abw. 11a1
 of _____
 Insured: SH6200H
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value: 64
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 G/A / PR Seen: 2 Consistent? : Yes or No
 Est. Repairs: 2 days Res.: Yes or No
 Lum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

20/7/18 1559.37 final by 1559.37 with L. n.d.
Red: 8033 35.66%

RECEIVED 24 JUL 2018

Veh No: SKS 9761Y Yr Regn: S-15
 Type: C Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CIA
 Make: KIA Forte K3 1591
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 101211 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KNAF241MF5349623
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Order / Jammed / Leaked / Burnt or
 Brake: Order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 215/45R17
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front 6 mm Rear 6 mm
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 18/4/18 D.O.I. 18/6/18
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 220/7/18 Typist☒ : Final ReportResurvey No. of Trip: 2

Date/Time, File Return to?

2)

Add Fee:

☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

Photos

Others

TOTAL

Report Format: TPLump Sum / I.B.I.: (\$ 1559.37)

135

50

50+50

30

315



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18003076MFSH

Date: 25/6/2018

Our Ref: CS/FCI18010910/Utd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SKS 9761Y

Please be informed that we had conducted the inspection of the abovementioned vehicle 18/06/2018 at the premises of M/s Abwin and have the following to report: -

Workshop Estimate Amount	: S\$ <u>4,242.50</u>
Revised Estimate Amount	: S\$ <u>1,209.00</u>
"Check" Items Amount	: S\$ <u>350.00</u>
Market Value	: S\$ <u> </u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Marcus

Automotive Assessor

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 25 June 2018 5:37 PM
To: Admin-D (LKKAuto); 'Claim Workflow System'; assignments
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18003076MFSH/1
Attachments: PRELI ADVISED SKS 9761Y.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SKS 9761Y**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 14 June 2018 4:18 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18003076MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 14 June 2018 3:12 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; MAYCHUA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18003076MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team

MOTOR SURVEY ASSIGNMENT

Date	20-04-2018	Our Ref No. D18003076MFSH
Accident Date	18-04-2018	Claim Type. Third Party
Insured Vehicle	SH6200H	Third Party Vehicle. SKS9761Y
Survey Location	NO 8 KAKI BUKIT AVE 4 #07-48 PREMIER @ KAKI BUKIT GATE 2	
Contact Person.	LINDA LIAO	
Contact No.	671339417/ 97519596	Fax No. 67139415
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ABWIN SERVICE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/239159)



PRI Documents



Close



PRI Header Details

Claim No	D18003076MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & ABWIN SE
Workshop Name	ABWIN SERVICE PTE LTD (Contact Person : LINDA LIAO)	Survey Location & Contact Details	NO 8 KAKI BUKIT AVE 4 #07-48 PREMIER @ KAKI BUKIT Mobile: 97519596 , Phone: 671339417 , Fax: 67139417 EmailId: LINDALIAO@ABWIN.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SH6200H	TP Vehicle No	SKS9761Y
PRI Recieved Date	13-06-2018 10:04:06 PM	Surveyor Appointed Date	14-06-2018 03:12:03 PM	Surveyor Accept Date	14-06-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	14-06-2018	Upload Survey Report *:	Choose File
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 1262Z

Vehicle Details

Vehicle No.: SKS9761Y

Vehicle to be Exported: No

Intended De-registration Date: 18 Jun 2018

Vehicle Make: KIA

Vehicle Model: FORTE K3 1.6A

Primary Colour: Black

Manufacturing Year: 2014

Engine No.: G4FGEH748063

Chassis No.: KNAFZ411MF5349623

Maximum Power Output: 95.3 kW (127 bhp)

Open Market Value: \$18,227.00

Original Registration Date: 19 May 2015

First Registration Date: 19 May 2015

Transfer Count: 1

Actual ARF Paid: \$13,227.00 661 }

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 18 May 2025

PARF Rebate Amount: \$9,920.00

Intended COE Rebate Details

COE Expiry Date: 18 May 2025

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$68,589.00

COE Rebate Amount: \$47,440.00

Total Rebate Amount: \$57,360.00

The information contained herein is correct as at 18 Jun 2018

OK

*Please arrange to survey vehicle at
8 KAKI BUKIT AVENUE 4 - GATE 2
#07-48 PREMIER @ KAKI BUKIT
SINGAPORE 415875

ABWIN 諭輝

LINDA LIAO
ABWIN SERVICE PTE LTD
DID: 67139417
Fax: 67139415
HP: 97519596

Date : 13/06/2018
TP Vehicle No. : SH -6200-H
To : **FIRST CAPITAL INSURANCE LTD**
Attn : **Motor Claim Department**

Owner : KOO BEE YONG (XU MEIRONG)
NTUC INCOME INSURANCE CO-OPERATIVE LTD
Certificate No. : 5090561340-01
Vehicle No. : SKS-9761-Y
Make & Model : KIA FORTE K3 1.6A

Accident Date: 18/04/2018

Take photo before repair.
Not Authorised
18/6/18

8/28/1559.37

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
-----	-------------	---------------	---------------

List Item

1	REAR BUMPR	\$650.00	<i>10/10.1</i>
1	REAR BUMPER RETAINER RH	\$35.00	<i>11</i>
1	REAR BUMPR RETAINER LH	\$35.00	<i>12</i>
1	REAR BUMPER BRACKET RH	\$95.00	<i>17</i>
1	REAR BUMPER BRACKET LH	\$95.00	<i>17</i>
10	REAR BUMPER CLIPS	\$60.00	<i>11</i>
1	REAR END PANEL	\$350.00	<i>11</i>
1	REAR END PANEL TOP GARNISH	\$95.00	<i>11</i>
10	REAR END PANEL TOP GARNISH CLIPS	\$60.00	<i>11</i>
Sub Total		\$1,475.00	<i>resurvey reinforced. one ✓</i>
Discount 10% on Parts		(\$147.50)	
		\$1,327.50	

Special Nett

1	REAR BUMPER REVERSE SENSOR	\$350.00	<i>811</i>
1	REAR NUMBER PLATE WITH CASING	\$65.00	<i>11</i>
Sub Total		\$415.00	

Labour & Misc

TO STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	\$1,200.00	<i>200</i>
TO SPRAY PAINT ON AFFECTED AREAS	\$1,000.00	<i>300</i>
TO CHECK ALL NECESSARY WIRINGS	\$150.00	<i>20</i>
TO INSTALL REVERSE SENSOR & CHECK FUNCTIONALITY	\$150.00	<i>50</i>
Sub Total	\$2,500.00	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

ABWIN SERVICE PTE LTD, 8 KAKI BUKIT AVENUE 4 - GATE 2, #07-48 PREMIER @ KAKI BUKIT, SINGAPORE 415875

Date:

Sub Total

\$4,242.50

4648.22

GST 7%

\$296.98

Total

\$4,539.48

Please arrange to survey vehicle at
8 KAKI BUKIT AVENUE 4 - GATE 2
#07-48 PREMIER @ KAKI BUKIT
SINGAPORE 415875

ABWIN 詢燁

SUPPLEMENTARY

Date : 05/07/2018
TP Vehicle No. : SH-6200-H
To : FIRST CAPITAL INSURANCE LTD
Attn : Motor Claim Department

LINDA LIAO
ABWIN SERVICE PTE LTD
DID: 67139417
Fax: 67139415
HP: 97519596

Owner : KOO BEE YONG (XU MEIRONG)
NTUC INCOME INSURANCE CO-OPERATIVE LTD
Certificate No. : S090561340-01
Vehicle No. : SKS-9761-Y
Make & Model : KIA FORTE K3 1.6A

Accident Date: 18/04/2018

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
<u>List Item</u>			
1	REAR BUMPER REINFORCEMENT <i>ADD</i>	<i>one</i> \$450.80	<i>389-30</i>
	Sub Total	\$450.80	
	Discount 10% on Parts	(\$45.08)	
		\$405.72	
	Sub Total	\$405.72	
	GST 7%	\$28.40	
	Total	\$434.12	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18010910/Utd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 30-07-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 6200H	Veh. Inspected	SKS 9761Y	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18003076MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	14/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	KIA FORTE K3 (A)	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KNAFZ411MF5349623	Colour	BLACK	
Odometer	101211	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/45 R17	GOODYEAR	6 mm	
L/H Front Tyre	215/45 R17	GOODYEAR	6 mm	
R/H Rear Tyre	215/45 R17	GOODYEAR	6 mm	
L/H Rear Tyre	215/45 R17	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/04/2018	Inspection Date	18/06/2018	
Survey held at	ABWIN SERVICE PTE LTD No. 8 KAKI BUKIT AVENUE 4 #07-48 PREMIER@KAKI BUKIT GATE 2 SINGAPORE 415875			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 9761Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DENTED / TORN	650.00	650.00
1	REAR BUMPER RETAINER RH	NOT NECESSARY	35.00	-
1	REAR BUMPER RETAINER LH	NOT NECESSARY	35.00	-
1	REAR BUMPER BRACKET RH	NOT NECESSARY	95.00	-
1	REAR BUMPER BRACKET LH	NOT NECESSARY	95.00	-
10	REAR BUMPER CLIPS	NECESSARY	60.00	60.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	350.00	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	95.00	-
10	REAR END PANEL TOP GARNISH CLIPS	NOT NECESSARY	60.00	-
1	REAR BUMPER REINFORCEMENT (ADDITIONAL)	CRACKED	450.80	389.30
	LESS 10% DISCOUNT		-192.58	-109.93
			1,733.22	989.37
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER REVERSE SENSOR (SN)	SERVICEABLE	350.00	-
1	REAR NUMBER PLATE WITH CASING (SN)	NOT NECESSARY	65.00	-
			415.00	-
<u>LABOUR</u>				
	TO STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS.INCLUSIVE OF THE REPAIR OF REAR END PANEL.		1,200.00	200.00
	TO SPRAY PAINT ON AFFECTED AREAS.		1,000.00	300.00
	TO CHECK ALL NECESSARY WIRINGS.		150.00	20.00
	TO INSTALL REVERSE SENSOR & CHECK FUNCTIONALITY.		150.00	50.00
	-		-	-
	-		-	-
	-		-	-
			2,500.00	570.00
GRAND TOTAL			4,648.22	1,559.37



RECOMMENDED COST OF REPAIRS			1,559.37
-----------------------------	--	--	----------

Report Ref No. CS/FCI18010910/Utd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.