

27/03/2007

ASS. REC. BY:

REF: CS/FCI/18010911/110302 Special Instruction:

ASSIGNMENT (Office)

From (Person): Sithara of FCI Date/Time: 14/6/18 @ 5.06pm

Estimated Cost: _____ Bill to: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SJY 5531B Insured: SHB 2223F

at Workshop m/s Progressive Automotive Tel: 67415336

of Blk 3022 Ubi Road 1 #01-45/46

Policy No: _____ Claim No: DISCB4693MPSTH

Sum Insured: _____ Excess: _____

Make of Veh:

(Client's Record)

D.O.A. 08/06/2018

CA / REV / REP. / REV 24 HRS

DS

18/06/2018

H.O.D. Endorsement: _____

Date/Time: 5.25pm @ 14/6/18

Person Contacted: peiwen

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate	
	<u>SJY 5531B - CS/AXA 14022669 / Utdl</u>	<u>DOA: 27/11/14</u>
	<u>SHB 2223E - CS/FCI 16013082 / Gtbn2</u>	<u>DOA: 9/6/2016</u>
	<u>Lump Sum \$11,500 (Red: 9407.57; 44%)</u>	

ASS. REC. BY: Adrian Ling

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SSY 5531B Yr Regn: 2010, Sept.Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Tucson c.c. 1998Colour: silver A/C: Insured / Std / NI / NASp. Reading: 103787 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHJ4818MBU056299Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/60R17R: 225/60R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 18/06/08Survey held at Progressive CubiDes. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction
TP 1st Cap.

MV: 33K.
 PV: 20.4K
 Net: 12.6K.

RECEIVED 12 SEP 2010

Date/Time, File Pass to?

1) 10/9 Typist

Date/Time, File Return to?

2) _____

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 12Resurvey No. of Trip: 2Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS SI

Photos 580

Others

11/6/18TOTAL 657

10X15: 150

170+150

50

50+50

123

593

Report Format: TPLump Sum / I.B.I. (%): 11,500/-

MOTOR SURVEY ASSIGNMENT

Date	12-06-2018	Our Ref No. D18004693MFSH
Accident Date	08-06-2018	Claim Type. Third Party
Insured Vehicle	SHB2223E	Third Party Vehicle. SJY5531B
Survey Location	BLK 3022A UBI ROAD 1 #01-45/46	
Contact Person.	PEIWEN	
Contact No.	67415336/ 0	Fax No. 67417208
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PROGRESSIVE AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/241385)



PRI Documents



Close



PRI Header Details

Claim No	D18004693MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & PROGRES
Workshop Name	PROGRESSIVE AUTOMOTIVE PTE LTD (Contact Person : PEIWEN)	Survey Location & Contact Details	BLK 3022A UBI ROAD 1 #01-45/46 Mobile: 0 , Phone: 67415336 , Fax: 67417208 EmailId: PEIWEN@PROG.AUTO.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHB2223E	TP Vehicle No	SJY5531B
PRI Recieved Date	14-06-2018 03:52:57 PM	Surveyor Appointed Date	14-06-2018 05:05:30 PM	Surveyor Accept Date	14-06-2018 0

Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	14-06-2018	Upload Survey Report *:	<input type="button" value="Choose File"/>
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select Year"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Monday, 10 September 2018 1:53 PM
To: Admin-D (LKKAUTO); 'Claim Workflow System'; assignments
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18004693MFSH/1
Attachments: PRELI ADVISED SJY 5531B.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SJY 5531B**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 14 June 2018 5:23 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18004693MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 14 June 2018 5:05 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SITHARA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18004693MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18004693MFSH

Date: 10/9/2018

Our Ref: CS/FCI18010911/Atd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJY 5531B

Please be informed that we had conducted the inspection of the abovementioned vehicle 18/06/2018 at the premises of M/s Progressive and have the following to report: -

Workshop Estimate Amount	: S\$ <u>20,907.57</u>
Revised Estimate Amount	: S\$ <u>11,500.00</u>
"Check" Items Amount	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the Front, rear portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Adrian

Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/06/2018 17:40
Date Of Accident	08/06/2018 10:50 ✓
Exact Location Of Accident	HOUGANG AVE 2
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJY5531B ✓
Insured/Policyholder	
Name Of Registered Owner	LIM YEW TEE EVEN
NRIC No	S1418062A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97351108
Alternative Phone No	OTHERS-83280925

Vehicle Particulars

Manufacturer	HYUNDAI
Model	TUCSON-2.0 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT/0026204/02
Cover Note Number	

Driver

Name of Driver	LIM ZHIWEN, CYRIL
NRIC No	S8902813B
Date Of Birth	23/01/1989
Occupation	INDOOR
Date Of Driving Pass	21/05/2009
Driving Experience	9 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83280925
Fax Number	
Contact Number	
EMail Address	NOEMAIL

* Address	26 SIMEI STREET 1 #05-01 SINGAPORE
Postcode	529947
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	DRIZZLING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ - SINGAPORE CITY
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE ATTACH STATEMENT RECORDED BY PEI WEN - PROGRESSIVE AUTOMOTIVE PTE LTD TEL 6741 5336

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHB2223E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	TOH KAI KEE
NRIC/Passport Number	S1171170G
Contact Number	97316287
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

• No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	GBB9969L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	PING AN
NRIC/Passport Number	
Contact Number	86483246
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	LIM ZHIWEN, CYRIL
Approximate Age	
Injuries Sustain	NECK & BACK PAIN
Injured person in which vehicle?	SJY5531B
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name: 
NRIC/FIN No: _____

Sketch Plan #2


SKETCH PLAN



Vehicle No.

A-SJY5531B
B-SHR223E
C-GBB9969L

Legend



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer To Attach Police Report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.
Please be advised that your insurer may have a 14 day clause whereby the claim against own policy must be made within the stipulated timeframe from the date of occurrence. Kindly check your policy for more details.

Policyholder's Signature
Date & Time:

Driver's Signature:
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: 007100

POLICE REPORT PAGE 1 Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180608/2104

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20180608/2104

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 08/06/2018 15:49		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: LIM ZHIWEN, CYRIL			Address: APT BLK 26 SIMEI ST 1 #05-01 MELVILLE PARK SINGAPORE 529947		
ID Type / ID No.: NRIC NO / S8902813B			Contact No.: Home/Office: Mobile: 83280925		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 29	Date of Birth: 23/01/1989	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: SELF EMPLOYED			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 08/06/2018 10:50	Type of Location: Straight Road
Location: Along Road 1 HOUGANG AVENUE 2				
Weather: Drizzling		Road Surface: Wet		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision:				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBB9969L	Lorry				Slightly Damaged	0
SHB2223E	Car				Seriously Damaged	0
SJY5531B	Car				Slightly Damaged	0



**SINGAPORE
POLICE FORCE**



T/20180608/2104

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20180608/2104

CONTINUATION OF REPORT

Brief Details.

ON THE ABOVE MENTIONED DATE AND LOCATION

I WAS DRIVING ALONG HOUGANG AVE 2..THE ROAD CONSIST OF 3 LANES AND I WAS IN THE MIDDLE LANE..I WAS GOING STRAIGHT AND THERE WAS A LORRY IN THE FRONT OF ME..JUST AT A TRAFFIC JUNCTION,THE LORRY STOPPED AT THE RED LIGHT SIGNAL.I SLOWED DOWN AS WELL.BUT THE TAXI WHICH WAS BEHIND ME,I GUESS THE DRIVER WAS SPEEDING,COULDNT STOP OR BRAKE ON TIME .THE DRIVER SMASHED INTO MY VEHECLE VERY BADLY. DUE TO THE IMPACT,MY CAR MOVED FORWARD AND HIT THE LORRY.

AFTER THE HIT,I APPROACHED THE DRIVERS TO CHECK ON THEM IF THEY WERE DOING FINE.ONE OF THE PESSANGER WAS INJURED AND NEEDED MEDICAL ATTENTION.SO I CALLED THE AMBULLANCE.THE TOWING CREW WAS ACTIVATED TOO. AMBULLANCE ARRIVED AT SCENE AND THE PESSANGER WAS BROUGHT OVER TO THE HOSPITAL.. TOWING SERVICE WAS AT THE SCENE AND TOWED BOTH MY CAR AND THE TAXI TO THE WORKSHOP..

THATS ALL..



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20180608/2104

3 of 3

Report No. T/20180608/2104

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:
TP /
YOGENDRAN S/O RAJASAKARAN

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIT /
SI NORASHIKIN BINTE DAUD
Contact No.: 65476439

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:
08/06/2018 15:49

Classification Of Case:

Signature: _____

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8062A
Vehicle Details	
Vehicle No.:	SJY5531B
Vehicle to be Exported:	Yes
Intended De-registration Date:	19 Jun 2018
Vehicle Make:	HYUNDAI
Vehicle Model:	LM TUCSON 2.0L AUTO ABS D/AB 2WD SDR
Primary Colour:	Grey
Manufacturing Year:	2010
Engine No.:	G4KDAA308048
Chassis No.:	KMHJU81BMBU056299
Maximum Power Output:	122.0 kW (163 bhp)
Open Market Value:	\$17,579.00
Original Registration Date:	14 Sep 2010
First Registration Date:	14 Sep 2010
Transfer Count:	1
Actual ARF Paid:	\$17,579.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Sep 2020
PARF Rebate Amount:	\$10,547.00
Intended COE Rebate Details	
COE Expiry Date:	13 Sep 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$44,129.00
COE Rebate Amount:	\$9,862.00
Total Rebate Amount:	\$20,409.00

The information contained herein is correct as at 19 Jun 2018

OK



WIDE RANGE OF PRE-OWNED TOYOTA AND OTHER MAKES AVAILABLE

VISIT OUR NEW SHOWROOM FOR A PREMIUM PRE-OWNED EXPERIENCE @ 2 PANDAN CRESCENT INCHCAPE CENTRE




LEARN MORE

FOR SALE BY OWNER

Post an Advertisement
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

 Post an Ad |
  Advertiser Login |
  Ways of Selling


New 5 Years Coe Renewal Toyota Altis 1.6a


\$2500 Downpayment Monthly
 From \$588 Onwards. Lowest 3.68%P.A@GV Cars Financing
 GV Credit Pre Ltd StarAd










KA-HUP

**VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND**

HOTLINE: 6741 9997 [view our cars](#)

Browse by Category  |
 Save Search  |
 Print  |
 Sort by Date Posted  |
 20 results/page 

4 vehicles | Search [Advanced Search](#) [Search](#) [View All](#)

Make  |
 Model  |
 Price  |
 Depreciation  |
 Reg Date  |
 Eng Cap  |
 Mileage  |
 Veh Type  |
 Status 

Search Selection	Tucson	Any	Any	2010	Any	Any	Any	Available
------------------	--------	-----	-----	------	-----	-----	-----	-----------




Hyundai Tucson 2.0A | **\$27,800** | **\$11,390 /yr** | **10-Feb-2010** | **1,998 cc** | **98,000 km** | **SUV** | **Available**

New Arrival, Cheapest SUV To Own In Town! Genuine Low Mileage Done! Very Well Maintained Original Paintwork, Very Clean Interior, High Loan Available, Trade In Are Welcome. Call Now Don't Miss.

Creative Auto

★ Posted: 11-Jun-2018 Tags: 2010 Hyundai Tucson, Hyundai Tucson, Hyundai, Tucson, Used Hyundai



Hyundai Tucson 2.0A Sunroof | **\$28,800** | **\$10,770 /yr** | **01-Mar-2010** | **1,998 cc** | **142,013 km** | **SUV** | **Available**

Cheapest, Depreciation At \$9k+ Only, Full Specs Tucson With Roof And Highest OMV In Town. Low Mileage Done, Well Maintained By Harmony Motors, Previous Owner With No Expenses Spared. No Repairs Needed...


★ Posted: 25-May-2018 Tags: 2010 Hyundai Tucson, Hyundai Tucson, Hyundai, Tucson, Used Hyundai



Hyundai Tucson 2.0A | **\$27,300** | **\$10,700 /yr** | **03-Mar-2010** | **1,998 cc** | **100,000 km** | **SUV** | **Available**

Cheapest SUV To Own In Town! One Owner Only! Genuine Low Mileage Done! Beautiful Stock Paintwork! Shelter Parking! Spacious Interior! Very Good Condition! Not To Be Missed! Call Us Now! High Loan Trad...

★ Posted: 17-Jun-2018 Tags: 2010 Hyundai Tucson, Hyundai Tucson, Hyundai, Tucson, Used Hyundai




Hyundai Tucson 2.0A Sunroof | **\$35,333** | **\$10,960 /yr** | **12-Oct-2010** | **1,998 cc** | **98,000 km** | **SUV** | **Available**

Fully Agent Maintained By Komoco Mileage Done Yearly 11K Only! Original Paintwork And Accident Free! Leather Seat And Interior Of Vehicle Is Beautifully Looks New Still, See Photo! Can Tell Well Maint...

★ Posted: 11-Jun-2015 Tags: 2010 Hyundai Tucson, Hyundai Tucson, Hyundai, Tucson, Used Hyundai

Save this search criteria, to get email alerts whenever a match is found. [Save Search](#)

Make  |
 Model  |
 Price  |
 Depreciation  |
 Reg Date  |
 Eng Cap  |
 Mileage  |
 Veh Type  |
 Status 


For old advertisements, view [Expired ads](#)

20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Tucson, Tucson Singapore, used Tucson, used vehicles Singapore or even buy used Tucson Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow [sgCarMart.com](#)



PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
 GST:201006949C RCB NO:201006949C

M/S : LIM YEW TEE EVEN
 BLK 26 #05-01 SIMEI ST 1 MELVILLE PARK
 SINGAPORE 529947

Estimate No: EST1503717
 Date: 08 Jun 2018
 Policy No:
 Veh Reg No: SJY5531B
 Make/Model: HYUNDAI LM TUCSON
 2.0L AUTO ABS D/AB
 2WD 5DR
 Chassis No: KMHJU81BMBU056299
 Engine No: G4KDAA308048
 Reg. Date: 14/09/2010

ATTN: FIRST CAPITAL INSURANCE

Your Ref No: TP 0618-5099
 Claim Type: Third Party
 Accident Date: 08/06/2018
 TP Veh Reg No: SHB 2223 E

Estimate Repair Cost to Vehicle No :SJY5531B

Description	U/Price	Quantity	Price S\$	Amount S\$
List Price				
1 BONNET Bent	1,452.40	1 PC	1,452.40	✓
2 BONNET HINGE - LH Bent	43.20	1 PC	43.20	✓
3 BONNET HINGE - RH Bent	43.20	1 PC	43.20	✓
4 BONNET LOCK Bent	41.10	1 PC	41.10	✓
5 BONNET RUBBER - INNER Bent	50.70	1 PC	50.70	✓
6 BONNET RUBBER - OUTER Bent	22.56	1 PC	22.56	✓
7 BONNET INSULATOR Bent	240.90	1 PC	240.90	✓
8 BONNET INSULATOR CLIPS Bent	2.00	11 PC	22.00	✓
9 FRONT BUMPER Bent	573.30	1 PC	573.30	✓
10 FRONT BUMPER CLIPS Bent	2.00	10 PC	20.00	✓
11 FRONT BUMPER SIDE HOLDER - LH Bent	18.20	1 PC	18.20	✓
12 FRONT BUMPER SIDE HOLDER - RH Bent	18.20	1 PC	18.20	✓
13 FRONT BUMPER FOAM Bent	48.40	1 PC	48.40	✓
14 FRONT BUMPER REINFORCEMENT Bent	560.50	1 PC	560.50	✓
15 FRONT BUMPER TOWING COVER - RH Bent	12.00	1 PC	12.00	✓
16 FRONT BUMPER CENTRE LOWER GRILLE Bent	206.00	1 PC	206.00	✓
17 FRONT BUMPER UNDER LOWER GARNISH, BLACK Bent	211.50	1 PC	211.50	✓
18 FRONT BUMPER FOG LAMP ASSY - LH Bent	145.00	1 PC	145.00	✓
19 FRONT BUMPER FOG LAMP ASSY - RH Bent	145.00	1 PC	145.00	✓
20 HEAD LAMP ASSY - RH Bent	667.60	1 PC	667.60	✓
21 HEAD LAMP LOWER RETAINER - RH Bent	30.00	1 PC	30.00	✓
22 HEAD LAMP ASSY - LH Bent	667.60	1 PC	667.60	✓
23 HEAD LAMP LOWER RETAINER - LH Bent	30.00	1 PC	30.00	✓
24 FRONT FENDER - RH Buckled	548.40	1 PC	548.40	✓
25 FRONT FENDER COWLING - RH Bent	67.40	1 PC	67.40	✓
26 FRONT FENDER COWLING CLIPS - RH Bent	2.00	10 PC	20.00	✓
27 GRILLE LOGO W/BASE & CHROME ASSY Bent	105.80	1 PC	105.80	✓
28 RADIATOR Bent	783.10	1 PC	783.10	✓
29 RADIATOR TOP HOSE Bent	79.70	1 PC	79.70	✓
30 RADIATOR BOTTOM HOSE Bent	81.90	1 PC	81.90	✓
31 RADIATOR SPARE TANK Bent	28.30	1 PC	28.30	✓
32 AIRCON CONDENSER Bent	682.00	1 PC	682.00	✓
33 AIRCON DISCHARGE PIPE Bent	258.80	1 PC	258.80	✓
34 AIRCON LIQUID TUBE Bent	168.60	1 PC	168.60	✓
35 AIRCON CONDENSER SIDE GARNISH - LH Bent	20.00	1 PC	20.00	✓
36 AIRCON CONDENSER SIDE GARNISH - RH Bent	20.00	1 PC	20.00	✓

PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road I #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
GST:201006949C RCB NO:201006949C

M/S : LIM YEW TEE EVEN
BLK 26 #05-01 SIMEI ST 1 MELVILLE PARK
SINGAPORE 529947

Estimate No: EST1503717
Date: 08 Jun 2018
Policy No:
Veh Reg No: SJY5531B
Make/Model: HYUNDAI LM TUCSON
2.0L AUTO ABS D/AB
2WD 5DR

ATTN: FIRST CAPITAL INSURANCE

Your Ref No: TP 0618-5099
Claim Type: Third Party
Accident Date: 08/06/2018
TP Veh Reg No: SHB 2223 E

Chassis No: KMHJU81BMBU056299
Engine No: G4KDAA308048
Reg. Date: 14/09/2010

Estimate Repair Cost to Vehicle No :SJY5531B

Description	U/Price	Quantity	Price S\$	Amount S\$
37 AIRCON W/RADIATOR FAN BLADE, FAN COWLING, FAN MOTOR ASSY <i>Cracked</i>	699.10	1 PC	699.10 ✓	
38 WIPER TANK MOTOR <i>2 new</i>	49.70	1 PC	49.70 ✗	
39 WIPER TANK CAP	4.00	1 PC	4.00 ✗	
40 WIPER TANK	68.60	1 PC	68.60 ✗	
41 SUPPORT PANEL ASSY <i>Cracked</i>	808.00	1 PC	808.00 ✓	
42 WIPER GARNISH, SMALL - RH <i>new</i>	20.00	1 PC	20.00 ✗	
43 REAR BOOT <i>Distorted</i>	1,431.50	1 PC	1,431.50 ✓	
44 REAR BOOT H LOGO	23.00	1 PC	23.00 ✓	
45 REAR BOOT HYUNDAI WORDING <i>new</i>	26.10	1 PC	26.10 ✓	
46 REAR BOOT TUCSON WORDING	29.10	1 PC	29.10 ✓	
47 REAR BOOT TRIM <i>new</i>	291.10	1 PC	291.10 ✗	
48 REAR BOOT TOP LOCK <i>new</i>	41.10	1 PC	41.10 ✓	
49 REAR BOOT BOTTOM LOCK <i>new</i>	143.30	1 PC	143.30 ✗	
50 REAR BOOT RUBBER <i>cut</i>	69.60	1 PC	69.60 ✓	
51 REAR BOOT REFLECTOR - LH <i>new</i>	202.90	1 PC	202.90 ✗	
52 REAR BOOT REFLECTOR - RH <i>new</i>	202.90	1 PC	202.90 ✗	
53 REAR PANEL ASSY <i>Distorted</i>	636.60	1 PC	636.60 ✓	
54 REAR PANEL TOP GARNISH <i>Defect</i>	55.00	1 PC	55.00 ✓	
55 REAR BUMPER <i>Distorted</i>	446.50	1 PC	446.50 ✓	
56 REAR BUMPER CLIPS <i>new</i>	2.00	10 PC	20.00 ✓	
57 REAR BUMPER SIDE HOLDER - LH <i>new</i>	24.60	1 PC	24.60 ✓	
58 REAR BUMPER SIDE HOLDER - RH <i>new</i>	24.60	1 PC	24.60 ✓	
59 REAR BUMPER FOAM <i>Cracked</i>	82.90	1 PC	82.90 ✓	
60 REAR BUMPER REINFORCEMENT <i>Best</i>	243.70	1 PC	243.70 ✓	
61 REAR BUMPER REFLECTOR - LH <i>new</i>	70.50	1 PC	70.50 ✗	
62 REAR BUMPER REFLECTOR - RH <i>Cracked</i>	70.50	1 PC	70.50 ✓	
63 REAR BUMPER LOWER GARNISH, BLACK <i>Distorted</i>	287.60	1 PC	287.60 ✗	
64 REAR EXHAUST PIPE - REAR <i>Best</i>	1,312.90	1 PC	1,312.90 ✓	
65 REAR EXHAUST PIPE TOP PLATE <i>Best</i>	82.70	1 PC	82.70 ✗	
66 REAR EXHAUST PIPE - CENTRE <i>new</i>	770.10	1 PC	770.10 ✗	
67 REAR EXHAUST PIPE MOUNTING <i>new</i>	15.00	3 PC	45.00 ✗	
68 REAR SPARE TYRE FLOOR PANEL <i>Repairs</i>	444.50	1 PC	444.50 ✗	
69 FRONT EXHAUST <i>new</i>	641.80	1 PC	641.80 ✗	
70 ENGINE MOUNTING - LH <i>new</i>	558.60	1 PC	558.60 ✗	
71 ENGINE MOUNTING - RH <i>new</i>	398.30	1 PC	398.30 ✗	
72 ENGINE MOUNTING - REAR <i>new</i>	305.00	1 PC	305.00 ✗	

PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
 GST:201006949C RCB NO:201006949C

M/S : LIM YEW TEE EVEN
 BLK 26 #05-01 SIMEI ST 1 MELVILLE PARK
 SINGAPORE 529947

Estimate No: EST1503717
 Date: 08 Jun 2018
 Policy No:
 Veh Reg No: SJY5531B
 Make/Model: HYUNDAI LM TUCSON
 2.0L AUTO ABS D/AB
 2WD 5DR
 Chassis No: KMHJU81BMBU056299
 Engine No: G4KDAA308048
 Reg. Date: 14/09/2010

ATTN: FIRST CAPITAL INSURANCE

Your Ref No: TP 0618-5099
 Claim Type: Third Party
 Accident Date: 08/06/2018
 TP Veh Reg No: SHB 2223 E

Estimate Repair Cost to Vehicle No :SJY5531B

Description	U/Price	Quantity	Price SS	Amount SS
73 POWER STEERING PUMP <i>HP m</i>	707.20	1 PC	707.20 <i>*</i>	
		Less 20%	19,471.96	15,577.57
Special Net				
74 REAR BUMPER SENSOR <i>Dmgd</i>	400.00	1 SET	400.00 <i>✓</i>	
75 FRONT NUMBER PLATE WITH CASING <i>Bent</i>	35.00	1 SET	35.00 <i>✓</i>	
76 REAR NUMBER PLATE WITH CASING <i>Bent</i>	35.00	1 SET	35.00 <i>✓</i>	
77 REAR BOOT CAMERA <i>HP m</i>	350.00	1 SET	350.00 <i>*</i>	
78 SEALANT <i>m</i>	20.00	2 PC	40.00 <i>✓</i>	
79 SPONGE TAPE <i>m</i>	20.00	1 PC	20.00 <i>✓</i>	
			880.00	880.00
Labour				
80 TO KNOCK OUT DENTS, CUT/WELD REAR PANEL, SUPPORT PANEL, REMOVE & REPLACE ACCIDENT PARTS	1,500.00	1 JOB	1,500.00 1400	
81 TO RESPRAY PAINT ON ACCIDENT PORTIONS	1,700.00	1 JOB	1,700.00 1600	
82 TO CHECK WIRING	50.00	1 JOB	50.00 <i>✓</i>	
83 TO REMOVE, REPLACE CONDENSER AND REFILL GAS	100.00	1 JOB	100.00 <i>✓</i>	
84 TO RESET CHECK LIGHT	100.00	1 JOB	100.00 <i>*</i>	
85 TO REMOVE, REPLACE FRONT EXHAUST, REAR EXHAUST PIPE, REPAIR CENTRE PIPE	180.00	1 JOB	180.00 80	
86 TO REMOVE, REPLACE 4PCS ENGINE MOUNTINGS	200.00	1 JOB	200.00 <i>*</i>	
87 TO REMOVE, REPLACE POWER STEERING	150.00	1 JOB	150.00 <i>*</i>	
88 TO TUFF-KOTE	120.00	1 JOB	120.00 60	
89 TO LIFT UP ENGINE	80.00	1 JOB	80.00 <i>*</i>	
90 TO REMOVE, REFIX REAR BOOT GLASS	120.00	1 JOB	120.00 <i>✓</i>	
91 TO REMOVE, REFIX REAR GARNISH	150.00	1 JOB	150.00 80	
			3490	4,450.00

PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
GST:201006949C RCB NO:201006949C

M/S : LIM YEW TEE EVEN
BLK 26 #05-01 SIMEI ST 1 MELVILLE PARK
SINGAPORE 529947

ATTN: FIRST CAPITAL INSURANCE

Your Ref No: TP 0618-5099
Claim Type: Third Party
Accident Date: 08/06/2018
TP Veh Reg No: SHB 2223 E

Estimate No: EST1503717
Date: 08 Jun 2018
Policy No:
Veh Reg No: SJY5531B
Make/Model: HYUNDAI LM TUCSON
2.0L AUTO ABS D/AB
2WD 5DR
Chassis No: KMHJU81BMBU056299
Engine No: G4KDAA308048
Reg. Date: 14/09/2010

Estimate Repair Cost to Vehicle No :SJY5531B

Description	U/Price	Quantity	Price	Amount
			<u>SS</u>	<u>SS</u>
			Total	S\$ 20,907.57
			Add GST @ 7%	1,463.53
			Total Amount Payable	S\$ 22,371.10

TOTAL: SINGAPORE DOLLAR TWENTY TWO THOUSAND THREE HUNDRED SEVENTY ONE AND CENTS TEN ONLY

Adrian Ling -
h/s 18/06/18.

12 Days

For PROGRESSIVE AUTOMOTIVE PTE LTD

AUTHORISED SIGNATURE

total: 14375.36
h/s 11 SK

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer


Signature:

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18010911/Atd3e2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 17-09-2018		
		Code : FCI2 ✓		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 2223E ✓	Veh. Inspected	SJY 5531B ✓	
Policy No.	D-18088937MFSH ✓	Coverage (\$)	0.00	
Claim No.	D18004693MFSH ✓	Excess (\$)	0.00	
Assign From	SITHARA ✓	Assign Date	14/06/2018 ✓	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI TUCSON ✓	c.c	1998 ✓	
Engine No.	HIDDEN	Year of Reg.	2010 ✓	
Chassis No.	KMHJU81BMBU056299 ✓	Colour	SILVER ✓	
Odometer	103787 ✓	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/60 R17 ✓	HANKOOK ✓	6 mm ✓	
L/H Front Tyre	225/60 R17 ✓	HANKOOK ✓	6 mm ✓	
R/H Rear Tyre	225/60 R17 ✓	HANKOOK ✓	6 mm ✓	
L/H Rear Tyre	225/60 R17 ✓	HANKOOK ✓	6 mm ✓	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/06/2018 ✓	Inspection Date	18/06/2018 ✓	
Survey held at	PROGRESSIVE AUTOMOTIVE PTE LTD BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. ✓ B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. ✓ C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. ✓				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days ✓		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJY 5531B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BONNET	DENTED	1,452.40	1,452.40
1	BONNET HINGE - LH	BENT	43.20	43.20
1	BONNET HINGE - RH	BENT	43.20	43.20
1	BONNET LOCK	DAMAGED	41.10	41.10
1	BONNET RUBBER - INNER	NOT NECESSARY	50.70	-
1	BONNET RUBBER - OUTER	NOT NECESSARY	22.56	-
1	BONNET INSULATOR	CRUMPLED	240.90	240.90
11	BONNET INSULATOR CLIPS @\$2.00	NECESSARY	22.00	22.00
1	FRONT BUMPER	DISTORTED	573.30	573.30
10	FRONT BUMPER CLIPS @\$2.00	NECESSARY	20.00	20.00
1	FRONT BUMPER SIDE HOLDER- LH	NECESSARY	18.20	18.20
1	FRONT BUMPER SIDE HOLDER - RH	NECESSARY	18.20	18.20
1	FRONT BUMPER FOAM	NOT NECESSARY	48.40	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	560.50	-
1	FRONT BUMPER TOWING COVER - RH	NOT NECESSARY	12.00	-
1	FRONT BUMPER CENTRE LOWER GRILLE	DISTORTED	206.00	206.00
1	FRONT BUMPER UNDER LOWER GARNISH, BLACK	NOT NECESSARY	211.50	-
1	FRONT BUMPER FOG LAMP ASSY - LH	NOT NECESSARY	145.00	-
1	FRONT BUMPER FOG LAMP ASSY - RH	NOT NECESSARY	145.00	-
1	HEAD LAMP ASSY - RH	CRACKED	667.60	667.60
1	HEAD LAMP LOWER RETAINER - RH	BENT	30.00	30.00
1	HEAD LAMP ASSY - LH	CRACKED	667.60	667.60
1	HEAD LAMP LOWER RETAINER - LH	BENT	30.00	30.00
1	FRONT FENDER - RH	BUCKLED	548.40	548.40
1	FRONT FENDER COWLING - RH	NOT NECESSARY	67.40	-
10	FRONT FENDER COWLING CLIPS - RH @\$2.00	NOT NECESSARY	20.00	-
1	GRILLE LOGO W/BASE & CHROME ASSY	DEFORMED	105.80	105.80
1	RADIATOR	BENT	783.10	783.10
1	RADIATOR TOP HOSE	NOT NECESSARY	79.70	-
1	RADIATOR BOTTOM HOSE	NOT NECESSARY	81.90	-
1	RADIATOR SPARE TANK	NOT NECESSARY	28.30	-

Report Ref No. CS/FCI18010911/Atd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	AIRCON CONDENSER	BENT	682.00	682.00
1	AIRCON DISCHARGE PIPE	BENT	258.80	258.80
1	AIRCON LIQUID TUBE	NOT NECESSARY	168.60	-
1	AIRCON CONDENSER SIDE GARNISH - LH	NOT NECESSARY	20.00	-
1	AIRCON CONDENSER SIDE GARNISH - RH	NOT NECESSARY	20.00	-
1	AIRCON W/RADIATOR FAN BLADE, FAN COWLING, FAN MOTOR ASSY	CRACKED	699.10	699.10
1	WIPER TANK MOTOR	NOT NECESSARY	49.70	-
1	WIPER TANK CAP	NOT NECESSARY	4.00	-
1	WIPER TANK	NOT NECESSARY	68.60	-
1	SUPPORT PANEL ASSY	CRACKED	808.00	808.00
1	WIPER GARNISH, SMALL - RH	NOT NECESSARY	20.00	-
1	REAR BOOT	DISTORTED	1,431.50	1,431.50
1	REAR BOOT H LOGO	NECESSARY	23.00	23.00
1	REAR BOOT HYUNDAI WORDING	NECESSARY	26.10	26.10
1	REAR BOOT TUCSON WORDING	NECESSARY	29.10	29.10
1	REAR BOOT TRIM	NOT NECESSARY	291.10	-
1	REAR BOOT TOP LOCK	DAMAGED	41.10	41.10
1	REAR BOOT BOTTOM LOCK	NOT NECESSARY	143.30	-
1	REAR BOOT RUBBER	CUT	69.60	69.60
1	REAR BOOT REFLECTOR - LH	NOT NECESSARY	202.90	-
1	REAR BOOT REFLECTOR - RH	NOT NECESSARY	202.90	-
1	REAR PANEL ASSY	DISTORTED	636.60	636.60
1	REAR PANEL TOP GARNISH	DEFORMED	55.00	55.00
1	REAR BUMPER	DISTORTED	446.50	446.50
10	REAR BUMPER CLIPS @\$2.00	NECESSARY	20.00	20.00
1	REAR BUMPER SIDE HOLDER - LH	NECESSARY	24.60	24.60
1	REAR BUMPER SIDE HOLDER - RH	NECESSARY	24.60	24.60
1	REAR BUMPER FOAM	CRACKED	82.90	82.90
1	REAR BUMPER REINFORCEMENT	BENT	243.70	243.70
1	REAR BUMPER REFLECTOR - LH	NOT NECESSARY	70.50	-
1	REAR BUMPER REFLECTOR - RH	CRACKED	70.50	70.50
1	REAR BUMPER LOWER GARNISH, BLACK	DEFORMED	287.60	287.60

Report Ref No. CS/FCI18010911/Atd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR EXHAUST PIPE - REAR	BENT	1,312.90	1,312.90
1	REAR EXHAUST PIPE TOP PLATE	BENT	82.70	82.70
1	REAR EXHAUST PIPE - CENTRE	NOT NECESSARY	770.10	-
3	REAR EXHAUST PIPE MOUNTING @\$15.00	DAMAGED	45.00	45.00
1	REAR SPARE TYRE FLOOR PANEL	TO REPAIR SEE LABOUR	444.50	-
1	FRONT EXHAUST	NOT NECESSARY	641.80	-
1	ENGINE MOUNTING - LH	NOT NECESSARY	558.60	-
1	ENGINE MOUNTING - RH	NOT NECESSARY	398.30	-
1	ENGINE MOUNTING - REAR	NOT NECESSARY	305.00	-
1	POWER STEERING PUMP	NOT NECESSARY	707.20	-
	LESS 20% DISCOUNT		-3,894.39	-2,582.38
			15,577.57	10,329.52
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER SENSOR (SN)	DAMAGED	400.00	400.00
1	SET FRONT NUMBER PLATE WITH CASING (SN)	BENT	35.00	35.00
1	SET REAR NUMBER PLATE WITH CASING (SN)	BENT	35.00	35.00
1	SET REAR BOOT CAMERA (SN)	NOT NECESSARY	350.00	-
2	SEALANT @\$20.00 (SN)	NECESSARY	40.00	40.00
1	SPONGE TAPE (SN)	NECESSARY	20.00	20.00
			880.00	530.00
	<u>LABOUR</u>			
	TO KNOCK OUT DENTS, CUT / WELD REAR PANEL, SUPPORT PANEL, REMOVE & REPLACE ACCIDENT PARTS. INCLUSIVE OF THE REPAIR OF REAR SPARE TYRE FLOOR PANEL.		1,500.00	1,400.00
	TO RESPRAY PAINT ON ACCIDENT PORTIONS.		1,700.00	1,600.00
	TO CHECK WIRING.		50.00	50.00
	TO REMOVE, REPLACE CONDENSER AND REFILL GAS.		100.00	100.00
	TO RESET CHECK LIGHT.	NOT NECESSARY	100.00	-
	TO REMOVE, REPLACE FRONT EXHAUST, REAR EXHAUST PIPE, REPAIR CENTRE PIPE.		180.00	80.00
	TO REMOVE, REPLACE 4PCS ENGINE MOUNTINGS.	NOT NECESSARY	200.00	-
	TO REMOVE, REPLACE POWER STEERING.	NOT NECESSARY	150.00	-

Report Ref No. CS/FCI18010911/Atd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TUFF KOTE.	NOT NECESSARY	120.00	60.00
	TO LIFT UP ENGINE.		80.00	-
	TO REMOVE, REFIX REAR BOOT GLASS.		120.00	120.00
	TO REMOVE, REFIX REAR GARNISH		150.00	80.00
			4,450.00	3,490.00
GRAND TOTAL			20,907.57	14,349.52

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				11,500.00
---	--	--	--	-----------

Report Ref No. CS/FCI18010911/Atd3e2

MARKET VALUE: \$33,000.00 (EST)-PAPER VALUE: \$20,400.00=NETT VALUE: \$12,600.00

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.