

LA Auto

106 Punggol Walk #09-16 Twin Waterfalls
Singapore 828793 Email : laautoamk@gmail.com

Not Authorised
Monday 11.3.1 8 days
Monday 34 rain

M/s AXA Insurance Singapore Pte Ltd

DATE 14.06.2018

No 8 Shenton Way #27-02 AXA Tower

CAR NO SLK 9028 L

S068811 Tel 63387288 Fax 68804838

MAKE Toyota Altis

ESTIMATED COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE

YOUR INSURED : SBM 3818 X

Pc	Pcs	MR053REH104551650	UNIT PRICE	AMOUNT	
1	pc	Right side front door outer mirror	SL	\$1,250.00	X
1	pc	Rear right side mudguard	B1	\$925.00	✓
1	pc	Rear right side mudguard inner cowling	SL	\$55.00	X
8	pcs	Rear right side mudguard inner cowling clips	\$5.00	\$40.00	X
1	pcs	Rear right side tyre rim <i>Pr ? (front & rear)</i>	SL	\$705.00	X2
1	pc	Rear right side tyre	CU 70%	\$399.60	70%
1	pc	Rear right side knuckle arm		\$214.00	?
1	pc	Rear right side lower arm		\$107.00	?
1	pc	Rear right side wheel bearing		\$58.85	?
1	pc	Rear right side door	B1	\$923.20	✓
1	pc	Rear right side door gear motor		\$586.60	?
1	pc	Rear right side door channel	SL	\$85.24	X
1	pc	Rear right side door inner board	SL	\$768.90	X
1	pc	Rear right side door top moulding	SL	\$85.00	X
1	pc	Rear right side door outer handle	SL	\$75.50	X
1	pc	Rear right side door vertical sticker	SL	\$75.90	✓
1	pc	Rear right side door horizontal "	SL	\$75.90	✓
1	pc	Rear right side door top hinge	SL	\$75.00	X
1	pc	Rear right side door lower hinge	SL	\$85.00	X
1	pc	Rear right side door stopper	B1	\$151.50	X
1	pc	Front right side door	B1	\$978.60	✓
1	pc	Front right side door gear motor		\$586.60	?
1	pc	Front right side door channel	SL	\$85.24	X
1	pc	Front right side door inner board	SL	\$768.90	X
1	pc	Front right side door vertical sticker	SL	\$75.90	✓
1	pc	Front right side door horizontal "	SL	\$75.90	✓
1	pc	Front right side door outer handle	SL	\$95.50	✓
1	pc	Front right side door top moulding	SL	\$85.00	X
1	pc	Front right side door top hinge	SL	\$75.00	X
1	pc	Front right side door lower hinge	SL	\$85.00	X
1	pc	Front right side door stopper	SL	\$151.50	X
1	pc	Front right side fender	B1	\$617.30	✓
1	pc	Front right side fender inner cowling	SL	\$236.70	✓
8	pcs	Front right side fender inner cowling clips	\$5.00	\$40.00	✓
1	pc	Rear wind screen moulding	SL	\$90.00	✓
			Total		

LA Auto

259

Page 1 Of 2

LA Auto

106 Punggol Walk #09-16 Twin Waterfalls
Singapore 828793 Email : laautoamk@gmail.com

M/s AXA Insurance Singapore Pte Ltd

DATE 14.06.2018

No 8 Shenton Way #27-02 AXA Tower

CAR NO SLK 9028 L

S068811 Tel 63387288 Fax 68804838

MAKE Toyota Altis

ESTIMATED COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE

YOUR INSURED : SBM 3818 X

Pc	Pcs	MR053REH104551650	UNIT PRICE	AMOUNT
		Continue from page one.		\$10,789.33
		To spray anti-rust coating on new & affected panels.		\$250.00 <i>120%</i>
		Computer alignment and jack camber.		\$180.00 <i>80%</i>
		Labour for jacking, knocking right side center door pillar, cutting right side rear mudguard, dismantle and replace the above mentioned parts.		\$1,500.00 <i>1100%</i>
		Labour for respray right side front fender, right side front door, center door pillar, right side rear door, right side rear mudguard & touch up front and rear bumper.		\$1,400.00 <i>120%</i>
		To apply silicon onto rear wins screen.		\$60.00 <i>40%</i>
		Labour for dismantle & refix rear wind screen.		\$140.00 <i>120%</i>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Page 2 Of 2

Total

\$14,319.33


LA Auto