

Surveyor:

Kenneth

DOI:

ASSIGNMENT

13-6-18

Date / Time:

13-6-18

Registered in Meriman:

13-6-18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHC 3801A

Name of Insured:

C/P

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

11-6-18

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

Ng Chuan Ho

Driver Tel No.:

88695282

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

562 72326



INSRS:

WSP:

Tel:

Liability:

RMKS:

Cheng Hoe



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

20/6  
WU

562 72326 - X

SHC 3801A - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Kenneth

Repair Cost:

UG

S\$ 3400.00

( 6 days)

Reduction:

2582.50 % 43

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

27

If NO or B 28, Ass. Lia.:

Repair Cost:

(W/MT)

S\$ 3638.00

Loss of Rental (LOR):

S\$ 223.08

( 8.5 days)

\* \$90.95

Loss of Use (LOU):

S\$

-

(\$

x

days)

Loss of Income (LOI):

S\$

-

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

(Tick only one)

GIA/LTA Search

S\$

-

Medical:

S\$

-

Disbursement:

S\$

-

(e.g. Tow/ Independent)

Legal Cost

S\$

-

Total:

S\$ 4411.08

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$ 4411.08

Name 1:

Cheng Hoe Motor Pte Ltd

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

#3291

COPY SENT  
19/11/18

REF: III

## ASSIGNMENT

From:

Date:

13/06/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SGZ 7232G

at Workshop m/s

Cheng Hoe Motor

of BIK 1019 Yishun Ind. Prk A #01-374

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.:

Yes or No

Lum Sum:

20 %

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted

Veh No:

SGZ 7232G Yr Regn: 11 07

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mit Laca GLX cc 1584

Colour:

n. Silver A/C Insured / Std / NI / NA

Sp. Reading

123984 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JMYSTCS3A8U 002768

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STE A/Rim or

Tyre Size:

F:

R:

195/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

11/6/18

D.O.I.

13/6/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

14/6 File parts to Coroner

11/7 4/Sup @ 3400 Confirm Ebooks (6x24x85+417)

(Red = \$7582.50 / 43%)

Date/Time: File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

1) 3-PC 94

2) Photos

3) Other

4) TOTAL

TOTAL

Add Fee:

☐

: Site Insp

☐

: Interview

☐

: Tech Inps

☐

: Weekend

Report Format :

Lump Sum / L.B.I. (\$) :

# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
 GST:201001158E RCB NO:201001158E

SGZ 7232G  
 TP/India

M/S : INDIA INT'L INSURANCE PTE LTD  
 64 CECIL STREET  
 #04/#05 IOB BUILDING  
 SINGAPORE 049711

TEL: 63476100  
 ATTN: Motor Claim Department

FAX: 62247743

Estimate No: ES1890648/YISHUN  
 Date: 12 Jun 2018  
 Policy No: SI18V05352/VPE/R03  
 Veh Reg No: SGZ7232G  
 Make/Model: MITSUBISHI LANCER  
 1.6 A

WS Ref: TP/INDIA/YS  
 Claim Type: Third Party  
 Accident Date: 11/06/2018  
 TP Veh Reg No: SHC3801A

Chassis No: JMYSTCS3A8U002768  
 Engine No: 4G18JL1124  
 Reg. Date: 15/11/2007

## Estimate Repair Cost to Vehicle No :SGZ7232G

PAGE:1/1

Description	U/Price	Quantity	List Price SS	Amount SS
<b>List Price</b>				
1 REAR BUMPER	689.00	1 PC	By 689.00	—
2 REAR BUMPER LOWER SKIRT	688.00	1 PC	By 688.00	—
3 REAR BUMPER LH RETAINER	50.00	1 PC	By 50.00	—
4 REAR BUMPER CLIPS	3.50	6 PCS	By 21.00	—
5 REAR BUMPER CENTRE BEAM	209.00	1 PC	By 209.00	—
6 TAILLAMPS	351.00	2 PCS	By 702.00	—
7 REAR BOOT	567.00	1 PC	By 567.00	—
8 REAR BOOT LOGO	55.00	1 PC	By 55.00	—
9 REAR BOOT EMBLEM 'LANCER'	30.00	1 PC	By 30.00	—
10 REAR BOOT EMBLEM 'GLX'	29.00	1 PC	By 29.00	—
11 REAR BOOT INNER LOCK	64.00	1 PC	By 64.00	—
12 REAR BOOT INNER RUBBER	175.00	1 PC	By 175.00	—
13 REAR PANEL	583.00	1 PC	By 583.00	—
14 REAR PANEL INNER GARNISH	156.00	1 PC	By 156.00	—
15 REAR PANEL INNER GARNISH CLIPS	3.50	6 PCS	By 21.00	—
16 REAR SPARE TYRE TOP BOARD	147.00	1 PC	By 147.00	—
17 REAR EXHAUST PIPE	439.00	1 PC	By 439.00	—
			4,625.00	
		Less 10%	462.50	4,162.50
<b>Labour</b>				
18 REMOVE & REFIX REAR BUMPER ASSY, TAILLAMPS, LOWER SKIRT, REAR BOOT & ATTACHMENT, TO CUT, WELD & RENEW REAR PANEL, KNOCK & REPAIR REAR FENDERS, REAR SPARE TYRE COMPARTMENT & REALIGN THE SAME	850.00	1 LA	850.00	700
19 PUTTY & RESPRAY ON REAR SPARE TYRE COMPARTMENT, REAR FENDERS, REAR BOOT, HINGES, REAR BUMPER, BEAM, LOWER SKIRT &	850.00	1 LA	850.00	750
20 TO REMOVE & REFIX REAR EXHAUST & CHECK SYSTEM	60.00	1 LA	60.00	—
21 RUSTPROOFING	60.00	1 LA	60.00	—
			1,820.00	1,820.00

Total SS \$5,982.50

Add GST @ 7% 418.78

Total Amount Payable SS \$6,401.28

LKK Auto Consultants hence notify  
 the Repairer of the following:  
 • To resurvey before/after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and  
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC  
Owner ID: 6098C

**Vehicle Details**

Vehicle No.: SGZ7232G  
Vehicle to be Exported: No  
Intended De-registration Date: 12 Jun 2018  
Vehicle Make: MITSUBISHI  
Vehicle Model: LANCER 1.6 A  
Primary Colour: Silver  
Manufacturing Year: 2007  
Engine No.: 4G18JL1124  
Chassis No.: JMYSTCS3A8U002768  
Maximum Power Output: 79.0 kW (105 bhp)  
Open Market Value: \$12,064.00  
Original Registration Date: 15 Nov 2007  
First Registration Date: 15 Nov 2007  
Transfer Count: 1  
Actual ARF Paid: \$13,152.00

**Intended PARF Rebate Details**

PARF Eligibility: Forfeited  
PARF Eligibility Expiry Date: -  
PARF Rebate Amount: \$0.00

**Intended COE Rebate Details**

COE Expiry Date: 14 Nov 2027  
COE Category: A - Car (1600cc & below)  
COE Period(Years): 10  
PQP Paid: \$41,994.00  
COE Rebate Amount: \$39,567.00  
**Total Rebate Amount: \$39,567.00**

The information contained herein is correct as at 12 Jun 2018

OK

## Nivitha (LKK Auto)

---

**From:** Motor Claim - III <motorclaim@iii.com.sg>  
**Sent:** Tuesday, 12 June 2018 4:18 PM  
**To:** Cheng Hoe Motor Pte Ltd (Yishun-June); 'sur@lkkauto.com'; Catherine Chong (LKK Auto)  
**Cc:** Zuhaidah Samsuri  
**Subject:** RE: Repair Survey (Single Joint Expert) - SGZ7232G

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SGZ7232G and let us have your report urgently.

This claim will be handled by Ms Aida.

\*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,  
Gabriel Wee  
Motor Claims Dept.  
India International Insurance Pte Ltd  
64 Cecil Street | #05 IOB Building | Singapore 049711  
Tel: 6347 6100, Ext - 248

-----Original Message-----

From: Cheng Hoe Motor Pte Ltd (Yishun-June) [mailto:chmotor@singnet.com.sg]  
Sent: 12 June, 2018 2:41 PM  
To: Motor Claim - III <motorclaim@iii.com.sg>  
Subject: Re: Repair Survey (Single Joint Expert) - SGZ7232G

Hi,

Our selection as below :-

- LKK Auto Consultants Pte Ltd

Pls assist to arrange for survey (SJE) asap.

Thank you.

Rgds  
June Phua  
Cheng Hoe Motor Pte Ltd  
Tel :67556142  
Fax : 67557719

-----Original Message-----

From: Motor Claim - III  
Sent: Tuesday, June 12, 2018 2:22 PM

4.24pm @ 12/6/18  
person @ effeda  
vehicle in  
average on 13/06/18

To: Cheng Hoe Motor Pte Ltd (Yishun-June)  
Subject: RE: Repair Survey (Single Joint Expert) - SGZ7232G

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,  
Gabriel Wee  
Motor Claims Dept.  
India International Insurance Pte Ltd  
64 Cecil Street | #05 IOB Building | Singapore 049711  
Tel: 6347 6100, Ext - 248

-----Original Message-----

From: Cheng Hoe Motor Pte Ltd (Yishun-June) [mailto:chmotor@singnet.com.sg]  
Sent: 12 June, 2018 1:30 PM  
To: Motor Claim - III <motorclaim@iii.com.sg>  
Subject: Repair Survey (Single Joint Expert) - SGZ7232G

Dear Sir,

OUR CLIENT – SGZ7232G  
DOA : 11/6/18 @7.15pm  
YR INSURED : SHC3801A

Kindly provide us of your surveyor listing for the selection on the survey.

Thank you.

Regards  
Efeeda  
Cheng Hoe Motor Pte Ltd  
Tel :67556142  
Fax : 67557719

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.  
It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful.

Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful.

Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

## Print Received Message

This mail is associated with :

**\*SGZ7232G (MCT18060344)**

**[SHC3801A]**

TP

KOH SWEE HENG BENJAMIN (XU RUIXING)

Jun 11 2018 7:00PM

[-]

Cheng Hoe Motor Pte Ltd

**From** India International Insurance Pte Ltd (HQ) (III\_SG), sent on 30/10/2019 09:23 AM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$4411.08) - SGZ7232G - Claim Handler: Zuhaidah Bte Samsuri

Approved:4411.08.



### ...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Jun 2018 <a href="#">Edit Reg</a>		13 Jun 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$3,400.00</b> <a href="#">Edit Estimates</a>	<b>S\$3,400.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

## CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Main Claimant:	KOH SWEE HENG BENJAMIN (XU RUIXING), ID: S8426098C		
Vehicle Reg. No.:	SGZ7232G	Date of Loss:	11/06/2018 19:00 - :59 [126 Months and 27 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MCT18060344	Policy/Cover Note No.:	MCOM0015
Vehicle Reg. No. (Insured):	SHC3801A	Policy No. (Claimant):	SI18V05352/VPE/R03
		Excess:	
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by <b>Zuhaidah Bte Samsuri</b> - 6347 6070]		
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... [Final Rpt due 27/06/2018]		

## ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- III\_SG (30/10/2019): Alert - Adj Mandate Approved (S\$4411.08) - SGZ7232G - Claim Handler: Zuhaidah Bt...
- III\_SG (23/10/2019): Alert - Adj Mandate Maintained - SGZ7232G - Claim Handler: Zuhaidah Bte Samsuri
- III\_SG (02/07/2018): Alert - Adj Mandate Approved (S\$0.00) - SGZ7232G - Claim Handler: Zuhaidah Bte S...

## ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SGZ7232G (MCT18060344)  
[SHC3801A]










































TP

KOH SWEE HENG BENJAMIN (XU RUIXING)

Jun 11 2018 7:00PM

[COMFORT TRANSPORTATION PTE LTD]

Cheng Hoe Motor Pte Ltd

Upload Documents   Upload Photos   Compose New Letter			View <span>View in Browser</span>	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/10/19 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
2	22/10/19 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
3	22/10/19 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
4	22/10/19 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
5	22/10/19 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
6	22/10/19 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
7	22/10/19 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
8	22/10/19 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
9	22/10/19 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
10	22/10/19 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
11	22/10/19 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
12	22/10/19 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
13	22/10/19 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
14	22/10/19 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
15	22/10/19 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
16	22/10/19 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
17	22/10/19 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
18	22/10/19 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
19	22/10/19 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
20	22/10/19 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
21	22/10/19 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
22	22/10/19 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
23	22/10/19 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
24	22/10/19 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
25	22/10/19 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
26	22/10/19 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
27	22/10/19 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
28	22/10/19 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
29	22/10/19 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
30	22/10/19 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
31	22/10/19 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
32	22/10/19 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
33	29/10/19 17:19	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
34	29/10/19 17:19	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
35	29/10/19 17:19	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/06/18 14:40	ACKNOWLEDGEMENT EMAIL TO III DD 12.06.2018	 Load PDF	
2	23/06/18 16:01	TP ESTIMATE - MARKED	 Load PDF	
3	23/06/18 16:01	TP GIA REPORT	 Load PDF	
4	21/10/19 17:13	WORKSHOP INVOICE	 Load PDF	
5	21/10/19 17:13	RENTAL RECEIPT	 Load PDF	
6	21/10/19 17:13	LOD	 Load PDF	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
7	20/12/19 14:07	AUTHORISATION TO ACT FORM	1	Load PDF	
8	20/12/19 14:07	DISCHARGE VOUCHER	1	Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	19/06/18 08:52	Singapore Accident Statement	1	Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<div> Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div></div> </div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18010945/KGA3Q2

Date: 20/12/2019

## REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015  
 Claimant: SGZ7232G Insured Vehicle No: SHC3801A  
 Vehicle No: SGZ7232G  
 Date of Loss: 11/06/2018 Nature of Claim: TP Claim No: MCT18060344

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SGZ7232G  
 Make & Model: MITSUBISHI LANCER, 1.6 (A) Engine No: 4G18JL1124  
 Reg. Date: 15/11/2007 (Man. Year: 2007) Chassis No: JMYSTCS3A8U002768  
 Colour: Metallic Silver Odometer: 123984 km  
 Engine Capacity: 1584 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 195/60 R15 Rear Tyre Size: 195/60 R15  
 Front Left Side: Yokohama 5 mm Rear Left Side: Yokohama 5 mm  
 Front Right Side: Yokohama 5 mm Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,162.50	2,724.50	1,438.00	34.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,820.00	1,570.00	250.00	13.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,982.50</b>	<b>4,294.50</b>	<b>1,688.00</b>	<b>28.22</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,400.00</b>		
(S\$)	5,982.50	3,400.00	2,582.50	43.17
<b>+ GST 7.00/7.00% (S\$)</b>	<b>418.78</b>	<b>238.00</b>	<b>180.78</b>	<b>43.17</b>
<b>Nett Amount (S\$)</b>	<b>6,401.28</b>	<b>3,638.00</b>	<b>2,763.28</b>	<b>43.17</b>
<b>+ Car Rental (8.5 x S\$90.95/day) (S\$)</b>		<b>773.08</b>		
<b>Nett Liability (S\$)</b>		<b>4,411.08</b>		

## INSPECTION

Date of Assignment: 13/06/2018  
 Date Inspected: 13/06/2018 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)  
 Blk 1019 #01-374/382, Yishun  
 Industrial Park A  
 Singapore 768761

Estimated Period of Repair: 6.0 days

**Adjuster:** KENNETH KONG

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 21 Oct 2019)
<b>Parts:</b>	143	MITSUBISHI LANCER 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SGZ7232G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	689.00 FL	*689.00 FL
2	1		*REAR BUMPER LOWER SKIRT	Buckled	688.00 FL	*688.00 FL
3	1		*REAR BUMPER LH RETAINER	Distorted	50.00 FL	*50.00 FL
4	6		*REAR BUMPER CLIPS	Necessary	21.00 FL	*21.00 FL
5	1		*REAR BUMPER CENTRE BEAM	Buckled	209.00 FL	*209.00 FL
6	1		*TAILLAMPS	O/S Cracked	702.00 FL	*351.00 FL
7	1		*REAR BOOT	Bent	567.00 FL	*567.00 FL
8	1		*REAR BOOT LOGO	Necessary	55.00 FL	*55.00 FL
9	1		*REAR BOOT EMBLEM LANCER	Necessary	30.00 FL	*30.00 FL
10	1		*REAR BOOT EMBLEM GLX	Necessary	29.00 FL	*29.00 FL
11	1		*REAR BOOT INNER LOCK	Dented	64.00 FL	*64.00 FL
12	1		*REAR BOOT INNER RUBBER (50%)	Dented / Distorted	157.50 FS	*87.50 FS
13	1		*REAR PANEL	Repair	583.00 FL	*- FL
14	1		*REAR PANEL INNER GARNISH	Mtg Cracked	156.00 FL	*156.00 FL
15	6		*REAR PANEL INNER GARNISH CLIPS	Necessary	21.00 FL	*21.00 FL
16	1		*REAR SPARE TYRE TOP BOARD	Serviceable	147.00 FL	*- FL
17	1		*REAR EXHAUST PIPE	Repair	439.00 FL	*- FL

F=Franchise part. S=SpcNelt. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>4,607.50</b>	<b>3,017.50</b>
<b>- List Item Discount on L Items 10.00/10.00% (S\$)</b>	<b>445.00</b>	<b>293.00</b>
<b>Total Parts (S\$)</b>	<b>4,162.50</b>	<b>2,724.50</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REFIX REAR BUMPER ASSY ,TAILLAMPS ,LOWER SKIRT ,REAR BOOT & ATTACHMENT ,TO CUT ,WELD & RENEW REAR PANEL KNOCK & REPAIR REAR FENDERS ,REAR SPARE TYRE COMPARTMENT & REALIGN THE SAME	New	850.00	700.00
2	PUTTY & RESPRAY ON REAR SPARE TYRE COMPARTMENT ,REAR FENDERS ,REAR BOOT ,HINGES ,REAR BUMPER ,BEAM ,LOWER SKIRT &	New	850.00	750.00
3	TO REMOVE & REFIX REAR EXHAUST & CHECK SYSTEM	New	60.00	60.00
4	RUSTPROOFING	New	60.00	60.00
Gross Labour Cost (S\$)			1,820.00	1,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >