

003 / LPO 180 10947, K1ea3n2

LKK:
DAC:

Surveyor:

AWK

DOI:

ASSIGNMENT

14-6-18

Date / Time:

14-6-18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLT 3927 J

Name of Insured:

ABDUL KAPIM B. SUDAN

Insured Tel No.:

HP: 91734987

Excess Sec II : S\$

D.O.A: 14-6-18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SHO 1212 H



INSRS:

WSP:

Tel:

Liability:

RMKS:

Premier



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

25/6

0800

SHO 1212 H. X; SLT 3927 J. X

FILE REVIEW: HZR.

31-7-18 FILE PASS TO TYPIST TO PREPARE REPORT.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time: 9-7-18

Confirm with:

Confirm by: AWK

Repair Cost:

PIP S\$3,604.85

(3 days)

Reduction:

63 %

Email

Call

FINAL SETTLEMENT

Date/Time: 10-09-18

Confirm with: GARY

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

w/651

S\$3,851.19

OI: REAR END TP

Loss of Rental (LOR):

S\$ 769.58

(7 days)

x *109.94

Loss of Use (LOU):

S\$ -

(\$

x

days)

Loss of Income (LOI):

S\$ -

(\$

x

days)

LOR only ☒LOU only ☐LOR + LOU ☐LOR + LOI ☐

(Tick only one)

GIA/LTA Search

S\$ 2.00

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

Total:

S\$ 4,628.71

Global Sum S\$:

FINAL PAYMENT

Date/Time: 10-09-18

Confirm with: GARY

Email

Call

Payee 1:

S\$ 4,628.71

Name 1:

PREMIER AUTOMOTIVE SERVICES PTE LTD

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

+ 150

COPY SENT
G17/10/18

(08/11/13)

Q Insure: Kalvin

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3 days

Res.: Yes or No

Lum Sum:

- %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHP1212H

Yr Regn:

2nd Mar, 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai 230

c.c. 15 &

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

74455

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

TMAD2814V.HJ125061

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / SIRim / STD / RIm or

Tyre Size:

F:

195 / 65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Maxxis

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

14/6/18

D.O.I.

14/6/18

Survey held at

Premier

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Loop as

Date / Time

Action / Instruction

PIP: 93.604.85 (RED: 76.06335 63%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format:

Lump Sum / I.B.I. (\$

Mei Kwan (LKKAUTO)

From: ONG LI LI <llong@lonpac.com>
Sent: Friday, 22 June, 2018 10:13 AM
To: Mei Kwan (LKKAUTO); MT_Claim_SG
Cc: Asher Sng (LKKAUTO); Joy Irene (LKKAUTO); Admin A
Subject: RE: Direct Settlement - Accident Involving SLT3927J (OI : LPC - 17/18/18/VP05/020682) AND SHD1212H (TP : LKK REF - CC3/LPC18010947/K1ea3) on 14/06/2018
Attachments: SLT3927J 140618.PDF
Categories: HMK

Dear Mei Kwan

Please see attached for our Insured's GIA report that you have requested.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]
Sent: Friday, 22 June, 2018 9:55 AM
To: MT_Claim_SG
Cc: GERALD POH WEE BIN; ONG LI LI; ERIC WOO JUN KIAT; Asher Sng (LKKAUTO); Joy Irene (LKKAUTO); Admin A
Subject: Direct Settlement - Accident Involving SLT3927J (OI : LPC - TBA) AND SHD1212H (TP : LKK REF - CC3/LPC18010947/K1ea3) on 14/06/2018

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case.

We had inspected TP vehicle SHD 1212H at M/s Premier Automotive Services Pte Ltd – Changi.

Enclosed for your perusal is:

- TP GIA report
- Estimated cost of repair
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Meanwhile, kindly assist to verify validity of our insured's policy and let us have a copy of insured's accident report for our necessary action.

Please take note that the case handler in-charge is Asher and she can be contacted at DID: 6841 6051.

To check availability of the case handler, you may contact the undersigned.

REPUBLIC OF SINGAPORE
 Identity Card No. S8233041J
 Name: SHEN XUMING
 Date of Birth: 05 Oct 1982
 Sex: M
 Country of Birth: SINGAPORE
 Issue Date: 17 Dec 2007
 Barcode: 001952501H

REPUBLIC OF SINGAPORE
 IDENTITY CARD NO. S8233041J
 Name: SHEN XUMING
 沈旭明
 Race: CHINESE
 Date of birth: 05-10-1982
 Sex: M
 Country of birth: SINGAPORE
 S8233041J

Land Transport Authority
 VOCATIONAL LICENCE
 Licence No. S8233041J
 Name: SHEN XUMING
 Issue Date: 24/4/2014
 Please visit www.lta.gov.sg to check the status of this vocational licence

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:
 Class 3 Motor Cars - < 3000kg with <= 7 passengers; exclusive of the driver, and other motor vehicles - < 2500kg
 PASS DATE: 17 Dec 2007
 Licence No. S8233041J
 NP228A

493559
 Barcode: S8233041J
 NRIC No. S8233041J
 Date of issue: 13-02-2013
 Address: APT BLK 122 BEDOK NORTH STREET 2 #11-106 SINGAPORE 460122

This card is not transferable and is the property of the Land Transport Authority (LTA). It must be surrendered to the LTA on request. If found, please return to LTA, 10 Sin Ming Drive, Singapore 575701.

Type	Description	Issue Date
02	TAXI VI	24/04/2014

Barcode

Enquire Vehicle Registration Details

Owner Particulars

NRIC/Passport/Company Cert No.: 200304975H

Owner ID Type: Company

☐ Owner Name: PREMIER TAXIS PTE. LTD.

Registered Address: 23 CHANGI SOUTH AVENUE 2 #04-03 SINGAPORE 486443

Mailing Address: -

Birth Date: -

Vehicle Particulars

Vehicle No.: SHD1212H

☐ Previous Vehicle No.: -

Effective Date of Ownership: 22 Mar 2017

Original Regn Date: 22 Mar 2017

Registration Date: 22 Mar 2017

Year of Manufacture: 2016

Vehicle Type: Public Transport Taxi (Motor Car)

Vehicle Scheme:	Taxi (Company)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Make:	HYUNDAI
Vehicle Model:	I30 GDH 1.6 TCI 5DR DCT
Primary Colour:	Silver
Secondary Colour:	-
Passenger Capacity:	4
Chassis No.:	TMAD281UVHJ125061
Engine No.:	D4FBGZ115766
Engine Capacity / Power Rating:	1582 cc / -
Maximum Power Output:	100.0 kW (134 bhp)
Propellant:	Diesel
Max Unladen Weight:	1496 kg
Maximum Laden Weight:	1940 kg
Open Market Value:	\$21,046.00
PARF Eligibility:	Yes

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number : 5095103893

Cover : Third Party

- | | |
|---|---------------------------|
| 1. Index mark and Registration Number of Vehicle | : SHD1212H |
| Chassis Number | : TMAD281UVHJ125061 |
| 2. Name of Policyholder | : PREMIER TAXIS PTE. LTD. |
| 3. Effective Date of Insurance | : 20 Oct 2017 |
| 4. Expiry Date of Insurance | : 19 Oct 2018 |
| 5. Persons or Classes of Persons entitled to drive* | |
| (a) The Policyholder. | |
| (b) Any licensed taxi driver driving on the Policyholder's order or with his/her permission.
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. | |
| 6. Limitations as to Use* | |
| (a) Use as a Taxi. | |
| (b) Use for social domestic and pleasure purposes. | |

This Policy does not cover

- (a) Use for racing, pace-making, reliability trial or speed-testing.
 - (b) Use whilst drawing a trailer except the towing (Other than for reward) of any one disabled mechanically propelled vehicle.
- * Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third- Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION I)	: N/A
EXCESS (SECTION II)	: S\$3,500
INSURE WITH COE	: N/A
HIRE PURCHASE COMPANY	: N/A
SUM INSURED	: N/A

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : HL SUNTEK INSURANCE BROKERS PTE LTD (00000690672)
Date of Issue : 16 Oct 2017 17:13 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:



Authorised Officer



Chief Executive

Enquire Vehicle Registration Details

Owner Particulars

NRIC/Passport/Company Cert No.:	200304975H
Owner ID Type:	Company
Owner Name:	PREMIER TAXIS PTE. LTD.
Registered Address:	23 CHANGI SOUTH AVENUE 2 #04-03 SINGAPORE 486443
Mailing Address:	-
Birth Date:	-

Vehicle Particulars

Vehicle No.:	SHD1212H
Previous Vehicle No.:	-
Effective Date of Ownership:	22 Mar 2017
Original Regn Date:	22 Mar 2017
Registration Date:	22 Mar 2017
Year of Manufacture:	2016
Vehicle Type:	Public Transport Taxi (Motor Car)

Taxi (Company)

Vehicle Scheme:

Vehicle Attachment 1:

Air-Con (Taxi)

Vehicle Attachment 2:

-

Vehicle Attachment 3:

-

Vehicle Make:

HYUNDAI

Vehicle Model:

I30 GDH 1.6 TCI 5DR DCT

Primary Colour:

Silver

Secondary Colour:

-

Passenger Capacity:

4

Chassis No.:

TMAD281UVHJ125061

Engine No.:

D4FBGZ115766

Engine Capacity / Power Rating:

1582 cc / -

Maximum Power Output:

100.0 kW (134 bhp)

Propellant:

Diesel

Max Unladen Weight:

1496 kg

Maximum Laden Weight:

1940 kg

Open Market Value:

\$21,046.00

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:	21 Mar 2025
Minimum PARF Benefit:	\$8,379.00
No. of Transfers:	0
IU Label No.:	1050700046
COE No.:	2017032201004195G
COE Expiry Date:	21 Mar 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Registration Category:	A - Car up to 1600cc & 97kW (130bhp)
Quota Premium (QP) / Prevailing Quota Premium:	- / \$49,429.00
PQP Paid:	\$39,544.00
QP (Regn Cat):	--
OPC Cash Rebate Eligibility:	No
QP during COE Bidding Exercise:	\$0.00
Additional Registration Fee Rate:	First \$20,000.00 (100%), next \$1,046.00 (140%)
Actual ARF Paid:	\$13,965.00
Vehicle Lifespan Expiry Date:	21 Mar 2025
CO2 Emission:	127.00 (g/km)

CEV/VES Rebate Utilised Amount: \$7,500.00

CO Emission: -

HC Emission: -

NOx Emission: -

PM Emission: -

Message:

The vehicle will be de-registered upon expiry of its 8-year COE on 21 Mar 2025. No further renewal will be allowed. This is a public service vehicle.

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

14-Jun-18

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1212 H

2 pcs	Rear n/s & o/s tail lamp @\$321.30	X	\$	642.60
2 pcs	Rear n/s & o/s reflector @\$295.10	N/S ✓ 0.5X	\$	590.20
1 pc	End panel	X	\$	853.85
1 pc	Rear windscreen moulding	X	\$	64.10
1 pc	Tailgate	X	\$	2,292.30
1 pc	Tailgate lower garnish	X	\$	362.61
2 pcs	Tailgate hinge @\$28.50	X	\$	57.00
1 pc	Tailgate trim	X	\$	431.12
2 pcs	Tailgate side n/s & o/s trim @\$90.42	X	\$	180.84
1 pc	Tailgate weatherstrip	X	\$	276.98
1 pc	Emblem I30	/	\$	27.80
1 pc	Emblem CRDI	/	\$	29.40
1 pc	Emblem Hyundai	/	\$	29.40
1 pc	Rear bumper	/	\$	811.11
1 pc	Rear bumper sponge	X	\$	79.20
1 pc	Rear bumper reinforcement	!	\$	815.64
1 pc	Rear bumper reinforcement centre	!	\$	79.20
2 pcs	Rear bumper n/s & o/s side bracket @\$52.20	!	\$	104.40
2 pcs	Rear bumper n/s & o/s reflector @\$107.50	!	\$	215.00
				\$ 7,942.75
Less 20%				\$ 1,588.55
				\$ 6,354.20

S/NETT

1 set	Rear bumper clips	/	\$	48.00
1 set	Reverse sensor	/	\$	280.00 200
1 set	Tailgate sticker	/	\$	100.00
1 set	Tailgate garnish clips	X	\$	38.00
1 pc	Rear no. plate	X	\$	50.00
1 pc	Sealant	X	\$	50.00

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1212 H

Towing Fee	\$	50.00 X
Sundry	\$	50.00 20
To dismantle and replace reverse sensor and test system	\$	80.00 20
To replace the rear windscreen into new shell tailgate	\$	120.00 X
To dismantle and refit the inner component into new tailgate, test wiper motor and water etc	\$	120.00 X
To labour charge for dismantle and renew the accident damaged parts. To heat/cut and weld on the end panel, rear o/s fender. Including to knock-out, straighten, repair, reshape of the floorboard, etc	\$	950.00 600
To putty and spray painting on the rear bumper, tailgate, tailgate lower garnish, end panel, floorboard panel	\$	1,200.00 720
To apply rustproofing on the repaired and replaced panels	\$	180.00 X
Total	\$	9,670.20

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalvin 11/11/14

14/6/18 1030 hrs.

3 Pgs.

P/P

Before Party photo

LKK Auto Cons. Parts Service notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is not "without prejudice" basis
- No illegal modification is allowed
- Supplementary claims must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

14-Jun-18

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1212 H

2 pcs	Rear n/s & o/s tail lamp @\$321.30	X <i>su</i>	\$ 642.60
2 pcs	Rear n/s & o/s reflector @\$295.10	N/S <i>su</i> <i>ok</i> <i>su</i>	\$ 590.20
1 pc	End panel	X <i>su</i>	\$ 853.85
1 pc	Rear windscreen moulding	X <i>su</i>	\$ 64.10
1 pc	Tailgate	X <i>su</i>	\$ 2,292.30
1 pc	Tailgate lower garnish	X <i>su</i>	\$ 362.61
2 pcs	Tailgate hinge @\$28.50	X <i>su</i>	\$ 57.00
1 pc	Tailgate trim	X <i>su</i>	\$ 431.12
2 pcs	Tailgate side n/s & o/s trim @\$90.42	X <i>su</i>	\$ 180.84
1 pc	Tailgate weatherstrip	X <i>su</i>	\$ 276.98
1 pc	Emblem I30	X <i>su</i>	\$ 27.80
1 pc	Emblem CRDI	X <i>su</i>	\$ 29.40
1 pc	Emblem Hyundai	X <i>su</i>	\$ 29.40
1 pc	Rear bumper	X <i>su</i>	\$ 811.11
1 pc	Rear bumper sponge	X <i>su</i>	\$ 79.20
1 pc	Rear bumper reinforcement	X <i>su</i>	\$ 815.64
1 pc	Rear bumper reinforcement centre	X <i>su</i>	\$ 79.20
2 pcs	Rear bumper n/s & o/s side bracket @ \$52.20	X <i>su</i>	\$ 104.40
2 pcs	Rear bumper n/s & o/s reflector @\$107.50	X <i>su</i>	\$ 215.00
			\$ 7,942.75
Less 20%			\$ 1,588.55
			\$ 6,354.20

S/NETT

1 set	Rear bumper clips	X <i>su</i>	\$ 48.00
1 set	Reverse sensor	X <i>su</i>	\$ 280.00 <i>200</i>
1 set	Tailgate sticker	X <i>su</i>	\$ 100.00
1 set	Tailgate garnish clips	X <i>su</i>	\$ 38.00
1 pc	Rear no. plate	X <i>su</i>	\$ 50.00
1 pc	Sealant	X <i>su</i>	\$ 50.00

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1212 H

Towing Fee	\$	50.00 X 1.1
Sundry <i>hpc</i>	\$	50.00 20
To dismantle and replace reverse sensor and test system	\$	80.00 20
To replace the rear windscreen into new shell tailgate	\$	120.00 X 1.1
To dismantle and refit the inner component into new tailgate, test wiper motor and water etc	\$	120.00 X 1.1
To labour charge for dismantle and renew the accident damaged parts. To heat/cut and weld on the end panel, rear o/s fender. Including to knock-out, straighten, repair, reshape of the floorboard, etc	\$	950.00 600
To putty and spray painting on the rear bumper, tailgate, tailgate lower garnish, end panel, floorboard panel	\$	1,200.00 720
To apply rustproofing on the repaired and replaced panels	\$	180.00 X 1.1
Total	\$	9,670.20

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalvin 11/11/14
14/6/18 1030 hrs.
3 Pgs.
PIP
Before Party photo
9/2/18
whl PIP \$3604.85/3hrs

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Report Remarks Entry - CC4/AIG17012989/Spa3

Remarks

Remarks

Add

	Remarks 1	By	On
<input type="checkbox"/>	XD 1480K ; SJU 7105G	HMK	4/7/2017 7:28:27 PM
<input type="checkbox"/>	EST : \$9154.63 --- SUR : YWK --- WKSP : LEE KUAN HWA MOTOR SERVICE	HMK	6/7/2017 1:35:38 PM
<input type="checkbox"/>	FILE PASS TO CHT	HMK	7/7/2017 9:34:23 AM
<input type="checkbox"/>	_	CHT	17/7/2017 12:23:35 PM
<input type="checkbox"/>	170717 Called OI, Mr Poh. Confirm accident. Inform TP claim. He disputed on TP claim. He said that due to heavy traffic, he had turned out from side road, TP moved out from stationary position and hit his car. His video had corrupted. Only 1 scene photo. Will review and get back to him	CHT	17/7/2017 12:23:30 PM
<input type="checkbox"/>	150817 Email to TP: Request for evidence	CHT	15/8/2017 3:12:17 PM
<input type="checkbox"/>	09/05/2018 at 04.15pm, spoke to OI (Mr Poh) at 9838 7416. Explain to OI, Liability is down against us as we dont have further evidence. OI mention he will try to retrieve the video footage, explain to OI even we have video footage, this case still not a strong case for us. [OI confirm agree to settle IF he FAIL to retrieve the video footage] will call OI back on this Friday. pohkin	CPK	9/5/2018 4:22:29 PM
<input type="checkbox"/>	11/05/2018, at 11am, call OI and ask about the video footage, OI mention he have no time to do this and request call back on next week. will call OI again on next monday. pohkin	CPK	11/5/2018 11:06:48 AM
<input type="checkbox"/>	23/05/2018, spoke to OI, OI mention he still haven retrieve the video footage as he is very busy and his father sick and in hospital, requested us give him some time and will get back to us. pohkin	CPK	23/5/2018 9:36:13 AM
<input type="checkbox"/>	17/07/2018, spoke to OI, OI mention he pass the SD card to whop retrieve video footatge, and ask what if he cant get the video footage or dont want settle claim. explain to OI, third party will proceed the matter to court and he might be have to attend court. and court might say he will be more liable as he come out from minor road (BIG stop line) MAG and BOLA still down against him. OI said he will think about it and request will call me back on friday.	CPK	17/7/2018 1:39:43 PM




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CC3/LPC18010947/K1ea3n2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 02-10-2018	
		Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLT 3927J	Veh. Inspected	SHD 1212H
Policy No.	Z17VP05016257	Coverage (\$)	0.00
Claim No.	17/18/18/VP05/020682	Excess (\$)	0.00
Assign From		Assign Date	14/06/2018
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI I30	c.c	1582
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	TMAD281UVHJ125061	Colour	SILVER
Odometer	74455	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	MAXXIS	7 mm
L/H Front Tyre	195/65 R15	MAXXIS	7 mm
R/H Rear Tyre	195/65 R15	MAXXIS	7 mm
L/H Rear Tyre	195/65 R15	MAXXIS	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	14/06/2018	Inspection Date	14/06/2018
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 1212H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
2	REAR N/S & O/S TAIL LAMP @\$321.30	SERVICEABLE	642.60	-
2	REAR N/S & O/S REFLECTOR @\$295.10	N/S CRACKED / O/S SERVICEABLE	590.20	295.10
1	END PANEL	TO REPAIR SEE LABOUR	853.85	-
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	64.10	-
1	TAILGATE	TO REPAIR SEE LABOUR	2,292.30	-
1	TAILGATE LOWER GARNISH	CRACKED	362.61	362.61
2	TAILGATE HINGE @\$28.50	SERVICEABLE	57.00	-
1	TAILGATE TRIM	SERVICEABLE	431.12	-
2	TAILGATE SIDE N/S & O/S TRIM @\$90.42	SERVICEABLE	180.84	-
1	TAILGATE WEATHERSTRIP	SERVICEABLE	276.98	-
1	EMBLEM I30	NECESSARY	27.80	27.80
1	EMBLEM CRDI	NECESSARY	29.40	29.40
1	EMBLEM HYUNDAI	NECESSARY	29.40	29.40
1	REAR BUMPER	DEFORMED	811.11	811.11
1	REAR BUMPER SPONGE	SERVICEABLE	79.20	-
1	REAR BUMPER REINFORCEMENT	BENT	815.64	815.64
1	REAR BUMPER REINFORCEMENT CENTRE	SERVICEABLE	79.20	-
2	REAR BUMPER N/S & O/S SIDE BRACKET @\$52.20	SERVICEABLE	104.40	-
2	REAR BUMPER N/S & O/S REFLECTOR @\$107.50	SERVICEABLE	215.00	-
	LESS 20% DISCOUNT		-1,588.55	-474.21
			6,354.20	1,896.85
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	SET REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	SET TAILGATE STICKER (SN)	NECESSARY	100.00	100.00
1	SET TAILGATE GARNISH CLIPS (SN)	NOT NECESSARY	38.00	-
1	REAR NO.PLATE (SN)	SERVICEABLE	50.00	-
1	SEALANT (SN)	NOT NECESSARY	50.00	-

Report Ref No. CC3/LPC18010947/K1ea3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No..2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			616.00	368.00
	LABOUR			
	TOWING FEE.	NOT NECESSARY	50.00	-
	TO DISMANTLE AND REPLACE REVERSE SENSOR AND TEST SYSTEM.		80.00	20.00
	TO REPLACE THE REAR WINDSCREEN INTO NEW SHELL TAILGATE.	NOT NECESSARY	120.00	-
	TO DISMANTLE AND REFIT THE INNER COMPONENT INTO NEW TAILGATE, TEST WIPER MOTOR AND WATER ETC.	NOT NECESSARY	120.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS .TO HEAT/CUT AND WELD ON THE END PANEL, REAR O/S FENDER .INCLUDING TO KNOCK -OUT ,STRAIGHTEN ,REPAIR ,RESHAPE OF THE FLOORBOARD ETC.INCLUSIVE OF THE REPAIR OF END PANEL AND TAILGATE.		950.00	600.00
	TO PUTTY AND SPRAY PAINTING ON THE REAR BUMPER ,TAILGATE ,TAILGATE LOWER GARNISH ,END PANEL, FLOORBOARD PANEL.		1,200.00	720.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	180.00	-
			2,700.00	1,340.00
	GRAND TOTAL		9,670.20	3,604.85
RECOMMENDED COST OF REPAIRS				3,604.85

Report Ref No. CC3/LPC18010947/K1ea3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.