

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

14-Jun-18

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1212 H

2 pcs	Rear n/s & o/s tail lamp @\$321.30	X	\$	642.60
2 pcs	Rear n/s & o/s reflector @\$295.10	n/s v o/s X	\$	590.20
1 pc	End panel	X n/s	\$	853.85
1 pc	Rear windscreen moulding	X	\$	64.10
1 pc	Tailgate	X n/s	\$	2,292.30
1 pc	Tailgate lower garnish	/	\$	362.61
2 pcs	Tailgate hinge @\$28.50	X	\$	57.00
1 pc	Tailgate trim	X	\$	431.12
2 pcs	Tailgate side n/s & o/s trim @\$90.42	X	\$	180.84
1 pc	Tailgate weatherstrip	X	\$	276.98
1 pc	Emblem I30	/	\$	27.80
1 pc	Emblem CRDI	/	\$	29.40
1 pc	Emblem Hyundai	/	\$	29.40
1 pc	Rear bumper	/	\$	811.11
1 pc	Rear bumper sponge	X	\$	79.20
1 pc	Rear bumper reinforcement	?	\$	815.64
1 pc	Rear bumper reinforcement centre	!	\$	79.20
2 pcs	Rear bumper n/s & o/s side bracket @ \$52.20	!	\$	104.40
2 pcs	Rear bumper n/s & o/s reflector @\$107.50	!	\$	215.00
				\$ 7,942.75
Less 20%				\$ 1,588.55
				\$ 6,354.20

S/NETT

1 set	Rear bumper clips	/	\$	48.00
1 set	Reverse sensor	/	\$	280.00 200
1 set	Tailgate sticker	/	\$	100.00
1 set	Tailgate garnish clips	X	\$	38.00
1 pc	Rear no. plate	X	\$	50.00
1 pc	Sealant	X	\$	50.00

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1212 H

Towing Fee	\$	50.00 X
Sundry	\$	50.00 20
To dismantle and replace reverse sensor and test system	\$	80.00 20
To replace the rear windscreen into new shell tailgate	\$	120.00 X
To dismantle and refit the inner component into new tailgate, test wiper motor and water etc	\$	120.00 X
To labour charge for dismantle and renew the accident damaged parts. To heat/cut and weld on the end panel, rear o/s fender. Including to knock-out, straighten, repair, reshape of the floorboard, etc	\$	950.00 600
To putty and spray painting on the rear bumper, tailgate, tailgate lower garnish, end panel, floorboard panel	\$	1,200.00 720
To apply rustproofing on the repaired and replaced panels	\$	180.00 X
Total	\$	9,670.20

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kaluk 11/11/14

14/6/18 1030 hrs.

3 Pgs.

PIP

Before Repair photo

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: