

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

13-Jun-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SJR 6326 H

1 pc	o/s headlamp ✓	\$	897.90
1 pc	Front bumper ✓	\$	885.00
1 pc	Front o/s fog lamp cover ✓	\$	75.00
1 pc	Front bumper o/s side retainer X	\$	35.00
1 pc	Front o/s fender ✓	\$	335.00
1 pc	Front o/s fender inner shield X	\$	130.00
		\$	<u>2,357.90</u>
		Less 20%	\$ 471.58
			<u>\$ 1,886.32</u>

S/NETT

1 set	Front bumper clips ✓	\$	48.00
1 set	Front o/s fender inner shield clips X	\$	28.00

Sundry		\$	50.00 20
To check wheel alignment		\$	80.00 X
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00 X
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of same, etc.		\$	650.00 400
To putty and spray painting on front bumper, front o/s fender		\$	450.00 360
To apply rustproofing on the repaired and replaced panels.		\$	120.00 50
		\$	<u>3,492.32</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalvin 10/16/18

14/6/18 1026 hrs
3 hrs

4/5
After Repair photo

KIA Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: