

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

13-Jun-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SJR 6326 H

1 pc	o/s headlamp	— Cra	\$	897.90
1 pc	Front bumper	— Deformed	\$	885.00
1 pc	Front o/s fog lamp cover	— scr	\$	75.00
1 pc	Front bumper o/s side retainer	X svc	\$	35.00
1 pc	Front o/s fender	— Dented	\$	335.00
1 pc	Front o/s fender inner shield	X svc	\$	130.00
			\$	<u>2,357.90</u>
		Less 20%	\$	471.58
			\$	<u>1,886.32</u>

S/NETT

1 set	Front bumper clips	— Nec	\$	48.00
1 set	Front o/s fender inner shield clips	X svc	\$	28.00

Sundry	\$	50.00 20
To check wheel alignment	\$	80.00 X nn
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00 X nn
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of same, etc.	\$	650.00 400
To putty and spray painting on front bumper, front o/s fender	\$	450.00 360
To apply rustproofing on the repaired and replaced panels.	\$	120.00 50
	\$	<u>3,492.32</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalvin 10/1/14

*M 14/6/18 102 hrs
3 hrs*

*4/5
After Repair photo*

ERK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: