

ASS. REC. BY:

REF:

CS/EG118010950/Uqb/n2

Special Instruction:

Surveyor:

Marcus

ASSIGNMENT (Office)

From (Person):

Yee Pei Li

of

EG1

Date/Time:

20/6/18 @ 4.29pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SFD 6922H

Insured:

SJD 56512

at Workshop m/s:

Fastech Auto

Tel:

6746 5405

of

1 Kaki Bukit Ave 6 #01-46

Policy No:

Claim No:

SJD 56512 / RH / pl

Sum Insured:

Excess:

Make of Veh:

D.O.A.

15/06/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

5.42pm @ 20/6/18

Person Contacted:

Nancy

Vehicle IN OUT

Date/Time

Action/Instruction

(✓)

Estimate

SFD 1922H - CS/TP1001253/Uqgl

D.O.A: 25/07/2010

SJD 56512 - X

21/6/18 @ 2.37pm

Informed Bohaini, we are pending estimate from receiver.

23/7/18 @ 11.42am

revised to Bohaini by email.

(08/11/13) wef

REF:

ASS. REC. BY: Marius

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SFD 5922Hat Workshop m/s 9.30

of _____

Insured: SJD 56517

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SFD 6922H Yr Regn: 5, 16Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: Mer Benz 530L c.c. 2996Colour: Black A/C: Insured / Std / NI / NASp. Reading: 69080 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD 222 1622 A 26 25 81Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 245/40 R20R: 275/35 R20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 15/6/18 D.O.I. 18/6/18

Survey held at _____

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop orRear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

21/7/18 LYA/139618 received. 1093-57 tailing 88.81
contacted w/s 10.200 w-lt Rm
CRK 14788.40, 59%

RECEIVED 23 JUL 2018

Date/Time, File Pass to?

☐ : Preli. Report17/7/18 turnover☐ : Final Report

Date/Time, File Return to?

2)

Report Format: 7PLump Sum / I.B.I. (\$) 10200Days Of Repair: 5Resurvey No. of Trip: 2

Add Fee:

☐ : Site Insp (\$ _____) S + RS \$ _____
☐ : Interview (\$ _____) Photos
☐ : Tech. Invs (\$ _____) Others
☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

TOTAL

350

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Wednesday, 20 June 2018 4:29 PM
To: 'admin-d@lkkauto.com'
Cc: ASSIGNMENTS@LKKAUTO.COM
Subject: OI : SJD5651Z / TP : SFD6922H/LKK / DOA : 15/06/2018
Attachments: SJD5651Z - SAS.pdf; SFD6922H - SAS.pdf; SFD6922H - PRS FORM.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **FASTECH AUTO PTE LTD.**

ADDRESS : 1 KAKI BUKIT AVENUE 6
#01-46/48/50 AUTOBAY
SINGAPORE 417883

PERSON TO CONTACT : NANCY LAM @ 6746 5405

ERGO OFFICER-IN-CHARGE : ROHAINI

Note: To survey on without prejudice basis. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are our insured's and TP's SAS (note: reports not to be released to any Third Party). No estimates was provided.

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

Date: 20.06.2018
Our Reference: SJD 5651Z/RH/pl
Your Reference: SFD 6922H

To: FASTECH AUTO PTE LTD

Sent via Fax
or
Email nancy.lam@fastechauto.com.sg

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SFD 6922H
Insured's Vehicle: SJD 5651Z
Date Of Accident: 15.06.2018

We acknowledge receipt of your request for PRS on: 20.06.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* LKK

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPk	JP Knights Pte Ltd	VAC	Vicom Ltd

☒	Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
☐	Your request for inspection does not have your client's GIA report, kindly forward a copy.
☐	We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
☐	Our Insured's driver has not reported the accident to us today.
☒	Others: <u>OFFICER-IN-CHARGE - ROHAINI</u>

Prepared by:		Pei Li	6829 9194	<u>claims@ergo.com.sg</u>
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .



Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 23 July 2018 11:42 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'; assignments; Rohaini Bte Hussain
Cc: SUR
Subject: RE: SJD5651Z / TP : SFD6922H/LKK / DOA : 15/06/2018
Attachments: CSEGI18010950Uqb.pdf

Dear Rohaini,

Enclosed herewith preliminary advice of SFD 6922H.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 21 June 2018 2:37 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments <assignments@lkkauto.com>; Rohaini Bte Hussain <Rohaini.Hussain@ergo.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SJD5651Z / TP : SFD6922H/LKK / DOA : 15/06/2018

Dear Rohaini,

Please be informed that we have inspected the vehicle SFD 6922H on 18/06/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 20 June 2018 5:54 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SJD5651Z / TP : SFD6922H/LKK / DOA : 15/06/2018

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: SJD5651Z/RH/pl

Date: 23th July 2018

Our Ref: CS/EG18010950/Uqb

The Motor Claims Department
ERGO Insurance

Attn: Pei Li

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SFD 6922H


We thank you for the instruction on 20/06/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 18/06/2018 at the premises of M/s FASTECH AUTO and have the following to report:-

Workshop Estimate Amount	: S\$ <u>24,988.40</u>
Revised Estimate Amount	: S\$ <u>10,200.00 (Lump Sum)</u>
"Check" Items Amount	: S\$ <u>-</u>
Lump Sum Repair Estimate Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages consistent.

Days of repair: 5 days.

We have NOT authorize repair.

Yours faithfully

CHUA KANG SENG
Licensed Appraiser

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 21 June 2018 2:37 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'; assignments; Rohaini Bte Hussain
Cc: SUR
Subject: RE: SJD5651Z / TP : SFD6922H/LKK / DOA : 15/06/2018

Dear Rohaini,

Please be informed that we have inspected the vehicle SFD 6922H on 18/06/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 20 June 2018 5:54 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SJD5651Z / TP : SFD6922H/LKK / DOA : 15/06/2018

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Wednesday, 20 June 2018 4:29 PM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Cc: ASSIGNMENTS@LKKAUTO.COM
Subject: OI : SJD5651Z / TP : SFD6922H/LKK / DOA : 15/06/2018

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **FASTECH AUTO PTE LTD.**

ADDRESS : 1 KAKI BUKIT AVENUE 6

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	0182E

Vehicle Details

Vehicle No.:	SFD6922H
Vehicle to be Exported:	No
Intended De-registration Date:	18 Jun 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	S320L (R19 LED)
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	27682430380854
Chassis No.:	WDD2221622A262581
Maximum Power Output:	200.0 kW (268 bhp)
Open Market Value:	\$89,948.00
Original Registration Date:	19 May 2016
First Registration Date:	19 May 2016
Transfer Count:	1
Actual ARF Paid:	\$133,907.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 May 2026
PARF Rebate Amount:	\$100,430.00

Intended COE Rebate Details

COE Expiry Date:	18 May 2026
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$49,501.00
COE Rebate Amount:	\$39,188.00
Total Rebate Amount:	\$139,618.00

The information contained herein is correct as at 18 Jun 2018

OK

Date of Accident : 15/6/2018 Accident Time: 7.05pm (24-HR-Format)

Accident Place : Along PIE towards Changi

Vehicle. No. (Car Plate No.) : SFD 69224 Make/Model:

Insurance Company : TI Policy No: M497436

Owner or Company Name / IC No. : Koh Chuan Hin / 50100182E

Owner or Company Contact No. : Owner's Hp 98562868 Company Tel

DRIVER'S Name / IC No. : Koh Kah Yoong / 57626817G

DRIVER'S Date Of Birth : 4/9/1976 DRIVER'S License Pass Date 29/8/1994

Relationship of Owner & Driver : Spouse \ Parents \ Children \ Sibling \ Employee \ Others:

DRIVER'S Address :

DRIVER'S Contact No. / Alt No. : 1) 82-000061 2)

DRIVER'S Occupation : INDOOR \ OUTDOOR (e.g. working inside or outside office)

Email Address :

Weather & Road Surface : CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET

Reporting Type : Reporting Only \ Claim Other Party \ Claim Own Insurance

Number of Passengers (Including Driver): 1. driver

Was there any video Captured by car camera: YES \ NO

Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose

Any Injury (If YES, Pls state): yes

Other Party Driver's Particular (if any)

Vehicle. No: SSD 56512 (Ergo) Vehicle. No:

Vehicle Make/Model: Vehicle Make/Model:

Name Driver: Name Driver:

IC No. Driver/Contact: IC No. Driver/Contact:

* NEW - Passenger's name & gender:

FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6
#01-46/48/50 Autobay
SINGAPORE 417883

VEHICLE NO: SFD 6922H

not Allowed
dble
2/5 & 10, 200
5 dy.
18/6/18

QTY	PARTICULAR (NETT ITEM)	AMOUNT
1 PCS	BOOTLID 2549.11	\$3,966.20 ✓
1 PCS	BOOTLID REAR LOGO	\$66.50 ✓
1 PCS	BOOTLID C&C LOGO	\$40.00 ✓
1 PCS	BOOTLID 'S320' EMBLEM	\$69.50 ✓
1 PCS	BOOTLID OUTER CHROME MOULDING	\$321.10 ✓
1 PCS	BOOTLID INNER LOCK	\$395.20 ✓
1 PCS	BOOTLID WEATHERSTRIP 266.05	\$362.30 ✓
1 PCS	BOOTLID INNER TRIM	\$495.20 X
2 PCS	BOOTLID HINGES @\$185.00	\$370.00 X
1 PCS	REAR BUMPER 2040.41	\$2,265.40 ✓
1 PCS	REAR BUMPER LOWER CENTRE GARNISH 435.01	\$981.10 ✓
1 PCS	REAR BUMPER CENTRE LAMP 266.05	\$322.20 ✓
2 PCS	REAR BUMPER REFLECTORS @\$150 82.11x2=164.22	\$300.00 ✓
4 PCS	REAR BUMPER PDC SENSOR @\$212.00 424	\$848.00 2 pcs
1 SET	REAR BUMPER PDC SENSOR WIRE	\$265.40 X
1 PCS	REAR BUMPER CENTRE RETAINER	\$199.20 ✓
2 PCS	REAR BUMPER SIDE HOLDERS @\$98.50	\$197.00 X
1 PCS	REAR BUMPER REINFORCEMENT	\$891.10 ✓
2 PCS	REAR BUMPER LOWER BRACKETS @\$65.00	\$130.00 ✓
1 PCS	REAR BUMPER LOWER DIFFUSER	\$488.50 X
2 PCS	TAILLAMPS @\$795.10	\$1,590.20 ✓
2 PCS	TAILLAMP OUTER GARNISH @\$38.20	\$76.40 ✓
1 PCS	REAR END PANEL 1093.57	\$1,155.00 ✓
1 PCS	REAR END PANEL TOP GARNISH	\$322.40 ✓
1 PCS	REAR FLOOR PANEL	\$1,150.20 X
1 PCS	REAR FLOOR PANEL TOP BOARD	\$785.00 X
2 PCS	REAR EXHAUST CHROMES @150.00	\$300.00 ✓
1 PCS	REAR EXHAUST MUFFLER 105x2=210	\$1,465.00 X
2 PCS	REAR BUMPER SIDE CHROME MOULDINGS @\$122.00	\$244.00 ✓
1 PCS	REAR BUMPER INNER LOCK SENSOR	\$166.30 X
2 PCS	REAR FENDER INNER TRIMS @\$425.00	\$850.00 X
1 PCS	REAR END PANEL SEALANT	\$50.00 X
		\$21,128.40

102

1185002
1066501

LABOUR CHARGES:

TO CHECK WIRING
TO DISMENTLE & REPLACING PDC SENSOR
TO DISMENTLE & REFIX SEAT,CUSHION UPHOLSTREY
TO DISMENTLE & REFIX REAR EXHAUST
TO DISMENTLE & REFIX REAR BOOTLID MECHANISM
TO SPRAY RUST PROOFING
TO MOUNT VEHICLE ON CAR O-LINER
LABOUR FOR PANEL BEATING & REPLACING PARTS
TO PUTTY & SPRAY PAINTING

\$80.00 30
\$100.00 50
\$120.00 80
11 \$150.00 x
\$150.00 80
\$100.00 60
11 \$380.00 x
\$1,280.00 800
\$1,500.00 1000

TOTAL \$24,988.40

1276501
10212.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EGI18010950/Uqbn2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 24-07-2018		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJD 5651Z	Veh. Inspected	SFD 6922H	
Policy No.		Coverage (\$)	0.00	
Claim No.	SJD5651Z/RH/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	20/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ S320L (A)	c.c	2996	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	WDD2221622A262581	Colour	BLACK	
Odometer	69080	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/40 R20	GOODYEAR	6 mm	
L/H Front Tyre	245/40 R20	GOODYEAR	6 mm	
R/H Rear Tyre	275/35 R20	GOODYEAR	6 mm	
L/H Rear Tyre	275/35 R20	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/06/2018	Inspection Date	18/06/2018	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFD 6922H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOTLID (N)	BADLY DENTED	3,966.20	2,549.11
1	BOOTLID REAR LOGO (N)	NECESSARY	66.50	66.50
1	BOOTLID C&C LOGO (N)	NECESSARY	40.00	40.00
1	BOOTLID 'S320' EMBLEM (N)	NECESSARY	69.50	69.50
1	BOOTLID OUTER CHROME MOULDING (N)	NECESSARY	321.10	321.10
1	BOOTLID INNER LOCK (N)	TWISTED / SHORTED	395.20	395.20
1	BOOTLID WEATHERSTRIP (N)	TWISTED	362.30	266.05
1	BOOTLID INNER TRIM (N)	NOT NECESSARY	495.20	-
2	BOOTLID HINGES @\$185.00 (N)	NOT NECESSARY	370.00	-
1	REAR BUMPER (N)	DENTED / DEFORMED	2,265.40	2,040.41
1	REAR BUMPER LOWER CENTRE GARNISH (N)	DENTED	981.10	435.01
1	REAR BUMPER CENTRE LAMP (N)	CRACKED	322.20	266.05
2	REAR BUMPER REFLECTORS @\$150.00 (N)	CRACKED	300.00	164.22
4	REAR BUMPER PDC SENSOR @\$212.00 (N)	SHORTED (2 PCS ONLY)	848.00	424.00
1	SET REAR BUMPER PDC SENSOR WIRE (N)	NOT NECESSARY	265.40	-
1	REAR BUMPER CENTRE RETAINER (N)	TWISTED / CRACKED	199.20	199.20
2	REAR BUMPER SIDE HOLDERS @\$98.50 (N)	NOT NECESSARY	197.00	-
1	REAR BUMPER REINFORCEMENT (N)	BENT	891.10	891.10
2	REAR BUMPER LOWER BRACKETS @\$65.00 (N)	BENT	130.00	130.00
1	REAR BUMPER LOWER DIFFUSER (N)	NOT NECESSARY	488.50	-
2	TAILLAMPS @\$795.10 (N)	CRACKED	1,590.20	1,590.20
2	TAILLAMP OUTER GARNISH @\$38.20 (N)	TORN	76.40	76.40
1	REAR END PANEL (N)	DENTED	1,155.00	1,093.57
1	REAR END PANEL TOP GARNISH (N)	TWISTED	322.40	322.40
1	REAR FLOOR PANEL (N)	TO REPAIR SEE LABOUR	1,150.20	-
1	REAR FLOOR PANEL TOP BOARD (N)	NOT NECESSARY	785.00	-
2	REAR EXHAUST CHROMES @\$150.00 (N)	BENT	300.00	300.00

Report Ref No. CS/EGI18010950/Uqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR EXHAUST MUFFLER (N)	NOT NECESSARY	1,465.00	-
2	REAR BUMPER SIDE CHROME MOULDINGS @\$122.00 (N)	NECESSARY	244.00	210.00
1	REAR BUMPER INNER LOCK SENSOR (N)	NOT NECESSARY	166.30	-
2	REAR FENDER INNER TRIMS @\$425.00 (N)	NOT NECESSARY	850.00	-
1	REAR END PANEL SEALANT (N)	NOT NECESSARY	50.00	-
	LESS 10% DISCOUNT		-	-1,185.00
			21,128.40	10,665.02
	LABOUR			
	TO CHECK WIRING .		80.00	30.00
	TO DISMANTLE & REPLACING PDC SENSOR .		100.00	50.00
	TO DISMANTLE & REFIX SEAT CUSHION UPHOLSTERY .		120.00	80.00
	TO DISMANTLE & REFIX REAR EXHAUST .	NOT NECESSARY	150.00	-
	TO DISMANTLE & REFIX REAR BOOTLID MECHANISM .		150.00	80.00
	TO SPRAY RUST PROOFING .		100.00	60.00
	TO MOUNT VEHICLE CAR-O-LINER .	NOT NECESSARY	380.00	-
	LABOUR FOR PANEL BEATING & REPLACING PARTS INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL .		1,280.00	800.00
	TO PUTTY & SPRAY PAINTING .		1,500.00	1,000.00
			3,860.00	2,100.00
GRAND TOTAL			24,988.40	12,765.02
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				10,200.00

Report Ref No. CS/EG18010950/Uqbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.