



丁旺

Think One Autocare Pte Ltd

18 Defu Ave 2 Singapore 539522

Tel: 6844 3300 Fax: 6842 4988

GBE7761R TOYOTA HIACE 3.0 DXMT

No	Qty	Parts Description	Estimate Parts Price
1	1	REAR BUMPER ASSY	\$ 1260.00
2	2	REAR BUMPER BRACKET	\$ 172.00
3	1	REAR BUMPER INNER BEAM	\$ 287.00
4	1	REAR TAILGATE ASSY	\$ 1862.00
5	1	REAR LEFT TAILAMP	\$ 785.00
6	1	REAR RIGHT FENDER PANEL ASSY	\$ 1800.00
Special Nett Items			
1	10	REAR BUMPER CLIPS	\$ 50.00
2	12	REAR TAILGATE INNER BOARD CLIPS	\$ 30.00
3	4	REAR TAILGATE OUTER GARNISH CLIPS	\$ 20.00
4	1	REAR TAILGATE '70KM/H' STICKER	\$ 30.00
LABOUR			
1		LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN FRONT RIGHT AFFECTED AREA AND REPLACE ACCIDENT DAMAGED PARTS.	\$ 1,000.00
2		TO PUTTY AND SPRAY PAINTING REAR LEFT PORTION.	\$ 1,000.00
3		TO APPLY ANTI RUST PROOFING TO FRONT RIGHT AFFECTED AREA.	\$ 120.00
4		LABOUR FOR DISMANTLE & INSTALL REAR TAILGATE ASSY	\$ 120.00
5		LABOUR FOR DISMANTLE & INSTALL REAR BUMPER ASSY	\$ 120.00
Not Affected Take photo after repair 3 days 1/8/18 9/9/18			
TOTAL:			\$ 8,656.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts price are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: