

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6

#01-46/48/50 Autobay

SINGAPORE 417883

VEHICLE NO: GZ 6321P

Not Authorized
date
1/5/2000
5/1/18
18/6/18

QTY	PARTICULAR	AMOUNT
1 PCS	TAILLAMP w/s	520 \$282.10 ✓
1 PCS	TAILLAMP BRACKET O/S	520 \$185.90 ✓
1 PCS	REAR EXHAUST PIPE	1 \$645.20 X
1PCS	REAR EXHAUST PIPE MOUNTING	11 \$66.50 X
1 PCS	REAR LICENCE PLATE BRACKET	520 \$188.20 ✓
1PCS	REAR SPARE TYRE BRACKET & CHAIN	1 w/s \$395.40 ✓
		\$1,763.30
		1051.6
		788.70
	S.NETT	
1 PCS	REAR CARGO BOX BACK DOOR O/S	520/cne \$2,000.00 1200
1 PCS	REAR CARGO BOX BACK DOOR LOCK O/S	1 \$600.00 X
1 PCS	REAR CARGO BOX REAR PILLAR O/S	50/cne \$1,200.00 1000
1 PCS	REAR CARGO BOX LOWER MEMBER	520/d/s \$1,020.00 800
1 PCS	REAR CARGO BOX LOWER O/S RAILING	520/d/s \$1,080.00 1000
1 PCS	REAR CARGO BOX INNER WOODEN	11 \$800.00 X
1 PCS	REAR LICENCE PLATE	520 \$20.00 14
1 PCS	REAR 'DYNA' STICKER	NN \$20.00 X
1 SET	REAR REVERSE SENSOR	NT \$300.00 X

LABOUR CHARGES:

TO CHECK WIRING	\$50.00 20
TO SPRAY RUST PROOFING	\$80.00 50
TO DISMENTLE & REPLACING REAR EXHAUST	\$80.00 60
LABOUR FOR PANEL BEATING & REPLACING PARTS	\$1,000.00 800
TO PUTTY & SPRAY PAINTING	\$880.00 550

TOTAL

\$10,893.30

6282

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: