

22/03/2002

ASS. REC. BY:

REF:

CS/A2618011027/Kvber

Special Instruction:

Survivor

Melimen

ASSIGNMENT (Office)

From (Person): Ashley Chan

of

Alli

Date/Time: 14062018 4:06pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

CB 6579L

Insured:

G8B 6364B

at Workshop m/s

Keng Hock Auto

Tel:

6468 5589

of

Blk 7 Sin Ming Ind Est #01-84

Policy No:

Claim No:

042214258886003

Sum Insured:

Excess:

Make of Veh:

D.O.A.

23052018

(Client's Record)

CA / REV / REP. / REV 24 HRS wpi

H.O.D. Endorsement:

Date/Time:

14062018 536pm

Person Contacted:

Thomas

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

CB 6579L - X

G8B 6364B - X

19/7/18

@308pm

11 Lm 375cl email confirmed with Thomas (Rec 4638.28, 5590)

REF: AIG

ASSIGNMENT

From: Date: 18/06/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: CB6579L
at Workshop m/s Keng Hock Auto
of Blk 7, Sin Ming Ind. Est. Sec. C #01-84
Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: Thomas B 9657 1534

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

| | |
|-----|-----|
| N/S | O/S |
| | |

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'up

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: CB 6579L Yr Regn: 07 05

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Hiace C.C. 2490

Colour: M. Silver A/C: Insured / Std / NI / NA

Sp. Reading: 592264 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KD17200 0010664

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195R15x8

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 23/5/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S/R

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

19/6 File pass to Catherine

RECEIVED 20 JUL 2018

Date/Time: File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time: File Return to?

2) 2017 - typist

Report Format:

merimen

Lump Sum / I.B.I. (\$) 3750/-

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee: 250

Transportation

) S + RS SI

) Photos

) Others

TOTAL

250

20

270

- Pre repair inspection request - CB6579L VS GBB6364B (OI) DOA 23/05/2018

From: Chan, Yoke Shi
To: ASSIGNMENTS@LKKAUTO.COM, admin-a@lkkauto.com
Cc: Tan, Lily (AIG), Fong, Andy-SY, Kaur, Baljit, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Supramaniam, Darshene, Mithoosingh, Aashweenjeetkaur, A
Sent: 14/6/2018 4:06:53 PM
Attachments:  PRIX848 KH.JPG

Hi,

Please refer to the enclosed request from **Keng Hock Auto**.

Claim no : 0422142588SG003
Case Owner : LEE MING YAO

If you have any queries/concerns, please let us know.
Kindly assist to assign **MA CHIN FOOK** as Single Joint Expert as requested.

Thank you.

Regards,

Yoke Shi @ Ashley
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)
Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel +6 03 2719 6000 | Ext 1012102

yokeshi.chan@aig.com | www.aig.com

5:36pm @ 14/6/18
vehicle in
person @ Thomas
arrange on 18/06/18.
* Thomas agreed to appoint another
surveyor to survey as he
chose Mr. Ma. Requested for
Kenneth.

From: tonygn tonygn [mailto:tonygn18@hotmail.com]

Sent: Thursday, June 14, 2018 3:56 PM

To: Chan, Yoke Shi

Subject: Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GBB6364B AND CB6579L ON 23/05/2018

We agree with your surveyors as follows:

1. **No.** ---- MA CHIN FOOK
2. **Name** ---- LKK Auto Consultants Pte. Ltd

Thank you.

Yours sincerely,
Keng Hock Auto

Sent from [Outlook](#)

From: Chan, Yoke Shi <yokeshi.chan@aig.com>

Sent: Thursday, June 14, 2018 11:24 AM

To: tonygn tonygn

Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Supramaniam, Darshene; Mithoosingh, Aashweenjeetkaur; Azlan, Syazairdina

Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GBB6364B AND CB6579L ON 23/05/2018

Dear Sir/Madam,

Reminder for pre-repair survey.
Kindly response to the email below whether agree to the appointment of any of these motor surveyors below as a single joint expert.

Thank you.

Regards,

Yoke Shi @ Ashley

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)
Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel +6 03 2719 6000 | Ext 1012102

yokeshi.chan@aig.com | www.aig.com

From: Chan, Yoke Shi

Sent: Wednesday, June 13, 2018 2:19 PM

To: tonygn tonygn

Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Supramaniam, Darshene; Mithoosingh, Aashweenjeetkaur; Azlan, Syazairdina

Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GBB6364B AND CB6579L ON 23/05/2018

Without Prejudice

Your Reference : 18-X848

Our Reference : 0422142588SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

| Name of Surveyor | Company Name |
|--------------------------|--|
| Lim Kok Chong | AIG Asia Pacific Insurance Pte Ltd |
| Kumar Uthaya | AIG Asia Pacific Insurance Pte Ltd |
| Ken Wong | AIG Asia Pacific Insurance Pte Ltd |
| Lawrence Ng Chun Kee | Priority Services |
| Jeffrey Ong Leng Kiat | Priority Services |
| Jimmy Lee | Priority Services |
| EC Looi | Automobile Inspection Services Pte Ltd |
| Ricky Teng | RT Appraisal Pte Ltd |
| Elson Teng | RT Appraisal Pte Ltd |
| Michael Cheong | RT Appraisal Pte Ltd |
| Pang Kiah Keen (Frankie) | Formteam Adjusters Pte Ltd |
| Ng You Han | Formteam Adjusters Pte Ltd |
| Soon HanXin (Gary) | Formteam Adjusters Pte Ltd |
| Chow Bo Xiong | Formteam Adjusters Pte Ltd |
| Chua Soo Teck (Benjamin) | Formteam Adjusters Pte Ltd |
| Kalvin Ang | LKK Auto Consultants Pte Ltd |
| Xing Guo Qiang | LKK Auto Consultants Pte Ltd |
| Marcus Chua | LKK Auto Consultants Pte Ltd |
| Mohamad Taufikh | LKK Auto Consultants Pte Ltd |
| Adrian Ling | LKK Auto Consultants Pte Ltd |
| Henry Ng | LKK Auto Consultants Pte Ltd |
| Mohammed Rasul | LKK Auto Consultants Pte Ltd |
| Steven Foong | LKK Auto Consultants Pte Ltd |
| Wei Jie | LKK Auto Consultants Pte Ltd |
| Ma Chin Fook | LKK Auto Consultants Pte Ltd |
| Kenneth Kong | LKK Auto Consultants Pte Ltd |

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

Yoke Shi @ Ashley

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)

Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel +6 03 2719 6000 | Ext 1012102

yokeshi.chan@aig.com | www.aig.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

KENG HOCK AUTO

Blk. 7, Sin Ming Industrial Estate C, #01 - 84, Singapore 575642

Fax : 6458 - 5589 / H/P : 9657 - 1534

Date :- 13 / 6 / 2018

BY HAND

Motor Claims Department

Ang Asia Pacific Insurance Pte. Ltd.

BY FAX :-

COPY

Dear Sir,

6415 - 3727

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

We have been appointed by the Owner to repair his/her motor vehicle

No. *CB 6579L* on *23-5-18* with another vehicle

No. *GBB6364 B* at *Mount Elizabeth Hospital*

Please be informed that the said vehicle can be inspected at:-

Contact

Workshop :

KENG HOCK AUTO

*Please call before
coming down. Vehicle
on the MVE*

Sector C, Blk. 7, #01 - 84

Sin Ming Road Singapore 575642

Fax

:

6458 - 5589

Contact

Person

:

Thomas / 9657 - 1534

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Holiday. We will commence repairs thereafter without further reference to you.

Yours faithfully,

Wu LLC - Law Firm - Tony Gn

Our Ref : 18

- X 848

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

| | |
|-------------------------------------|----------------|
| Vehicle Owner Particulars | |
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 4832F |
| Vehicle Details | |
| Vehicle No.: | CB6579L |
| Vehicle to be Exported: | No |
| Intended De-registration Date: | 19 Jun 2018 |
| Vehicle Make: | TOYOTA |
| Vehicle Model: | HIACE 2.5 M |
| Primary Colour: | Silver |
| Manufacturing Year: | 2004 |
| Engine No.: | 2KD1224522 |
| Chassis No.: | KDH2000010664 |
| Maximum Power Output: | - |
| Open Market Value: | \$31,974.00 |
| Original Registration Date: | 02 Jul 2005 |
| First Registration Date: | 02 Jul 2005 |
| Transfer Count: | 3 |
| Actual ARF Paid: | \$1,599.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | No |
| PARF Eligibility Expiry Date: | - |
| PARF Rebate Amount: | \$0.00 |
| Intended COE Rebate Details | |
| COE Rebate Amount: | \$0.00 |
| Total Rebate Amount: | \$0.00 |

The information contained herein is correct as at 19 Jun 2018

OK

→ King Hock Auto

A16

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 24/05/2018 15:37
Date Of Accident 23/05/2018 16:00
Exact Location Of Accident NEAR MOUNT ELIZABETH HOSPITAL
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number CB6579L
Insured/Policyholder
Name Of Registered Owner SENG CHEE KIONG
NRIC No S1544832F
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-84321168
Alternative Phone No OFFICE-84321168

Vehicle Particulars

Manufacturer TOYOTA
Model
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
Fleet Policy NO
Policy Number DMB1SN3068041700
Cover Note Number

Driver

Name of Driver YEO LIAT CHENG
NRIC No
Date Of Birth 13/10/1940
Occupation
Date Of Driving Pass
Driving Experience 42 YEARS AND 6 MONTHS
Gender MALE

Mobile Number
Fax Number SER.# : E74269MSN975839
Contact Number TEL :
EEmail Address NAME : NOEMAIL
TIME : 11/02/2017 07:18

TRANSMISSION VERIFICATION REPORT

DATE, TIME
FAX NO./NAME
DURATION
PAGE(S)
RESULT
MODE

Address

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident SIDE SWIPE

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 4

Passenger 1 NAME: : PASSENGER

GENDER: : MALE

Passenger 2 NAME: : PASSENGER

GENDER: : FEMALE

Passenger 3 NAME: : PASSENGER

GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

refer attached report.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBB6364B

Vehicle Make/Model/Colour

Details Of Properties


Vehicle Category COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number 96755504

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 23.05.18 at about 15.57pm I was driving my Van CB 6579L along Mount Elizabeth near to Mt. Elizabeth hospital entrance suddenly the Van GBB 6364B which was stopped there suddenly drive out and hit onto my left front side.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

慶福摩哆
KENG HOCK AUTO
SECTOR C, BLK 7 #01-84
SIN MING ROAD SINGAPORE 575642
TEL/FAX: 6458 5589 H/P: 9657 1534

| | |
|--------------------|----------------------|
| Name: | Date: 13/6/18 |
| | Terms: |
| Address: Quotation | |
| | Regn. No: CB 6579L |
| | Vehicle Make: TOYOTA |
| Tel. No: | Mileage: |

| Parts Replaced / Labour Charges / Other Services | | Qty | U/Price \$ | Amount \$ | |
|--|----------------------|---------|------------|-----------|-------|
| 1 PC | Bumper | 473.00 | Actual | 685 | 60 ✓ |
| 1 PC | Bumper side retainer | | DI | 120 | 68 ✓ |
| 1 set | Bumper clip | | m | 20 | 00 ✓ |
| 1 PC | Headlamp | | LT | 780 | 70 ✓ |
| 1 PC | door | 1434.20 | B | 1,620 | 80 ✓ |
| 1 PC | door lock | | R | 350 | 16 X |
| 2 PC | door hinge | | R | 110 | 00 X |
| 1 PC | Radiator | | B/H/P | 1,350 | 08 ✓ |
| 1 PC | Radiator fan motor | | T | 420 | 10 Z |
| 1 PC | Radiator fan Cowling | | C/M | 130 | 90 Z |
| 1 PC | step board | | C/M | 180 | 60 ✓ |
| 1 PC | door rubber | | G | 160 | 00 50 |
| 1 PC | grille | | S | 350 | 00 X |
| | | 258 | | | |

To remove/renew L/H door quarter glass 150 00 60

To remove/renew Radiator fan motor 50 160 00

panel beating 500 950 00

Spray painting 320 850 00

Not Authorized 8388.28

61 Sep 83750

Repair After Paint 6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation E. & O. E.
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Total

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|---|---------------|---|--|--|-------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
| Main | 20 Jun 2018 Edit Reg | | 14 Jun 2018 00:00 Edit Adj Rpt | S\$3,750.00 Edit Estimates | S\$3,750.00 View Rpt | | Pending for Survey Report Cancel Case |

| Main | Reference | Claim Details | Documents | Show All |
|------|-----------|---------------|-----------|----------|
|------|-----------|---------------|-----------|----------|

CLAIM SUBFOLDER DETAILS [Created by adjuster]

| | | | |
|-----------------------------|--|------------------------|---|
| Insured: | THE SUNBIRD CHILD DEVELOPMENT CENTRE PTE LTD , Co. Reg. No.: 200206272D | | |
| Main Claimant: | SENG CHEE KIONG , ID: S1544832F | | |
| Vehicle Reg. No.: | CB6579L | Date of Loss: | 23/05/2018 16:00 - :59 [154 Months and 21 Days From LTA Reg Date (Man Yr)] |
| Claim Type: | TP / 0422142588SG | Policy/Cover Note No.: | 2100159689 (Comprehensive) |
| Vehicle Reg. No. (Insured): | GBB6364B | Policy No. (Claimant): | |
| | | Excess: | |
| Repairer: | Keng Hock Auto (HQ) No 8 Burn Road Trivex, #08-02/03, 369977 Sin Ming - Tel: | | |
| Handling Insurer: | AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 28/06/2018] | | |
| Claimant's Solicitor: | WU LLC - Tel: 63271276 | | |

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. | | | | | | | | | |

Claim Documents

*CB6579L (0422142588SG)

[GBB6364B]

TP

SENG CHEE KIONG

May 23 2018 4:00PM

[THE SUNBIRD CHILD DEVELOPMENT CENTRE PTE LTD]

Keng Hock Auto

| Upload Documents | | Upload Photos | | Compose New Letter | | Upload Video | | Upload Audio | | View View in Browser | | |
|----------------------|-----------------|---|--|--------------------|-------------------------------------|--------------|--|--------------|--|---|--|--|
| Photos/Images | | | | | | | | | | 3 per page 3 per page <input checked="" type="checkbox"/> | | |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | Thumbnail | Print | | | | | | | |
| 1 | 19/06/18 12:10 | General View | | Load JPG | <input checked="" type="checkbox"/> | | | | | | | |
| 2 | 19/06/18 12:10 | General View | | Load JPG | <input checked="" type="checkbox"/> | | | | | | | |
| 3 | 19/06/18 12:10 | General View | | Load JPG | <input checked="" type="checkbox"/> | | | | | | | |
| 4 | 19/06/18 12:10 | General View | | Load JPG | <input checked="" type="checkbox"/> | | | | | | | |
| 5 | 19/06/18 12:10 | General View | | Load JPG | <input checked="" type="checkbox"/> | | | | | | | |
| 6 | 19/06/18 12:10 | General View | | Load JPG | <input checked="" type="checkbox"/> | | | | | | | |
| 7 | 19/06/18 12:10 | General View | | Load JPG | <input checked="" type="checkbox"/> | | | | | | | |
| 8 | 19/06/18 12:10 | General View | | Load JPG | <input checked="" type="checkbox"/> | | | | | | | |
| 9 | 19/06/18 12:10 | General View | | Load JPG | <input checked="" type="checkbox"/> | | | | | | | |
| 10 | 19/06/18 12:10 | General View | | Load JPG | <input checked="" type="checkbox"/> | | | | | | | |
| 11 | 19/06/18 12:10 | General View | | Load JPG | <input checked="" type="checkbox"/> | | | | | | | |
| 12 | 19/06/18 12:10 | General View | | Load JPG | <input checked="" type="checkbox"/> | | | | | | | |
| 13 | 19/06/18 12:10 | General View | | Load JPG | <input checked="" type="checkbox"/> | | | | | | | |
| 14 | 19/06/18 12:10 | General View | | Load JPG | <input checked="" type="checkbox"/> | | | | | | | |
| 15 | 20/07/18 11:26 | Reinspection Photo | | Load JPG | <input checked="" type="checkbox"/> | | | | | | | |
| 16 | 20/07/18 11:26 | Reinspection Photo | | Load JPG | <input checked="" type="checkbox"/> | | | | | | | |
| 17 | 20/07/18 11:26 | Reinspection Photo | | Load JPG | <input checked="" type="checkbox"/> | | | | | | | |
| 18 | 20/07/18 11:26 | Reinspection Photo | | Load JPG | <input checked="" type="checkbox"/> | | | | | | | |
| Documentation | | | | | | | | | | 1 per page 1 per page <input checked="" type="checkbox"/> | | |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | Thumbnail | Print | | | | | | | |
| 1 | 19/06/18 12:09 | TP GIA REPORT | | Load PDF | | | | | | | | |
| No | Finalized On | AIG Asia Pacific Insurance Pte. Ltd. (SG) | | Thumbnail | Print | | | | | | | |
| 1 | 20/06/18 12:28 | OI GIA REPORT | | Load PDF | | | | | | | | |

Documents Checklist

| | | | | |
|--|--|-------|------|-------|
| DOCUMENTS CHECKLIST | | Reset | Save | Print |
| There are no document checklists configured. | | | | |
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) | | | | |
| <div style="border: 1px solid black; width: 100%; height: 100%;"></div> | | | | |
| Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small> | | | | |

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG18011027/KVBE2

Date: 01/08/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100159689
Claimant Vehicle No : CB6579L **Insured Vehicle No :** GBB6364B
 Date of Loss: 23/05/2018 Nature of Claim: TP Claim No: 0422142588SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **CB6579L**
 Make & Model: TOYOTA HIACE, 2.5 (A) Engine No: 2KD1224522
 Reg. Date: 02/07/2005 (Man. Year: 2004) Chassis No: KDH2000010664
 Colour: Metallic Silver Odometer: 592264 km
 Engine Capacity: 2494 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195 R15X8 Rear Tyre Size: 195 R15X8
 Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm
 Front Right Side: Michelin 7 mm Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-----------------|-----------------|-----------------|--------------|
| Parts | 6,278.28 | 3,763.23 | 2,515.05 | 40.06 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,110.00 | 930.00 | 1,180.00 | 55.92 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 8,388.28 | 4,693.23 | 3,695.05 | 44.05 |
| Approved Total (Overridden) (S\$) | | 3,750.00 | | |
| Nett Amount (S\$) | 8,388.28 | 3,750.00 | 4,638.28 | 55.29 |

INSPECTION

Date of Assignment: 14/06/2018
 Date Inspected: 18/06/2018 Inspected At: Keng Hock Auto (HQ)
 BLK 7, SIN MING ROAD,
 SECTOR C #01-84,
 SINGAPORE 575642

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-----------------------|-------------------|------------|--------------|
| 1 | 1 | | *BUMPER | Buckled / Cracked | 685.60 F | *475.00 FL |
| 2 | 1 | | *BUMPER SIDE RETAINER | Distorted | 120.08 F | *120.08 FL |
| 3 | 1 | | *BUMPER CLIPS | Necessary | 20.00 F | *20.00 FL |
| 4 | 1 | | *HEADLAMP | Cut | 780.10 F | *780.10 FL |
| 5 | 1 | | *DOOR | Bent | 1,620.80 F | *1,434.20 FL |
| 6 | 1 | | *DOOR LOCK | Repair | 350.10 F | *- FL |
| 7 | 2 | | *DOOR HINGE | Repair | 110.00 F | *- FL |
| 8 | 1 | | *RADIATOR | Bent / Punctured | 1,350.00 F | *1,350.00 FL |
| 9 | 1 | | *RADIATOR FAN MOTOR | Torn | 420.10 F | *420.10 FL |
| 10 | 1 | | *RADIATOR FAN COWLING | Cracked | 130.90 F | *130.90 FL |
| 11 | 1 | | *STEP BOARD | Cracked | 180.60 F | *180.60 FL |
| 12 | 1 | | *DOOR RUBBER (50%) | Cut | 160.00 FS | *80.00 FS |
| 13 | 1 | | *GRILLE | Serviceable | 350.00 F | *- FL |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|---|-----------------|-----------------|
| Sub Total (\$) | 6,278.28 | 4,990.98 |
| - List Item Discount on L Items 0.00/25.00% (\$) | 0.00 | 1,227.75 |
| Total Parts (\$) | 6,278.28 | 3,763.23 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------|--|----------|------------|--------|
| <u>Labour Items</u> | | | | |
| 1 | TO REMOVE / RENEW L/H DOOR QUARTER GLASS | New | 150.00 | 60.00 |
| 2 | TO REMOVE / RENEW RADIATOR & FAN MOTOR | New | 160.00 | 50.00 |
| 3 | PANEL BEATING | New | 950.00 | 500.00 |
| 4 | SPRAY PAINTING | New | 850.00 | 320.00 |
| Gross Labour Cost (\$\$) | | | 2,110.00 | 930.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >