

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0688/2018/GW
Date : 16-Jun-18

Vehicle not IN workshop. Kindly arrange for survey.

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

Owner's Name : Ms.Teh Guek Ngor Engelin
Address : 12 Sime Road
Singapore 288287
Telephone : HP +65 91720255
Type of Claim : Third Party Claims
Policy No. : 5073945922-01
Vehicle No : **ET 888 R**
Model Code : Audi A6 1.8 TFSI Ultra S
Model / Year : Sep-15
Engine No : CYG 004783
Chassis No : WAUZZZ4G8FN081217
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 12-Jun-18
Place of Accident : ST. ANDREW'S ROAD

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle ET888R.

S/n	Nature of Jobs	Estimated Charges
1	To remove and transfer rear parking aid and rear lid kick sensor assy. Check function.	S/N \$ 360.00
2	To dismantle and renew rear bumper. Re-organise rear crash management components. Reinstall all parts removed.	\$ 900.00
3	To respray rear bumper	\$ 800.00
4	To carry out diagnostic check.	S/N \$ 192.00
TOTAL LABOUR CHARGES		: <u>\$ 2,252.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.ET888R.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER	\$ 2,300.00	
2	REAR BUMPER COVER	\$ 234.00	
3	REAR BUMPER FIXING PARTS	\$ 23.00	
4	REAR BUMPER SPOILER	\$ 416.00	
5	REAR BUMPER GUIDE SECTION-RH/LH	2 \$ 92.00	
6	REAR BUMPER GUIDE SECTION-CENTER	\$ 91.00	
7	REAR SENSOR	2 \$ 421.00	
8	REAR BUMPER CARRIER	\$ 851.00	
9	REAR BUMPER SEAL-LH/RH	2 \$ 24.00	
10	REAR BUMPER SECURING STRIP	\$ 191.00	
11	REAR BUMPER CLOSING ELEMENT -LH/RH	2 \$ 138.00	
12	SUNDRIES	\$ 200.00	
TOTAL SPARE PARTS CHARGES :		\$ 4,981.00	
TOTAL LABOUR CHARGES		\$ 2,252.00	
GRAND TOTAL		\$ 7,233.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant