

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 7441Y

DATE 18/6/2018 14:28

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Fender (RH) <i>X rep.</i>			\$ 2,020.10
	Rear Fender Inner Lining (RH) <i>X</i>			\$ 164.40
	Rear Windscreen Moulding <i>X</i>			\$ 60.00
	Rear Door Protector(RH) <i>X</i>			\$ 56.90
	Front Door (RH) <i>X rep.</i>			\$ 1,403.05
	<i>Rear Door (RH) X rep.</i>			
	<i>Rear Bumper X rep.</i>			
	SUB TOTAL			\$ 3,704.45
	LESS 20%			\$ 740.89
	DISCOUNTED TOTAL			\$ 2,963.56
	Rear Windscreen Sealant <i>X</i>			\$ 46.00
	Rear Door Tel No. Sticker (RH) <i>/</i>			\$ 10.00
	Front Door Coloured Comfort Logo (RH) <i>-</i>			\$ 75.00
				\$ 131.00
	Labour Charge			
	Panel Beating			\$ 1,000.00 <i>400</i>
	Spray Painting Charge-2 x Door/Fender/Bumper			\$ 1,000.00 <i>800</i>
	Tuff Kote			\$ 50.00 <i>X</i>
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 <i>X</i>
	Remove/Refix Rear Windscreen Glass			\$ 120.00 <i>X</i>
	Remove/Refix Reverse Sensor			\$ 120.00 <i>X</i>
	Transfer of Door			\$ 120.00 <i>X</i>
	TOTAL LABOUR			\$ 2,560.00
	ESTIMATE TOTAL			\$ 5,654.56

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

/Kahar 16/6/18

11, 8/6/18 1540hr
2 hrs.

43

After Repair photo

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.