

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 965E

MAKE :

MODEL : MERCEDES BENZ VIANO (REAR)

DATE 18/6/2018 15:11

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper ✓			\$ 1,372.00
	Bumper L/H Side, RR <i>x 14.2</i>			\$ 473.60
	Bumper R/H Side, RR ✓			\$ 473.60
	Bumper Refector RR/LH/RH <i>LH x RH ✓</i>		\$ 46.00	\$ 92.00
	Crossmember Rear ?			\$ 369.60
	Crossmember Stay Rear (2 Pcs) ?			\$ 94.38
	Tail Gate Assy ✓			\$ 3,951.98
	Tail Gate Mercedes Star Logo ✓			\$ 45.46
	Tail Gate "2.2" Logo ✓			\$ 78.00
	Tail Gate "CDI" Logo ✓			\$ 78.00
	Tail Gate Via No Logo ✓			\$ 78.00
	Tail Gate Lock Outer Handle ✓			\$ 175.54
	SUB TOTAL			\$ 7,282.16
	LESS 20%			\$ 1,456.43
	DISCOUNTED TOTAL			\$ 5,825.73
	Reverse Sensor ✓			\$ 288.00 Nett
	Rear Bumper Rubber Mat <i>x</i>			\$ 50.00 Nett
	Tail Gate "MAXICAB" Logo ✓			\$ 30.00 Nett
				\$ 368.00
	Labour Charge			400
	Panel Beating			\$ 1,000.00
	Spray Painting Charge			\$ 500.00 <i>400</i>
	Wiring Charge			\$ 50.00 <i>30</i>
	Towing Charges			\$ 50.00 <i>x</i>
	Tuff Kote			\$ 50.00 <i>20</i>
	TOTAL LABOUR			\$ 1,650.00
	ESTIMATE TOTAL			\$ 7,843.73
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK/kalwin

H/Sun

Like

AIG

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Kok's 10/10/18
11, 8/6/18 1600h
3 hrs
4 hrs
After Repair photo