

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA6205L

MAKE : HYUNDAI

MODEL : SONATA

Date : 18.06.2018

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	Rear Door – LH <i>X repair</i>			\$ 1,294.70
1	Rear Door Protector – LH <i>X repair</i>			\$ 54.50
1	Rear Fender – LH <i>X repair</i>			\$ 1,935.90
1	Wheel cover – LH			\$ 145.00
SUB TOTAL				\$ 3,430.10
LESS 20%				686.02
DISCOUNTED TOTAL				\$ 2,744.08
1	Rear Door Tel Sticker			\$ 10.00
				Nett
				\$ 10.00
Labour Charge				
Panel Beating				
Spray Painting Charge				
Transfer of Door				
Wiring Charge				
Tuff Kote				
<i>Kalin 10/11/18</i> <i>18/6/18 16:15 hrs</i> <i>2 hrs</i> <i>4/5</i> <i>After Repair photo</i>				
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Signature: _____				
TOTAL LABOUR				\$ 1,330.00
ESTIMATE TOTAL				\$ 4,084.08

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.