

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5843R****AAD1711-127***Not Authorised**\$220k**18/11/18  
Tm1*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

**SHC 5843R**

VF1ABL15AUC281421

RENAULT

LATITUDE

10.11.2017

**AIG**

| PART |                                | LIST |             |
|------|--------------------------------|------|-------------|
| 1    | 1 BUMPER COVER REAR            | \$   | SH 1,108.46 |
| 2    | 1 BUMPER LOWER REAR            | \$   | SH 768.84   |
| 3    | 1 BUMPER BRACKET CTR REAR      | \$   | SH 113.47   |
| 4    | 1 BUMEP R BRACKET SIDE RH REAR | \$   | SH 135.97   |
| 5    | 1 BUMEP R RETAINER RH REAR     | \$   | SH 44.99    |
| 6    | 1 BUMPER REFLECTOR RH          | \$   | SH 43.61    |
| 7    | 1 BUMEP R BRACKET SIDE LH REAR | \$   | SH 135.97   |
| 8    | 1 BUMEP R RETAINER LH REAR     | \$   | SH 44.99    |
| 9    | 1 BUMPER REFLECTOR LH          | \$   | SH 43.61    |
| 10   | 1 BUMPER BEAM REAR             | \$   | N 777.52    |
| 11   | 1 BUMPER BEAM BRACKET LH REAR  | \$   | N 225.95    |
| 12   | 1 BUMPER BEAM BRACKET RH REAR  | \$   | N 225.95    |
| 13   | 1 BOOT REAR                    | \$   | N 2,872.68  |
| 14   | 1 BOOT FINISHER                | \$   | SH 470.06   |
| 15   | 1 BOOT WHEATERSTRIP            | \$   | SH 323.05   |
| 16   | 1 BOOT REFLECTOR LAMP LH       | \$   | SH 493.35   |
| 17   | 1 BOOT REFLECTOR LAMP RH       | \$   | SH 493.35   |
| 18   | 1 BOOT BADGE 'RENAULT'         | \$   | na 225.36   |
| 19   | 1 BOOT BADGE                   | \$   | na 225.36   |
| 20   | 1 BOOT STRUT LH                | \$   | SH 276.08   |
| 21   | 1 BOOT STRUT RH                | \$   | SH 276.08   |
| 22   | 1 BOOT HINGE LH                | \$   | N 367.84    |
| 23   | 1 BOOT HINGE RH                | \$   | N 367.84    |
| 24   | 1 BOOT INNER TRIM              | \$   | SH 586.45   |
| 25   | 1 BOOT SWITCH                  | \$   | SH 168.13   |
| 26   | 1 BOOT LOCK                    | \$   | N 202.67    |
| 27   | 1 BOOT LOCK CATCH              | \$   | N 74.40     |
| 28   | 2 LICENCE PLATE LAMP           | \$   | SH 50.52    |
| 29   | 2 BOOT RUBBER PLUG             | \$   | SH 221.81   |

**Trans-cab Auto Services Pte Ltd****AAD1711-127**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5843R**

|    |                                           |    |                   |          |
|----|-------------------------------------------|----|-------------------|----------|
| 30 | 1 DOOR PANEL REAR LH                      | \$ | <i>N</i> 2,844.66 | <i>X</i> |
| 31 | 1 FENDER PANEL INNER TRIM REAR LH         | \$ | <i>Sn</i> 671.45  |          |
| 32 | 1 FENDER PANEL REAR LH                    | \$ | <i>N</i> 3,299.13 |          |
| 33 | 1 WHEELARCH REAR LH                       | \$ | <i>Sn</i> 543.47  |          |
| 34 | 1 FENDER PANEL INNER TRIM REAR RH         | \$ | <i>Sn</i> 671.45  |          |
| 35 | 1 FENDER PANEL REAR RH                    | \$ | <i>N</i> 3,299.13 |          |
| 36 | 1 WHEELARCH REAR RH                       | \$ | <i>Sn</i> 543.47  |          |
| 37 | 1 TAILLAMP RH                             | \$ | <i>Sn</i> 552.55  |          |
| 38 | 1 TAILLAMP PANEL RH                       | \$ | <i>N</i> 986.70   |          |
| 39 | 1 TAILLAMP LH                             | \$ | <i>Sn</i> 552.55  |          |
| 40 | 1 TAILLAMP PANEL LH                       | \$ | <i>N</i> 986.70   |          |
| 41 | 1 OUTER PANEL REAR (End Panel)            | \$ | <i>N</i> 1,471.77 |          |
| 42 | 1 OUTER PANEL REAR (End Panel)TRIM        | \$ | <i>Sn</i> 404.56  |          |
| 43 | 1 SPARE WHEEL PANEL (Luggage Floor Panel) | \$ | <i>N</i> 2,189.88 |          |
| 44 | 1 SPARE WHEEL PANEL TRIM                  | \$ | <i>Sn</i> 612.21  |          |
| 45 | 1 EXHAUST REAR                            | \$ | <i>N</i> 7,489.05 |          |
| 46 | 1 EXHAUST CAP REAR                        | \$ | <i>N</i> 230.49   |          |
| 47 | 1 FUEL FLAP L70Y                          | \$ | <i>Sn</i> 343.57  |          |
| 48 | 1 FENDER WHEEL HOUSE PANEL REAR LH        | \$ | <i>N</i> 3,039.04 |          |

|              |           |                  |
|--------------|-----------|------------------|
| <b>TOTAL</b> | <b>\$</b> | <b>42,096.20</b> |
| <b>10%</b>   | <b>\$</b> | <b>4,209.62</b>  |
|              | <b>\$</b> | <b>37,886.58</b> |

**Special Nett**

|    |                                     |    |                  |          |
|----|-------------------------------------|----|------------------|----------|
| 1  | 1SET PARKING AID                    | \$ | <i>Sn</i> 700.00 | <i>X</i> |
| 2  | 1SET REAR BUMPER CLIP               | \$ | <i>na</i> 66.00  |          |
| 3  | 1SET BUMPER BRACKET CTR CLIP        | \$ | <i>na</i> 33.00  |          |
| 4  | 1SET BUMPER BRACKET SIDE CLIP RH RR | \$ | <i>na</i> 10.00  |          |
| 5  | 1SET BUMPR RETAINER RH CLIP RR      | \$ | <i>na</i> 20.00  |          |
| 6  | 1SET BUMPR BRACKET SIDE CLIP LH RR  | \$ | <i>na</i> 10.00  |          |
| 7  | 1SET BUMPR RETAINER CLIP LH RR      | \$ | <i>na</i> 20.00  |          |
| 8  | 1SET BUMPER LOWER REAR RIVET        | \$ | <i>na</i> 22.00  |          |
| 9  | 1SET BUMPER LOWER REAR CLIP         | \$ | <i>na</i> 66.00  |          |
| 10 | 1 EXHAUST MOUNTING REAR             | \$ | <i>na</i> 17.82  |          |
| 11 | 1SET BOOT FINISHER CLIP             | \$ | <i>na</i> 24.20  |          |
| 12 | 1 BOOT STICKER "Trans-cab"          | \$ | <i>na</i> 30.00  |          |
| 13 | 1 BOOT STICKER "6555-3333"          | \$ | <i>na</i> 30.00  |          |

**Trans-cab Auto Services Pte Ltd**

AAD1711-127

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5843R**

|    |                                     |    |    |        |   |   |
|----|-------------------------------------|----|----|--------|---|---|
| 14 | 1 BOOT INNER TRIM CLIP              | \$ | na | 45.00  | } | X |
| 15 | 1SET FENDER WHEELARCH REAR RH CLIP  | \$ | na | 35.00  |   |   |
| 16 | 1SET FENDER WHEELARCH REAR LH CLIP  | \$ | na | 35.00  |   |   |
| 17 | 1 FENDER INNER TRIM CLIP LH         | \$ | na | 28.00  |   |   |
| 18 | 1 FENDER INNER TRIM CLIP LH         | \$ | na | 28.00  |   |   |
| 19 | 1 TAILLAMP CLIP RH                  | \$ | na | 5.00   |   |   |
| 20 | 1 TAILLAMP CLIP LH                  | \$ | na | 5.00   |   |   |
| 21 | 2 REAR WINDSCREEN SELANT            | \$ | na | 80.00  |   |   |
| 22 | 1 WINDSCREEN MOULDING               | \$ | na | 100.00 |   |   |
| 23 | 1 REAR WINDSCREEN INNER SPONGE SEAL | \$ | na | 100.00 |   |   |
| 24 | 1 SPARE TYRE RIM (ROUE 7J 16H 2547) | \$ | SH | 385.00 | } |   |
| 25 | 1 SPARE TYRE                        | \$ | SH | 330.00 |   |   |

**TOTAL \$ 2,225.02****TOTAL PARTS \$ 40,111.60****LABOUR**

|                                                                                                                           |    |             |      |
|---------------------------------------------------------------------------------------------------------------------------|----|-------------|------|
| Putty And Spray Painting Of The Affected Portion.                                                                         | \$ | 6,000.00    | 2201 |
| Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same | \$ | na 4,200.00 | X    |
| To Rust-Proofing Of The Affected Areas.                                                                                   | \$ | na 170.00   | X    |
| To reinstall rear bumper parking sensor.                                                                                  | \$ | na 170.00   | X    |
| To transfer of bootlid fittings, attachments and perform water seepage test.                                              | \$ | na 170.00   | X    |
| To repair and realign rear exhaust pipe.                                                                                  | \$ | na 170.00   | X    |
| To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.                                      | \$ | na 170.00   | X    |

**Trans-cab Auto Services Pte Ltd**

AAD1711-127

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5843R

|                                                                                              |    |        |   |
|----------------------------------------------------------------------------------------------|----|--------|---|
| To transfer of rear end panel fittings, attachment and perform water seepage test.           | \$ | 170.00 | X |
| To transfer of rear luggage floor panel fittings, attachment and perform water seepage test. | \$ | 170.00 | X |
| To supply and re-do rear luggage floor panel insulation padding.                             | \$ | 380.00 | X |
| To transfer of rear fender fittings, attachment and perform water seepage test.              | \$ | 380.00 | X |
| To transfer of rear windscreen fittings and conduct water seepage test.                      | \$ | 170.00 | X |
| To check steering geometry and computer wheel alignment                                      | \$ | 220.00 | X |
| To transfer of rear door fittings, attachment and perform water seepage test.                | \$ | 380.00 | X |

**TOTAL \$ 12,540.00****Over All Total \$ 52,651.60****(LUMP SUM)****Repair Days****20 DAYS**  
*1 day*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: