



HUA HONG PRIVATE LIMITED

25D Sungei Kadut Street 1 Singapore 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huhong.com.sg

Estimate Repair List

21 June 2018

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#09-16 AIG Building
Singapore 079120

Attn: Motor Claims Department

ACCIDENT INVOLVING SJU 9955 G & SLJ 1325 L ON 17/06/2018 ALONG MARSILING DRIVE AT ABOUT 0020 HOURS

Insured : YONG YI JING
Vehicle Registration No : SJU 9955 G
Vehicle Make : BMW
Vehicle Model : 520i AUTO ABS AIRBAG 2WD XENON HEADLAMP
Vehicle Chassis No : WBANT12000CX30325
Policy No : GA088482/1
Date of Accident : 17/06/2018

HHTPClaims18-55

3 days

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "No Prejudice" basis
• No illegal modification allowed
• Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

			Type of Claim: Third Party	
S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Rear Bumper (M3) ✓ DMH		\$ 1,502.05 ✓
2	10	Rear Bumper Clip ✓ NEL	\$ 5.00	\$ 50.00 30 ✓
3	2	Rear Bumper Retainer (LH/RH) 3 X NN	\$ 142.55	\$ 285.10 X
4	1	Rear Bumper Lower Garnish RX		\$ 170.00 X
5	1	Rear Reinforcement 3 - Bonf	529.25	\$ 529.25 ✓
6	1	Rear Tail Lamp (LH) ✓ SCR		\$ 478.00 ✓
7	1	Rear Exhaust Silencer RX		\$ 1,098.80
				\$ 4,113.20
			Less 10%	\$ (411.32)
				\$ 3,701.88

8 2 Rear Reverse Sensor (LH) ✓ ~~NETT~~ \$ 220.00 \$ 440.00

To dismantle & change rear bumper, rear reinforcement, rear LH tail lamp, knocking & pull straight rear end panel and all area affected by accident.

To perform wire checking.

To dismantle & refit rear bumper sensor.

To dismantle & refit rear exhaust pipe.

To spray rear bumper, rear bumper garnish, reinforcement & rear end panel.

Authorised by Claims
Mrs Tan @ 9639 9195



7% GST
Total

\$ 6,171.88
\$ 432.03
\$ 6,603.91

Co. Reg. No. 200900309M | huhong.com.sg

GST Reg. No. 200900309M

L/S: \$2600 @ 3 days



HUA HONG PRIVATE LIMITED

25D Sungei Kadut Street 1 Singapore 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Supplementary List

28 June 2018

HHTPClaims18-55

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#09-16 AIG Building
Singapore 079120

Attn: Motor Claims Department

ACCIDENT INVOLVING SJU 9955 G & SLJ 1325 L ON 17/06/2018 ALONG MARSILING DRIVE AT ABOUT 0020 HOURS

Insured : YONG YI JING
Vehicle Registration No : SJU 9955 G
Vehicle Make : BMW
Vehicle Model : 520i AUTO ABS AIRBAG 2WD XENON HEADLAMP
Vehicle Chassis No : WBANT12000CX30325
Policy No : GA088482/1
Date of Accident : 17/06/2018

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Rear End Panel <i>x repair</i>		\$ 800.95 <i>x</i>
2	1	Rear Bumper Foam <i>- torn</i>		\$ 280.00 <i>✓</i>
				\$ 1,080.95
			Less 10%	\$ (108.10)
				\$ 972.86
			7% GST	\$ 68.10
			Total	\$ 1,040.95

6/7/19
4/5 3300 / 3 By



Authorised by Claims Dept
Mrs Tan @ 9639 9195