

PROGRESSIVE AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6844 4620 FAX: 6844 4625 Email: claims@progressiveauto.sg

GST:200712509E RCB NO:200712509E

Not Affected
2/1/18
Excess 4500
12/1/18
19/1/18
1st plus 10%
1/5/18
The ph. Aff.
ng.

M/S : ECICS LIMITED
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987

TEL: 6337-4779 FAX: 6338-9267

ATTN: Motor Claim Department

Your Ref No: SKR5389X

Claim Type: Own Damage

Accident Date: 13-06-2018

Estimate No: EST0000643
Date: 14 Jun 2018
Policy No: MPC18A00035402
Veh Reg No: SKR5389X
Make/Model: HONDA VEZEL 1.5X A
Chassis No: RU11014172
Engine No: L15B3514187
Reg. Date: 13-02-2015

Estimate Repair Cost to Vehicle No :SKR5389X

Description	U/Price	Quantity	List Price S\$	Amount S\$
HONDA VEZEL 1.5X A				
List Price				
1 Front Bonnet <i>3uc</i>	892.3000	1 PC	892.30	
2 Front Bonnet Lock <i>twi</i>	87.9000	1 PC	87.90	
3 Front Bonnet Lock Cable <i>u1</i>	40.1000	1 PC	40.10	
4 Front Bonnet Hinges <i>rel</i>	48.5000	2 PC	97.00	
5 Front Bonnet Center Rubber <i>rel</i>	28.8000	2 PC	57.60	
6 Front Bumper Side Rubber <i>rel</i>	24.9000	2 PC	49.80	
7 Front Bonnet Insulator <i>To 11</i>	122.3000	1 PC	122.30	
8 Front Bonnet Insulator Clipse <i>rel</i>	5.5000	7 PC	38.50	
9 Front Support Panel <i>rel/twi</i>	576.2000	1 PC	576.20	
10 Front Support Panel Top Garnish <i>dis</i>	85.3000	1 PC	85.30	
11 Front Support Panel Top Garnish Clipse <i>rel</i>	5.5000	9 PC	49.50	
12 Front Support Panel Side Garnish <i>To 11</i>	38.6000	2 PC	77.20	
13 Front Support Panel Side Garnish Clipse <i>rel</i>	5.5000	6 PC	33.00	
14 Front Wheel Housing Member	692.7000	1 PC	692.70	
15 Front Wheel Housing Sub Member	592.6000	1 PC	592.60	
16 Front Fender <i>M/S Buc 0/5K</i>	580.0000	2 PC	1,160.00	12C
17 Front Fender Dust Cover <i>M/S Torn</i>	140.7000	2 PC	281.40	12C
18 Front Fender Dust Cover Clipse <i>rel</i>	5.5000	16 PC	88.00	305.2
19 Front Fender Protector <i>26/To 11</i>	195.0000	2 PC	390.00	
20 Front Chassis Sub-Frame LH <i>n</i>	755.4000	1 PC	755.40	X
21 Front Windscreen <i>320</i>	2,315.900	1 PC	2,315.90	
22 Front Windscreen Moulding <i>rel</i>	131.5000	1 PC	131.50	
23 Front Wiper Panel Garnish <i>twi n1</i>	240.7000	1 PC	240.70	X
24 Front Wiper Panel Side Rubber <i>0/5 twi</i>	40.7000	2 PC	81.40	12C
25 Front Head Lamp Assy <i>one/320</i>	1,784.500	2 PC	3,569.00	
26 Front Head Lamp Lower Bracket <i>one</i>	35.0000	2 PC	70.00	
27 Front Grille <i>one</i>	351.8000	1 PC	351.80	
28 Front Grille Inner <i>one</i>	421.8000	1 PC	421.80	
29 Front Grille Moulding <i>rel</i>	95.0000	1 PC	95.00	
30 Front Alternator	1,850.600	1 PC	1,850.60	
31 Front Battery Tray	96.0000	1 PC	96.00	
32 Front Horn	42.1000	1 PC	42.10	
33 Front Washer Tank	85.0000	1 PC	85.00	
34 Front Washer Tank Motor <i>u1</i>	75.8000	1 PC	75.80	X
35 Front Engine Mounting RH <i>twi</i>	164.8000	1 PC	164.80	
36 Front Engine Mounting Bracket RH <i>one</i>	132.4000	1 PC	132.40	
37 Front Gearbox Mounting LH	295.2000	1 PC	295.20	
38 Front Centre Engine Mounting	135.0000	1 PC	135.00	

PROGRESSIVE AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6844 4620 FAX: 6844 4625 Email: claims@progressiveauto.sg

GST:200712509E RCB NO:200712509E

M/S : ECICS LIMITED
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987

TEL: 6337-4779 FAX: 6338-9267

ATTN: Motor Claim Department

Your Ref No: SKR5389X

Claim Type: Own Damage

Accident Date: 13-06-2018

Estimate No: EST0000643

Date: 14 Jun 2018

Policy No: MPC18A00035402

Veh Reg No: SKR5389X

Make/Model: HONDA VEZEL 1.5X A

Chassis No: RU11014172

Engine No: L15B3514187

Reg. Date: 13-02-2015

Estimate Repair Cost to Vehicle No :SKR5389X

Description	U/Price	Quantity	List Price	Amount
			SS	SS
39 Front Drive Shaft RH	1,100.600	1 PC	1,100.60	?
40 Front Drive Shaft Support Bracket RH	601.7000	1 PC	601.70	?
41 Front Cross Member	954.2000	1 PC	954.20	?
42 Front Shock Absorber LH	344.7000	1 PC	344.70	X
43 Front Lower Arm LH	181.5000	1 PC	181.50	?
44 Front Hub Bearing LH	181.5000	1 PC	181.50	?
45 Front Rod Link LH	68.2000	1 PC	68.20	?
46 Front Steering Wheel AirBag	1,605.900	1 PC	1,605.90	?
47 Front Dashboard	849.2000	1 PC	849.20	?
48 Front LH Air Bag	2,236.800	1 PC	2,236.80	?
49 Front Seat Belt R & L	564.7000	2 PC	1,129.40	?
50 Front Air Bag (Electric Control Unit)	916.7000	1 PC	916.70	?
51 Front Engine Dust Cover	245.2000	1 PC	245.20	?
52 Front Engine Side Dust Cover R & LH	124.2000	2 PC	248.40	?
53 Front Grille Support	98.2000	1 PC	98.20	?
54 Front Grille Emblem	28.4000	1 PC	28.40	?
55 Front Grille Top Garnish	85.0000	1 PC	85.00	?
56 Front Grille Clipse	5.5000	8 PC	44.00	?
57 Front Bumper	801.7000	1 PC	801.70	?
58 Front Bumper Reinforcement	321.0000	1 PC	321.00	?
59 Front Bumper Side Retainer	18.0000	2 PC	36.00	?
60 Front Bumper Reinforcement Garnish	34.9000	2 PC	69.80	?
61 Front Bumper Reinforcement Garnish Clipse	5.5000	4 PC	22.00	?
62 Front Bumper Lamp Grille	381.5000	1 PC	381.50	?
63 Front Bumper Fog Lamp	327.7000	2 PC	655.40	?
64 Front Bumper Fog Lamp Cover	38.5000	2 PC	77.00	?
65 Front Bumper Fog Lamp Bracket	20.7000	2 PC	41.40	?
66 Front Bumper Lower Pad	294.8000	1 PC	294.80	?
67 Front Aircon Condenser	850.6000	1 PC	850.60	?
68 Front Air Con Condensor Bracket	17.1000	2 PC	34.20	?
69 Front Aircon Liquid Pipe	295.0000	1 PC	295.00	?
70 Front Aircon Section Hose	142.5000	1 PC	142.50	?
71 Front Aircon Discharge Hose	261.0000	1 PC	261.00	?
72 Front Aircon Fan Cowling	98.0000	1 PC	98.00	?
73 Front Air Con Fan Blade	68.5000	1 PC	68.50	?
74 Front Aircon Fan Motor	328.0000	1 PC	328.00	?
75 Front Fan Belt	80.3000	1 PC	80.30	?
76 Front Radiator	1,250.600	1 PC	1,250.60	?
77 Front Radiator Top Rubber Bush	13.0000	2 PC	26.00	?
78 Front Radiator Lower Rubber Bush	13.0000	2 PC	26.00	X

PROGRESSIVE AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6844 4620 FAX: 6844 4625 Email: claims@progressiveauto.sg

GST:200712509E RCB NO:200712509E

M/S : ECICS LIMITED
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987
TEL: 6337-4779 FAX: 6338-9267
ATTN: Motor Claim Department
Your Ref No: SKR5389X
Claim Type: Own Damage
Accident Date: 13-06-2018

Estimate No: EST0000643
Date: 14 Jun 2018
Policy No: MPC18A00035402
Veh Reg No: SKR5389X
Make/Model: HONDA VEZEL 1.5X A
Chassis No: RU11014172
Engine No: L15B3514187
Reg. Date: 13-02-2015

Estimate Repair Cost to Vehicle No :SKR5389X

Description	U/Price	Quantity	List Price S\$	Amount S\$
79 Front Radiator Top Hose	42.0000	1 PC	42.00	?
80 Front Radiator Lower Hose	39.6000	1 PC	39.60	?
81 Front Radiator Spare Tank	85.5000	1 PC	85.50	?
82 Front Radiator Fan Cowling	145.0000	1 PC	145.00	?
83 Front Radiator Fan Motor	348.8000	1 PC	348.80	?
84 Front Radiator Fan Blade	68.5000	1 PC	68.50	?
85 Front Air Cleaner Box	189.5000	1 PC	189.50	?
86 Front Air Cleaner Air Duct	77.5000	1 PC	77.50	?
87 Front Air Cleaner Air Duct Joint Hose	56.9000	1 PC	56.90	?
88 Front Windscreen Gum	80.0000	1 PC	80.00	405.00
89 Front I.U Bracket	30.0000	1 PC	30.00	205.00
90 Front Number Plate	50.0000	1 PC	50.00	405.00
91 Front Battery	180.0000	1 PC	180.00	?
92 Front Intake Manifold	894.4000	1 PC	894.40	?
			35,689.40	
		Less 20%	7,137.88	28,551.52
Labour				
93 Towing - King Drolley	100.0000	1 PC	100.00	✓
94 Panel Beating	2,800.000	1 PC	2,800.00	1200
95 Check Wiring And Diagnose Test	350.0000	1 PC	350.00	300
96 To Remove & Refit Engine	580.0000	1 PC	580.00	250 + telephone?
97 To Remove & Replace Air Bag And Dashboard	580.0000	1 PC	580.00	300
98 To Remove & Replace Front Under Carriage	350.0000	1 PC	350.00	?
99 To Remove & Replace Aircon Condensor And Charge Gas	160.0000	1 PC	160.00	100
100 To Remove & Replace Radiator	80.0000	1 PC	80.00	x
101 To Spray Painting	1,400.000	1 PC	1,400.00	1000
102 To Remove & Replace Front Windscreen	160.0000	1 PC	160.00	120
			6,560.00	6,560.00
			Total	S\$ 35,111.52

TOTAL: SINGAPORE DOLLAR THIRTY FIVE THOUSAND ONE HUNDRED ELEVEN AND CENTS FIFTY TWO ONLY

LKKA to Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

For PROGRESSIVE AUTO PTE LTD

AUTHORISED SIGNATURE