

ASS. REC. BY:

REP: CS/CTI18011058/Ktd3ez

Special Instruction:

Surveyor
Merimen

Kenneth

ASSIGNMENT (Office)

From (Person):

Jouny Tay

of

CTI

Date/Time:

19/6/18 @ 9:50am

Estimated Cost:

Bill to:

☒ OD / TP / FWS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YN 9590J

Insured:

at Workshop m/s

Cheng Hoe Motor

Tel:

6755 6142

of

Blk 1019 # 01-374 / 382 Yishun Ind. Park A

Policy No:

DMCVSN1544961702

Claim No:

SNM18D02966C01

Sum Insured:

Excess:

\$550.00

Make of Veh:

(Client's Record)

D.O.A. 12/06/2018

CA / ☒ REV /

REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:39am @ 19/6/18

Person Contacted:

offeada

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

YN 9590J - CC3/CTI18010858/Kle63

DOA: 12/06/2018

20/6-

Report via merimen.

21/6-

17:09 inform by Susan Teo authorise repair

21/6-

@ 6:02pm inform Cheng Hoe via email authorise repair
excess \$550-

ASS. REC. BY:

REF: 6721

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: 5500

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 8640

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 1.131% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: YN 9590J Yr Regn: 10, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: Hit Carc c.c. 2998

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 47851 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: FEB 21EA 10364

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: _____

R: 195/85R15(D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal. 3 mm

L/Bal. 3 mm

D.O.A. 12/6/18

Rear

R/Bal. 4 4 mm

L/Bal. 4 4 mm

D.O.A. 19/6/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

20/6 File passed to Customer

28/1 Final Figure at \$4348, 8 days. (Red: 1220, 21%)
Confirm

[Signature]
28/1/2019

Date/Time, File Pass to?

☐ : Prel. Report

1) 28/1 Typist

☒ : Final Report

Date/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Survey Fee: 220

Transportation: _____

S + RS. \$ _____

Fixtots _____

Others _____

TOTAL

220

Report Format: OD

Lump Sum / I.B. (\$) 4348

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Jun 2018 Sendback Est	18 Jun 2018 14:02 S\$5,568.00	19 Jun 2018 09:50 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	XINGFU TRADING PTE LTD , Co. Reg. No.: 199006085W		
Vehicle Reg. No.:	YN9590J	Date of Loss:	12/06/2018 10:00 - :59 [32 Months and 6 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / SNM18D02966C01	Policy/Cover Note No.:	DMCVSN1544961702 (Comprehensive) Coverage: 06/10/2017 -
		Excess:	S\$550.00
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 28/06/2018]		
Driver/Custodian:	KOO CHUAN HENG (56 / Male), NRIC: S1557519J		
Adj Asg. Remarks:	PLEASE PROCEED TO SURVEY & REVERT. EXCESS OF \$550.00 APPLIES.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS ☐

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CT118011058/Ktd3

3 ANSON ROAD #16-00

SPRINGLEAF TOWERS SINGAPORE 079909

Date : 19-06-2018



Code : CTI

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	YN 9590J
Policy No.	DMCVSN1544961702	Coverage (\$)	0.00
Claim No.	SNM18D02966C01	Excess (\$)	550.00
Assign From	MERIMEN (JOWYN TAY)	Assign Date	19/06/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

5. General Information

Accident Date	12/06/2018	Inspection Date	
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		

5a. Remarks

- A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Thursday, 21 June 2018 6:02 PM
To: Efeeda (Cheng Hoe -Yishun)
Cc: SUR
Subject: YN 9590J / OD / CHINA

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **YN9590J (Excess \$550/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

YN9590J (SNM18D02966C01)

OD

Jun 12 2018 10:00AM

[XINGFU TRADING PTE LTD]

Cheng Hoe Motor Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on **21/06/2018 17:09 PM.**

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$5028.00) - YN9590J - Claim Handler: Jowyn Tay

Approved:5028.00.

DOCUMENTS SUMMARY

There are no documents.

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	6085W
Vehicle Details	
Vehicle No.:	YN9590J
Vehicle to be Exported:	No
Intended De-registration Date:	13 Jun 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	CANTER FEB21ER3SDEB
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	4P10B76386
Chassis No.:	FEB21EA10364
Maximum Power Output:	-
Open Market Value:	\$28,868.00
Original Registration Date:	06 Oct 2015
First Registration Date:	06 Oct 2015
Transfer Count:	0
Actual ARF Paid:	\$1,444.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	05 Oct 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$5,138.00
COE Rebate Amount:	\$3,756.00
Total Rebate Amount:	\$3,756.00

The information contained herein is correct as at 13 Jun 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/06/2018 09:45
Date Of Accident	12/06/2018 10:20
Exact Location Of Accident	JUNCTION OF CHIN SWEE RD & OUTRAM RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YN9590J
Insured/Policyholder	
Name Of Registered Owner	XINGFU TRADING PTE LTD
Co Reg No	199006085W
Email Address	XINGFU@SINGNET.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-67559257

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	CANTER FEB21ER3SDEB
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN1544961702
Cover Note Number	06/10/17 - 05/10/18

Driver

Name of Driver	KOO CHUAN HENG
NRIC No	S1557519J
Date Of Birth	24/04/1962
Occupation	INDOOR
Date Of Driving Pass	28/11/1979
Driving Experience	38 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96331127
Fax Number	
Contact Number	
Email Address	XINGFU@SINGNET.COM.SG

Address 1 SENGKANG EAST AVE #16-02
 Postcode 544811
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : WORKER
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

Upon reaching the above junction, traffic was green and car B made a U-turn where he made an abrupt e-brake. I was proceeding straight that I could not react in time and collided onto the rear left of car B. While checking with the said driver on why he made e-brake, he claimed that he noticed vehicle moving at his right side junction that caused him to react by e-brake.


Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SH8215C
 Vehicle Make/Model/Colour BLUE COMFORT TAXI
 Details Of Properties
 Vehicle Category TAXI
 Name of Driver SELVARAJ S/O RAMU
 NRIC/Passport Number S1377625C
 Contact Number 82356286
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Upon reaching the above junction, traffic was green and car B made a U-turn where he made an abrupt e-brake. I was proceeding straight that I could not react in time and collided onto the rear left of car B. While checking with the said driver on why he made ebrake, he claimed that he noticed vehicle moving at his right side junction that caused him to react by ebrake.

Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: (YS)
NRIC/FIN No.:

SKETCH PLAN


VEHICLE NO.: YN 9590J
 INSURER : China Taiping
 DATE & TIME: 12/6/18 @ 10:20am

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: 1951
NRIC/FIN No.: 13/6/18

**CHENG HOE MOTOR PTE LTD**

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

INSURER: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD-CHINA
Policy No:	DMCVSN1544961702	Date of Loss:	12/06/2018
Vehicle Reg. No.:	YN9590J	Driveable?	
Driver Age/Info:	56 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	XINGFU TRADING PTE LTD		
Driver:	KOO CHUAN HENG		
Make/Model:	mitsubishi canter, 3.0 D FEB21ER3SDEB (M)	Vehicle Reg. Date:	06/10/2015
Vehicle Colour:	WHITE		
Engine No:	4P10B76386	Chassis No:	FEB21EA1034
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	0 <i>5 days</i>		
Present Location:	CHENG HOE MOTOR PTE LTD (YISHUN)		

CL 15154

Not Authorised
1-B1
Survey by person
Ex B 5501

COST OF CLAIMS

	Amount
Parts	3,908.00
Miscellaneous Items	0.00
Labour	1,660.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	5,568.00
+ GST 7.00% (\$\$)	389.76
Nett Amount (\$\$)	5,957.76

This claim is handled by: **NG CHENG CHOO**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS

YN9590J

Reference

ED/C.HINA

Part Source: (Last Synchronised: 18 Jun 2018)

Parts: N/A MITSUBISHI CANTER 3.0 D FEB21ER3SDEB (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Cheng Hoe Motor Pte Ltd/YN9590J/18/06/2018 14:02

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT BUMPER	0.00	0.00	*550.00 F	7 ✓
2	1		*FRONT BUMPER RH PAD	0.00	0.00	*180.00 F	✓
3	1		*FRONT BUMPER RH BRACKET	0.00	0.00	*120.00 F	XX
4	1		*RH HEAD LAMP	0.00	0.00	*330.00 F	✓
5	1		*RH SIGNAL LAMP	0.00	0.00	*165.00 F	✓
6	1		*RH SIDE LAMP	0.00	0.00	*110.00 F	✓
7	1		*FRONT RH DOOR	0.00	0.00	*1,050.00 F	✓
8	1		*FRONT RH STEP TRAY	0.00	0.00	*340.00 F	✓
9	1		*FRONT GRILLE	0.00	0.00	*540.00 F	7X
10	1		*FRONT RH DOOR STICKER DUONIC	0.00	0.00	*48.00 F	7 ✓
11	1		*FRONT RH DOOR AIR-SCROP GRILLE	0.00	0.00	*30.00 F	✓
12	1		*FRONT RH DOOR LOWER RUBBER	0.00	0.00	*50.00 F	✓
13	1		*FRONT RH DOOR LOWER HINGES	0.00	0.00	*90.00 F	7
14	1		*FRONT RH DOOR INNER LOCK	0.00	0.00	*190.00 F	7
15	1		*FRONT RH DOOR INNER AIR-SCROP GRILLE	0.00	0.00	*30.00 F	X
16	1		*RH HEAD LAMP LOWER RUBBER	0.00	0.00	*15.00 F	✓
17	1		*FRONT RH WHEEL ARP GARNISH	0.00	0.00	*70.00 F	X

F=Franchise part.

Total Parts (\$\$) 3,908.00

Cheng Hoe Motor Pte Ltd/YN9590J/18/06/2018 14:02. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	REMOVE AND REFIX FRONT BUMPER ASSY, HEAD LAMPS AND SIDE LAMP, GRILLE, FRONT LH DOOR AND TRANSFER DOOR, ATTACHMENT. TO STRAIGHTEN. KNOCK AND REPAIR FRONT RH WINDSCREEN PILLAR, FRONT RH WHEEL ARP PANEL AND REAILGN THE SAME	New	800.00
2	PUTTY AND RESPRAY ON FRONT BUMPER, FRONT GRILLE, FRONT RH DOOR, FRONT RH WINDSCREEN PILLAR, FRONT RH CORNAL PANEL, PILLAR AND ALL AFFECTED AREA	New	800.00
3	REMOVE AND REFIX FRONT RH DOOR GLASS	New	60.00
Gross Labour Cost (\$\$)			1,660.00

Cheng Hoe Motor Pte Ltd/YN9590J/18/06/2018 14:02. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Attn: Kenneth

YN9590J

01/CHINA

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 18 Jun 2018)
 Parts: N/A MITSUBISHI CANTER 3.0 D FEB21ER3SDEB (M) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Cheng Hoe Motor Pte Ltd/YN9590J/18/06/2018 14:02
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT BUMPER	0.00	0.00	*550.00 F	7✓
2	1		*FRONT BUMPER RH PAD	0.00	0.00	*180.00 F	✓
3	1		*FRONT BUMPER RH BRACKET	0.00	0.00	*120.00 F	X X
4	1		*RH HEAD LAMP	0.00	0.00	*330.00 F	✓
5	1		*RH SIGNAL LAMP	0.00	0.00	*165.00 F	✓
6	1		*RH SIDE LAMP	0.00	0.00	*110.00 F	✓
7	1		*FRONT RH DOOR	0.00	0.00	*1,050.00 F	✓
8	1		*FRONT RH STEP TRAY	0.00	0.00	*340.00 F	✓
9	1		*FRONT GRILLE	0.00	0.00	*540.00 F	X X
10	1		*FRONT RH DOOR STICKER DUONIC	0.00	0.00	*48.00 F	✓
11	1		*FRONT RH DOOR AIR-SCROP GRILLE	0.00	0.00	*30.00 F	✓
12	1		*FRONT RH DOOR LOWER RUBBER	0.00	0.00	*50.00 F	✓
13	1		*FRONT RH DOOR LOWER HINGES	0.00	0.00	*90.00 F	7 X
14	1		*FRONT RH DOOR INNER LOCK	0.00	0.00	*190.00 F	7 ✓
15	1		*FRONT RH DOOR INNER AIR-SCROP GRILLE	0.00	0.00	*30.00 F	X ✓
16	1		*RH HEAD LAMP LOWER RUBBER	0.00	0.00	*15.00 F	✓
17	1		*FRONT RH WHEEL ARP GARNISH	0.00	0.00	*70.00 F	X

F=Franchise part.

Total Parts (\$\$) 3,908.00

Cheng Hoe Motor Pte Ltd/YN9590J/18/06/2018 14:02. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Parts #3008
 Labour #1340
 #4348

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	REMOVE AND REFIX FRONT BUMPER ASSY, HEAD LAMPS AND SIDE LAMP, GRILLE, FRONT LH DOOR AND TRANSFER DOOR, ATTACHMENT. TO STRAIGHTEN. KNOCK AND REPAIR FRONT RH WINDSCREEN PILLAR, FRONT RH WHEEL ARP PANEL AND REAILGN THE SAME	New	800.00
2	PUTTY AND RESPRAY ON FRONT BUMPER, FRONT GRILLE, FRONT RH DOOR, FRONT RH WINDSCREEN PILLAR, FRONT RH CORNAL PANEL, PILLAR AND ALL AFFECTED AREA	New	800.00
3	REMOVE AND REFIX FRONT RH DOOR GLASS	New	60.00
Gross Labour Cost (\$\$)			1,660.00

Cheng Hoe Motor Pte Ltd/YN9590J/18/06/2018 14:02. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >



明義汽車私人有限公司
MIN GHEE AUTO PTE LTD

TAX INVOICE

8, Jalan Lembah Kallang, #01-01 Min Ghee Building Singapore 339564
Main Tel: 6298 3888 Fax: 6291 2172, 6294 1450 Accounts Tel: 6291 6118 Accounts Fax: 6297 0863
Email: info@minghee.com (Main), account@minghee.com (Accounts)
Website: http://www.minghee.com

GST REG. NO.: M2-0090482-6 CO REG. NO.: 198905613E

ACCOUNT NUMBER : CHEONGH2 TIME:14:14

CHENG HOE MOTOR PTE LTD
BLK 1019, YISHUN INDUSTRIAL
PARK 1, #01-374/382,
SINGAPORE 768761
768761
Telephone No : 67556142

ROUTE

DELIVER TO :

CHENG HOE MOTOR PTE LTD
CHENG HOE WOODLAND IND PARK E1
#05-04
YN 9590T FEB21



INVOICE NO.

8113426

DATE	06/07/2018	PAGE	1
TERM	30 Days Net	SALESMAN	Lau Gee Chai
CUSTOMER REF.		OUR REF.	24762

PART NO.	PARTICULARS	LOC	QUANTITY	UNIT PRICE	AMOUNT
1 MIMC978516	BUMPER FRT	4E-1DD	1 PC	550.00	550.00
2 MIMKS80552	HEAD LAMP ASSY-RH	2F-06D	1 PC	330.00	330.00
3 MIMKS80528	LAMP, FRT SIGNAL RH	1H-1AA	1 PC	165.00	165.00
4 MIMKS80530	LAMP, H/LAMP SIDE RH	1F-03J	1 PC	110.00	110.00
5 MIMKS676949	SIDE STEP, FR RH	1F-05I	1 PC	340.00	340.00
6 MIMKS80695	BEZEL H/ LAMP LWR L/R	1G-10K	1 PC	15.00	15.00

GOODS RECEIVED IN GOOD ORDER
AND CONDITION.

*GOODS SOLD ARE NOT RETURNABLE.
*OVERDUE ACCOUNTS SHALL BEAR INTEREST AT UOB'S
PREVAILING LENDING RATE
*CASH INVOICE MUST BE PAID WITHIN 7 DAYS
FROM DATE OF INVOICE.

Exclusive Distributor

HDK

Stockists

Payment via telegraphic transfer to
Name of Bank: United Overseas Bank
Account Name: Min Ghee Auto Pte Ltd
Branch Code: 046
Account No.: 503-309-511-3
Please send a screen shot of your payment/
transfer confirmation to
account@minghee.com

TOTAL	SIN	1,510.00
ADD GST	7%	105.70
AMOUNT DUE	SIN	1,615.70

SIGN & COMPANY'S STAMP

DATE

ALL CHEQUES MUST BE MADE PAYABLE TO
MIN GHEE AUTO PTE. LTD.

MOTOWA

BMW

HONDA TOYOTA MITSUBISHI



biSAFE

For MIN GHEE AUTO PTE. LTD.



日美汽車私人有限公司 JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9939



Dept Direct: 6305 9010

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794



Dept Direct: 6417 9795



Dept Direct: 6417 9796



Dept Direct: 6417 9797

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

CHENG HOE MOTOR PTE LTD
38 WOODLAND INDS PKS E1
#05-04

SINGAPORE
TEL : 67656142 FAX : 67692687
ATTN : GUAN 91834720

TAX INVOICE : AR201807-02025
DATE : 04/07/2018
CUSTOMER ID : CHE002
VEH REG. NO. : YN9590T
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : SGD

SO STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. MK618527 (ROC)	FR BUMPER COVER RH(004-002-MBP-OR)	PA	1	180.00	180.00
2. MK997202	FR DOOR RH	PL2-N1-05B PA	1	1050.00	1,050.00
3. MK487814	FR DOOR AIR VENT GARNISH	PL3-L1-060 PA	1	30.00	30.00
4. MK676978	MARK,DUONIC RH	PL3-P1-04A PA	1	48.00	48.00
5. MK434982	FR DOOR INR LOCK RH	PL3-N1-02F PA	1	190.00	190.00
		PL3-P1-03B			

SUB-TOTAL : 1,498.00
ADD GST 7.00 % 104.86

E. & O.E

TOTAL AMOUNT SGD : 1,602.86

[P] 04/07/2018 12:40:10PM

[E] 04/07/2018 12:35:44PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: EDWARD

This is computer generated document.
No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Jun 2018 Sendback Est	18 Jun 2018 14:02 \$5,568.00	19 Jun 2018 09:50 Edit Adj Rpt	\$4,348.00 Edit Estimates	\$4,348.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: XINGFU TRADING PTE LTD , Co. Reg. No.: 199006085W									
Vehicle Reg. No.: YN9590J		Date of Loss: 12/06/2018 10:00 - :59 [32 Months and 6 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / SNM18D02966C01		Policy/Cover Note No.: DMCVSN1544961702 (Comprehensive) Coverage: 06/10/2017 -							
		Excess: \$550.00							
Repairer: Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 28/06/2018]									
Driver/Custodian: KOO CHUAN HENG (56 / Male), NRIC: S15575193									
Adj Asg. Remarks: PLEASE PROCEED TO SURVEY & REVERT. EXCESS OF \$550.00 APPLIES.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• CHINA_TAIPING (21/06/2018): Alert - Adj Mandate Approved (\$5028.00) - YN9590J - Claim Handler: Jowyn Tay									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

YN9590J (SNM18D02966C01)
OD
Jun 12 2018 10:00AM
[XINGFU TRADING PTE LTD]
Cheng Hoe Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		Thumbnail Print
1	18/06/18 14:02	Repairer Estimates		Load HTM
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	20/06/18 14:22	Adjuster Immediate Advice		Load HTM
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	20/06/18 12:05	General View		Load PDF
2	28/01/19 11:05	Reinspection Photo		Load PDF
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		Thumbnail Print
1	18/06/18 13:49	E-filed GIA report		Load PDF
2	18/06/18 13:49	DRIVER NRIC/DRIVING LICENCE		Load JPG <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	20/06/18 12:13	ESTIMATE		Load PDF
2	28/01/19 15:35	Parts Invoice		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI18011058/KTD3E2

Date: 28/01/2019

REFERENCE

Insured/Claimant: XINGFU TRADING PTE LTD Policy No: DMCVSN1544961702
Date of Loss: 12/06/2018 Nature of Claim: OD Claim No: SNM18D02966C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **YN9590J**
Make & Model: MITSUBISHI CANTER, 3.0 D FEB21ER3SDEB (M) Engine No: 4P10B76386
Reg. Date: 06/10/2015 (Man. Year: 2015) Chassis No: FEB21EA10364
Colour: White Odometer: 47851 km
Engine Capacity: 2998 cc
Market Value/New Car Price: S\$64,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/85 R15 Rear Tyre Size: 195/85 R15 (D)
Front Left Side: Bridgestone 3 mm Rear Left Side: Bridgestone 4/4 mm
Front Right Side: Bridgestone 3 mm Rear Right Side: Bridgestone 4/4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,908.00	3,008.00	900.00	23.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,660.00	1,340.00	320.00	19.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,568.00	4,348.00	1,220.00	21.91
- Excess (S\$)	0.00	550.00	-550.00	
(S\$)	5,568.00	3,798.00	1,770.00	31.79
+ GST 7.00/7.00% (S\$)	389.76	265.86	123.90	31.79
Nett Amount (S\$)	5,957.76	4,063.86	1,893.90	31.79

INSPECTION

Date of Assignment: 19/06/2018 Present Location: Cheng Hoe Motor Pte Ltd (Yishun)
Date Inspected: 19/06/2018 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun Industrial Park A
Singapore 768761

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 28 Jan 2019)	
Parts:	N/A	MITSUBISHI CANTER 3.0 D FEB21ER3SDEB (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YN9590J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	550.00 F	*550.00 F
2	1		*FRONT BUMPER RH PAD	Buckled	180.00 F	*180.00 F
3	1		*FRONT BUMPER RH BRACKET	Repair	120.00 F	*- F
4	1		*RH HEAD LAMP	Broken	330.00 F	*330.00 F
5	1		*RH SIGNAL LAMP	Broken	165.00 F	*165.00 F
6	1		*RH SIDE LAMP	Broken	110.00 F	*110.00 F
7	1		*FRONT RH DOOR	Buckled	1,050.00 F	*1,050.00 F
8	1		*FRONT RH STEP TRAY	Dented / Cut	340.00 F	*340.00 F
9	1		*FRONT GRILLE	Serviceable	540.00 F	*- F
10	1		*FRONT RH DOOR STICKER DUONIC	Necessary	48.00 F	*48.00 F
11	1		*FRONT RH DOOR AIR-SCROP GRILLE	Distorted	30.00 F	*30.00 F
12	1		*FRONT RH DOOR LOWER RUBBER	Serviceable	50.00 F	*- F
13	1		*FRONT RH DOOR LOWER HINGES	Repair	90.00 F	*- F
14	1		*FRONT RH DOOR INNER LOCK	Dented	190.00 F	*190.00 F
15	1		*FRONT RH DOOR INNER AIR-SCROP GRILLE	Repeated	30.00 F	*- F
16	1		*RH HEAD LAMP LOWER RUBBER	Torn	15.00 F	*15.00 F
17	1		*FRONT RH WHEEL ARP GARNISH	Serviceable	70.00 F	*- F
Total Parts (S\$)					3,908.00	3,008.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE AND REFIX FRONT BUMPER ASSY, HEAD LAMPS AND SIDE LAMP, GRILLE, FRONT LH DOOR AND TRANSFER DOOR, ATTACHMENT. TO STRAIGHTEN. KNOCK AND REPAIR FRONT RH WINDSCREEN PILLAR, FRONT RH WHEEL ARP PANEL AND REAILGN THE SAME	New	800.00	600.00
2	PUTTY AND RESPRAY ON FRONT BUMPER, FRONT GRILLE, FRONT RH DOOR, FRONT RH WINDSCREEN PILLAR, FRONT RH CORNAL PANEL, PILLAR AND ALL AFFECTED AREA	New	800.00	680.00
3	REMOVE AND REFIX FRONT RH DOOR GLASS	New	60.00	60.00
Gross Labour Cost (\$\$)			1,660.00	1,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >