

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

90 survey by CLKK 1

VEHICLE NO : SHC 2855B

DATE : 14.06.2018

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI SONATA

FAX : 6542 6039

ECICS

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Bonnet <i>Dented</i>			\$ 1,151.80	✓
	Bonnet Moulding <i>cut</i>			\$ 120.90	✓
	Bonnet Lock <i>bt</i>			\$ 48.80	✓
	Radiator Grille <i>broken</i>			\$ 282.10	✓
	Radiator Grille U Moulding <i>broken</i>			\$ 108.90	✓
	Front Bumper Cover <i>Dented</i>			\$ 538.80	✓
	Front Bumper Sponge <i>to r</i>			\$ 136.30	✓
	Front Bumper Reinforcement <i>bt</i>			\$ 504.10	✓
	Front Bumper Centre Grille <i>SLC</i>			\$ 131.10	X
	Front Bumper Bracket Top (LH/RH) <i>SLC</i>	\$	22.40	\$ 44.80	X
	Front Bumper Protector (LH/RH) <i>rep</i>	\$	29.20	\$ 58.40	X
	Front Bumper Bracket (LH/RH) <i>SLC</i>	\$	20.10	\$ 40.20	X
	Front Bumper Side Bracket <i>SLC</i>	\$	14.30	\$ 28.60	X
	Headlamp Support Panel Assy <i>Dented</i>			\$ 1,023.00	✓
	Headlamp (LH/RH) <i>broken</i>	\$	797.90	\$ 1,595.80	✓
	Radiator <i>bt</i>			\$ 814.80	✓
	Radiator Fan Blade, Cowling, Motor Assy <i>crack</i>			\$ 651.30	✓
	Radiator Bracket <i>SLC</i>	\$	6.20	\$ 12.40	X
	Aircon Condenser <i>bt</i>			\$ 1,089.90	✓
	Inter Cooler <i>bt</i>			\$ 771.50	✓
	Inter Cooler Mounting (2 PCS) <i>HW</i>			\$ 24.80	X
	Wiring-ECM <i>crack</i>			\$ 3,107.80	✓
	SUB TOTAL			\$ 12,286.10	
	LESS 20%			\$ 2,457.22	
	DISCOUNTED TOTAL			\$ 9,828.88	
	Front Number Plate <i>crack</i>			\$ 25.00	Nett ✓
	Front No Plate Trim Cover <i>bt</i>			\$ 30.00	Nett ✓
				20.00	
				\$ 55.00	
	Labour Charge				
	Panel Beating			\$ 1,000.00	500/-
	Spray Painting Charge			\$ 1,000.00	400/-
	Wiring Charge			\$ 50.00	30/-
	Tuff Kote			\$ 100.00	30/-
	Towing Charge			\$ 50.00	HW
	Remove/Refix Aircon & Refill Gas			\$ 150.00	80/-
	Remove/Refix Dashboard			\$ 450.00	180/-
	Remove/Refix Fuse Box			\$ 180.00	HW
	TOTAL LABOUR			\$ 2,980.00	

SHC 2855B

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid <i>huc</i>			\$ 1,349.50	✓
	Boot Lid Rubber <i>deformed</i>			\$ 110.90	✓
	Boot Lid Hinge (LH/RH) <i>regr</i>	\$	170.60	\$ 341.20	✗
	Boot Lid Lock Upper <i>✗ hst</i>			\$ 132.10	✓
	Boot Lid Lock Lower <i>✗ hst</i>			\$ 30.30	✓
	Boot Lid Key Lock <i>svc</i>			\$ 78.20	✗
	Boot Lid Sonata Plate <i>huc</i>			\$ 43.60	✓
	Boot Lid Hyundai Plate <i>huc</i>			\$ 24.20	✓
	Boot Lid 'H' Emblem <i>huc</i>			\$ 26.10	✓
	Boot Lid CRDI Plate <i>huc</i>			\$ 22.70	✓
	Boot Lid Lamp (LH/RH) <i>broken</i>	\$	230.20	\$ 460.40	✓
	Licence Lamp (LH/RH) <i>svc</i>	\$	32.50	\$ 65.00	✗
	Boot Lid Trimboard <i>✗ torn</i>			\$ 165.40	✓
	Boot Lid Trimboard Clips (11pcs) <i>✗ huc</i>			\$ 11.00	✓
	Rear Bumper <i>broken</i>			\$ 578.40	✓
	Rear Bumper Reinforcement <i>✗ huc</i>			\$ 483.30	✓
	Rear Bumper Clip <i>huc</i>			\$ 22.00	✓
	Rear Bumper Bracket <i>svc</i>	\$	49.00	\$ 98.00	✗
	Rear Bumper Sponge <i>✗ torn</i>			\$ 137.40	✓
	Rear Bumper Under Cover <i>torn</i>			\$ 185.80	✓
	Rear Bumper Protector (LH/RH) <i>hst</i>	\$	38.00	\$ 76.00	✓
	Tail Lamp (LH/RH) <i>dislodged</i>	\$	344.00	\$ 688.00	✓
	Tail Lamp Quarter Panel (LH/RH) <i>✗ Dent</i>	\$	93.80	\$ 187.60	✓
	Rear Panel <i>✗ huc</i>			\$ 391.80	✓
	Rear Panel Garnish <i>✗ deformed</i>			\$ 95.80	✓
	Spare Tyre Holder <i>huc</i>			\$ 27.60	✗
	Tail Lamp Panel Top (LH/RH) <i>✗ Dent</i>	\$	217.40	\$ 434.80	✓
	Spare Tyre Panel <i>✗ huc</i>			\$ 863.00	✓
	Spare Tyre Panel Cushion <i>huc</i>			\$ 200.30	✗
	Rear Towing Hook <i>huc</i>			\$ 135.30	✗
	Member Assy- Rear Floor Centre <i>huc</i>			\$ 163.60	✗
	Panel Assy-Rear Floor Side (LH/RH) <i>huc</i>	\$	88.55	\$ 177.10	✗
	Extension Assy-Rear Floor <i>huc</i>			\$ 172.00	✗
	Rear Floor Chassis Member <i>huc</i>			\$ 1,280.50	✗
	Exhaust Pipe Insulator <i>✗ svc</i>			\$ 56.10	✗
	Exhaust Silencer <i>✗ svc</i>			\$ 723.00	✗
	Exhaust Pipe Hanger <i>svc</i>			\$ 56.10	✗
	Rear Fender (LH/RH) <i>huc</i>	\$	1,935.90	\$ 3,871.80	✓
	Rear Fender Inner Panel (LH/RH) <i>regr</i>	\$	1,255.00	\$ 2,510.00	✗
	Rear Fender Inner Lining (LH/RH) <i>huc</i>	\$	74.10	\$ 148.20	✗
	Rear Fender Corner Hardboard Cover (LH) <i>✗ deformed</i>			\$ 204.30	✓
	Rear Tray Lugg Side (RH) <i>✗ deformed</i>			\$ 37.40	✓
	Rear Fender Air-Duct <i>✗ svc</i>			\$ 49.40	✗
	Rear Fender Trim Board (LH/RH) <i>✗ hst</i>	\$	180.90	\$ 361.80	✓
	Rear Windscreen Moulding <i>huc</i>			\$ 60.00	✓
	Rear Wiring Assy <i>huc</i>			\$ 1,458.00	✗
	Fire Extinguisher Holder <i>huc</i>			\$ 35.00	✗
	SUB TOTAL			\$ 18,830.00	
	LESS 20%			\$ 3,766.00	
	DISCOUNTED TOTAL			\$ 15,064.00	

SHC 2855B

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid Comfort Logo & Tel No. Sticker <i>HL</i>			\$ 30.00	Nett ✓
	Rear No. Plate <i>dislodged</i>			\$ 25.00	Nett ✓
	Rear Bumper Rubber Mat <i>dyed</i>			\$ 50.00	Nett ✓
	Rear Windscreen Sealant <i>HL</i>			\$ 46.00	Nett ✓
				\$ 151.00	
	Labour Charge				
	Panel Beating			\$ 2,800.00	1200/-
	Spray Painting Charge			\$ 2,000.00	800/-
	Wiring Charge			\$ 100.00	30/-
	Tuff Kote			\$ 150.00	40/-
	Rear Chassis Alignment Charge			\$ 400.00	Nil
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00	80/-
	Remove/Refix Rear Windscreen Glass			\$ 120.00	80/-
	Remove/Refix Fuel Tank			\$ 150.00	Nil
	Remove/Refix Exhaust Pipe			\$ 150.00	60/-
	TOTAL LABOUR			\$ 6,020.00	
	ESTIMATE TOTAL			\$ 34,098.88	
18/06/18 @ 12:00pm Not Actual L/S on 12 days Ryan LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					