

Attn: Heng

6296 0725.

Cost Price.



Ethicarz Pte. Ltd. 56 Loyang Way, Singapore (508775) #04-04

Loyang Enterprise Building, Email: johnong@ethicarz.sg

Tel: 63844404, FAX: 63840444

VEHICLE NUM:

MBM7512

MAKE & MODEL:

HINO

MILEAGE:

TYRE:

CHASSIS NUM:

XZU423R-HKMMB3

ATTN:		
QTY	DESCRIPTION - PARTS	PRICE
1	TAILGATE (UPPER)	1100.00
4	TAILGATE HINGE 20 x 4	80.00
4	TAILGATE LOCK 25 x 4	100.00
1	TAILGATE	900.00
4	TAILGATE HINGE	80.00
1	TAILGATE HINGE BRACKET	45.00
2	TAILGATE LOCK (L+R)	120.00
1	TAILGATE STEP BAR	S/N
2	TAIL LIGHTS 280 x 2	560.00
2	TAIL LIGHTS BRACKET 120 x 2	240.00
1	FLOOR PANEL	180.00
1	NUMBER PLATE BRACKET	60.00
2	NUMBER PLATE LAMP LH+RH 30 x 2	60.00
1	CHASSIS MEMBER	300.00
6	CHASSIS MEMBER U-BOLT 25 x 6	150.00
1	REAR AXLE	3650.00
2	PROF SHAFT 960 x 2	1920.00
2	PROF SHAFT MOUNTING 90 x 2	180.00
1	ENGINE MOUNTING	120.00
1	FRONT BUMPER	640.00
1	FRONT BUMPER REINFORCEMENT	230.00
2	FRONT BUMPER FOG LAMP LH+RH 158 x 2	316.00
2	HEADLAMP LH+RH 200 x 2	640.00
2	HEADLAMP SEAL LH+RH 10 x 2	20.00
8	HEADLAMP SEAL CLIPS 10 x 8	80.00
1	FRONT GRILLE	360.00
1	FRONT GRILLE LOGO	90.00
1	FRONT PANEL	480.00
2	FRONT SIDE PANEL LH+RH 150 x 2	300.00

1	AIR FILTER HOUSING ASSY OUTER	560.00
1	AIR FILTER HOUSING ASSY INNER	280.00
1	AIR DUCT INTAKE UPPER	75.00
1	AIR DUCT INTAKE LOWER	75.00
1	CABIN LOCK ASSY	90.00
1	CABIN BRACKET	60.00
1	FRONT MUDFLAP LH	25.00
1	CABIN RELEASE BRACKET	30.00
1	WHEEL ARCH LH	160.00
QTY	DESCRIPTION - SPECIAL NETT	PRICE
1	TAILGATE LOWER STICKER (70/80 KMJ)	50
1	TAILGATE LOWER STICKER (REFLECTOR)	100
1	REAR CARPLATE	80
2	FRONT CARPLATE	80
2	REAR CARPLATE BRACKET	200
1	REVERSE BUZZER SIREN	400
1	REAR STEPBAR	1500
		2410.00
QTY	DESCRIPTION - LABOUR	PRICE
1	TO RNR ACCIDENT AFFECTED AREA	3000
1	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	2500
1	TO RUST PROOF ACCIDENT AFFECTED AREA	300
1	TO RNR ENGINE ASSY	2500
1	TO RNR UNDERCARRIAGE ASSY	2500
1	TO RNR PROF SHAFT	1200
1	TO RNR RADIATOR AIR CON ASSY AND REFILL GAS	200
1	TO CHECK CHASSIS ALIGNMENT	1500
1	TO RNR REAR CABIN	6000
1	TO CHECK WIRING AND HEADLAMP FOCUS FUNCTION	150
1	TO CHECK WIRING AND TAILLAMP FUNCTION	150
1	TO CHECK WIRING AND REVERSE SIREN FUNCTION	150
1	TO CHECK WATER SEEPAGE	150
1	TO RNR REAR CABIN COMPARTMENT	200
1	TO RNR TAILGATE MECHINISM	120
		206
		total:

LKK Auto Consultants hence notify the Repairer of the following:

- * To resurvey before/after spray painting
- * To display damaged part(s) during resurvey
- * Parts prices are subject to confirmation
- * Third party survey is on a "Without Prejudice" basis
- * No illegal modification(s) is allowed
- * Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Without Prejudice.
W: Jan, LKK
23/2/2018
** To Dovent Backs For Consistency*