

7/03/2018

ASS. REC. BY:

REF:

CS3/AIG18011068/U24d357

Special Instruction:

Supervisor:

Marcus

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

AIG

Date/Time: 19/6/18 @ 10:02am

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGX 7513 G

Insured:

SLL 8102

at Workshop m/s

G speed Autowerkz

Tel:

8533 2934

of

68 Kaki Bkt Ave 6 # 02-05

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A. 14/06/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

1up

H.O.D. Endorsement:

Date/Time:

11:25am @ 19/6/18

Person Contacted:

sun sun

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate	
	SGX 7513 G - NAICTI18010944/K4	DOA: 14/06/2018
	SLL 8102 - NAICTI18010944/K4	DOA: 14/06/2018
20/6/18	Dismantled.	DAR?
26/6/18	After Repair	

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGX75136at Workshop in/s 6 speedof Nov 05

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 31k.

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: 2 Consistent? : Yes or NoEst. Repairs: 7 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTA 21402

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SGX75136 Yr Regn: 9 07Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: Toyota wish C.C. 1794Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 132486 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 2NE 100370487Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

6

Rear

6

R/Bal. _____ mm

R/Bal. _____ mm

L/Bal. _____ mm

L/Bal. _____ mm

D.O.A. 14/6/18D.O.A. 19/6/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision:

Date / Time Action / Instruction

No settlement. car until 31/8/2022 4 yrs 2mth. Net 1598

320/7/18 Submit DAR report

RECEIVED 23 JUL 2018

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / I.B.I. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG18011068/Uz4d3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 19-06-2018



Code : AIG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLL 810Z	Veh. Inspected	SGX 7513G
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CHIN LEE YING	Assign Date	19/06/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	14/06/2018	Inspection Date	19/06/2018
Survey held at	-		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

**- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE
SLL810Z AND SGX7513G ON 14/06/2018**

From: Chin, Lee-Ying
To: assignments@lkkauto.com, Admin A
Cc: Fong, Andy-SY
Sent: 19/6/2018 10:02:24 AM
Attachments:  SLL810Z--PRI.TIF  surveyor list.jpg

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards
Lee Ying, Chin
AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

CATHERINE LIM LLC

林 律師
ADVOCATES & SOLICITORS
林 律師
NOTARY PUBLIC - 公証官
林 律師
COMMISSIONER FOR OATHS - 宣誓官

林 律師
CATHERINE C. LIM
林 律師
DIRECTOR

林 律師
LL.B (HONS) SINGAPORE-法律系-律師
M.B.A. (BUSINESS LAW)-商業系-碩士

20 Havelock Road #03-01
Central Square Singapore 050765
UEN No. 201310922K

Tel: (65) 6438 5500
Fax: (65) 6438 0111
www.catherinelimllc.com
Email: info@catherinelimllc.com
CATHERINE LIM LLC is a law corporation
with limited liability

Your Ref: SLL 810Z
Our Ref: CL/180635/1/SAW.nk

18 June 2018

AIG Asia Pacific Insurance Pte Ltd
AIG Building
78 Shenton Way
#07-16

Singapore 079120
Attn: Motor Claims Department

Lim Thye Hoe
125 Meyer Road
#01-02
Singapore 437936

Dear Sir

via fax: 6415 3727 & By Hand

CERTIFICATE OF POSTING
(Please be informed that all supporting documents
have been forwarded to your insurer.)

**RE: NOTICE TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO
PRE-ACTION PROTOCOL FOR NON-INJURY MOTOR ACCIDENT CLAIMS (NIMA)
ACCIDENT INVOLVING SGX 7513G / SLL 810Z ON 14.06.2018 ALONG BRADDELL ROAD TOWARDS
CTE AMK**

We are instructed by NOR SYABARIYAH BTE SAIRI to notify you of a road traffic accident involving our
client's vehicle No. SGX 7513G and vehicle No. SLL 810Z driven by you at the material time. A copy of the
Singapore Accident Statement and/or Police Report is enclosed.

As a result of the accident, our client's motor vehicle has been damaged. Before our client proceed to repair the
damaged motor vehicle, please let us know within 2 working days of your receipt of this notice whether you your
insurer would like to conduct a pre-repair survey of the motor vehicle. If we do not receive any reply from you your
insurer within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please let us know your appointed surveyor.

Company Name: 6 Speed Autoworks Pte Ltd

Location: 68 Kaki Bukit Ave 6 #02-05 ARK@KB (S) 417896

Contact person: Sun Sun (8533 2934)

Yours faithfully,


cc: clients

TO WHOM IT MAY CONCERN

NAME OF MOTOR SURVEYOR

- 1 CHANG FUH KEONG, DAVE
- 2 HO JOO LOONG, DANNY
- 3 HOW ANDREW
- 4 LEE KOK WENG
- 5 LIM YONG TIAN, SEBASTIAN
- 6 ONG AH KENG, KENT
- 7 ONG POH MENG, AMAS
- 8 PHILIP FOO
- 9 TEO HOON TONG, KELVIN
- 10 THOR TECK SOON, DAVID

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/06/2018 13:51
Date Of Accident	14/06/2018 21:25
Exact Location Of Accident	BRADDELL RD TWDS CTE AMK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGX7513G
Insured/Policyholder	
Name Of Registered Owner	MDM NOR SYABARIYAH BTE SAIRI
NRIC No	S7810077Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91874892
Alternative Phone No	OTHERS-91874892

Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH 1.8 A
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3061001700
Cover Note Number	

Driver

Name of Driver	SUHAIMIY B ABDUL JALIL A M D
NRIC No	S1805355A
Date Of Birth	04/03/1967
Occupation	INDOOR
Date Of Driving Pass	27/06/1996
Driving Experience	21 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91874892
Fax Number	
Contact Number	OTHERS-91874892
Email Address	NOEMAIL

Address	BLK 712 TAMPINES STREET 71 #03-156
Postcode	520712
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TAMPINES NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 6 TAMPINES AVE 4 , POSTCODE: 529682 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-5871999 - FAX NO: 65871699
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE POLICE REPORT : T/20180616/2029

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLL810Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LOUIS
NRIC/Passport Number	
Contact Number	93877087
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1


Name	SUHAIMIY B ABDUL JALIL A M D
Approximate Age	
Injuries Sustain	SLIGHT
Injured person in which vehicle?	SGX7513G
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	

Sketch Plan #2

SKETCH PLAN

A SGV 7513G

B SLL 810Z



Braddell Rd
towards CTE AMK

RECORD CIRCUMSTANCES OF THE ACCIDENT

AS per Police
Report
T/20180616/2029

CIRCUMSTANCES

Other details, including photographs and sketches, may be added.

Date & Time

x R/R

Officer's Name (Print Name)

Rank

Signature

Officer's Name (Print Name)

Rank

Signature

18/6/2018

Sketch Plan #3



SINGAPORE
POLICE FORCE



T/20180616/2029

Police Station Of Origin
Tampines N P C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

Report No: T/20180616/

CONTINUATION OF REPORT

Brief Details:

On the 14th of June 2018 at about 2:25hrs, I was traveling (SGX7513G) on the first lane along Braddell Road, towards Central Expressway, Ang Mo Kio. The traffic was moving slowly and my car was stationary, behind another vehicle. When I was about to move off, the car (SLL810Z) behind me hit onto the rear portion of my car.

Due to the accident, my rear bumper had dents. The other vehicle only had dent on his front plate number.

The other driver is namely Louis (hp no: 93877067).

At that point of time, no one was injured. On the 15th of June 2018, I started to feel pain on my neck, down to my lower back. I went to see the doctor and obtained 3 days MC from 15th to 17th of June 2018.

Accident Sketch Plan

Driver



Driver



Author: Nils	Editor: 18/06/2012	Rev: 70000040
--------------	--------------------	---------------

FIELD DATA

Class 1B	Motorcycle - not exceeding 200 cc.	14 May 1961
Class 1A	Motorcycle - between 201 cc. and 400 cc.	14 May 1961
Class 2	Motor Cycle and Motor Tractor The weight 1.07 gallon - between 400 cc. and 750 cc. 400 cc. and 750 cc.	21 June 1964

1997-1998

X1597

Police Report



**SINGAPORE
POLICE FORCE**



T/20180616/2029

1 of 3

Police Station Of Origin:
Tampines N.P.C.
6 Tampines Avenue 4 SINGAPORE 529682
Tel No. 1800-5871999

Report No. T/20180616/2029

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made 16/06/2018 10:32		Vide Report No.		Station Diary No. 45	
Informant's Particulars					
Name of Informant SUHAIMIY B ABDEL JALIL A M D			Address APT BLK 712 TAMPINES STREET 71 #03-156 SINGAPORE 520712		
ID Type / ID No NRIC NO / S1805355A			Contact No Home/Office Mobile: 91874892		
Nationality SINGAPORE CITIZEN			Email		
Sex Male	Age 51	Date of Birth 04/03/1967	Type of Informant Driver		
Race Malay			Language		Institution / School Name
Occupation TECHNICIAN			Driving Licence Information Class		Date of Expiry

General Information of the Accident

Type of Accident	Injury Others	Drink Drive No	Date/Time of Accident 14/06/2018 21:25	Type of Location Straight Road
Location Along Road 1 BRADDELL ROAD				
TOWARDS CTE, AMK				
Weather Clear		Road Surface Dry		Road Speed Limit
Traffic Flow Dual Carriage Way		Traffic Control Not Controlled		Traffic Volume Heavy
Type of Collision Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SGX7513G	Car	TOYOTA	WISH 1.8 A	Grey	Slightly Damaged	0
SLL810Z	Car	SUBARU	OUTBACK 2.5i-S CVT AWD SR	Silver	Slightly Damaged	0

Police Report



SINGAPORE
POLICE FORCE



T/20180616/2029

Police Station Of Origin:
Tampines N P C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No. 1800-5871999

Report No. T/20180616/

CONTINUATION OF REPORT

Brief Details.

On the 14th of June 2018 at about 2125hrs, I was travelling (SGX7513G) on the first lane along Braddell Road, towards Central Expressway, Ang Mo Kio. The traffic was moving slowly and my car was stationary behind another vehicle. When I was about to move off, the car (SLL810Z) behind me hit onto the rear portion of my car.

Due to the accident, my rear bumper had dents. The other vehicle only had dent on his front plate number.

The other driver is namely Louis (hp no. 93877087).

At that point of time, no one was injured. On the 15th of June 2018, I started to feel pain on my neck, down to my lower back. I went to see the doctor and obtained 3 days MC from 15th to 17th of June 2018.

Police Report



SINGAPORE
POLICE FORCE



T/20180616/2029

Police Station Of Origin

Tampines N.P.C

6 Tampines Avenue 4 SINGAPORE 529662

Tel No. 1800-587 1999

Page 13

Report No. T/20180616/2029

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report

G /

Sgt 3 NURHIDAYAH BINTE IADIL

47551 STATION

1180510

Signature Of Interpreter

Not applicable

Officer In Charge Of Case

TP / AEIT /

SSI KASMAWATI BTE SAMIAN

Contact No. 65476179

Signature Of Informant

Date/Time

16/06/2018 10:32

Classification Of Case

Authentication Stamp

NP168

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0077Z
Vehicle Details	
Vehicle No.:	SGX7513G
Vehicle to be Exported:	No
Intended De-registration Date:	19 Jun 2018
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 A
Primary Colour:	Grey
Manufacturing Year:	2007
Engine No.:	1ZZ2927743
Chassis No.:	ZNE100370487
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$16,606.00
Original Registration Date:	05 Sep 2007
First Registration Date:	05 Sep 2007
Transfer Count:	2
Actual ARF Paid:	\$18,267.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Aug 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$25,486.00
COE Rebate Amount:	\$21,402.00
Total Rebate Amount:	\$21,402.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 19 Jun 2018

OK



Toyota Wish

Price Range ▼

Depreciation ▼

> 10 year(s) ▼

Vehicle Type ▼

Home » Used Cars » Prime Motor & Leasing » Toyota Wish 1.8A X Limited (COE till 11/2022)

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Toyota Wish 1.8A X Limited (COE till 11/2022)

Overview

Financial

Accessories

Similar

Research

Photos

Map

**PRIME MOTOR & LEASING**

(CHENG YONG CREDIT ENTERPRISES PTE LTD GROUP OF C

• PRIME CAR RENTAL & TAXI SERVICES PTE LTD • SECTION CREDIT & MOTOR LEASING PTE LTD • BEST PETROL AND DIESEL S

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Car Details

Price	\$35,500	
Depreciation	\$7,970 /yr	?
Reg Date	12-Dec-2007 (4yrs 5mths 11days COE left)	
Manufactured	2007	?
Mileage	-	
Transmission	Auto	
Engine Cap	1,794 cc	
Road Tax	\$1,069 /yr	?
Power	97.0 kW (130 bhp) View specs of the Toyota Wish (2008-2009)	
Curb Weight	1,300 kg	?
Features	Airbags, ABS, Reliable And Fuel Efficient 1.8L DOHC VVTI Engine, 4 Speed Steptronic Gear Box, Digital Climate Control Aircon.	
Accessories	Leather Seats, Sports Rims, DVD Player, Solar Film, Reverse Sensor.	
Description	Very Well Kept, \$4000 Drive Away, Perfect Condition.	
COE	\$25,084	?
OMV	\$18,810	?
ARF	\$20,691	?



Seller Infor

Company

Address

Commercial Vehicle



Compare

[New Cars](#)[Used Cars](#)[Sell My Car](#)[Directory](#)[Products](#)[Insurance](#)[Article](#)

Toyota Wish

Price Range ▼

Depreciation ▼

> 10 year(s) ▼

Vehicle Type ▼

[Home](#) » [Used Cars](#) » [Carzbond](#) » [Toyota Wish 1.8A \(COE till 05/2022\)](#)

Resources

[Car Buying](#)[Car Selling](#)[Car Ownership](#)[Car Aftermarket](#)[On The Move](#)[Lifestyle](#)

Car Rental

For Private &
Commercial Vehicles
Rental From

\$50/Day

Rent



Toyota Wish 1.8A (COE till 05/2022)

[Overview](#)[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)[Add to Shortlist](#)[Add to Compare](#)[Add a Note](#)[Report Error](#)[More Actions](#)

Car Details

Price \$29,800**Depreciation** \$7,540 /yr**Reg Date** 19-Jun-2007
(3yrs 11mths 12days COE left)**Manufactured** 2007**Mileage** -**Transmission** Auto**Engine Cap** 1,794 cc**Road Tax** \$1,069 /yr**Power** 97.0 kW (130 bhp)
[View specs of the Toyota Wish \(2008-2009\)](#)**Curb Weight** 1,300 kg**Features** -**Accessories** -**COE** \$26,246**OMV** \$15,788**ARF** \$17,367**Dereg Value** \$20,738 as of today (change)**No. of Owners** 3**Type of Veh** MPV**Category** COE Car**Availability** Available

Location Ma

[Seller Infor](#)[Company](#)[Address](#)[Location](#)[Office No](#)[Compare](#)[Add to Shortlist](#)[Add to Compare](#)[Add a Note](#)

	Rear windscreen moulding	rec
	Rear windscreen sealant	rec
	Rear windscreen inner feel	rec
	Tailgate	Body
	Tailgate rear logo	rec
	Tailgate outer chrome moulding	sent/cre
	Tailgate inner lock	DD/Stub
	Tailgate inner trim board	Del/Trim
	Tailgate weatherstrip	Trim
2pc	Tailgate dampers @	Range
	Rear licence plate	SW
	Rear bumper	DIS
	Rear bumper bracket OLS	DD
2pc	Rear bumper retainers	sent
1set	Rear bumper clips	rec
	Rear bumper reverse sensor	Stub
	Rear end panel	DD
	Rear end panel lower member	Repair
	Rear end panel top garnish	Twisted
2pc	Taillamps	cracked
	Taillamp housing panel	Repair
	Rear floor panel	Repair
	Rear fender inner trim board OLS	Del/cre
	Rear reverse camera	?
	Rear exhaust	Repair
	Rear exhaust heat shield	Repair

1dy.

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Jun 2018 Edit Reg		19 Jun 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main		Reference		Claim Details		Documents		Show All
------	--	-----------	--	---------------	--	-----------	--	----------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	LIM THYE HOE, ID: S6938158H		
Main Claimant:	MDM NOR SYABARIYAH BTE SAIRI, ID: S7810077Z		
Vehicle Reg. No.:	SGX7513G	Date of Loss:	14/06/2018 21:00 - :59 [129 Months and 9 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 2534531514SG	Policy/Cover Note No.:	2100500928 (Comprehensive)
Vehicle Reg. No. (Insured):	SLL810Z	Policy No. (Claimant):	
		Excess:	
Repairer:	6 Speed Autowerkz Pte Ltd (HQ) 68 KAKI BUKIT AVENUE 6, #02-05 ARK@KB, 417896 Kaki Bukit - Tel: 85332934		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 29/06/2018]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (21/06/2018): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)





























Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SGX7513G (2534531514SG)**
[SLL810Z]
TP
MDM NOR SYABARIYAH BTE SAIRI
Jun 14 2018 9:00PM
[LIM THYE HOE]
6 Speed Autowerkz Pte Ltd

<div>Upload Documents</div> <div>Upload Photos</div> <div>Compose New Letter</div> <div>Upload Video</div> <div>Upload Audio</div>			View	View in Browser
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/06/18 16:58	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
2	20/06/18 16:58	General View	Load JPG	<input checked="" type="checkbox"/>
3	20/06/18 16:58	General View	Load JPG	<input checked="" type="checkbox"/>
4	20/06/18 16:58	General View	Load JPG	<input checked="" type="checkbox"/>
5	20/06/18 16:58	General View	Load JPG	<input checked="" type="checkbox"/>
6	20/06/18 16:58	General View	Load JPG	<input checked="" type="checkbox"/>
7	20/06/18 16:58	General View	Load JPG	<input checked="" type="checkbox"/>
8	20/06/18 16:58	General View	Load JPG	<input checked="" type="checkbox"/>
9	20/06/18 16:58	General View	Load JPG	<input checked="" type="checkbox"/>
10	20/06/18 16:58	General View	Load JPG	<input checked="" type="checkbox"/>
11	20/06/18 16:58	General View	Load JPG	<input checked="" type="checkbox"/>
12	20/06/18 16:58	General View	Load JPG	<input checked="" type="checkbox"/>
13	20/06/18 16:58	General View	Load JPG	<input checked="" type="checkbox"/>
14	20/06/18 16:58	General View	Load JPG	<input checked="" type="checkbox"/>
15	20/06/18 16:58	General View	Load JPG	<input checked="" type="checkbox"/>
16	20/06/18 16:58	General View	Load JPG	<input checked="" type="checkbox"/>
17	20/06/18 16:58	General View	Load JPG	<input checked="" type="checkbox"/>
18	20/06/18 16:58	General View	Load JPG	<input checked="" type="checkbox"/>
19	20/06/18 16:58	General View	Load JPG	<input checked="" type="checkbox"/>
20	20/06/18 16:58	General View	Load JPG	<input checked="" type="checkbox"/>
21	20/06/18 16:58	General View	Load JPG	<input checked="" type="checkbox"/>
22	20/06/18 16:58	General View	Load JPG	<input checked="" type="checkbox"/>
23	20/06/18 16:58	General View	Load JPG	<input checked="" type="checkbox"/>
24	20/06/18 16:58	General View	Load JPG	<input checked="" type="checkbox"/>
25	20/06/18 16:58	General View	Load JPG	<input checked="" type="checkbox"/>
26	20/06/18 16:58	General View	Load JPG	<input checked="" type="checkbox"/>
27	20/06/18 16:58	General View	Load JPG	<input checked="" type="checkbox"/>
28	20/06/18 16:58	General View	Load JPG	<input checked="" type="checkbox"/>
29	20/06/18 16:58	General View	Load JPG	<input checked="" type="checkbox"/>
30	20/06/18 16:58	General View	Load JPG	<input checked="" type="checkbox"/>
31	20/06/18 16:58	General View	Load JPG	<input checked="" type="checkbox"/>
32	20/06/18 16:58	General View	Load JPG	<input checked="" type="checkbox"/>
33	20/06/18 16:58	General View	Load JPG	<input checked="" type="checkbox"/>
34	20/06/18 16:58	General View	Load JPG	<input checked="" type="checkbox"/>
35	20/06/18 16:58	General View	Load JPG	<input checked="" type="checkbox"/>

Photos/Images				
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	20/06/18 16:58	General View	 Load JPG	<input checked="" type="checkbox"/>
37	20/06/18 16:58	General View	 Load JPG	<input checked="" type="checkbox"/>
38	20/06/18 16:58	General View	 Load JPG	<input checked="" type="checkbox"/>
39	20/06/18 16:58	General View	 Load JPG	<input checked="" type="checkbox"/>
40	20/06/18 16:58	General View	 Load JPG	<input checked="" type="checkbox"/>
41	20/06/18 16:58	General View	 Load JPG	<input checked="" type="checkbox"/>
42	20/06/18 16:58	General View	 Load JPG	<input checked="" type="checkbox"/>
43	20/06/18 16:58	General View	 Load JPG	<input checked="" type="checkbox"/>
44	20/06/18 16:58	General View	 Load JPG	<input checked="" type="checkbox"/>
45	20/06/18 16:58	General View	 Load JPG	<input checked="" type="checkbox"/>
46	20/06/18 16:58	General View	 Load JPG	<input checked="" type="checkbox"/>
47	20/06/18 16:58	General View	 Load JPG	<input checked="" type="checkbox"/>
48	20/06/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	20/06/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	20/06/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	20/06/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	20/06/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	20/06/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	20/06/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	20/06/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	20/06/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	20/06/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	20/06/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	20/06/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	20/06/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	20/06/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	20/06/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	20/06/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	20/06/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	20/06/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	20/06/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	20/06/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	20/06/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	20/06/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	20/06/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	20/06/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	20/06/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	20/06/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	20/06/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	20/06/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	20/06/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	20/06/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	20/06/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	20/06/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	20/06/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	20/06/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	20/06/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	20/06/18 16:59	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Photos/Images				
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	20/06/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	20/06/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	20/06/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	20/06/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	26/06/18 20:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	26/06/18 20:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	26/06/18 20:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	26/06/18 20:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	26/06/18 20:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	26/06/18 20:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	26/06/18 20:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	26/06/18 20:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	26/06/18 20:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	26/06/18 20:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	26/06/18 20:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	26/06/18 20:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	26/06/18 20:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	26/06/18 20:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	23/07/18 10:27	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
103	23/07/18 10:27	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
104	23/07/18 10:27	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
105	23/07/18 10:27	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
106	23/07/18 10:27	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
107	23/07/18 10:27	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
108	23/07/18 10:27	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
109	23/07/18 10:27	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
110	23/07/18 10:27	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
111	23/07/18 10:27	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
112	23/07/18 10:27	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
113	23/07/18 10:27	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
114	23/07/18 10:27	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
115	23/07/18 10:27	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	21/06/18 17:12	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured..

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties..

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18011068/UZ4D3S2
 Date: 23/07/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100500928
 Claimant Vehicle No: SGX7513G Insured Vehicle No: SLL810Z
 Date of Loss: 14/06/2018 Nature of Claim: TP Claim No: 2534531514SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGX7513G**
 Make & Model: TOYOTA WISH, 1.8 (A) Engine No: 1ZZ2927743
 Reg. Date: 05/09/2007 (Man. Year: 2007) Chassis No: ZNE100370487
 Colour: Silver Odometer: 132486 km
 Engine Capacity: 1794 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16
 Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
 Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 19/06/2018
 Date Inspected: 19/06/2018 Inspected At: 6 Speed Autowerkz Pte Ltd (HQ)
 68 KAKI BUKIT AVENUE 6, #02-05 ARK@KB
 Singapore 417896
 Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	0.00 F	*- F
2	1		*REAR WINDSCREEN SEALANT	Necessary	0.00 F	*- F
3	1		*REAR WINDSCREEN INNER SEAL	Necessary	0.00 F	*- F
4	1		*TAILGATE	Badly Dented	0.00 F	*- F
5	1		*TAILGATE REAR LOGO	Necessary	0.00 F	*- F
6	1		*TAILGATE OUTER CHROME MOULDING	Bent / Cracked	0.00 F	*- F
7	1		*TAILGATE INNER LOCK	Dented / Shorted	0.00 F	*- F
8	1		*TAILGATE INNER TRIM BOARD	Deformed / Torn	0.00 F	*- F
9	1		*TAILGATE WEATHERSTRIP	Torn	0.00 F	*- F
10	2		*TAILGATE DAMPERS	Damaged	0.00 F	*- F
11	1		*REAR LICENCE PLATE	Broken	0.00 F	*- F
12	1		*REAR BUMPER	Distorted	0.00 F	*- F
13	1		*REAR BUMPER BRACKET O/S	Dented	0.00 F	*- F
14	2		*REAR BUMPER RETAINERS	Bent	0.00 F	*- F
15	1		*SET REAR BUMPER CLIPS	Necessary	0.00 F	*- F
16	1		*REAR BUMPER REVERSE SENSOR	Shorted	0.00 F	*- F
17	1		*REAR END PANEL	Dented	0.00 F	*- F
18	1		*REAR END PANEL LOWER MEMBER	Repair	0.00 F	*- F
19	1		*REAR END PANEL TOP GARNISH	Twisted	0.00 F	*- F
20	2		*TAILLAMPS	Cracked	0.00 F	*- F
21	1		*TAILLAMP HOUSING PANEL	Repair	0.00 F	*- F
22	1		*REAR FLOOR PANEL	Repair	0.00 F	*- F
23	1		*REAR FENDER INNER TRIM BOARD O/S	Deformed / Cracked	0.00 F	*- F
24	1		*REAR REVERSE CAMERA	*Check	0.00 F	*- F
25	1		*REAR EXHAUST	Repair	0.00 F	*- F
26	1		*REAR EXHAUST HEAT SHIELD	Repair	0.00 F	*- F

F=Franchise part.

Total Parts (\$\$)

0.00

0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >